JOURNAL

OF THE

AMERICAN WATER WORKS ASSOCIATION

COPYRIGHT, 1945, BY THE AMERICAN WATER WORKS ASSOCIATION

Reproduction of the contents, either as a whole or in part, is forbidden, unless specific permission has been obtained from the Editor of this JOURNAL. The Association is not responsible, as a body, for the facts and opinions advanced in any of the papers or discussions published in its proceedings.

Vol. 37

. 37

ereand han

ent

and the

lled

the reen

The om-

ing.

rom

cifi-

g or

ould

de-

1 - 3,

pay-

-12.

ion."

bid

d an

iling

October 1945

No. 10

Transformations of Iron by Bacteria in Water

By Robert L. Starkey

Assoc. Microbiologist, New Jersey Agric. Expt. Sta., Rutgers Univ., New Brunswick, N.J.

A contribution to the Journal

ONDITIONS in water favor the growth of many different microorganisms. Principal among these are algae which require only mineral nutrients from the water and obtain their energy from sunlight. There are also many bacteria, as well as filamentous fungi and protozoa, that grow on organic materials and develop extensively in waters containing large amounts of organic matter. Still other bacteria can develop in water containing little or no organic matter but in which there are ferrous or manganous compounds, sulfides or certain other incompletely oxidized mineral substances which can be used by iron bacteria, sulfur bacteria or other autotrophic bacteria as sources of energy for growth. The development of algae, heterotrophic micro-organisms and autotrophic bacteria may be so profuse in water supplies that it is necessary to provide a means to prevent their growth and the formation of their objectionable products.

In developing methods of control it is desirable to establish the nature of the organisms causing the trouble and to know the characteristics and growth requirements of these organisms.

The iron bacteria, which are members of the third group, are some of the most important fouling organisms, since they not only produce troublesome accumulations of cell material but also still greater quantities of ferric hydrate. In addition to the iron bacteria there are various other bacteria, including sulfur bacteria and sulfatereducing bacteria, which are responsible for various transformations of iron. Some bring iron into solution, others cause its precipitation and, in certain instances, the bacteria are responsible for corrosion. These reactions may be due to changes in pH, to oxidation or reduction, to production of sulfide, to differences in concentration of CO₂ or to the formation and decomposition of organic compounds of iron, all of which

00

or

iro

as

fro

wa

but

iro

tan

wat

tion

coll

crea

ppn

the

forn

ferr

loos

Gall

but

also

belie

resp

wate

Ther

brow

the v

a bla

that

wells

odors

bacte

after

for se

tion o

and s

pipes,

jection

organ

many

from t

are fila

tribute

monly

The

can be brought about by micro-organisms. The reactions affect inorganic compounds of iron in solution or in the solid state, organic compounds, and even metallic iron.

Some of the iron transformations are brought about by bacteria having specific physiological characteristics intimately associated with the iron transformations, whereas in other cases the transformation of the iron is incidental to the normal development of the bacteria. It is important to establish the characteristics of the different bacteria in order to understand their relationships to the various changes which iron undergoes. Some of these bacteria and their actions are:

1. Iron bacteria. Oxidize ferrous iron to ferric iron and effect the precipitation of ferric hydrate.

2. Non-specific bacteria. Cause changes in the iron content of water by altering the environmental conditions.

(a) Cause changes in reaction. Increase in acidity tends to bring iron into solution while decrease in acidity tends to cause precipitation.

(b) Cause changes in the degree of oxidation and reduction. Oxidation tends to favor precipitation, whereas reduction favors solution.

(c) Produce and decompose organic compounds of iron. Organic iron compounds which are slightly ionized tend to remain in solution, but decomposition of slightly ionized organic compounds of iron leads to iron precipitation.

(d) Cause changes in the CO_2 content of water. Increase in CO_2 content tends to favor solution, large amounts of CO_2 may cause precipitation, and decrease in CO_2 content favors precipitation.

3. Sulfur bacteria. Some of the bac-

teria increase the acidity and thus tend to dissolve iron; under specific conditions insoluble iron sulfate may be produced.

4. Sulfate-reducing bacteria. Iron becomes precipitated by a direct reaction with sulfide which is produced by sulfate reduction. These bacteria also effect the anaerobic corrosion of iron, but by another reaction.

It is apparent that there are numerous changes of iron in which bacteria take part in addition to those which are brought about by the iron bacteria. Whereas non-specific bacteria may be associated with iron precipitation, some of them are also important as agents of solution of iron, and, as such, provide conditions favorable for subsequent precipitation which may lead to turbidity of water or fouling of pipes.

Iron Bacteria

The development of iron bacteria may manifest itself in several ways. There may be hard deposits which tend to fill up the pipes and reduce their water-carrying capacity. and accumulations of filamentous bacteria may form on the walls of pipes and water holders and scum may be produced on the water surface. These bacteria may cause turbidity and discoloration of water and be responsible for some of the unpleasant tastes and odors which are produced either directly or indirectly as the dead bacterial cells are decomposed by other micro-organisms. Cases of very profuse development of the filamentous iron bacteria have been referred to as "water calamities."

Control problems have arisen with water from some deep wells (1, 3) and organic soils (8), since these waters carried considerable amounts of iron

01.37

tend

ndi-

pro-

Iron

reac-

d by

also

iron,

merteria

1 are

eria.

y be

some

gents

proabse-

id to

ipes.

teria

vavs.

vhich

duce

Slime

bac-

pipes

y be

These

dis-

isible

and

r di-

bac-

other

pro-

ntous

to as

with

) and

raters

iron

or manganese in solution as inorganic or organic compounds. Surface waters may also cause difficulties, due to the iron content of the raw water as well as to iron which becomes dissolved from pipes and other equipment. Larson (5) reports a case where the water was iron-free upon leaving the plant but where there was as much as 8 ppm. iron at the end of the line a short distance away which gave rise to "red water." Tenny (8) reports a condition in Des Moines, Iowa, where water, collected below ground, showed an increase in iron content to more than 0.6 opm. In the concrete gallery where the water was gathered iron bacteria formed thread-like growths coated with ferric hydrate, some of which broke loose and gave the water a red color. Gallionella was particularly prominent, but Leptothrix and Sphaerotilus were also encountered. Iron bacteria are believed by Carroll (3) to have been responsible for bad odor and taste of water which came from deep wells. There was a heavy deposit of soft brown material in the reservoir, and the water at the ends of the lines had a black color. Alexander (1) states that even though the water from deep wells may be free from bacteria and odors when the deposit is first tapped, bacteria and their products may appear after the deposit has been drawn upon for some time. The result is formation of slime and development of iron and sulfur bacteria in the tanks and pipes, causing the water to have an objectionable odor and taste.

The iron bacteria are typical water organisms. They are aerobic, and many of them differ morphologically from the common bacteria in that they are filamentous. They are widely distributed in nature and are found commonly in stagnant water, wells, mines.

springs and in quiet parts of streams, marshes and lagoons, as well as in reservoirs and water pipes, but seldom in open water. They are not normal inhabitants of water that does not contain an appreciable amount of iron in solution.

They are characterized by an unusual capacity for accumulating ferric hydrate around their cells, which gives them a brown to rust-red color. Manganese compounds also are oxidized by some of the iron bacteria and compounds of manganese may sometimes exceed in amount those of iron in the material precipitated by the bacteria (7, 11). It is generally assumed that the iron and manganese have played some role of importance to the cells preceding their precipitation.

The iron bacteria are fouling organisms and not agents of corrosion. It sometimes happens that the surface of the fouled metal shows evidences of corrosion, but in such cases it is probable that the corrosion was caused only indirectly by the iron bacteria.

Iron bacteria are particularly important fouling organisms since they accumulate large amounts of ferric hydrate, amounts many times greater than those of the bacterial cell material. It has been calculated that, as a result of growth of the bacteria on the ferrous iron in solution, there will be about 500 times as much precipitate of ferric hydrate as cells of the iron bacteria. This is of particular importance in establishing the cause of water troubles. It is apparent that, in cases where the iron bacteria have been the sole cause of the trouble, there will be an abundance of ferric hydrate and that the cells of the bacteria will be comparatively inconspicuous. If the fouling material consists principally of bacterial filaments and slimes with com-

tl

he

be

th

no

M

th

lik

occ

ter

cha

orio

The

tail

fere

Ord

Ord

F

Orde

Fa

Man

teria

nume

gener

paratively little ferric hydrate, the condition could not have been due to growth of the bacteria on ferrous iron to any appreciable extent. In such cases it is more likely that the bacteria had developed on the organic constituents of the water or some material other than the ferrous iron.

Some of the ferric hydrate which becomes precipitated on the walls of a pipe may come from the pipe itself and go into solution at one point only to be oxidized and deposited elsewhere. The principal source of iron in many cases, however, is the water delivered to the distribution system. This has been demonstrated where deposition has been controlled by freeing water of iron at the water works. There is further evidence in the results of Schorler (7), who found that pipes which were coated inside with asphalt became heavily incrusted with iron even though the surface of the pipe was intact and free from corrosion. Iron bacteria also develop on concrete if the water contains sufficient iron and if other conditions are favorable for their development. A case of this type was discussed by Tenny (8). Reddick and Linderman (6) concluded, however, that cement prevents tuberculation, since it both covers the metal and makes the reaction alkaline.

Further evidence that the iron need not come from the surface upon which the iron bacteria develop is provided by tests made with inert materials. In cases where iron deposition occurred, growth of iron bacteria was obtained on glass surfaces submerged in the water. In fact, microscope slides and coverslips which have been exposed in this way have been used to study the morphology of iron bacteria.

Although it is important to microbiologists to establish the mechanism of

precipitation, this information is not always necessary in order to deal with the troublesome accumulation of iron deposits in water distribution systems. Nevertheless, more definite information regarding these bacteria may serve as a guide for the development of more effective control measures. The pertinent fact is that these bacteria occur in accumulations of precipitated iron and are concerned in the formation of these accumulations. Any means which can be used to prevent their development can be expected to aid in preventing fouling. Control procedures may center about the destruction of the bacteria themselves or the removal of the iron from the water before it enters the distribution system. Their ability to precipitate iron depends on the composition of the water, and particularly on the presence of iron in the water and the compounds in which it occurs.

Many conflicting ideas have been expressed concerning the iron bacteria their physiology and their relationships to the precipitation of iron. According to some investigators they are the principal agents of iron precipitation in nature and the cause of most of the trouble resulting from iron precipitation in water works and distribution systems. Others consider that these bacteria are but one of several agents responsible for the precipitation of There is similar lack of agreement regarding the means by which the iron is precipitated by the bacteria Whereas there is widespread belief that iron bacteria are autotrophicthat is, that they live on the energy released by the oxidation of ferrous im to ferric iron-it is contended by other that many, if not most, of the iron barteria live on organic materials and fect the precipitation of iron incident

ol. 37

s not

with

iron tems.

orma-

serve

more

per-

occur

iron

on of

neans

ir de-

id in

oroce-

action

ne re-

before

Their

ds on

i par-

in the

nich it

en ex-

cteria

nships

ording

prin-

on in

of the

cipita-

bution

these

agents

on o

agree-

ich the

cteria

belie

phic-

rgy it

is iron

others

on bac

and e

cident

ally during their growth. It is probable that the iron bacteria are not all alike physiologically and that no single explanation of the precipitation of iron would be equally applicable to all of them. There is no reason to doubt, however, that there are bacteria which become coated with ferric hydrate, that these bacteria have distinctive morphological characteristics, or that their normal habitat is iron-bearing waters.

Morphology

The iron bacteria can be placed in three different morphological groups:

1. Haplobacteria, which are shaped like the common bacteria; and which occur singly or in irregular aggregates.

2. Trichobacteria or filamentous bacteria, whose filaments are composed of chains of cells enclosed in a sheath.

3. Stalked bacteria, which are oriented from top to base.

They have been classified more in detail under three orders in several different genera, the principal of which are listed below:

Order I. Eubacteriales (true bacteria)

Genus 1. Siderocapsa

Order II. Chlamydobacteriales (filamentous bacteria)

Family 1. Chlamydobacteriaceae

Genus 1. Sphaerotilus

Genus 2. Clonothrix Genus 3. Leptothrix

Genus 4. Crenothrix

Order III. Caulobacteriales (stalked bacteria)

Family 1. Gallionellaceae Genus 1. Gallionella

Many additional genera of iron bacteria have been proposed and also numerous species of most of these genera have been described, but only

a few typical species are mentioned below. [For further details see the monographs by Cholodny (13) and Dorff (15).]

Siderocapsa. These organisms are coccoid cells or short rods occurring in small colonies composed of from one to 30 cells, most frequently less than ten, surrounded by a mucoid capsule. In all colonies the outer deposit surrounding the capsule of a single colony or a group of colonies is rust-brown in color due to accumulated ferric hydrate. The cells of S. treubii are 0.6 to 1.6µ in diameter, whereas S. major is a small rod measuring 1.4 to $1.0 \times 2\mu$. The cells are readily stained by an ammonium-oxalate crystal-violet solution. Most results seem to indicate that these bacteria live on organic materials and are not autotrophic. It is possible that the occurrence and development of Siderocapsa is sometimes overlooked and their importance as fouling organisms is underestimated, since they are less readily detected than the large filamentous bacteria.

Chlamydobacteriales. Bacteria of this order are filamentous, alga-like and sheathed. Most of them are unbranched, but some show false branching. In the latter case the branches arise following displacement of the cells in the filament from which new branches are formed. Thus the sheath is branched whereas the filaments are separate. The sheath may be composed entirely of organic matter, or of organic matter impregnated with iron, or entirely of ferric hydrate. In some cases conidia and motile swarmer cells are produced.

Sphaerotilus (Cladothrix). These are colorless filaments attached at the base and showing false branching. The filaments are composed of rod-shaped or oval cells surrounded by a firm

sheath which is soft and slimy and contains no ferric hydrate. Reproduction is by non-motile conidia or motile swarmer cells. The most common species is *S. natans*. It is very widely distributed and is generally found in waters containing organic materials such as sewage or water where leaves and algae are undergoing decomposition. It has been cultivated in organic media, but its ability to live on iron compounds is questioned.

Clonothrix. These are filaments attached at the base and showing false branching. The sheath is organic and encrusted with iron. The filaments are broader at the base $(5-7\mu)$ than at the tapering tips (2μ) . The cells are cylindrical and reproduce by spherical conidia which are formed in chains by transverse fission. The type species, Clonothrix fusca, has been reported to be a common iron bacterium in water works and pipes carrying water.

Leptothrix (Chlamydothrix). Members of this genus consist of cylindrical cells joined in long filaments enclosed in a common sheath which is first thin and colorless and later thicker, vellow or brown, and encrusted with ferric hydrate. There is very little evidence of a sheath in the young cells, and the sheath of old cells can be almost entirely dissolved with dilute HCl, suggesting that it contains very little organic matter. When the sheath is removed with acid the inner cells are revealed. Reproduction is by cell division, fragmentation of filaments and motile cylindrical swarmer cells measuring 0.7×2 to 14μ . Some species show true branching. Most cells are not attached, whereas some are attached at the base by holdfasts. The filaments of the type species L. ochracea have an inner diameter of

about 1µ and a sheath from 0.5 to 1µ thick. The filaments may attain a length of 1 cm. The brittle and delicate sheath enclosing the cells becomes thickened and brown as iron is deposited. The cells may creep out of old sheaths and leave behind the empty tubes of ferric hydrate. The new cells then form a new sheath. These bacteria are common inhabitants of running and stagnant iron-bearing waters and are encountered in water works. L. ochracea is likely to occur in pure well waters and springs which are poor in organic matter, whereas L. crassa is found more commonly in slow-flowing water containing some organic matter. Among the species of Leptothrix are facultative autotrophs. Some have been cultivated in organic media.

Crenothrix. These are unbranched filaments which are attached at the base. The cells are enclosed in a sheath composed of organic matter which is at first thin and colorless and later becomes thickened and takes on the brown color of the precipitated ferric hydrate. The cells are cylindrical to spherical, dividing in three planes to produce non-motile conidia 1 to 2μ in diameter. The type species is C. polyspora, which differs from other iron bacteria in that it is very large; the filaments may be several millimeters long and 2μ in diameter. The filaments expand toward the tip where conidia are released. It has been found commonly in wells and water pipes and frequently occurs together with Gallionella. It also grows in running water containing organic matter and iron salts and produces thick masses having a brown or green color. It has been reported to be one of the most troublesome iron bacteria in water supplies. C. polyspora is probably a facultative autotroph.

Fig. showing false be Molisc

colo

abou

(17)

1.37

1 μ a a cate mes deof pty ells oacunters rks. ure oor a is ring ter. are ave

hed

the

n a tter and on ated vlinhree idia ecies rom very reral eter. tip has and to-OWS anic uces reen one

teria

a is

oph.

Fig. 1. Siderocapsa treubii. Multiple colonies surrounded by ferric hydrate. Mag. about 500 ×. From Hardman and Henrici (17), Fig. 4.



Fig. 2. Sphaerotilus dichotoma. Sketch showing false branching. Mag. about 230 ×. From Molisch (18), Fig. 3b.



Fig. 3. Clonothrix ferruginea. Sketch showing cells enclosed within a sheath, and false branching. Mag. about 430 ×. From Molisch (18), Fig. 4.



F₁₆. 4. Leptothrix ochracea. Sheaths from an accumulation of precipitated ferric hydrate in iron-bearing water. Mag. about 390 ×. From Molisch (18), Fig. 5.



Fig. 5. Leptothrix ochracea. Cells coming out of their sheath. Mag. about $2200 \times$. From Cholodny (13), Plate 4, Fig. 20.




Fig. 6. Crenothrix polyspora. Sketch showing details of false branching of cells within the sheath. Mag. about 380 ×. From Harder (16), Plate 1, Fig. A.



Fig. 7. Crenothrix polyspora. Cells enclosed within a sheath of ferric hydrate, and showing false branching. Mag. about 390 ×. From Harder (16), Plate 3, Fig. B.



Fig. 8. Crenothrix polyspora. Conida can be seen inside and coming out at the ends of the filaments. Mag. about 345 ×. From Cholodny (13), Fig. 5.

FI ends vision Plan

lik

Fr




Fig. 9. Gallionella ferruginea. Sketch showing cells at the ends of the long, ribbon-like excretion bands. Mag. about $540 \times$. From Cholodny (13), Fig. 9.

ketch

cells

From

onidia

e ends

From



Fig. 10. Gallionella major. Curved cells at the ends of excretion bands. Mag. about $1120 \times$. From Cholodny, *Planta*, V. 8, 1929, Fig. 6.




Fig. 11. Gallionella major. Cells at the ends of the excretion bands undergoing division. Mag. about 1180 ×. From Cholodny, Planta, V. 8, 1929, Fig. 3.




Fig. 12. Various iron bacteria including *Leptothrix* and *Gallionella* in accumulated precipitate of ferric hydrate in gallery water. From Tenny (8), Fig. 4.



Spiral cells of the sulfate-reducing bacterium Sporocubro desulfuricans. Mag. about 1660 ×. FIG. 13.




Fig. 14. Curved small cells of Sporovibrio desulfuricans. Mag. about 1600 x.

ce rice slet tir boo bac cur. Fe con by vis fila vis bra imp bra ma: The Cel The wand H is o iron cour and less

There has been an unwarranted tendency to label as "Crenothrix fouling" any trouble in water supplies caused by filamentous organisms without establishing the nature of the fouling organism.

Gallionella (Spirophyllum). The cells are asymmetrical and secrete ferric hydrate on one side to form a long slender twisted ribbon composed entirely of ferric hydrate. These ribhons serve as stalks which support the bacterial cells. The cells are small. curved, kidney-shaped rods $0.5 \times 1.2\mu$. Ferric hydrate is secreted from the concave side of the cells. They divide by transverse fission and, after division, each cell produces a secretion filament. At the point where cell division occurs, the secretion strand branches and this gives the erroneous impression that the organism itself is branched. The secretion filaments may attain a length of 200μ or more. The type species is G. ferruginea. Cells of G. major are larger $(1 \times 3\mu)$. These bacteria occur in iron-bearing water, are sensitive to organic matter and are believed to be strict autotrophs.

Harder (16) states that Gallionella is one of the most widely distributed iron bacteria, nearly as commonly encountered as Leptothrix. Crenothrix and Clonothrix, he says, are somewhat less common.

Physiology

desulfuricans. Mag. about 1660 X.

Although Ehrenberg associated micro-organisms with precipitation of iron in 1836 and Cohn presented a theory to explain this precipitation in 1875, particular interest in this phenomenon is traced to later work of Winogradsky whose ideas have dominated the subject as they have that of the physiology of the nitrifying and sulfur bacteria. His first report on

the iron bacteria, which appeared in 1888, followed studies of the sulfur bacteria which he had found were able to oxidize sulfur and utilize the energy released by this oxidation for their growth. It is not surprising that he came to the conclusion that iron bacteria were similar physiologically and that they used ferrous iron as a source of energy for development. It was Winogradsky who developed the concept of autotrophic bacteria, with which the iron bacteria and sulfur bacteria are The autotrophic bacteria are characterized by the following physiological properties:

1. They can develop in a medium containing no organic material and they require no externally supplied organic substances.

2. Their carbon requirements can be satisfied by dissolved CO₂.

3. All of the required energy can be obtained from the oxidation of some specific incompletely oxidized inorganic substance.

In the case of strict autotrophic bacteria some organic materials are toxic except at extremely low concentrations and the bacteria are unable to utilize the organic compounds which are generally included in culture media. There are certain facultative autotrophic bacteria which can develop in media containing only inorganic substances but which are able to grow on organic compounds as well.

The reaction by which the iron bacteria are presumed to live as autotrophs is as follows:

$$4 \text{ Fe(HCO}_3)_2 + 2 \text{ H}_2\text{O} + \text{O}_2 = 4 \text{ Fe(OH)}_3 + 8 \text{ CO}_2$$

This is an exothermal reaction which is believed to release sufficient energy to satisfy all of the requirements of the

C

SI

Cile

cl

m

re

de

ce

ne

ter

the

ide

im

bac

iro

tim

F

on

lish

for

reac

tion

are

crea

wate

Red

"Ou

belie

wate

bacteria. The strictly autotrophic iron bacteria, such as Gallionella ferruginea, are believed to depend on this reaction. whereas the facultative iron bacteria. including Crenothrix polyspora and some species of Leptothrix, are not limited to growth at the expense of ferrous iron but can also grow on organic compounds. Thus, those bacteria which are able to grow on either ferrous iron or organic materials may produce large amounts of precipitated ferric hydrate when they live on the ferrous iron, and produce accumulations of filamentous fouling material under conditions where they develop on the organic constituents of the water. In the former case they live as autotrophic iron bacteria and in the latter case they grow as heterotrophic bacteria.

In his initial studies on iron bacteria, Winogradsky presented convincing evidence in support of his conclusions that they oxidize ferrous iron in their cells, precipitate the resulting ferric hydrate outside the cells, and utilize the energy liberated by the oxidation reaction. His explanation of the mechanism of precipitation of iron has received additional support from the results of numerous studies, particularly those of Lieske and Cholodny, but it has not been universally accepted, and many theories have been advanced to explain the nutritional peculiarities of the iron bacteria. The results of Molisch (18) and others, the latest being Cataldi (12), have shown that many of the iron bacteria are able to grow on organic materials, and there is reason to believe that at least in the case of certain organisms classified as iron bacteria, precipitation of iron is the result of the decomposition of organic compounds of iron and not the oxidation of inorganic iron compounds.

The reason why progress in the study of the physiology of the iron bacteria has been slow is that it is very difficult to cultivate these organisms in laboratory media. With a few exceptions, they cannot be grown on ordinary media, and there are no known simple procedures for cultivating them. As a result, in most cases, studies have been limited to microscopic observations.

A brief consideration of some of the factors affecting growth of iron bacteria may aid in suggesting the conditions under which they are likely to be encountered, as well as give some indication of their physiological characteristics.

Temperature. Some of the iron bacteria show preference for low temperatures. According to Lieske, G. ferruginea grew under laboratory conditions from 0° to 22°C. with an optimum of 6°C. It has been commonly encountered in springs and cool waters but also in water pipes. Volkova (19) found Gallionella in mineral springs with temperatures as high as 27° to 32°C, but not at 40° to 50°C. Species of Leptothrix have also been found in waters at 1° to 2°C, but their optimum is reported to be higher than that of Gallionella. Lieske and Molisch obtained good growth of Leptothrix at 25°C. Others reported the optimum temperature as 15°C.

Light. The iron bacteria are not sensitive to light and have been found in exposed locations and in shade as well as within pipes where light is completely excluded.

Concentration of iron. The iron bacteria are greatly affected by the presence of dissolved iron but they tolerate considerable differences in iron concentration. Though they have been found in waters with from 10 to 30

1.37

the

iron

t is

gan-

few

on

no

vat-

ases,

сто-

the

bac-

ondi-

o be

e in-

char-

bac-

pera-

fer-

ondi-

opti-

nonly

aters

(19)

rings

7° to

pecies

nd in

imum

at of

h ob-

ix at

imum

e not

found

de as

com-

iron

y the

they

n iron

e been

to 30

ppm. iron, they also occur where the amount of iron is as low as from 0.1 to 0.3 ppm., particularly in moving water where the supply of iron is continuously renewed. Harder (16) reports active development of iron bacteria in pipes carrying water with 1.3 ppm. iron. Halvorson (31) found them in springs having 1 to 10 ppm. Schorler (7) records incrustation of 10-cm. pipes carrying water with from 0.2 to 0.3 ppm. iron. In 30 years a deposit was formed 3 cm. thick, leaving an opening only 4 cm. in diameter. In contrast, Knudsen (4) states that to cause tuberculation the water must contain 2 ppm. or more. It has been stated that fouling by iron bacteria occurs only with water containing at least 0.2 ppm. iron. It may be concluded that, though iron bacteria are most likely to appear in water with relatively high iron content, they may develop in water with low iron concentration if the supply of iron is renewed in flowing water.

The general occurrence of iron bacteria in iron-bearing waters is one of the strongest arguments in favor of the idea that the iron plays some role of importance in the development of the bacteria and that the precipitation of iron is the result of some reactions intimately related to their physiology.

Reaction. The influence of reaction on iron bacteria is not definitely established, but there are indications that for many of the organisms slightly acid reactions, such as those caused by solution of considerable amounts of CO₂, are most favorable. Slight acidity increases the iron-carrying capacity of water. With regard to tuberculation, Reddick and Linderman (6) state: "Our investigations to date lead us to believe that an alkaline iron-bearing water, having only a small content of

organic matter, will not tuberculate, and that a slightly acid water containing iron and having a high organic matter content will readily tuberculate." Knudsen (4) also concluded that tuberculation was more likely to occur in slightly acid waters. On the other hand, Volkova (19) found Gallionella in mineral springs having a pH of from 7.0 to 7.6. Wilson (9) reports a case of profuse development of Crenothrix in a large main which carried water nearly free of iron and manganese and having a pH of from 7.3 to 8.0. The organism grew in gelatinous masses, and it was presumed that the iron was derived from the pipe through the bases of the bacteria. In this case there is reason to suspect that the water contained organic materials which supported growth of the bacteria. Hardman and Henrici (17) recovered Siderocapsa regularly from alkaline hard water lakes but never from neutral or acid soft water lakes. These authors, as well as Cholodny, express the opinion that iron precipitates only incidentally during the development of these bacteria and that organic matter supplies their energy requirements for growth. Cataldi (12) cultivated Sphaerotilus and Leptothrix at pH 6.8 but organic media were used and conditions were not representative of those under which iron becomes precipitated. Wilson (10) controlled fouling by Crenothrix by making the water alkaline (pH 8.5) with sodium carbonate. Control may have been effected by making the reaction unfavorable to the iron bacteria, or it may have been due to the elimination of iron, manganese or organic matter upon which the bacteria depended for growth.

Oxygen. The iron bacteria are aerobic and as such are dependent on the presence of free oxygen. In stag-

nant water they are found only at the surface but they may find conditions favorable for growth below the surface adjacent to green plants which liberate oxygen through photosynthesis.

Organic matter. There is much conflicting evidence regarding the influence of organic materials on iron bacteria, but it has been definitely established that some of these organisms can grow on organic compounds, and it appears probable that at least some of the organisms which are now classified with iron bacteria actually require organic matter for growth. Sphaerotilus (Cladothrix) has been repeatedly grown on organic media, first in 1904 by Adler who used iron ammonium citrate, and subsequently by Molisch on mangan peptone, iron ammonium tartrate and other organic compounds. Most recently, Cataldi (12) reported that Sphaerotilus, as well as Leptothrix, was readily cultivated on organic media, but that it failed to grow in mineral media in which ferrous and manganous salts were used as the only sources of energy. Molisch carried L. crassa through 47 successive transfers in a nutrient solution containing from 1 to 2 per cent peptone to which no iron was added. Under these conditions the cells were colorless and had no iron in their delicate sheaths.

Although these results indicate that some of these bacteria can grow in the absence of organic matter, they do not prove that the bacteria are unable to grow by the oxidation of ferrous iron under suitable cultural conditions. In fact, it is significant that no one has succeeded in obtaining growth of *Gallionella* in organic media. Furthermore, Lieske found that certain organic compounds were actually toxic. Concentrations of from 0.25 to 0.35 per

cent of asparagin, sucrose and peptone inhibited growth; some depression was noted even at 0.01 per cent. This response is similar to that of some other autotrophic bacteria and suggests that Gallionella may indeed be strictly autotrophic. Gallionella has been encountered, nevertheless, in waters containing considerable organic matter, such as water in aquariums and ditches, as well as in springs and streams which are relatively free of organic matter.

On the basis of the scattered evidence of the influence of organic matter on the iron bacteria it may be tentatively concluded that Sphaerotilus, Siderocapsa and L. crassa require organic matter and may be strictly heterotrophic, that Crenothrix and Leptothrix ochracea are facultative autotrophs and that Gallionella is strictly autotrophic. In waters containing relatively large amounts of organic matter it is common to encounter Crenothrix and Leptothrix, whereas in water low in organic matter Gallionella is prominent.

Sources of nitrogen. The amounts of nitrogen required by the iron bacteria are very small compared to the requirements for iron and it is probable that the nitrogen content of most waters meets their needs. There is no specific information regarding the nitrogen compounds that they use, but some information can be obtained by checking the constituents of the culture media which have been used to grow the bacteria. Some of the media contained complex and diverse organic compounds of nitrogen, such as beef extract, peptone and plant extracts. Iron bacteria have also been cultivated in simpler media containing iron ammonium citrate and similar compounds and presumably the bacteria used the ammonium nitrogen to meet their retat att bac of ma

p

b

I

qt

ce

N

ni

Tr

the sim ade back formation num cond

of in In of ir the iin th

alter medi velop 1.37

one

was

re-

ther

that

uto-

un-

ain-

such

, as

hich

evi-

nat-

ten-

ilus,

or-

eter-

pto-

uto-

ictly

rela-

mat-

eno-

rater

a is

unts

bac-

the

orob-

most

is no

e ni-

, but

d by

cul-

ed to

nedia

ganic

beef

racts.

vated

am-

unds

d the

r re-

T.

quirements. Lieske stated that he succeeded in growing a culture of Leptothrix in a strictly mineral medium in which the nitrogen was supplied as ammonium sulfate. The medium in which he grew Gallionella contained both ammonium and nitrate nitrogen and it cannot be stated which was used by the organism. No definite conclusion can be drawn from such incomplete information except that certain hacteria can use inorganic nitrogen. It is of interest to note, however, that with some of the autotrophic bacteria, ammonium nitrogen is preferred or required and that nitrate nitrogen and certain amino acids are even toxic. With some other bacteria as well, such as the methane bacteria, ammonium nitrogen is used, whereas nitrate is toxic.

Transformations of Iron by Nonspecific Bacteria

In most discussions of iron precipitation by micro-organisms, principal attention has been devoted to the iron bacteria, in fact almost to the exclusion of all other microbial activities which may be directly or indirectly related to the phenomenon. This is an oversimplification of the subject and inadequately evaluates other important bacterial activities. As with all transformations in nature, iron precipitation in water occurs in the presence of numerous micro-organisms and under conditions where various strictly chemical reactions may alter the solubility of iron.

In cases where the transformations of iron are due to non-specific bacteria, the iron has no particular significance in the metabolism of the bacteria but is altered as a result of changes in the medium brought about by bacterial development. From the following re-

actions it is possible to make some predictions regarding the changes which may occur as a result of changes in reaction (pH)as well as those controlled by oxidation and reduction (33):

In the presence of solid ferric hydrate

$$\frac{[Fe^{++}]}{[H^+]^2} = \frac{K}{[O_2]^{0.25}}$$

Under atmospheric conditions or with constant oxygen pressure the reaction becomes

$$\frac{[Fe^{++}]}{[H^+]^2} = K'$$

In cases where the solution is saturated with iron, where there is an excess of solid ferric hydrate and where the oxidations by molecular oxygen are reversible, changes in the hydrogen-ion concentration and the oxygen pressure (degree of oxidation or reduction) will result in changes in the amounts of iron in solution. With a decrease in the oxidizing intensity, but at constant pH, there will be an increase in the concentration of ferrous ions. Since ferrous iron is more soluble than ferric iron, some of the solid ferric hydrate will go into solution and become With increasing oxygen pressure at constant hydrogen-ion concentration there will be a tendency for ferrous iron to become oxidized to ferric and, if the solution was initially in equilibrium, the increase in ferric iron will result in precipitation and a decrease in the amount of iron in solution.

With increase in hydrogen-ion concentration, but at constant oxygen pressure, there will also be an increase in the amount of dissolved ferrous iron through reduction of some of the ferric iron, which will cause some of the solid ferric hydrate to go into solution.

cl

di io pl

ab

ne

iro

to

noi

but

mic

cha

tion

of o

the

tion

the

stric

conc

the

the I

oxid

othe

other

no di

the

P

TABLE 1
Influence of Bacterial Development on Solution and Precipitation of Iron

Medium	pl	H	Fe++ in Solution, mg./100 ml.		
	Anaerobic	Aerobic	Anaerobic	Aerobic	
Dextrose	3.0	3.1 3.1*	0	0	
$\mathrm{Dextrose} + \mathrm{Fe}(\mathrm{OH})_{\mathfrak{d}}$	6.0	5.3 4.2*	71.88	12.50 11.88*	
Dextrose + Fe(OH) ₃	6.0	4.6 4.3*	73.75	21.88 12.50*	
Peptone	6.2	8.0 7.8*	0	0*	
Pe pto e + Fe(OH) ₃	6.4	8.2 8.0*	22.98	0	
Peptone + $Fe(OH)_3$	6.4	7.7 7.7*	16.25	0 0*	

^{*} Cultures treated with phenol at time of exposure to free air.

With decrease in the hydrogen-ion concentration, there will be a tendency for ferrous iron to be oxidized to ferric iron and precipitate. Some of the data in Table 1 show that during bacterial development in organic media, where conditions became strongly reducing because of lack of diffusion of oxygen, iron went into solution. In this experiment, culture media treated with either dextrose or peptone, with or without ferric hydrate, were inoculated with soil and incubated for three weeks. The medium nearly filled the culture flasks and thus suppressed diffusion of oxygen. As shown in the next to the last column, considerable iron was dissolved in the dextrose medium. This was due in part to the production of acid and it can be noted that the iron exerted a buffering effect and prevented the shift to the low pH shown in the medium containing no iron. The reaction of the peptone medium remained nearly constant irrespective of the presence of ferric hydrate and, even though the pH was close to neutrality, appreciable iron remained in solution. The results show that iron was dissolved under anaerobic conditions not only during decomposition of the carbohydrate where there was an increase in the acidity, but also during decomposition of nitrogenous materials where there was relatively little change in pH.

After the cultures had developed for three weeks, the solutions were poured into flat vessels to provide large surfaces in contact with the air. During the two-week period that these cultures were kept under aerobic conditions all of the iron precipitated from the peptone solutions and a large part disappeared from the dextrose media but some iron still remained in solution. These changes were independent of the action of bacteria, since phenotreated solutions behaved the same as

those in which no attempt was made to control bacterial development. Precipitation was doubtless due to an increase in the oxidizing intensity. It is of interest that there was an increase in the hydrogen-ion concentration in both the sterile and non-sterile dextrose solutions during aerobic treatment.

Even though the solutions which initially contained dextrose became more acid during exposure to the air, less iron was held in solution. This may seem contradictory, since an increase in the hydrogen-ion concentration favors solution of iron. changes in amounts of dissolved iron were caused by an increase in the oxidizing intensity and not the hydrogenion concentration. In fact, the completeness of precipitation of the iron during exposure to the air was probably limited somewhat by the acidity; if the reaction had remained close to neutrality, it is probable that all of the iron would have been precipitated.

Changes such as these are not due to the action of any specific bacteria nor are they caused by bacteria alone, but they can be effected by various micro-organisms and the extent of the changes is proportional to the alteration in the reaction and in the degree of oxidation. The principal effect of the bacteria in the experiment mentioned above was the solution of iron; the precipitation was the result of strictly chemical reactions. It can be concluded that generally an increase in the oxygen pressure or a decrease in the hydrogen-ion concentration leads to oxidation of iron and its precipitation.

Precipitation of iron by algae and other water plants may be cited as another example of a reaction which has no direct connection with the growth of the organism responsible for the

change. These green plants liberate oxygen by photosynthesis and thus provide more strongly oxidizing conditions in the water, leading to the oxidation and precipitation of iron on the plant surfaces. This type of reaction is relatively common in iron-bearing waters.

Mention should be made also of some of the changes which are caused by differences in the concentration of dissolved carbon dioxide (31). This gas is produced in such abundance that in some subterranean waters it greatly affects the solubility of iron. It is also produced in quantities by micro-organisms, by animals and by higher plants in the dark. Relatively large amounts of CO₂ may be removed from solution by green plants during photosynthesis. The mixed population of micro-organisms in general tends to increase the carbon dioxide concentration.

In order to follow the influences of carbon dioxide on iron concentrations. consider a solution which is saturated with CO2 and in which there is an excess of solid ferrous carbonate. CO₂ is removed from such a solution some of the solid ferrous carbonate goes into solution to replace the dissolved CO₂. This increases the ferrous iron concentration above the stable value and results in its oxidation to ferric iron followed by its precipitation as ferric hydrate. As more CO₂ is removed this sequence of events continues until all of the solid ferrous carbonate has become dissolved. amount of iron remaining in solution at the time when the CO₂ has all been removed would be determined principally by the reaction (pH) of the solution. The more acid the solution the greater would be the amount of dissolved iron. One would expect that there would be a slight decrease in the

8 0*

01.37

ml.

ic

ve of even rality, ation. diss not car-

erease ecomwhere n pH. eloped were ovide

these confrom

solundent nenol-

me as

0

cip

or

wh

sol

not

tio

ma

Sul

cas

tict

eler

fila

tro

Oth

rosi

T

cha

sulf

gen

reac

are

bact

filan

are ; 24),

are

logic

filan

orga

terec

wate

tribu

rega

they of s

whic

grow

films

teria

into able

Or

hydrogen-ion concentration as the $\rm CO_2$ was removed after the last portion of solid ferrous carbonate had gone into solution.

If CO2 were added to a solution which was saturated with ferric hydrate and in which there was an excess of ferric hydrate, there would be at first a slight increase in acidity. Some ferric hydrate would go into solution and a portion of this would be reduced to ferrous carbonate. Thus, in water stored under conditions where there is an increase in the CO2 concentration, conditions are favorable for solution of iron. As more ferrous carbonate was produced with the addition of more CO₂, the solution would become saturated, and further addition of CO. would result in the precipitation of ferrous carbonate. Continuous addition of CO2 would cause solution of more ferric hydrate and result in its reduction and subsequent precipitation as ferrous carbonate. This would continue until all of the ferric hydrate had become dissolved.

Thus by decreasing the partial pressure of CO, in the atmosphere below that of the solution there will be a tendency for CO, to come from the solution and this will favor precipitation of ferric hydrate. In addition, when the oxidation-reduction potential is increased there will be a tendency for oxidation and precipitation of Consequently, when subterranean waters come to the surface, conditions are favorable for both of these changes. In many cases this is responsible for the precipitation of ferric hydrate from the iron-laden waters issuing from the earth. The CO., escapes and there is some decrease in acidity, and this is followed by oxidation of ferrous to ferric iron which is precipitated as ferric hydrate. These

changes can occur in the absence of micro-organisms but it is possible that various organisms accelerate the reactions.

In studying the iron bacteria and other micro-organisms concerned in iron precipitation, organic media have been frequently used and, as mentioned earlier, ferric ammonium citrate is one of the common medium constituents. Although large amounts of organic compounds of iron may remain in solution at alkaline reactions, they remain soluble by reason of the fact that they are poorly ionized. If such compounds are decomposed by microorganisms, ionic iron is released in the medium and precipitates as ferric hydrate. There is nothing specific about the organisms concerned in this transformation except their ability to decompose the organic portion of the Studies with ferric amcompound. monium citrate are particularly informative in this connection. Escherichia coli and Aerobacter aerogenes differ in ability to decompose citrate. If flasks of a culture medium containing ferric ammonium citrate are inoculated with these two bacteria, iron will precipitate from the solution inoculated with Aer. aerogenes, but not from the one inoculated with Esch. coli. Iron precipitation by phenomena of this type is widespread. Many different organic compounds of iron occur in natural waters and various bacteria are concerned in the precipitation of iron from them.

In certain cases, the opposite may occur. During decomposition of organic matter by micro-organisms, iron may combine with some of the products of decomposition and form stable organic compounds. Thus, in certain locations iron may go into solution through microbial action and be pre-

ol. 37

e of

that

re-

and

d in

have

men-

trate

stitu-

f or-

main

they

fact

such

icro-

1 the

hy-

ransde-

the

am-

incher-

rate.

tain-

e in-

iron

in-

t not

Esch.

mena

dif-

occur

teria

11 of

may

or-

iron

orod-

table

rtain

ution

pre

cipitated some distance away through breakdown of the initially produced organic compounds.

Consideration of the various ways in which micro-organisms can affect the solution and precipitation of iron leads to the conclusion that iron bacteria are not the only agents of iron transformation but that various other bacteria may be of considerable importance.

Sulfur Bacteria

Some of the sulfur bacteria are occasionally encountered in water, particularly in water containing sulfide or elemental sulfur. In exceptional cases filamentous sulfur bacteria have been troublesome as fouling organisms. Other sulfur bacteria may cause corrosion.

The sulfur bacteria as a group are characterized by their ability to oxidize sulfur or various sulfur compounds, generally to sulfate, and to utilize these reactions in their development. There are morphologically different sulfur bacteria, varying from the complex filamentous organisms, some of which are pigmented and photosynthetic (20, 24), to the small simple bacteria which are hardly distinguishable morphologically from Esch. coli (23). The filamentous forms are typical water organisms and are sometimes encountered together with iron bacteria in water basins and even in water distribution systems. Little need be said regarding these organisms except that they may contribute to the formation of slimes and possibly to the tastes which develop in water where there is growth and breakdown of the slime films.

One of the typical, simple sulfur bacteria may bring large amounts of iron into solution under conditions favorable for its development. This is

Thiobacillus thiooxidans, an aerobic bacterium which has the capacity of oxidizing sulfur and certain incompletely oxidized sulfur compounds with the production of very high acidity (22). It is able not only to tolerate high acidity but to produce the acid as well. It has been recovered principally from soils and sulfur springs but it may also be encountered in water under special conditions. In several instances it was isolated from soils where the acidity was so extreme as to indicate an abnormality. In artificial media it has been cultivated at reactions close to pH 0 and it has produced acidity as high as 10 per cent sulfuric acid.

One of the most remarkable phenomena in which this organism played an important part was that recently reported by Harmsen (21), dealing with changes in some soils of the Wieringen Polder, an area of land reclaimed from the Zuiderzee in Holland. The bottom material of this arm of the ocean was black with sulfide. When the area was diked, the water pumped out and the soil drained, the sulfide underwent change, partly chemical and partly bacteriological. Some of the sulfide was oxidized to elemental sulfur, which was then attacked by T. thiooxidans. In locations where there was an abundance of lime in the soil the sulfuric acid which was formed became neutralized, as a result of which the rate of reclamation was greatly accelerated. In locations where there was little or no lime there was a rapid increase in acidity and large amounts of iron were dissolved from the soil materials. This went on to such an extent that quantities of basic ferric sulfate accumulated in the soils and gave them a characteristic yellowish to gray color. In some of the poorly buffered sandy soils the reaction became exceedingly

00

the

tan

tha

sol

wat

odo

par

sulf

are

ros

nisi

Wo

thes

ana

be

mai

that

cori

of t

that

pro

by

occt

bact

soils

sion

usua

that

acce

corr

to

Und

gen

proc

1

acid and in certain cases even had a negative pH.

It has been reported that these bacteria are concerned in the corrosion of iron pipelines. One case has been reported where a calking compound which contained sulfur was responsible for the trouble. When the sulfur was attacked by T. thiooxidans sufficient acid was produced to corrode the pipe severely at the joint.

Abnormally high acidity (below pH 2.0) has in the past served as a clue leading to the detection of this bacterium and to its identification as the agent responsible for the acid condition.

Sulfate-Reducing Bacteria

The sulfate-reducing bacteria are responsible for still other iron transformations than those discussed thus far. Sulfide, which is one of the principal products of their development, reacts with dissolved iron or metallic iron to form black insoluble iron sulfide. Furthermore, the bacteria have assumed particular significance since it was discovered that they are agents of corrosion.

They are not the only bacteria which form sulfide but they produce most of the sulfide of bacterial origin. Some sulfide is produced by various bacteria during decomposition of organic sulfur compounds under conditions of deficient aeration such as occur in sewage. Sulfide can also be formed by numerous bacteria by reduction of sulfite, thiosulfate, elemental sulfur and other incompletely oxidized inorganic sulfur compounds. Most of the sulfide in black muds of ocean sediments and tidal basins, as well as in poorly drained heavy soils, comes from the reduction of sulfate.

The bacteria which reduce sulfate to sulfide are of considerable interest, par-

ticularly because of their ability to effect this reaction. So far as is known there is only one specific group of bacteria which can reduce sulfate to sulfide. Thus, the sulfate-reducing bacteria are a highly specialized physiological group. Furthermore, they are morphologically distinct. They are curved cells, occasionally having a spiral shape. They are actively motile and form spores under suitable conditions. From time to time they have been listed under the genera Spirillum. Microspira, Vibrio, Desulfovibrio and. most recently, Sporovibrio. The most pro common species are Sporovibrio desulfuricans and S. rubentschickii. They are strict anaerobes and are heterotrophic. Sulfate is the specific hydrogen acceptor which serves the same purpose as free oxygen in the development of strict aerobic bacteria. Organic materials which provide energy for the growth of the sulfate-reducing bacteria become oxidized by the sulfate which is reduced to sulfide. One of the typical reactions whereby lactate is broken down to acetate and CO, and whereby sulfate is reduced to sulfide, is shown below:

$$2 \text{ CH}_3.\text{CHOH.COONa} + \text{CaSO}_4$$
Sodium lactate
$$= 2 \text{ CH}_3.\text{COONa} + \text{H}_2\text{S}$$
Sodium acetate
$$+ \text{CaCO}_3 + \text{CO}_2 + \text{H}_2\text{O}$$

This reaction is exothermal and can provide all the energy necessary for development of the bacteria. different compounds can be used, including numerous organic acids, carbohydrates, alcohols, amino acids and more complex organic nitrogenous substances.

The different species of sulfate-reducing bacteria are alike morphologically as far as is known and they differ only in the organic compounds which they are able to attack (28).

These bacteria are of some importance in water distribution systems in that they produce sulfide which is dissolved in the water and makes the water objectionable by reason of the odor, the presence of suspended black particles and the corrosive effect of the sulfide on steel and other metals. They are of still greater importance as corrosive agents through another mechanism of action.

Their relationship to this corrosion process was discovered in 1934 by von Wolzogen Kühr (30) who showed that these bacteria cause corrosion under anaerobic conditions where it would be expected that the iron would remain passive. He was led to conclude that the bacteria were responsible for corrosion, since iron sulfide was one of the principal products of corrosion; that sulfate was reduced during the process; that hydrogen was taken up by micro-organisms where corrosion occurred; and that the sulfate-reducing bacteria were active in the anaerobic soils and environments where corrosion occurred. There is nothing unusual in the bacterial corrosion process that distinguishes it from the generally accepted electrochemical mechanism of corrosion except that the bacteria serve to activate the cathodic hydrogen. Under aerobic conditions this hydrogen is oxidized by oxygen of air in the process of rusting, as shown below.

Under conditions where oxygen is excluded, the system becomes polarized, since the hydrogen which accumulates at the cathode is not removed. In the absence of some depolarizing agent there is no corrosion. The sulfate-reducing bacteria serve as depolarizing agents under anaerobic conditions by removing the hydrogen and oxidizing it at the expense of sulfate which is reduced to sulfide. The reactions on page 980 were proposed to explain this transformation.

As will be seen from the last equation, the products of corrosion are ferrous sulfide and ferrous hydrate, the quantities of which are in the proportion of 1 to 3. Following von Wolzogen Kühr's study of the process, others have sought to establish whether or not anaerobic corrosion was a factor of importance in various locations throughout the world (25, 26, 29). Principal interest has been focused on corrosion in soil. Results of numerous studies have indicated that this type of corrosion is not only widespread but may be so severe as to cause pipe failure within a period of a few years. A steel pipe 200 mils thick may be penetrated in eight to ten years under conditions where this corrosion is severe (26).

With steel the metal is pitted and frequently the pits are sufficiently close together to coalesce and cause slab corrosion. Under this condition a large portion of the pipe surface may lose

$$\begin{array}{c} 4\text{HOH} \rightleftharpoons 4\text{H}^{\cdot} + 4\text{OH}^{\prime} \\ 2\text{Fe} + 4\text{H}^{\cdot} \rightleftharpoons 2\text{Fe}^{\cdot} + 4\text{H} \end{array} \right\} \text{Anodic solution of iron} \\ 4\text{H} + \text{O}_2 \rightarrow 2\text{HOH} \qquad \text{Depolarization} \\ 2\text{Fe}^{\cdot} + 4\text{OH}^{\prime} \rightarrow 2\text{Fe}(\text{OH})_2 \\ 2\text{Fe}(\text{OH})_2 + \frac{1}{2}\text{O}_2 + \text{H}_2\text{O} \rightarrow 2\text{Fe}(\text{OH})_3} \end{array} \right\} \text{Corrosion products} \\ 3\text{HOH} + 2\text{Fe} + 1\frac{1}{2}\text{O}_2 \rightarrow 2\text{Fe}(\text{OH})_3 \qquad \text{Summary} \end{array}$$

ol. 37

nown f bacsulbacnysio-

y are are ng a notile

have illum, and,

most desul-They eterotydrosame

e decteria. nergy lucing e sul-

One actate CO₂, o sul-

- H₂O

)4

d can ry for Many ed, in-

ls and is sub-

ate-renologidiffer

00

be

sic

ho

fu

ter

col

pre

on

bla

fid

filr

He

sul

ext

fact

unli

able

teria

cone

corr

a m

drat

as tl

thou

the fouli

rosiv

rosic cum

the 1

likel has

metal, but at different rates so that the metal surface is very uneven. When a corroding steel surface is exposed, the spots where corrosion had occurred appear as raised areas where the corrosion products had accumulated.



Fig. 15. 6-in. Steel Pipe Pitted by Anaerobic Corrosion During Eight Years Burial in Soil-Specimen Provided by R. F. Hadley.

There is frequently a hard black crust of corrosion products, beneath which is softer material which is black or mixed black FeS and white ferrous hydrate. When the corrosion products are removed the metal surface is bright and silvery. There is no tendency for the corrosion products to adhere tightly to the metal surface and thus to stifle corrosion, as sometimes occurs with rusting.

With cast iron a condition is encountered which has been called "graphitization." Iron showing such attack is somewhat soft and can be penetrated with a knife. This is caused as a result of loss of iron from the pipe, leaving a porous residual structure consisting of a mixture of iron and carbon which resembles graphite. When the pipe dries out this material hardens.

Graphitization does not always characterize anaerobic corrosion of cast iron. In some cases there is a heavy accumulation of corrosion products which may be an inch or more in thickness and contain an abundance of ferrous sulfide. Beneath this crust the metal is bright but not noticeably softened. In such cases it seems likely that most of the iron has come from the surface of the pipe.

This type of corrosion is not confined to soils, although most of the studies have been made on metal buried in soils. It also occurs in fresh water and salt water, as well as in the sediments and bottom materials of lakes, rivers and oceans. It has been en- pri countered in various tanks where sediment covered the steel surface or where the the metal was incompletely coated so as to exclude oxygen or oxygenated water tha without preventing exchange of salts and organic materials contained in the ana water. Anaerobic corrosion is impor- era tant in sewerage equipment where pos anaerobic conditions prevail.

Conditions are more readily con- pipe trolled in domestic water distribution plie systems than in sewage where there is intense bacterial activity supported by the abundance of organic matter. Pomeroy (27) reported an interesting case where an 8-in. cast-iron pipe became nearly filled with corrosion products consisting principally of iron sulfide and iron oxide. After 13 years only a 3-in, opening remained.

$$8HOH \rightleftharpoons 8H' + 8OH' \}$$

$$4Fe + 8H' \rightleftharpoons 4Fe'' + 8H \}$$

$$CaSO_4 + 8H \rightarrow H_2S + 2HOH + Ca(OH)_2$$

$$Fe'' + H_2S \rightarrow FeS + 2H' \}$$

$$3Fe'' + 6OH' \rightarrow 3Fe(OH)_2$$
Anodic solution of iron
$$Counting the 1 form the 1 for$$

charf cast heavy oducts

thickof ferst the y softly that ne sur-

t conof the buried water e sedilakes. en en-

e sediwhere d so as water f salts in the impor-

where

bution here is ted by matter. resting

ipe beprodon sulyears The

ion of

on

conditions under which the corrosion occurred and the nature of the corrosion products suggest that there had been anaerobic corrosion.

There is still another type of corrosion associated with development of both sulfate-reducing bacteria and sulfur bacteria which has been encountered in both iron pipes and concrete conduits. In cases where the water contains sulfide or where sulfide is produced as in sewage, and the pipe is only partly filled so that there is an air blanket over the water, some of the sulfide becomes dissolved in the moisture film on the upper walls of the pipe. Here it undergoes oxidation, caused principally by sulfur bacteria, and the sulfuric acid which is formed attacks the pipe, causing its disintegration.

It has been definitely established that under certain soil conditions the exterior of pipes may be attacked by anaerobic corrosion, but little consideration has as yet been given to the possibility that this corrosion is a factor on the inside surface of water v con- pipes. Water is generally well supplied with oxygen and it might seem unlikely that conditions would be favorable for development of anaerobic bacteria. Nevertheless, there are certain conditions under which this type of corrosion may occur, one of which is a metal surface coated with ferric hydrate and other fouling material such as that produced by iron bacteria. Although the organisms which produce the incrustation and accumulate the fouling material are not themselves corrosive, there is some evidence that corrosion occurs beneath the nodular accumulations. This corrosion may be the result of electrolysis caused by difoducts ferential aeration, but it seems more likely that in some cases at least there has been anaerobic corrosion. The

mixture of ferric hydrate and organic materials could serve as a barrier preventing oxygenated water from reaching the metal surface and thus provide anaerobic conditions. The accumulations should not be so tight as to exclude contact of the films of water with the metal. Furthermore, there should be an exchange of dissolved materials between the main body of water and the water in contact with the metal. This set of conditions should favor development of anaerobic sulfate-reducing bacteria; they could obtain a supply of nutrient elements from the water films, possibly some organic matter from the same source, and some organic nutrients from residues of microbial cells contained in the layer of material coating the metal.

The possibility of anaerobic corrosion under these conditions is not entirely theoretical. The appearance of the underlying metal in badly fouled pipes suggests that anaerobic bacteria develop at the metal surface. Larson (5) reported that at pipe joints and extending from these points for various distances there was an accumulation of material consisting of a surface crust of hard, yellow-brown material beneath which was black loose slime containing sulfide. He stated, "The outer coating does not appear to be sufficiently impermeable to prevent corrosion, but appreciable inhibition is afforded." The descriptions by Reddick and Linderman (6) and Knudsen (4) of the tubercles on water mains leave little doubt regarding the presence of sulfate-reducing bacteria in the tubercles. Furthermore, these incrustations were also found to produce conditions favorable for corrosion. cone-like structures were described as consisting of an outer coating of red ferric oxide mixed with black magnetic

00

the

wit

the

iron oxide and of a center which was black and soft and frequently contained sulfide. When the black material was exposed to the air it became oxidized to red ferric oxide. Beneath the tubercles which tended to coalesce and cover large areas there were pitting and other evidences of corrosion.

Methods of Study

The relationships of micro-organisms to iron transformations are such that no single set of methods can be used to determine the nature of the organisms or their role in the transformations. The organisms are diverse, and special procedures are required for each group. No routine chemical or cultural tests have been developed such as those which are so effectively used to test water for sewage pollution. In order to determine whether such bacteria as those under discussion are responsible for undesirable conditions in the water or the distribution system it is of primary importance to know the characteristics of these bacteria.

Study of the iron bacteria is complicated by the fact that there are no simple methods for their cultivation. Whereas some of these bacteria have been grown in pure culture in artificial media, this is not readily accomplished. In only a few instances have iron bacteria been grown at all in inorganic media. Their study is consequently limited almost entirely to microscopic observations and simple chemical tests.

Material suitable for examination may be obtained from fouled surfaces, but only fresh material should be used, since the cells become distorted by desiccation and the material in which they are imbedded cannot be readily redispersed. With water which supports active development of iron bac-

teria, culture material may be obtained by running a slow stream into a glass cylinder or over a trough for several days. A slimy growth may appear in which there are iron bacteria together with precipitated ferric hydrate. This material can then be used for microscopic studies. Culture slides or cover slips can be kept submerged in the running water for days or weeks and the iron bacteria which become attached to the surfaces can be studied. Wilson (9) suggested that glass slides be inserted in pipes in specially devised stuffing boxes in such a manner that the bacteria would be able to develop under conditions which are typical for the inside of the pipes. Periodically the slides could be removed and studied to determine the abundance and type of organisms which become attached to the slides. Metal slides could also be similarly used in cases where it was desirable to make tests under conditions more representative of the pipes themselves.

Microscopic preparations should be first examined in a fresh condition and before treatment with any chemical. The material could be subsequently treated in various ways to bring out the characteristics of the bacterial cells. Gallionella can be stained with crystalviolet or carbol-fuchsin in a wet preparation in order to reveal the terminal curved cells at the ends of the bands of ferric hydrate excreted by the bacteria. Many of the iron bacteria are so coated with deposits of ferric hydrate that the characteristics of the cells cannot be distinguished until the preparations are treated with dilute acid which removes most of the ferric Acid treatment is not desirable in the case of Gallionella since this dissolves the characteristic bands of excreted material. Preparations of

late vel not be

abı

the that that or term fair best

whi

to c

quir Sor bac cur of The

wat the teris an crea whi mer cult

the in s thei tern

teria

tained

a glass

several

ear in

gether

micro.

cover

in the

s and

ne at-

udied.

slides

evised

r that

evelop cal for

dically

stud-

e and

ne at-

slides

cases

tests

itative

ald be

n and

mical.

uently

g out

cells.

rystal-

prep-

rminal

bands

e bac-

ia are

ic hy-

of the

til the

dilute

ferrio

ot de-

since

bands

ons of

This

other iron bacteria which have been treated with acid and subsequently washed in water can be stained with the common bacteriological stains or with dilute iodine solution which stains the cells very lightly and reveals cell structures which are obscured when other stains are used.

The presence of iron in the accumulated material where the bacteria develop is generally so obvious that it is not necessary to test for it but it may be desirable to test for the relative abundance of iron and manganese in the products.

Where attempts are made to grow the organisms it should be kept in mind that the iron bacteria are aerobic, and that many of them grow best at neutral or slightly acid reactions, and that the temperature of incubation should be fairly low. Some of the bacteria grow best at 10°C. or less. The methods which have been most successfully used to cultivate the iron bacteria have been summarized by Cholodny (14).

Study of the sulfur bacteria also requires the use of special methods. Some of the higher filamentous sulfur bacteria can be recognized by the occurrence of highly refractive globules of sulfur within the cells (20, 24). They may appear in sulfide-containing water which is brought in contact with the air. During growth of these bacteria there is a decrease in the sulfide, an increase in the acidity and an increase in the amount of sulfate, all of which can be tested. Though the filamentous sulfur bacteria are not readily cultivated in artificial media, some of the simple sulfur bacteria will grow in special solution media (22, 23) and their relative abundance can be determined.

The anaerobic sulfate-reducing bacteria are also a distinct physiological

group of organisms. Their development is characterized by the accumulation of sulfide which reacts with iron to produce black iron sulfide. Water in which they develop may become black or have a sulfide odor. In special cases the activity of these organisms is confined to certain areas of the pipe surface. At these locations there is black material which should give a positive test for sulfide. Sulfate-reducing bacteria can also be cultivated in special media (28), by use of which their relative abundance can be determined and their morphological characteristics ascertained.

References

Iron Bacteria As Fouling Organisms

- ALEXANDER, L. J. Control of Iron and Sulfur Organisms by Super-chlorination and De-chlorination. Jour. A.W. W.A., 32: 1137 (1940); 36: 1349 (1944).
- Brown, K. W. The Occurrence and Control of Iron Bacteria in Water Supplies. Jour. A.W.W.A., 26: 1684 (1934).
- CARROLL, E. B. Control of Iron Bacteria by Super-chlorination. Jour. A. W.W.A., 33: 168 (1941).
- KNUDSEN, H. A. Corrosion and Tuberculation. Jour. A.W.W.A., 32: 387 (1940).
- LARSON, T. E. Bacteria, Corrosion and Red Water. Jour. A.W.W.A., 31: 1186 (1939).
- 6. Reddick, H. G. and Linderman, S. E. Tuberculation of Mains as Affected by Bacteria. J.N.E.W.W.A., 46: 146 (1932).
- Schorler, B. Die Rostbildung in den Wasserleitungsröhren. Centr. Bakt. II (Ger.), 15: 564 (1906).
- Tenny, M. K. Des Moines Iron Problem. Jour. A.W.W.A., 31: 96 (1939).
- Wilson, C. Bacteriology of Water Pipes. Jour. A.W.W.A., 37: 52 (1945).
- Crenothrix: Alive, Dead and Entombed. W.W. & Sew., 92: 90 (1945).

Iron Bacteria

11. BEGER, H. Leptothrix echinata, ein neues vorwiegend Mangan fällendes Eisenbakterium. Zentr. Bakt. II (Ger.), 92: 401 (1935).

12. CATALDI, M. S. Estudio Fisiologico y Sistematico de Algunas Chlamydobacteriales. Thesis, Buenos Aires, Argentina, 96 pp. (1939).

Die Eisenbakterien. 13. CHOLODNY, N. (Ger.) Gustav Fischer, Jena. 162 pp. (1926).

-. Methoden zur Kultur der Eisenbakterien. Handbuch d. Biol. Arbeitsmethoden (Ger.) (E. Abderhalden) 12: 2: 889 (1935).

15. Dorff, P. Die Eisenorganismen. (Ger.)

Gustav Fischer, Jena. 62 pp. (1934). 16. Harder, E. C. Iron-Depositing Bacteria and Their Geologic Relations. U.S. Geol. Survey, Prof. Paper 113, 89 pp. (1919).

17. HARDMAN, Y. AND HENRICI, A. T. Studies of Fresh-Water Bacteria. V. The Distribution of Siderocapsa treubii in Some Lakes and Streams. J. Bact., 37: 97 (1939).

18. MOLISCH, H. Die Eisenbakterien. (Ger.) Gustav Fischer, Jena. 83 pp. (1910).

19. Volkova, O. Y. Ferrobacteria of Caucasian Mineral Springs and Their Role in the Formation of Ferrous Deposits. Microbiology (U.S.S.R.) (1939).

Sulfur Bacteria

20. BAVENDAMM, W. Die farblosen und roten Schwefelbakterien. (Ger.) Gus-

tav Fischer, Jena. 156 pp. (1924). 21. HARMSEN, G. W. Biologische ijzeromzettingen in den boden. (Neth.) Chem. Weekblad, 35: 495 (1938).

22. STARKEY, R. L. Concerning the Physiology of Thiobacillus thiooxidans, an Autotrophic Bacterium Oxidizing Sulfur Under Acid Conditions. J. Bact., 10: 135 (1925).

-. Isolation of Some Bacteria Which Oxidize Thiosulfate. Soil Sci., 39: 197 (1935).

24. VAN NIEL, C. B. On the Morphology and Physiology of the Purple and Green Sulfur Bacteria. Arch. Mikrobiol. (Ger.) 3: 1 (1931).

Sulfate Reduction and Iron Corrosion

- 25. BUNKER, H. J. Microbiological Experiments in Anaerobic Corrosion. J. Soc. Chem. Ind. (Br.) 58: 93 (1939).
- 26. HADLEY, R. F. Studies in Microbiological Anaerobic Corrosion. Rpt. of the Technical Section of the Am. Gas Assn., 23 pp. (1940).
- 27. Pomeroy, R. Corrosion of Iron by Sulfides. Calif. Sewage Works J., 13: 31 (1941).
- 28. STARKEY, R. L. A Study of Spore Formation and Other Morphological Characteristics of Vibrio desulfuricans. Arch. Mikrobiol. (Ger.) 9:268 (1938).
- WIGHT, K. M. Soil Areas Corrosive to Metallic Iron Through Activity of Anaerobic Sulfate-reducing Bacteria, Am. Gas Assn. Monthly, 25: 223 (1943).
- 30. VON WOLZOGEN KÜHR, C. A. H. AND VAN DER VLUGT, L. S. Graphitization of Cast Iron as an Electro-biochemical Process in Anaerobic Soils. Water (Neth.) 18: 147 (1934).

Various Sulfur Transformations

- 31. HALVORSON, H. O. Studies on the Transformations of Iron in Nature. III. The Effect of CO2 on the Equilibrium in Iron Solutions. Soil Sci., 32: 141 (1931).
- 32. O'CONNELL, W. J., JR. Characteristics of Microbiological Deposits in Water Circuits. Am. Petrol. Inst., Div. of Refining, Eleventh Mid-year Meeting. 19 pp. (1941).
- 33. STARKEY, R. L. AND HALVORSON, H. O. Studies on the Transformations of Iron in Nature. II. Concerning the Importance of Micro-organisms in the Solution and Precipitation of Iron Soil Sci., 24: 381 (1927).

ph tin

filt raj siv wi

and

to 1 1 tion mei to 4

The pro the proc

sum sugg new their R

orate Labor Comr

Feder Munio Railro Unive

Feder

Ge lows: 13. P east 6

Tal used

Trends in Water Laboratory Practice

By D. W. Graham

Chief Chemist, San. Eng. Div., Dept. of Water & Power, Los Angeles, Calif.

Presented on Oct. 26, 1944, at the California Section Meeting, Los Angeles, Calif.

THE current trend in water laboratory practice is from chemical to physical methods of analysis. The time-honored routine of "precipitating, filtering, igniting and weighing" is rapidly losing ground and the progressive technician must become familiar with an increasing array of technics and instruments that belong primarily to the fields of physics and engineering.

In order to study this trend, a questionnaire covering laboratory equipment and analytical methods was sent to 46 representative water laboratories. The answers to this questionnaire proved to be of considerable value in the re-evaluation of current laboratory procedures and it was thought that a summary of this information might suggest to other laboratory workers new methods and equipment to use in their studies and investigations.

Replies were received from 41 lab-

oratories, classified as follows	•	
	N_1	umber
Laboratory Classification	Re	borting
Commercial and consulting		11
Federal and state public health		
Federal and state water resources		
Municipal water works		
Railroad		
University (sanitary engineering)		2

Geographical distribution was as follows: Canada 1, East 9, Middle West 13, Pacific Coast 9, South 3 and Southeast 6.

Table 1 is a record of the equipment used by the participating laboratories.

The list was confined to equipment used for the mineral analyses of water and to supplemental rather than basic items.

Equipment Questionnaire

Current advances in instruments and instrumentation are producing a body of knowledge which comprises an entire subject by itself and will be touched upon here only briefly. For a very excellent and comprehensive discussion of present-day instrumentation the reader is referred to the works of Müller (1, 2).

Widespread publicity has been given to pH as the key to the solution of all water problems. This is reflected in the fact that 37 of the 41 reporting laboratories have potentiometric instruments for pH determination. In addition, fifteen laboratories use potentiometric titration technics. More than half estimate total solids by conduc-The present trend in current measurement appears to be toward visual indicators, such as the alternating current galvanometer and the electronic bridge-balance indicator. The conventional telephone receiver has been found to be neither convenient nor comfortable and is disadvantageous especially in portable equipment.

Due to their speed and sensitivity colorimetric methods of analyses have always been popular with laboratory personnel. With new and improved

Vol. 37

le and Mikro-

Experi-J. Soc.

Rpt. of m. Gas

by Sul-13: 31 Spore

ological uricans. (1938). as Corgh Ac-

I onthly,

H. AND

itization

hemical

Water

Trans-III. The rium in 12: 141

ristics of ter Cirof Reing. 19

of Iron the Imin the

ar

tor str and sea lab

and

che

and

van

wh:

mer

cen

Act

tori

pers

equi

a hi

ject

pare

and wate

porta

and

necti

and

TABLE 1
Summary of Equipment Used by 41 Water Laboratorie

pH meter Electrometric titration apparatus		37 15	Microscope Clinical (oil immersion)	33	3
Conductivity equipment Microphone hummer and tele-		22	Petrographic accessories Stereoscopic low-power	5 10	
phone receiver Alternating current galvanomete Electronic bridge—balance indi-			Centrifuge Vacuum pump		3 2
Electrodeposition equipment	7	5	Radioactivity apparatus Photomicrographic equipment		1
Polarigraph		2	Metallographic equipment Microchemical apparatus		1
Colorimetric equipment Colorimeter Photo-electric photometer	24 17	30	Glassblowing equipment Spectrometer		1
Abridged spectrophotometer Spectrophotometer	5 5		Spectrograph Quartz	2	
Turbidimeter		34	Grating	2	
Jackson Hellige Baylis St. Louis type	31 12 7		Laboratory water still Demineralized water by cation-anion exchanger		3
Parr Special design—photo-electric	1 3		Vacuum oven Gas analysis equipment		
Special design—optical	2		Potentiometric temperature recorder		

instruments becoming commercially available, even greater emphasis is being put on this technic. This statement is strikingly confirmed by the fact that approximately 70 per cent of all recent articles on water analyses recommend the use of such instruments. All but ten of the reporting laboratories employ instruments using this principle. A trend from visual to photo-electric methods of colorimetric analysis is also evident. Seventeen laboratories have photo-electric colorimeters and in addition ten have spectrophotometers or abridged spectrophotometers. The relatively inexpensive photo-electric colorimeter is superior to visual methods because it eliminates errors due to personal factors and gives better reproducibility of readings than is possible with the eye. Unfortunately, however, most of them employ barrier-layer cells which are

notoriously insensitive at low levels of illumination. The most reliable general utility instrument appears to be the spectrophotometer because any colorimetric problem can be reduced to the fundamental wave-lengths involved.

Although the listing of four spectrographs cannot be called a stampede to the spectrographic method of analysis, this is a good showing when the relatively high initial expense is considered. Spectroscopy is one of the most reliable means of identifying elements known. This is due to the fact that each element, under suitable conditions of excitation, will emit characteristic spectral lines. The instrument which produces these lines and records them on a photographic emulsion is called spectrograph. The image may be recorded on plates or film and the is tensity of the characteristic lines measure ured photo-electrically. The plotting

Vol. 37

39

30

29

11

4

19

34

3

1

vels of

e gen-

to be

e anv

iced to

volved.

pectro-

ede to

alvsis,

e rela-

consid-

e most

ements

ct that

teristic

which

s them

alled a

be re-

the in-

meas

lotting

of intensity against concentration gives quantitative measurements and furnishes a most useful analytical tool. Advantages include speed, extreme sensitivity, permanent photographic record of the analyses, low operating cost and the ability to make simultaneous determinations of many components, including those whose presence may not have been previously suspected. The principal disadvantage is the initial cost and the necessity for considerable preliminary development and standardization of methods and operating conditions.

The inclusion of petrographic and metallographic apparatus indicates increasing interest in pipe corrosion and incrustation problems. The use of photomicrographic equipment demonstrates interest in biochemical control and research. Further evidence of research is found in the fact that nineteen laboratories do their own glass blowing and in the increasing interest in microchemical tests, polarigraphic methods and radioactivity.

Although it is gratifying that advances have been made, it is a somewhat sobering thought that this supplemental or specialized equipment is concentrated in only a few laboratories. Actually the majority of water laboratories are under-equipped and their personnel is carrying on investigation and research in spite of inadequate equipment. Water quality control is a highly technical and specialized subject and it is becoming increasingly apparent, and rightfully so, that water laboratories should conduct research and provide limited service relating to water problems. The increased importance and knowledge of corrosion and incrustation problems, cross-connections, biological control, boiler-scale and other industrial problems indicate

an increasing need for pH meters, conductivity, metallographic, petrographic, photomicrographic, spectrophotometric and spectrographic equipment.

Analytical Questionnaire

The scope of the questionnaire on analytical methods (see summary, Table 2) was limited primarily to procedures which have been developed since the 1936 edition of Standard Methods for the Examination of Water and Sewage (3) and to those which appear to be controversial. Thus, methods for calcium, chloride, copper, etc., were not investigated because it was assumed, from the lack of contrary evidence, that the present procedures were satisfactory or that technics improving on those now popular have not, as yet, been developed. When a laboratory reported the use of two or more methods, all were included in the summary. This accounts for the fact that the total number of methods used always exceeds the number of laboratories making that particular determination.

It should be kept in mind that most water laboratories will normally use the methods set forth in Standard Methods because of legal considerations and because of the inherent prestige of these methods which reflect study and analysis by qualified committees. Therefore, the use of other methods may reflect dissatisfaction with the standard methods or may indicate that the alternate methods will give the desired information either with greater accuracy or with a saving of time and materials. In any event, when another method is used by any of the leading laboratories, it is worthy of consideration and its multiple use justifies examination by those who have not already investigated.

Si

AR

FLU

N S

LEA C B D Sp

TABLE 2

Summary of Analytical Methods Used by 41 Water Laboratories		
EXPRESSION OF RESULTS		4
Parts per million Grains per gallon	40	
Milliequivalents per liter	16 13	
Equivalents per million	7	
Parts per million as CaCO ₃	1	
TOTAL DISSOLVED SOLIDS		4
Drying at 103°C. (Standard Methods)	33	•
Estimated from specific conductance	15	
Calculated from sum of cations and anions plus silica	9	
Drying at 180°C.—Ind. Eng. Chem.—Anal. Ed., 5: 4 (1933)	5	
Converted to and weighed as sulfates	2	
Drying at 105°C.–110°C.	1	
TOTAL HARDNESS		41
Soap method (Standard Methods)	28	
Calculated from calcium and magnesium results	28	
Motorized method of Langelier—Jour. A.W.W.A., 32: 279 (1940)	7	
Titration with potassium palmitate	6	
Soda reagent method U.S.G.S.—modified soap method	4	
Metarized method Dr. Hele's medification	1	
Motorized method—Dr. Hale's modification Brown—Villarruz soap method—Jour. A.W.W.A., 30 : 1021 (1938)	1	
ALKALINITY		40
By titration using methyl orange indicator (Standard Methods)	35	40
By titration using bromocresol green-methyl red indicator—Ind. Eng. Chem.		
Anal. Ed., 13: 466 (1941)	8	
By electrometric titration	8	
By titration using methyl red indicator	4	
CARBONATE EQUILIBRIA (CO2, OH, CO3, HCO3)		40
By titration (Standard Methods)	29	
By computation, tables or graphs from total alkalinity and pH results	20	
Carbon dioxide by absorption—CO ₃ , HCO ₃ and OH (Standard Methods)	2	
Carbon dioxide by titration after fixation with marble chips, CO ₃ , HCO ₃ and by titration using phenolphthalein, methyl red and air	I OH	
		24
SATURATION INDEX Calculated or from charts, graphs, slide rule, etc., based on Langelier's tables	22	31
By actual saturation of sample with CaCO ₈	16	
Enslow apparatus	1	
ALUMINUM		31
Precipitation as Al(OH) ₃ and ignition (Standard Methods)	21	
Colorimetric with hematoxylin	16	
Colorimetric with Alizarin S	2	
Spectrographic	2	
ODIUM		37
Calculated as sodium and potassium from difference between determined anions	and	
cations and reported as sodium	24	
By separation with potassium as the mixed chlorides, determination of potas	sium	
as platinic chloride or equivalent metallic platinum and calculation of so		
by difference (Standard Methods)	11	

ol. 37

TABLE 2-Continued

TABLE 2—Continued	
Sodium—Continued By separation with potassium as the mixed chloride, determination of potassium as	
the perchlorate and calculation of sodium by difference (Standard Methods) Gravimetric determination as sodium zinc uranyl acetate	4 9
POTASSIUM By separation with sodium as the mixed chlorides and subsequent determination of potassium as the platinic chloride or equivalent metallic platinum (Standard Methods)	19
By separation with sodium as the mixed chlorides and subsequent determination of potassium as the perchlorate (Standard Methods) Precipitation as the cobaltinitrite and titration with ferrous sulfate and ceric sulfate—Ind. Eng. Chem.—Anal. Ed., 10: 652 (1938)	4 3
Gravimetric determination as the cobaltinitrite—Ind. Eng. Chem.—Anal. Ed., 9: 136 (1937) Sherrill Centrifuge Method (Precipitation as cobaltinitrite in special tubes. Esti-	2
mated by volume as compared to standards) Spectrographic	1
CHLORINE Colorimetric with ortho-tolidine Jodometric	38 38 3
Colorimetric with p-aminodimethylaniline—Jour. A.W.W.A., 35: 427 (1943) Glass electrode meter	2
Method of Laux—Jour. A.W.W.A., 32 : 1027 (1940) Method of Laux-Nickel—Jour. A.W.W.A., 34 : 1785 (1942) Method of Hallinan—Jour. A.W.W.A., 36 : 296 (1944)	1 1 1
Sulfides Titration with iodine	33
Pomeroy methylene blue method—Jour. A.W.W.A., 33 : 943 (1941) Colorimetric with antimony potassium tartrate	8 7
Precipitation as ZnS and titration Fixation with CdCl ₂ and titration Methylene blue method after precipitation as ZnS	2 2 1
Arsenic	23
Colorimetric method of Jacobs and Nagler—Ind. Eng. Chem.—Anal. Ed., 14: 442 (1942)	3
Colorimetric method of Chaney and Magnusun—Ind. Eng. Chem.—Anal. Ed., 12: 691 (1940) Spectrographic	1
FLUORIDE Colorimetric method of Elvove (Standard Methods)	32
Colorimetric method of Scott-Sanchis—A.W.W.A. Committee Report—Jour. A.W.W.A., 33: 1965 (1941)	25
Colorimetric method of Lamar and Seigmiller—Ind. Eng. Chem.—Anal. Ed., 13: 901 (1941) Method of Willard and Winter—Ind. Eng. Chem.—Anal. Ed., 5: 7 (1933)	2
Sanchis method—Ind. Eng. Chem.—Anal. Ed., 6: 134 (1934) Method of Talvitie—Ind. Eng. Chem.—Anal. Ed., 15: 620 (1943)	1 1
LEAD Colorimetric as sulfide (Standard Methods)	26
By dithizone	9
	1

B

Ċ

P

Co

00

Tu

Ox

Di

An

All

Or

Fre

TABLE 2-Continued

ZINC		25
Turbidimetric with ferrocyanide (Standard Methods)	14	
Turbidimetric with diethyldithiocarbamate—Jour. A.W.W.A., 33: 246 (1941)	9	
Dithizone	2	
Spectrographic	2	
Precipitation as ZnS	1	
Sulfates		41
Gravimetric as BaSO ₄ (Standard Methods)	38	
Turbidimetric	13	
Titration with tetrahydroxyquinone (T.H.Q.)	4	
Benzidine method	1	

Expression of Results

Continuing the quest of more than half a century, water chemists are still striving to agree on common terminology for the exchange of information. Inspection of current methods of expressing the results of a water analysis reveals two distinct, divergent and yet understandable trends. First, there is a definite trend in all laboratories toward the use of the term "parts per million" (ppm.) and away from the term "grains per gallon" (gpg.). Results of the questionnaire clearly prove that "ppm." has become the almost unanimous choice of water technicians, and while many continue to supplement their reports with results calculated as "gpg.," this practice is admitted to be because of tradition rather than choice. The "ppm." has the advantage of being convenient for measuring the gross amount of material in water, is an easily understandable unit, and its constant use facilitates comparisons with results published in the literature of the field.

The second trend is the attempt to standardize on a term which reflects true stoichiometric relationship and can be used for balancing analyses, for facilitating calculations in water treatment problems and for presenting results graphically. Unfortunately, this second trend, although holding the center of interest, appears to be deteriorating in so far as practical results are concerned. The two leading methods of stoichiometric expression are milliequivalents per liter (mE/l.) and equivalents per million grams (epm.). The thirteen-to-seven lead held by the term "mE/l." in the summary is somewhat misleading, as "mE/l." is older, better established and recommended by *Standard Methods*,*

^{*} The following statement by Langlier (Jour. A.W.W.A., 34: 335 (1942)) epitomizes the attitude of the editors of Standard Methods: "The unit 'equivalents per million grams' (epm.), tentatively approved by the American Society for Testing Materials in 1940, appears to be more consistent when used together with the firmly established 'parts per million' (ppm.), because each is a 'weight per weight' unit. The abbreviation (epm.), however, introduces a serious inconsistency in that the letter m stands for 'million grams' rather than for 'million equivalents' as might be inferred from its significance in the term (ppm.). Because of this, and also because, in the use of weight per weight units, it is not always clear whether weights of solution or weights of solvent is meant, the authors prefer to use the weight per volume units, i.e., milligrams per liter (mg./1.) and milligram equivalents per liter (mE/l.). Each of these is consistent with the other, and, in the case of saline waters, there can be no uncertainty as to whether or not a specific gravity correction has been applied."

ol. 37

25

41

g the be deal reeading ession nE/L) grams lead sumg, as ed and hods,*

anglier epito-Standnts per pproved ng Mansistent estabbecause t. The duces a etter m han for inferred (ppm.). the use always weights r to use **lligrams** ivalents is concase of certainty vity cor-

TABLE 3
Suggested Group Determination

Suggested Group Determinations										
	Mineral Analyses	Sanitary Analyses	Public Health Standards	Corrosion	Industrial Analyses	Agricultural Analyses	Distribution Quality	Biological Correlation Studies	Suspected Organic Pollution	Determination of Source
Specific Conductance Dissolved Solids (103°C.) Calcium (Ca) Magnesium (Mg)	x x x		x x	x	х	x		x	0	х
Palmitate Hardness Potassium (K) Sodium (Na) Percentage Sodium	x x				х	X O X X				0
Alkalinity (CaCO ₃) Chlorides (Cl) Sulfates (SO ₄) Nitrate (NO ₃)	X X X X	o x	x x x	х	x x x o	X X X		x o	0	0 0
Temperature pH Carbon Dioxide (CO ₂) Saturation Index	0 0		o	X X X	o x		х о о	x x x o	0	
Silica (SiO ₂) Iron (Fe) Manganese (Mn) Aluminum (Al)	X X O O		x x	0	0 0		0	0 0		
Arsenic (As) Boron (B) Chromium (Cr) Copper (Cu)	0		x x x			x		0		0
Fluoride (F) Lead (Pb) Selenium (Se) Zinc (Zn)	0		X X X X	0						0
Phenols Phosphates (PO ₄) Sulfides (S) Color	0	0 0 x	0 0 X			0	o x	0	0	0
Odor Turbidity Oxygen Consumed Dissolved Oxygen		x x x x	x x	x			x x o x	0	0 0	0
B.O.D. Ammonia (NH ₂) Nitrites (NO ₂) Albuminoid Nitrogen		X X X O					0 0 0	0	o x x	
Organic Nitrogen Free Chlorine (Cl ₂)		X O	x				0	0	0	0

Note: x Determinations usually made.

o Supplementary tests, of value under certain conditions.

whereas "epm." has but recently come into prominence (4). Actually, the fact that it is already being used by seven laboratories indicates a definite trend in its favor. From a practical laboratory standpoint either method

should be acceptable.

An insight into the problem of achieving a mutual understanding in this field may be obtained by examining the latest recommendation by various organizations interested in water chemistry. The recommendation of the Manual of the Railway Engineering Association is "gpg." (1932); joint American Public Health Association and the American Water Works Association, "ppm." and "mE/l." (1936); Association of Official Agricultural Chemists, "mg./l." (1940); American Society for Testing Materials, "ppm." and "epm." (1940); American Society of Mechanical Engineers, "ppm." and "gpg." (1943); Water and Sewage Unit, Repairs and Utilities Branch, Construction Division, Office of Chief Engineer, War Department. "ppm." and "epm." (1943).

It is unfortunate that all organizations interested in water analysis cannot get together and adopt a joint standard. The confusion caused by the present inconsistent terminology, due in part to stubborn defense of each method, is not a healthy condition for the interchange of information between the various organizations.

Specialized Analyses

The trend toward specialization in water analyses is readily apparent in the tables. The typical old-style analysis, which covered total solids, silica, iron and aluminum oxides, calcium, magnesium, alkalinity, chlorides, sulfates and sodium by difference, is no longer adequate. For example, such

an analysis will not tell whether a water may cause mottled teeth, whether it is potentially corrosive, or whether it can be safely used for irrigation of citrus trees. A specialized analysis, in addition to giving the required information, will save time and material, as fewer determinations are usually required to secure the desired information. A laboratory guide showing determinations usually run in the Los Angeles Sanitary Engineering Division laboratory is shown in Table 3. Individual circumstances will of course alter recommended determinations.

Complete Mineral Analyses

Recent developments in analytical technics have enabled chemists to report complete mineral analyses with greater accuracy and confidence than has heretofore been possible. In the past, complete analyses have not always been satisfactory due to the traditional practice of calculating the amount of sodium and potassium from the difference between the total determined cations and anions and reporting the result as sodium. In addition to the inherent error present in any determination by difference, significant quantities of nitrates and other anions were often missed, which caused low results for the alkalis. Even when sodium and potassium were laboriously determined, major compensating errors in balancing the sums of cations and anions were difficult to detect. Improved technics for determining sodium, potassium and conductance now make it possible to check the actual conductance of the sample with the calculated conductance of all the determined ions, in addition to checking the stoichiometric equivalents of the cations and anions.

in

sl

ec

to

is

tic

th

fre

tic

ab

tui

Wartime Pollution

Although not readily discernible from the summary, wartime conditions have greatly stimulated interest in the development of tests for the detection of pollution due to enemy activities, either deliberate or accidental. Goudey (5) has recommended that laboratories be on the alert for arsenical compounds, heavy metals, cyanides, phenolic derivatives, alkaloids and war gases and has suggested methods for their determination. He points out the significance of abnormal variations in odor, chlorides, sulfates, nitrates, B.O.D., oxygen consumed, pH and chlorine demand and he recommends routine methods for the detection of pollution. Buswell et al. (6) have proposed methods for distinguishing between different war gases by differential titration of excess chlorine at different pH values.

Current Standards Inadequate

A study of the summary also reveals that the traditional retention of obsolete methods will retard the adoption of newer technics by many laboratories; conversely, an encouraging proportion of the reporting laboratories do not feel tied down by the Standards and do not hesitate to use new methods which they consider to be superior. The latter are the leaders in their specialized field and any proposed changes in the current Standard Methods should take advantage of the knowledge and experience of these laboratories. The Joint Editorial Committee is presumably well aware of this situation and it can be assumed that from their review of current literature and from extensive laboratory investigation there will emerge the most suitable methods for inclusion in our future standards.

Comment on Methods

In order to assist in evaluating the summary of the analytical questionnaire and to facilitate the study and investigation of any procedure, a brief summary of the current status of each individual determination follows:

Total Dissolved Solids

The limitations of determining dissolved solids by evaporation methods are well known and accepted as inevitable. This has resulted in increasing interest in the estimation of dissolved solids by electrical conductivity. Twenty of the reporting laboratories use this method. Scofield and Wilcox (7) first showed that a definite relationship existed between the specific conductance and the dissolved solids in a water and that the solids could be estimated by multiplying the conductance by an appropriate factor which depended on the predominate anions. Kitto (8) prepared empirical curves plotting total dissolved solids against the conductance of synthetic salt solutions and determined the solids from the specific conductance and the results of the CO₃, SO₄, Cl and NO₃ analysis. Sokoloff (9), in a study of several thousand irrigation waters, found that variations in the ratio of either anions or cations to the specific conductance were primarily affected by the ratio of sodium to total cations, the ratio of chloride to total anions, and the total concentration of electrolytes. Using these observations as a basis, he presented a means of checking the accuracy of a complete analysis, and of calculating the sum of calcium and magnesium based on three determinations, namely, conductance, sodium and chloride. Gustafson and Behrman (10) have shown that specific conduct-

ol. 37

her it on of alysis, ed interial, lv re-

ormang dee Los Divible 3.

ns.

lytical to rewith than In the tot altradimount

rmined ing the to the etermiquans were results sodium ily de-

he dif-

errors
ns and
. Imng soce now
actual

the denecking of the

ti

H

th

ta

ar

ad

SC

tic

Al

con

du

use

em

pre

pro

a c

ard

sult

gra

not

lyze

is re

curr

ses

patil

The

tirel

ance can be more than a rough empirical index. Recognizing that conductivity is a definite function of and varies with the individual ions, they have proposed a method of checking the determined conductivity with the calculated conductivity. The procedure is applicable to all different types of water ordinarily encountered and the accuracy is comparable to that of other routine analytical methods.

Hardness

While conceding that calculation from calcium and magnesium results is the most accurate method, the trend in determining hardness is toward refinements of the standard soap procedure designed to improve accuracy without sacrificing speed. Proposed variations seem innumerable and five are reported in the summary.

Alkalinity

Even the "old reliable" methyl orange titration for total alkalinity has recently been under fire. In addition to the recognized difficulty of perceiving the color change at the end-point, its accuracy in waters of low alkalinity has been seriously questioned. Cooper (11) has shown that the pH at the equivalence point in very dilute carbonate solutions is a function of the residual carbonic acid and that, for waters containing less than 1.2 millimoles per liter, high results will be obtained when methyl orange is used. He suggests the use of bromocresol green-methyl red indicator and proposes a method whereby the pH values to be obtained at the final end-point can be ascertained before that point is reached and thus allow the selection of the proper indicator color.

In order to check Cooper's findings as applied to Los Angeles waters, a

series of electrometric titrations were made on samples of varying alkalinity and the true equivalence points were compared with the methyl orange and bromocresol green-methyl red end. points. The error using methyl orange was found to be negligible with waters low in free carbon dioxide and containing over 80 ppm, alkalinity (CaCO₂). With lower alkalinity however, the error became appreciable and a mountain source having an alkalinity of 20 ppm, showed a plus error of 8 per cent. Using bromocresol green-methyl red it was possible to titrate to the true equivalence point which occurred at a pH of 5.0. Titrating to this higher pH value also reduced the inherent positive error due to the buffer capacity of pure water.

In spite of the advantages of the bromocresol green-methyl red indicator, it is probable that methyl orange will continue to be used with waters having an equivalence point in the pH range of 4.4-4.7 because from a practical standpoint the advantage of being able to continue the chloride determination without marked interference from the alkalinity titration indicator outweighs the advantages of the newer indicator. Bromocresol green-methyl red indicator should be favored when chlorides are not to be determined and with waters of very low carbonate content.

Carbonate Equilibria

A definite trend toward the mathematical approach to carbonate equilibria problems is confirmed by 20 of the reporting laboratories. Recent investigators (11, 12, 13) applying mass action relations to carbonate equilibria in water supplies have shown inherent errors in the titration method. De-Martini's (14) equations have made

possible the calculation of the carbon dioxide, normal carbonate and hydroxide from the pH and total alkalinity results. Moore (15) and Dye (16) have presented these equations as graphs and nomographs, and Hirsch (17) has simplified calculation of the relationship by means of a slide rule.

Saturation Index

Langelier's 1936 paper (18) on anticorrosion water treatment stimulated widespread interest in the theoretical aspects of calcium carbonate deposition. Correlation of the theoretical approach with practical field observations has proven valuable in corrosion and incrustation control. Hoover (19), Larson and Buswell (20) and Hirsch (21, 22) have contributed to the practical application of Langelier's tables by the introduction of a graph and nomograms, minor corrections and additions, and special slide rule and scalar diagram for facilitating calculations.

Aluminum

The trend in determining aluminum continues toward colorimetric procedures. Sixteen reporting laboratories use the hematoxylin procedure and two employ the Alizarin S reagent. present practice of listing a gravimetric procedure as the standard method and a colorimetric method as a non-standard method is regrettable, as this results in many laboratories using the gravimetric method when it is actually not suitable for the water being analyzed. Confirmation of this statement is readily obtained by inspection of the current literature. Innumerable analyses show high results entirely incompatible with the complete analyses. The water technician cannot be entirely blamed for this situation as he

has faithfully followed Standard Methods to obtain his results. In addition. many laboratories realize the inherent inaccuracy of the method but justify its use because it is the standard method and because if they abruptly changed to the more suitable colorimetric procedure it would be embarrassing to explain the discrepancy to those who regularly reviewed their reports. This is a most unsatisfactory condition which could be corrected by the adoption of a sensitive colorimetric procedure as the standard. If it were felt necessary, the gravimetric method could be referred to as suitable for unusual waters, although in the actual determination of aluminum in hundreds of southwestern waters only one sample has been encountered when the gravimetric procedure would be more accurate than the colorimetric. This water was from a volcanic hot spring and even in this isolated case satisfactory colorimetric results could be obtained by dilution of the original sample.

Sodium and Potassium

The fact that 24 reporting laboratories resort to the determination of the alkalis by calculation testifies to the complexity and inaccuracy of the present procedures. The questionnaire shows a strong trend toward the use of the zinc uranyl acetate reagent for sodium and the increasing use of some variation of the cobaltinitrite method for potassium. The problems pertinent to the sodium and potassium determination are in many respects similar to those of aluminum. These sections of Standard Methods have not been materially changed for six editions and the current methods are entirely inadequate.

were

ol. 37

were and endange aters

conlinity, inity, iable, alka-

error resol le to point itrat-

er.
f the
dicarange
raters

e pH pracbeing ermirence

cator newer nethyl when 1 and con-

atheuilibof the vestiss acria in

Demade

(

p

a

b

Y

d

ir

y

th

cl

fo

(

ea

re

0.

ir

C

st

to

of

Po

sp

re

ro

th

lo

tic

be

pe

wi

Free Chlorine

Current investigation of methods for the determination of free chlorine is confined primarily to refinements in the ortho-tolidine procedure. Methods have been proposed by the A.W. W.A. Committee on Control of Chlorination (23) which reduce present interference, measure both high and low residuals in the field as well as in the laboratory, determine chlorine demand under variable conditions and differentiate between chlorine and chlora-Major recommendations include the use of ortho-tolidine dihvdrochloride instead of ortho-tolidine because of the greater purity of the commercial product, a change in acid ratio of the ortho-tolidine reagent, the use of the modified Scott chromatedichromate permanent standards and the use of the iodometric method for determining higher chlorine residuals.

Sulfides

The choice of methods for determining sulfides appears to be dependent on the concentration of sulfide present and on the accuracy required. When the concentration exceeds 1.0 ppm., the iodometric technic is the most accurate and is generally in favor with the reporting laboratories. As concentrations decrease, however, any blank due to iodine-consuming compounds other than H_oS will become of increasing magnitude and casts serious doubts on the quantitative or even the qualitative accuracy. The Antimony Tartrate procedure is fairly satisfactory in concentrations of from 0.1 to 5.0 ppm. The results cannot be considered truly quantitative, as the accuracy is limited by the variable color, turbidity and degree of dispersion of the antimony sulfide precipitate. This method, however, is simple and practically foolproof, since a precipitate will form under a wide variety of conditions and is satisfactory when only semi-quantitative results are required. The methylene blue technic is the most sensitive and accurate in low concentrations and is suitable for concentrations of from 0.01 to 5.0 ppm. It is the only satisfactory method for the estimation of traces of hydrogen sulfide such as are encountered in dead-ends and in the lower levels of stratified reservoirs.

Arsenic

The preponderance of laboratories using the Gutzeit method for arsenic is due in part to tradition and in part to the simplicity of this technic. If arsenic is present in significant amounts. however, methods employing the molybdenum blue reaction are to be preferred, as they have superior accuracy and sensitivity. Either the Jacobs and Nagler technic (which, together with the Gutzeit method, has recently been recommended by the Advisory Committee on the Revision of Drinking Water Standards (24)) or the Chaney and Magnusun procedure is satisfactory.

Miscellaneous Methods

The appreciable majority of laboratories using the Scott-Sanchis (A.W. W.A. Committee Report) method for fluoride and the dithizone technic for lead speaks for itself. The carbamate method for zinc is being adopted by an increasing number of laboratories. It is more sensitive than the standard ferrocyanide procedure and has the additional advantage of having the reagent already prepared in laboratories which use the standard carbamate method for copper.

The standard method of determining sulfates gravimetrically as barium sulfate is one of the older methods which continue to defy all competition. Turbidimetric procedures are possibly superior to the gravimetric procedure in concentrations under 5 ppm., but, due to the non-uniformity of dispersion and grain size, this method gives results which should be considered only rough approximations. Direct titration methods have been found advantageous for hoiler and other saline waters but as vet are not sufficiently sensitive for determining the small quantities of sulfates encountered in normal potable waters. Determinations not included in the summary but which appear worthy of investigation are the titan vellow method (25) for magnesium, the diphenylcarbazide method (26) for chromium, and Knudson's et al. (27) modification of the molybdate method for silica. In addition, Kehoe et al. (28), in a survey of trace elements in eastern and central United States, have recently described methods that detect 0.001 mg. per 1. of manganese, lead, tin, iron, aluminum, copper, silver, zinc, arsenic and mercury.

Conclusion

1. Physical methods of analysis, stimulated in part by improved laboratory instruments, are replacing many of the traditional chemical procedures. Potentiometers, spectrophotometers and spectrographs, formerly restricted to research, are now finding a place in routine laboratory control.

2. The development of new tests and the increasing knowledge of physiological, biological and industrial relationships have resulted in analyses being streamlined for specific purposes, permitting more pertinent information with economy of time and material. 3. To insure accuracy and confidence in a complete mineral analysis, all cations, including sodium and potassium, should be individually determined and checked against both the total anions and the specific conductance.

4. Standard Methods for the Examination of Water and Sewage, due to its infrequent revision and cumulative nature, must necessarily always be in arrears of the latest developments. The results of the analytical questionnaire show certain portions of Standard Methods to be inadequate and in need of revision.

5. It is the obligation of progressive water chemists to keep abreast of current progress and to take the initiative in the development, investigation and adoption of new methods and equipment.

References

- MÜLLER, RALPH HOLCOMBE. American Apparatus, Instruments and Instrumentation. Ind. Eng. Chem—Anal. Ed., 12: 571 (1940).
- Instrumental Methods of Chemical Analyses. Ind. Eng. Chem.—Anal. Ed., 13: 667 (1941).
- Standard Methods for the Examination of Water and Sewage. Am. Public Health Assn. and Am. Water Works Assn., 8th Edition (1936).
- ADAMS, ROBERT C. Reporting the Results of Water Analyses. Proc. A.S. T.M., 40: 1307 (1940).
- GOUDEY, R. F. Wartime Protection of Water Supplies. Am. J. Pub. Health, 31: 1174 (1941).
- 6. BUSWELL, A. M., GORE, R. C., HUDSON, H. E., JR., WIESE, A. C. & LARSON, T. E. War Problems in Analysis and Treatment. Jour. A.W.W.A., 35: 1303 (1943).
- Scofield, C. S. & Wilcox, L. V. Boron in Irrigation Waters. U.S. Dept. Agric. Tech. Bul. 264 (1931).
- KITTO, W. H. A Contribution to Water Analysis—Specific Conductivity as a Measure of Total Dissolved Solids. Analyst (Br.), 63: 162 (1938).

roof,

ol. 37

ler a satisative

ylene and and is

0.01 ctory races

enower

tories senic part

unts, mopre-

uracy s and with been

Comnking naney isfac-

A.W.
od for
amate

by an s. It d feraddiagent

eagent which od for

0

0

01

W

co

si

ly

ha

ge

us

De

tw

SI

be

ch

gr

ca

of

to

pla

all

thi

be

tor

filt

bri me ver

a I

fiel

X-I

ver

typ

pho

acc

wil

diu

- 9. Sokoloff, V. P. A Rapid Method of Checking the Accuracy of Reported Water Analyses. Soil Sci., 49: 57 (1940).
- GUSTAFSON, H. & BEHRMAN, A. S. Determination of Total Dissolved Solids in Water by Electrical Conductivity.
 Ind. Eng. Chem.—Anal. Ed., 11: 355 (1939).
- COOPER, STANCIL S. The Mixed Indicator Bromocresol Green-Methyl Red for Carbonates in Water. Ind. Eng. Chem.—Anal. Ed., A: 13: 466 (1941).
- SCHROEDER, W. C. Errors in the Determination of Carbonate in Boiler Waters. Ind. Eng. Chem.—Anal. Ed., 5: 389 (1933).
- Public Health Service Drinking Water Standards and Manual of Recommended Water Sanitation Practice. Pub. Health Rpts., 58: 69 (1943).
- DEMARTINI, F. E. Corrosion and the Langelier Calcium Carbonate Index. Jour. A.W.W.A., 30: 85 (1938).
- MOORE, EDWARD W. Graphic Determination of Carbon Dioxide and the Three Forms of Alkalinity. Jour. A.W.W.A., 31: 51 (1939).
- Dye, John F. The Calculation of Alkalinities and Free Carbon Dioxide in Water by the Use of Nomographs. Jour. A.W.W.A., 36: 895 (1944).
- Hirsch, A. A. A Slide Rule for Carbonate Equilibria and Alkalinity in Water Supplies. Ind. Eng. Chem.— Anal. Ed., 14: 943 (1942).
- 18. Langelier, W. F. The Analytical Control of Anti-Corrosion Water Treat-

- ment. Jour. A.W.W.A., 30: 1802 (1936).
- HOOVER, C. P. Practical Application of the Langelier Method. Jour. A.W. W.A., 30: 1802 (1938).
- LARSON, T. E. & BUSWELL, A. M. Calcium Carbonate Saturation Index and Alkalinity Interpretations. Jour. A.W. W.A., 34: 1667 (1942).
- HIRSCH, A. A. Special Slide Rule for Calcium Carbonate Equilibrium Problems in Corrosive Control of Water Supplies. Ind. Eng. Chem.—Anal. Ed., A: 14: 178 (1942).
- Scalar Diagram for pH of Calcium Carbonate Equilibrium. Jour, A.W.W.A., 35: 594 (1943).
- Control of Chlorination—Committee Report. Jour. A.W.W.A., 35: 1315 (1943).
- Reprint No. 2440 from Pub. Health Rpts., 58: 69 (1943).
- Ludwig, E. C. & Johnson, C. E. Spectrophotometric Determination of Magnesium by Titan Yellow. Ind. Eng. Chem.—Anal. Ed., 14: 895 (1942).
- GRAHAM, D. W. Chromium—A Water and Sewage Problem. Jour. A.W. W.A., 35: 159 (1943).
- 27. KNUDSON, HAROLD W., JUDAY, С. & MELOCHE, V. W. Silicomolybdate Method of Silica. Ind. Eng. Chem.— Anal. Ed., 12: 270 (1940).
- 28. Kehoe, Robert A., Cholak, Jacob & Largent, Edward, J. The Concentration of Certain Trace Metals in Drinking Water. Jour. A.W.W.A., 36: 637 (1944).

DISCUSSION-M. C. Schwartz

Asst. Director, Engineering Expt. Station, Louisiana State Univ., Baton Rouge, La.

Insofar as Mr. Graham's article points out the newer trends in water analysis and urges the further development of both personnel and equipment in our laboratories, his paper serves a very useful purpose. However, if one of his reasons for writing this paper is to demonstrate that the eighth edition of *Standard Methods* is in need of

revision, his article is hardly necessary. The Joint Editorial Committee, as well as a number of individuals, has been aware of this fact for several years and the ninth edition of *Standard Methods* is being prepared for distribution this year. The ninth edition would undoubtedly have appeared much earlier had it not been for the war. It is quite

ol. 37

1802

on of

A.W.

Cal-

and A.W.

e for

Prob-

Vater

Anal.

Cal-

Jour.

Re-

1315

ealth

Spec-

Mag-

Eng.

2).

Vater

A.W.

C. &

bdate

em.—

OB &

ncen-

ls in

N.A.,

La.

sary.

well

been

and

hods

this

unrlier

quite

possible that a preview of the contents of the ninth edition should have appeared in print before now, thereby reassuring those interested that recent developments were under consideration.

The analysis of water and the various deposits arising from contact of water (or steam) with the material conveying the water (or steam) is simply a specialized branch of analytical chemistry. The last ten years have seen remarkable advances in the general field, particularly toward the use of "instrumental methods." This period practically covers the gap between the eighth and ninth editions of Standard Methods.

As Mr. Graham points out, there has been a considerable shift from the chemical methods, as exemplified by gravimetric analysis, to physical-chemical methods, as exemplified by the use of filter photometers or spectrophotometers. This change has been taking place not only in water analysis but in all fields of analytical chemistry. The three types of instruments which have been widely adopted by water laboratories are the electronic pH meters, the filter photometers and spectrophotometers, and the electrolytic conductivity The spectrograph and the bridges. metallographic microscope have had very limited use in the field of water. The polarigraph will undoubtedly have a more widespread application in this field than it is presently receiving. The use of the petrographic microscope and x-ray diffraction analysis equipment is very limited in this field but in some instances it is indispensable. A new type of photometer, called the flame photometer, is now available. Its use, according to the writer's experience, will revolutionize the analysis of sodium and potassium.

In the ninth edition of Standard Methods the chapters on "Sanitary and Mineral Analyses" have been consolidated, thus eliminating the artificial distinction and the frequent duplication involved. The number of substances for which methods of analysis are given has been increased and the scope of the methods of analysis for a given substance has also been increased to include other methods beside gravimetric methods. There is a tendency in making a widespread revision to throw out old standards. gradual transition in this direction is better since Standard Methods must show a reasonable amount of conservatism and let some of the newer methods prove themselves.

One particular point that seems to justify some discussion is the apparent desire of some to discard gravimetric methods entirely. This idea, I believe, is unsound. For example, in the determination of very small amounts of aluminum, it is admitted a good colorimetric method will be more satisfactory than a gravimetric method. However, the colorimetric method must at some time be standardized against known solutions of aluminum whose analysis will be made by gravimetric methods.

One fundamental problem in water analysis consists of the identification of compounds formed by evaporation of water. For years we have been using various schemes of hypothetical combinations. We do have available the petrographic microscope and the x-ray diffraction analysis equipment for direct identification of these compounds. Excellent results are being obtained from their application.

Determination of sodium and potassium has also been a sore spot in water analysis for many years. Some of the newer methods of determining sodium and potassium are included in the ninth edition. The use of the flame photometer, however, is not covered because of its extreme newness. However, it appears to be the coming method.

It would be out of place to present a more detailed analysis of the contents of the ninth edition in a discussion of this paper, particularly in view of the fact that the book is scheduled to appear this year. Mr. Graham's interest and desire to use the latest developments in the field of analytical chemistry is very commendable. The most satisfactory way of meeting the desires and demands of such people is to revise Standard Methods more frequently.

DISCUSSION-Harry E. Jordan

The Los Angeles Department of Water and Power has provided for the control of water quality in its service area a competent sanitary engineering and laboratory staff and the most adequate equipment for the work to be done. Mr. Graham, as the department's Chief Chemist, is entitled to full consideration of the opinions which he records. The survey of practice in American water control laboratories which he has made is of great value and executives who deal with policymaking in water control laboratories should give heed to the ideas which this article offers.

Mr. Graham gives some attention to the merits as well as the deficiencies of Standard Methods for the Examination of Water and Sewage. Dissent is the privilege, in fact the obligation, of technical and professional men. writer has been a dissenter re Standard Methods at times. He was later Chairman of the Joint Editorial Committee which prepared the eighth (current) edition. No informed person will deny that the ninth edition is technically long past due. But it is of interest to note that, as the ninth edition moves towards completion, certain very important procedures are still the subject of much debate and some dissent—even as they go into print.

The JOURNAL has been the medium of presentation of many articles concerning water examination methods. which later have been accepted by the editors of Standard Methods. very first formal article in Vol. 1, No. 1 (March 1914) of this Journal expressed dissent with the 1912 edition of Standard Methods in its substitution of the plate count on agar for the plate count on gelatin and the change in incubation time and temperature from 48 hours at 20°C. to 24 hours at 37°C. There is no doubt that when the ninth edition appears, someone will object to the methods for bacteriological examination therein contained and, in all probability, the JOURNAL will print articles which discuss the subject.

Quite a while ago the writer reached the opinion that a standard text cannot be a daring or exploratory text. Daring and exploration belong to individuals, not to standards. A standard method must be one which has long since passed the stage of publication of the original article about it. The method must have been tried by those competent to appraise it objectively (the original author rarely is)

of the to apnterest evelophemise most desires to ree fre-

dissent

by the
The
1, No.
AL exedition
abstitufor the

erature ours at when ne will riologied and,

change

at will subject. reached ct can-

to instandch has oublica-

out it. ried by objecely is) and by those who are not so competent but who need precise, foolproof direction and who, even with their limited ability, are able to apply the method in the control of water purification or production. When a method has had this type of seasoning and it serves a need in the appraisal of water quality, it earns its way into Standard Methods.

The very background of Standard Methods makes its preparation laborious. A single author could write such a text with the greatest of ease—if the author were competent. A committee of a single association could work with considerable ease and speed, provided that the association did not set up too much "procedure" to control the committee. But Standard Methods is a two-association sponsored document, with a long tradition and much protocol behind it. The committee which edits

the text must discuss its proposals with various interested groups in each association. It likewise attempts fully to take into account the opinions and suggestions of other groups in other associations competently interested in the subject matter. And when a new edition appears, it will contain some mistakes of judgment and some methods which, in the opinion of part of its clientele, are obsolescent when the text appears. But nowhere else in the world has there been a manual comparable to it—the product of a combination of professional democracy and representative action, always behind the experimentalists, it remains the accepted and safe guide to the many thousands of earnest workers who control water quality and protect the public health by their devotion to duty.



Development and Practice of Municipal Water Softening

By H. M. Olson

Advisory Maint. Engr., The Ohio Salt Co., Wadsworth, Ohio
A contribution to the Journal

THE first municipal water softening plants were installed at Southampton and Canterbury, England, in 1888. North America's first plant was installed at Winnipeg, Canada, in 1901, and the first in the United States was placed in operation at Oberlin, Ohio, in 1904. St. Louis, Mo., also in 1904, introduced lime softening and a similar plant was installed at Columbus, Ohio, in 1908.

The largest population now served with a softened supply is at Ventura, Calif., from which over 2,000,000 people in twelve communities receive water from a combination lime-sodaash-zeolite plant treating water from Boulder Dam, Colo. The smallest community served is Cameo, W.Va., where a zeolite system furnishes soft water to a population of 100. A Spaulding Precipitator at the 120-mil. gal, sludge-blanket type plant at Minneapolis, Minn., softens Mississippi River water for 429,000 people who, in 1939, used an average of 50 and a maximum of 104 mgd. of water. At Kansas City, Mo., the old filtration plant, using Missouri River water, was converted to a softening plant with a capacity of 150 mgd., without additional operating cost.

There were 576 municipal water softening plants in operation as of Dec. 1, 1941 (1). In a later survey made

by the author (2) it was shown that as of Jan. 1, 1945, there were 665 softening plants in the United States representing a gain of 89 plants in approximately three years' time. These plants serve 900 communities with a total population of about 12.000,000 In addition there are from 400,000 to 450,000 privately-owned domestic softener units in operation. About 350 communities in 25 states have soft water service, either privately or municipally operated, with 200 regenerating stations in which approximately 105.-000 units with from 190,000 to 210.-000 regenerations per month are used. Florida had only one such system operating in November 1944. In Indiana, as of Jan. 1, 1945, there were twelve communities with this service. using 10,000 regenerations per month and softening 15 mil.gal. of water to zero hardness. Rockford, Ill., has 2,600 units with 8,000 regenerations per month and Canton, Ohio, has 1,600 units with 2,400 regenerations per The latter two systems are month. both privately operated.

30

the

tho

for

135

on

You

the

the

sect

van

all o

star

side

ness

redu

some

the

tribu

trolle

50-p

facto

V

Over 69 per cent of all the municipal water softeners are installed in the so-called hard water area of the United States, which includes Wisconsin, Illinois, Michigan, Indiana, Ohio and surrounding states. Ohio alone had 127 plants as of Jan. 1, 1945.

er

that

soft-

tates.

n ap-

These

rith a

0,000.

000 to

soft-

t 350

ft wa-

unici-

rating

105,-

210.-

used.

vstem

n In-

were

ervice.

month

ter to

, has

ations

1,600

s per

nicipal

he so-

United

n. Illi-

d sur-

ad 127

Some of the larger cities in the hard water area that are contemplating water softening are Louisville, Ky.; Davenport, Iowa; Dayton, Springfield and Zanesville, Ohio; and Freeport, Ill.

Chicago's South Side Filtration plant, which is now approaching completion, and the recently completed filtration plant at Milwaukee, Wis., are so equipped that water softening can be started, with a minimum expenditure, on the Lake Michigan supply which has a hardness of approximately 128 ppm.

In general the following phrases describe varying degrees of hardness:

Soft—Hardness of less than 50 ppm. Moderately Hard—Hardness between 50 and 150 ppm.

Hard—Hardness between 150 and 300 ppm.

Very Hard—Hardness over 300

Hardness, however, is only relative. Persons living in Miami when the water was not softened (290 ppm.) thought when they were in Chicago, for instance, that the water was soft at 135-ppm. hardness. Chicago residents, on the other hand, think that New York City water at 33 ppm. is soft and the people of New York City think that the waters in some of the mountainous sections of New England and Pennsylvania are soft at 17 ppm., and so it is all over the country.

When municipal softening was first started the distributed water was considered satisfactory at 100-ppm. hardness but now the general practice is to reduce the hardness to 65 ppm. Under some conditions, depending on whether the corrosive tendencies in the distributed supply can be properly controlled to correct red water troubles, a 50-ppm. supply has been found satisfactory.

Methods of Obtaining Soft Water

Soft water may be obtained in the following ways:

- 1. Year-round collection of water from "soft water" watershed areas into reservoirs, as is done for the New York City water supply and which is now being contemplated for the Pittsburgh area.
- 2. Collection of "soft water" runoff from watersheds, streams, rivers, etc., during those periods of the year when the supply is soft, as is the practice at Oklahoma City, Okla., and Morgantown, W.Va.
- Collection of rain water in cisterns.
- 4. Domestic water softeners, available only since zeolite water softeners came into use about 1914.
- 5. Softening with soap and chemicals aided by heating.
- 6. Soft water service—domestic and commercial—consisting of the installation of small zeolite units that are periodically regenerated at a central plant.
- 7. Evaporating and condensing water to and from steam—a very expensive process.
- 8. Central water softening plants for the entire city supply.

There are two plans now possible for softening a municipal water supply, both of which will give good results if properly operated: (1) The entire municipal supply is softened to around 120 ppm. with chemical control balance in the water. In addition to this, a soft water service may be provided for those who wish to pay an extra charge for water softened to zero hardness. (2) The water at the central plant is softened to 50 ppm. A water of this hardness content has been found satisfactory in most cases but the im-

eı

w

Sil

Sig

eit

the

nit

in

sol

ma

the

its

for

per

on

ame

har

etc.

back

exa

tion

portant thing is to maintain a proper chemical balance. The economics involved in each case should be studied to determine which method is better for the conditions prevailing.

There are two general methods of water softening now employed: (1) chemical precipitation and (2) zeolite or base exchange. Occasionally a combination of these methods is used. These methods do not include forms of water conditioning for the removal of iron, manganese, gases, etc. It must be borne in mind, however, that in a great many instances, by the use of additional chemicals and proper control of operations, some or all of these nuisances can be removed at the same time and with the same equipment as is needed for softening.

Chemical Precipitation

The development of chemical precipitation in recent years has been marked. Certain chemicals, usually lime, soda ash, caustic soda, etc., depending on the raw water characteristics and final quality desired, are added to the water supply in direct proportion to the flow. The chemicals are mixed, settled, filtered, recarbonated and corrected for corrosion stabilization. This process results in a reduction of the total solids content of the water.

There are several different types of design used in chemical precipitation plants. They are:

(1) Old conventional type with single basins of different shapes—circular, square, oblong and variations—and different depths, depending on the designer and previous experiences. This type requires from eight to 144 hours' settling time.

(2) New conventional type with premixing, presettling, dual basins,

flocculators and separate recarbonation, etc.

(3) Sludge blanket type where sludge or slurry may be recirculated. Generally from three-fourths to one and one-half hours' detention time is required, depending on the water characteristics and the formation of the sludge.

(4) Contact type where the precipitation depends on a catalyst or granule. The time of actual precipitation is about three minutes; designed detention time is usually fifteen minutes.

(5) Combinations of the above types.

Sand or anthracite coal (Anthrafilt) filters are used with this type of equipment, which includes proper apparatus for control and operations. It has been suggested, however, that the contact type unit could be used to remove the calcium and the sludge blanket unit (arranged in series) to remove the magnesium without the use of a filter.

Zeolite or Base Exchange

The term "zeolite" is applied to a class of alumino-silicates which contain readily replaceable ions such as sodium and potassium. When added to water the zeolite takes up the calcium and magnesium ions (which constitute hardness in water) and gives up in exchange replaceable sodium or potassium ions. The total solids content remains unchanged.

When the non-hardening ions have been depleted the softening capacity of the zeolite is restored by regenerating with a solution of common salt.

Control is usually obtained (I) manually, hydraulically, electrically of hydraulically-automatically in operation or (2) by means of cation and anim exchangers using salt, alkali and acid

bonawhere

Vol. 37

alated.
o one
ime is
char-

of the

yst or recipisigned

above

equipparatus as been contact ove the et unit

ve the

ed to a contain sodium

o water am and enstitute p in expotasatent re-

ns have pacity of nerating t.

ed (1) ically of peration and anion

as regenerants or stabilizers that will remove all the insoluble and soluble salts in a water, making it as good as, if not better than, distilled water.

In base-exchange operations the following kinds of exchange minerals are used: natural greensand, high-capacity greensand, synthetic silica gel, refined bentonitic clay, and carbonaceous and resinous zeolites.

All of the above types can be regenerated with salt brine but the carbonaceous and resinous zeolites can also be regenerated with acids and alkalis.

Developments are rapid in this field and other types of minerals no doubt will soon be on the market. Experiments have been made with bituminous coal wastes to obtain at a small cost a base-exchange mineral that will be good for one or just a few regenerations.

In operating a base-exchange softener the mineral is placed in a container, of gravity or pressure type, which is supported on layers of gravel similar to those used in sand filter design. The incoming water is passed either downward or upward through the granular zeolite bed at certain definite rates of flow. The hardness ions in the water are exchanged for the insoluble sodium ions of the zeolite, thus making the water soft but retaining the total solids content.

When a particular unit has exhausted its base-exchange capacity, it is ready for regeneration. The length of the period between regenerations depends on the type of mineral used, the total amount of raw water flowing through, hardness, rate of flow, the total solids, etc. To regenerate, the softener is backwashed for about ten minutes, the exact period depending on the condition of the backwash water used. Then

a predetermined amount of salt brine is distributed evenly over the top of the zeolite bed and passed down through it, reacting with the zeolite to remove the calcium, magnesium, ferrous iron and manganous manganese and at the same time restoring the zeolite to its original condition. The amount of salt is determined in proportion to the exchange capacity and the cubic feet of mineral in the bed and varies with each type of mineral and form of operation —from 0.35 lb. per 17,100 ppm, hardness as CaCO, removed with the synthetic gel zeolites to 0.55 lb. per 17,100 ppm. for the bentonitic zeolite types.

The last step in the regeneration process is the salt rinse, which consists of washing the calcium and magnesium and excess salt to the sewer outlet by means of a slow flow of water through the bed. The rate of flow depends on the type of mineral, the depth of the bed, etc., and the time usually required is from 20 to 25 minutes with greensand to 65 minutes for some types of gravity-operated synthetics. After the rinse the softener is returned to service.

The electric cell method of softening, which requires low cost electric power, is now being developed and may be used in future softening operations. As yet, however, no plants in the installation stage are yet in operation.

Avoiding Red Water Troubles

With the chemical precipitation type of equipment the water is softened to a definite hardness, as required or as predetermined, and is then conditioned for distribution. With the zeolite type of softening, the raw water is softened to zero hardness, and then a part of it is properly treated and bypassed to obtain the predetermined hardness in the distributed supply.

17

Th

ex

nai

sof

ing

sali

ize

sive

pro

soft

nar

ope

soft

tral

san

stat

sum

Plan

T

stall

for

then

mun

which

posi

oppo

preli

view

ficial

paig

lesso

appli

comp

addr

In order to be free from red water troubles it is necessary to stabilize or inhibit the water in the distribution system. This may be done by recarbonating the chemically precipitated water or adding lime to condition with sodium hexametaphosphate. In the zeolite system it is necessary to add either soda ash, caustic soda, caustic soda and sodium silicate or sodium hexametaphosphate to maintain the proper calcium carbonate stability. This is usually at a pH of about 7.9–8.0 on a distributed supply of from 65-to 85-ppm, hardness.

There are only two combination chemical precipitation-zeolite plants operating on municipal supplies at the present time; one is at LaGrange, Ill., the other at Ventura, Calif. There is one Spiractor at Teutopolis, Ill.; one brine-well-zeolite system at Westview, Pa. (suburb of Pittsburgh); and one sea water regenerated zeolite system at Sarasota, Fla.

At LaGrange, Ill., where lime pretreatment, reducing the raw water from 1,060 ppm. to 273 ppm., is followed by an upflow synthetic zeolite process, it was found that the addition of lime or Calgon as a stabilizer did not eliminate red water troubles. Consequently 2 per cent of the raw water was bypassed to provide enough calcium in the distributed water so that soda ash would react to provide the proper pH and calcium carbonate stability.

Benefits From a Softened Supply

The numerous benefits derived from a softened water supply fall into the following categories:

1. Savings in household operations involved in the use of soap and cleaning compounds.

2. Elimination of the cost of installing household water softeners or reduc-

tion in the cost of operation of those already installed.

3. Elimination of separate soft water storage and piping systems.

 Reduction in the cost of process water for industrial and commercial establishments.

5. Increased revenues of the public utility by virtue of greater sales of water for all purposes in the community.

"Savings in household operations involved in the use of soap and cleaning compounds" will account for approximately one-half of all the savings to be made with a softened water supply. The savings will vary, however, with the hardness of the raw water, the hardness of the distributed supply and the types of industry and homes involved.

In a southern city which has a population of 310,000 served by water softening plants, the raw water has been softened from 297 ppm. to 72 ppm. The estimated cost of soap, based on 1938 prices, would be \$6.38 per capita at 297 ppm. and \$5.14 per capita at 72 ppm.—a difference of \$1.25 per capita or a total savings of approximately \$385,000 per year. It is reasonable to expect that the total benefits would represent a saving of from \$800,000 to as high as \$1,200,000 per year.

A middle western city of 400,000 population with a public supply having a raw water hardness of 250 ppm, would save from \$1,000,000 to \$1,250,000 per year by installing a water softening plant which would reduce hardness to 85.5 ppm.

Charles P. Hoover, in a report of the operations of the Columbus, Ohio, water softening plant, stated that if, of the entire supply of that city, where hardness is reduced from an average of 265 ppm. to 87 ppm., only 1 per cent were used with soap each day, the soap savings effected by softening the whole supply would be about \$650,000.

Hoover further states that in Columbus the average family of five uses 175 gpd. of water at a cost of 2.9¢. The average yearly cost of water per family of five is \$10.60, with a savings in soap alone of \$9.77 per year.

Softening water for cleansing purposes cannot be avoided unless very expensive compounds are used. Ordinarily soap is used in the home as a softening agent but it has little cleansing value or action until it lathers and it will not lather until the hardness salts in the water have been neutralized. Softening with soap is expensive—\$0.0075 worth of lime, when properly applied and controlled, will soften as much as \$3.00 worth of ordinary soap when used in household operations. It is therefore cheaper to soften the entire city supply at a central source than to do it in the thousands of homes, even though, as Hoover states, only 1 per cent of the water consumed needs to be soft.

Planning a Water Softening System

Those who are interested in the installation of a water softening system for their community should organize themselves and carefully study the community attitude toward the project which they wish to promote. Some opposition may be encountered. As these opposing viewpoints appear during the preliminary study they can be reviewed with engineers and public officials who have conducted similar campaigns in other communities and the lessons that they have learned may be applied to the local situation. Finally, competent speakers may be invited to address public meetings or committees, by way of insuring a general understanding of the subject.

The next step should be an investigation of ways and means—that is, a study of state laws to see if the necessary expenditures can be made.

When it has been determined that funds can be procured, an engineer should be consulted for advice regarding the type of treatment, the maximum capacity possible with the funds available and similar problems. The engineer should then submit a comprehensive report making specific recommendations on these points and covering costs of construction and operation, provision for future expansion, adjustment to changes in water supply, etc.

The report should be carefully studied. If it is necessary to obtain public approval for the bond issue to finance the construction of the plant, a group of public-spirited citizens, recognized as leaders in the various parts of the community, should band themselves together to promote an affirmative public attitude. When public approval has been obtained for the construction of the softening plant, final plans can be drawn, the contractor's bids solicited and construction begun.

Costs

At this point it becomes necessary to make a careful analysis of installation and operating costs and reserve funds for future contingencies, in order to make sound calculations of returns required. In arriving at the true cost of the plant the following items must be known and totaled: (1) cost of developing community interest; (2) cost of preliminary studies, including visits to other communities; (3) costs incurred in investigating state laws and means of financing the project; (4)

those

ol. 37

water

ocess ercial

oublic es of com-

aning proxito be apply.

with the y and es in-

popur sofbeen ppm. ed on capita at 72

capita nately ble to would 000 to

ppm., \$1,water

Ohio, nat if, where werage

r cent

Oct.

TABLE 1 Cost of Constructing Softening Plants

Location	Type of Plant	Year In- stalled	Designed Capacity 1,000 gpd.	Raw Water Hard- ness ppm.	Treated Water Hard- ness ppm.	Average Consumption 1,000 gpd.	Peak Con- sump- tion 1,000 gpd.	Cost of Con- struction	Remarks
Ambridge, Pa.	Gravity type with filters and green- sand softeners	1934	1,800	350	70	1,450	1,800	\$60,000	During last two years demands went to a mgd. when a great deal of hard water had to be pumped into mains due to undercapacity in the softening plant.
Coraopolis, Pa.	Automatic green- sand, pressure type, zeolite sys- tem, with manga- nese zeolite pres- sure unit for con- ditioning bypass water	1935	1,500	150- 300	60	950	1,279	40,000	ment only.
Cuyahoga Falls, Ohio	Gravity filter, syn- thetic zeolite	1936	4,000	256	63	1,214	1,945	69,000	Cost included fine brick building.
Lake, Wis.	Zeolite (silica gel)	1938	1,150	425	102		-	1,350,000 (includ- ing \$550,000 WPA funds)	Complete new system installed, including 200,000-gal tail on a 150-ft. tower, jail, street cleaning department, etc., all housed in ornamestal concrete layout on 5-acre landscaped ground area.
Lancaster, Ohio	Gravity filter and softener layout (silica gel)	1934	3,000	360	85	1,250	2,000	74,000	Cost included hand- some brick building and excellent labor- tory facilities.
New Philadel- phia, Ohio	Gravity type, syn- thetic zeolite (silica gel)	1935	1,500	400	72	905	1,750	75,000	Zeolite has been installed in a third unit to take care of increase in demand due to war plants and increase in harden because of drought conditions.
Rittman, Ohio	Pressure zeolite	1935	550	200	65	180	225- 385	19,700	Cost included building but not consulting engineer's fee.
Sewickley, Pa.	Gravity type zeolite (greensand)	1929	1,750	210	65	750	1,750	262,000	Cost included building, landscaping and engineer's fees.

cost of surveys and reports by engineers; (5) cost of advertising for bids, total construction costs and extra costs not covered in contractor's bids; (6) special costs of placing the plant in operation, and of initial inspections or surveys which are not a part of the regular operating costs.

In addition to the foregoing analysis to establish the actual cost of construct ing and developing the plant, operating costs should be computed with the greatest possible accuracy. It is desirable to include in such computations all chemicals and materials used, maintenance, labor, depreciation, supervi-

supervi-

TABLE 2 Cost of Chemicals

				emicals			
Location	Type of Plant*	Amount of Water Treated mgd.	Raw Water Hard- ness ppm.	Treated Water Hard- ness ppm.	Chemical Cost per mil.gal.	Chemical Cost per mil.gal. per 100 ppm.	Chemicals Used
Beverly Hills, Calif.	CP	6.00	250	150	\$12.43	\$12.43	
Santa Barbara, Calif.	СР		479	240	23.09	9.67	Gas, lime, soda ash, alum
Miami, Fla.	L-S	30.0	270	72	13.97	6.98	Lime, alum, chlo- rine, ammonia, fuel oil
St. Petersburg, Fla.	CP	4.50	190	98	16.48	17.90	Lime, iron
Bloomington, III.	CP	3.96	160	40	7.90	6.58	Lime, alum
Decatur, Ill.	CP	9.50	200	85	5.93	4.39	Lime, alum, am- monium sulfate, chlorine, calgon
LaGrange, III.	Z	0.75	890	85	72.07	8.94	Chlorine, salt, lime, soda ash
Ft. Wayne, Ind.	CP	14.80	308	94	15.51	5.98	Lime, soda ash, cal- gon, chlorine
Lebanon, Ind.	CP	0.42	396	105	20.85	7.18	Lime, calgon
Rochester, Ind.	Z	0.35	291	52	59.88	25.03	Salt, caustic soda, sodium silicate
Cedar Rapids, Iowa	СР	5.75	195	88	16.68	15.59	Lime, alum, ferrous sulfate, ferric sulfate, suspension catalyzer, chlorine, ammonia, ammonium sulfate, activated carbon, soda ash, copper sulfate, fuel oil (CO ₂)
Ottumwa, Iowa	СР	4.40	284	84	37.65	18.82	Lime, soda ash, iron sulfate, òil (CO ₂)
Coffeyville, Kan.	СР	2.30	175	75	16.67	16.67	Lime, alum, chlo- rine, natural gas, soda ash, activated carbon

^{*}CP = chemical precipitation; L-S = lime-soda; Z = zeolite.

00

Bis

Cu

Lai

Ok

Alie Bel Abe

Na

Hur Elk Lak She

sion lation The be

TABLE 2-Continued

Location	Type of Plant*	Amount of Water Treated mgd.	Raw Water Hard- ness ppm.	Treated Water Hard- ness ppm.	Chemical Cost per mil.gal.	Chemical Cost per mil.gal. per 100 ppm.	Chemicals Used
Lawrence, Kan.	CP	1.70	163	104	12.72	21.60	Lime, oil, calgon, chlorine
Topeka, Kan.	СР	6.00	340	90	12.20	4.88	Lime, calgon, alum, soda ash, chlorine, carbon
Ann Arbor, Mich.	СР	4.74	310	85	12.10	5.38	Lime, carbon, am- monia, soda ash, chlorine
Flint, Mich.	СР	20.00	288	91	12.12	6.12	Lime, soda ash, chlorine, ammonium sulfate, carbon, alum
Lansing, Mich.	CP	13.24	400	85	15.10	4.78	Lime, soda ash, coke, calgon
Minneapolis, Minn.	СР	43.4	176	78	8.32	8.48	Lime, alum, soda ash, ferrous sulfate
St. Paul, Minn.	CP	25.5	177	77	6.77	6.77	
Booneville, Mo.	CP	0.5	260	9	23.00	13.50	
Kansas City, Mo.	СР	62.0	215	110	10.57	10.35	Calgon, alum, sul- furic acid, anhy- drous ammonia, ammonium sulfate, chlorine, lime, soda ash, ferrous sulfate, ferric sulfate
St. Louis, Mo.	СР	146.0	191	98	5.35	5.75	Lime, alum, iron, chlorine, ammo- nium sulfate, so- dium silicate, acti- vated carbon
Miles City, Mont.	СР	0.66	239	52	19.05	10.18	Lime, alum, aluminate gas
Falls City, Neb.	CP	1.0	550	200	20.00	5.70	
East Aurora, N.Y.	Z	0.372	380	36	21.20	6.20	
Elizabeth City, N.C.	CP	1.1	150	70	18.00	22.50	

ol. 37

sed

algon,

alum, orine,

am-

ash, onium n,

sh,

soda ulfate

anhyia, ilfate, soda ilfate,

iron, nosoacti-

lumi-

TABLE 2-Continued

Location	Type of Plant*	Amount of Water Treated mgd.	Raw Water Hard- ness ppm.	Treated Water Hard- ness ppm.	Chemical Cost per mil.gal.	Chemical Cost per mil.gal. per 100 ppm.	Chemicals Used
Bismarck, N.D.	CP	1.3	170	75	18.00	18.50	
Columbus, Ohio	L-S	37.6	278	81	13.32	6.97	Lime, chlorine, soda ash, coke, bauxite, carbon, sulfuric acid, sodium hexa- metaphosphate, copper sulfate
Cuyahoga Falls, Ohio	Z	1.5	265	60	24.15	11.80	Salt, chlorine
Findlay, Ohio	CP	1.82	355	80	18.40	6.68	Lime, soda ash, chlorine
Lancaster, Ohio	Z	1.5	440	84	40.60	11.48	Salt, soda ash
New Philadelphia, Ohio	Z	1.5	410	76	43.00	12.90	Salt, chlorine, soda
Oklahoma City, Okla.	CP	18.0	260	100	12.55	7.85	Lime, soda ash, cal- gon, chlorine
Aliquippa, Pa.	Z	1.6	340	25	24.00	9.05	Lime, salt, chlorine
Bellevue, Pa.	Z	5.1	215	85	2.58	2.01	Salt, chlorine
Aberdeen, S.D.	CP		220	44	23.07	13.10	Pyrophosphate, ammonia, carbon, lime, alum, sodium aluminate, chlorine
Natchez, Tenn.	CP	1.2	300	76	22.00	8.92	Lime, ferric chlo- ride
Huntsville, Tex.	Z	0.388	148	42	16.30	15.38	Salt
Elkhorn, Wis.	CP	0.25	310	80	21.00	9.13	Lime, alum
Lake, Wis.	Z	0.4	467	102	34.00	9.32	Salt
Sheboygan Falls, Wis.	Z	0.22	525	95	84.71	19.50	Salt, calgon

sion and control, interest, and accumulation of reserve funds for future needs. The estimate of operating costs must be based on clearly-defined specifications as to raw water analysis, type of treatment, etc., but it may be well to work out other estimates based on possible changes, especially expansion of the plant, so as to prepare for unforeseen contingencies. In other

Co

tui

inc

pre

bu

Th

and

are

sin

ma

Du

are

pac

sin

per

dui

wa

wai

pur bas

4,0

psi.

elev

stop

ent

basi tion tinu Thi

words, financial planning should carefully consider the effect on operating costs of such possibilities as a sudden increase in demand for softened water, the introduction of new industries into the area served or the possibility of an error in water analysis or estimated

plant capacity.

Table 1 gives a general idea of the cost of constructing water softening plants in various sections of the country. It should be pointed out, however, that these figures are not consistent with the estimating costs used by some consulting engineers which are: \$75,000 per mil.gal. for plants under 1-mgd. capacity, from \$50,000 to \$55,000 per mil.gal. on plants of from 3- to 4-mgd. capacity and from \$25,000 per mil.gal. up on very large plants of from 5- to 50-mgd. capacity.

It should also be borne in mind that the plants at Lancaster, Ohio, Ambridge, Pa., and Cuyahoga Falls, Ohio, were built before the war and that similar plants today would cost at least one and one half times as much to construct. The general opinion of persons associated with the construction industry is that no substantial reduction in cost will occur for an extended period

after the war is over.

Table 2 is a summary of the data compiled from questionnaires sent to the various plants listed requesting information on the cost of chemicals used in the softening process.

Consumer Reaction

The author recently submitted a series of questions to 125 cities where water softening plants were in operation. Replies were received from 60. In response to the question concern-

ing the customer's reaction to the availability of a softened water supply. it is recorded that 90 per cent of the replies reported that the public reaction was favorable to a supply softened for all purposes. The question was asked whether or not it would appear advisable to provide a greater degree of softening in the supply than the community now had. The general reaction to this was that the plant was then operating to produce as soft a supply as the conditions in the community would permit. While a softer water would result in certain additional soan savings to the consumers, it would also tend to make the water more corrosive. The increase in per capita consumption of the public supply after a softening plant was installed varied from 5 to 40 per cent. In general, it was indicated that domestic water softeners which had been installed before the municipal plant started operation continued to operate but naturally required less attention than was necessary before the public supply was softened.

It is of greatest importance, once the plant is built, that a competent staff be assigned to operate it and to maintain proper records. If no qualified chemist is available in the community, one should be engaged from outside, since state health departments lack the manpower to handle the control work.

References

 OLSON, H. M. Census of Municipal Water Softening Plants. Jour. A.W. W.A., 33: 2153 (1941).

 1944 Census of Municipal Water Softening Plants. Jour. A.W.W.A., 37: 585 (1945).

Reduction of Chemical Odors at Nitro, West Virginia

By Lawson Haynes and Wallace Grant

Plant Supt., West Virginia Water Service Co., Charleston, W.Va. Chemist, West Virginia Water Service Co., Charleston, W.Va.

Presented on Oct. 26, 1944, at the West Virginia Section Meeting, Parkersburg, W.Va.

THE Nitro water purification plant 1 of the West Virginia Water Service Company was built during World War I to serve the city, which manufactured explosives, with domestic and industrial water. It also furnished fire protection. The original plant was built for 40-mgd. capacity (Fig. 1). The original basins, filters, clear wells and pipe system connecting the same are still in operation today. However, since the daily output is now approximately only 3 mgd., the size of the pumps has been reduced and the filters are rotated for use periodically.

ol. 37

the pply, f the reac-

was

pear

comreac-

then

pply

unity

soap

also

sive.

ımp-

ften-

5 to

indi-

eners

the

con-

re-

eces-

was

e the

ff be

ntain

nem-

one

since

man-

icipal

A.W.

Vater

., 37:

The raw water pumps have a capacity of 4,000 gpm. each and operate singly for approximately thirteen hours per day. Raw water is not pumped during the rest of the day. The raw water pump delivers water to a raw water pit and from there to the aerator pump at the influent of the 10-mil.gal. basin. The aerator pump delivers 4,000 gpm. through the aerator at 55 psi. When the basin reaches a certain elevation, the raw water pump is stopped and a check valve at the effluent of the basin opens to permit the basin water to feed back into the suction of the aerator pump which continues to operate for the full 24 hours. This permits some of the water to receive double aeration. Either or both of the basins may be bypassed and the water carried direct to the filters by using stoplogs.

Two filters are in use for about 20 hours per day until the loss of head becomes great enough to necessitate washing. Then two clean filters are placed in service after which the two dirty filters are cleaned, refilled and held in reserve. By this method all filters are maintained in operating condition.

Filtered water flows by gravity through one of two 6-ft. wood-stave pipelines from the 600,000-gal. clear well to the 5-mil.gal. clear well. The latter is maintained full or nearly so at all times.

Chemical Dosage

The chemical dosage varies as the condition of the raw water changes. However, there is no great change except for the chlorine and carbon. During the months of low flow the chlorine demand is excessive because of the nitrite content of the raw water. The threshold odor value of the raw water determines the carbon dosage. Carbon is fed continuously in varying amounts to the effluent of the 10-mil. gal. basin. Carbon is fed to the raw




Fig. 1. Flow Graph-Nitro, W.Va., Water Plant

W T b th w b th fit gr

ga m th

fo

pl str ch du re ch wl cer sta be 6,1 sio 19 est ply Jan nat vea

Chl Nite Sulf Cale May Sodi Alka M

nun

water before aeration when necessary. The carbon dosage to the 10-mil.gal. basin effluent is so located that, when the raw water pump is off and the water in the basin is recirculated, carhon is applied to the 10-mil.gal. basin, thereby helping to reduce the odor further and to keep down algae growths.

Chlorine is applied to the 600,000gal, clear well in sufficient quantities to maintain a residual of 1.0 ppm. through

the large clear well.

Lime is also applied to the first basin

for final pH correction.

The source of supply for the Nitro plant is the Kanawha River. stream from Nitro are numerous large chemical plants which discharge industrial wastes into the river. As a result the Kanawha at Nitro has some chemical odor even in flood stage, while in periods of low flow the concentration of odor-producing substances in this water is almost beyond belief. A threshold odor number of 6.125 was recorded on several occasions during the summer and fall of 1944 for the Nitro supply. The lowest threshold odor found for this supply in the past two years was 19 on Jan. 4, 1945.

In November 1944 a mineral examination of Kanawha River water revealed:

	ppm.		ppm.
Chloride	52	Free Carbon	
Nitrate	4.4	Dioxide	10
Sulfate	33.6	Iron	0.14
Calcium	32.5	Manganese	Trace
Magnesium	4.7	Hardness,	
Sodium	19.6	as CaCOa	101
Alkalinity—		pH	6.7
M.O., as CaC	O ₂ 33		

Monthly average threshold odor numbers on Kanawha River water at Nitro for the year beginning May 1944 were:

1944		1944		
May	188	November	1,435	
June	743	December	124	
July	1,539	1945		
August	942	January	42	
September	4,300	February	78	
October	2,179	March	317	
		April	1,055	

Water from Coal River, which empties into the Kanawha River at St. Albans, furnishes water to the St. Albans purification plant of the West Virginia Water Service Company. Coal River water is of excellent quality, so that during the winter and spring months there is no trouble with odors at that plant. In the summer and autumn months of low flow, however, the Kanawha River water backs upstream into the Coal River, creating odor problems as bad as, and sometimes worse than, those in Nitro. The highest threshold odor number ever determined at the Charleston laboratory of the West Virginia Water Service Company was 8,333. This was on a river sample from St. Albans collected on Sept. 7, 1944.

Continued operation of the two plants using this supply made it necessary to devise a method of either removing or greatly reducing this odor. This work was started in 1935 when odor was first encountered in any serious measure.

Odor Control

A plan of treatment using aeration and activated carbon operated with considerable success until the summer of 1943. Until that time the odor could best be described as "sweet-chemical." The opening of a synthetic rubber plant and a butadiene plant above the

thr

ter:

jug

and

Nit

tair

car

of

sult

cure

bev

to c

flow

abou

sam

an (

Oct.

Oct.

Oct.

Nov.

Nov.

Nov.

Nov.

Jan.

lan.

Jan.

Feb.

Feb.

Mar.

Mar.

Mar.

Apr.

intakes at Nitro and St. Albans, along with increased industrial wastes from other chemical industries rushed with war work, has made this problem acute in the past two years. At the same time the odor changed to an unpleasant one, smelling like varnish at times and at other times like mustard.

Three methods of odor reduction have been investigated, some results of which are reported below.

Break-Point Chlorination

A series of laboratory experiments and one plant-scale test have been conducted to determine the efficiency of break-point chlorination as a means of odor reduction in Kanawha River water. Ammonia nitrogen concentration is 4 ppm. or more in the summer and autumn months. Break-point chlorine demand ranges from 3.5 ppm. in the winter to 46 ppm. or more in dry months.

Aerated raw water was used for the laboratory break-point and combined odor tests. One-half of the sample was retained as a control and the other half chlorinated about 1.5 ppm. above break-point. Both portions were then allowed to stand for a contact period which varied with different samples from two to 22 hours. After the contact periods, threshold odors were determined on both portions. The chlorinated portion was not de-chlorinated. In all cases the threshold odor numbers of the two portions of any particular sample were the same or very nearly so.

Break-point chlorination on a plant scale was tried at Nitro from Apr. 28 to May 2, 1944. Chlorine was added to the filtered rather than to the raw water for several reasons: (1) This required no change in chlorinating equipment, as chlorine is normally fed at this point. (2) Because this water had to pass through the 5-mil.gal. clear well, ample contact time was assured. (3) By chlorinating the raw supply it might have taken over a week to get a free chlorine residual through the 10-mil.gal. basin.

Chlorine was added to the small clear well at the rate of from 8 to 10 ppm. during the hours of filtration on these days. By May 2 a free chlorine residual of 1.3 ppm. was found in the plant effluent. Throughout the test the odor number of the filtered water. before chlorination, was 12. On May 1 the odor number of the plant effluent was 5, while on May 2, the first day to show free chlorine, it was 12. Since no odor reduction was found from this test or in the laboratory experiments, it was concluded that breakpoint chlorination reduces this type of odor very little or not at all.

Activated Carbon

From plant experience and laboratory tests it has been found that beyond a certain point the addition of more activated carbon removes little odor and certainly is not economical. At one time, before the introduction of double aeration, the rate of feed of carbon at the St. Albans plant was over 340 ppm., and this did not solve the odor problem by any means. For the rest of the period preceding double aeration, 170 ppm. was not an uncommon dose.

In one laboratory test aerated raw water from the St. Albans aerator was treated with varying amounts of Aqua Nuchar up to 855 ppm. A little alum was added and a contact period allowed equal to that in the basins at St. Albans. Results were as follows:

1.37

fed

ater

lear

red. ly it

get

10-

mall

10

on on

rine

the

test

ater,

May

fflu-

first

12.

und

ex-

eak-

e of

ora-

vond

nore

odor

At

n of

car-

over

the

r the

ouble

com-

raw

was Aqua

alum

d al-

is at

ows:

Activated Carbon lb./mil.gal.	Threshold Odor Number After Treatment
0	420
1,430	124
2,145	62
2,860	41
3,575	15
7,150	6

Filtration of the finished water through granular activated carbon filters has received attention. Two 1-gal. jugs were arranged as upflow filters and set to run 24 hours per day, using Nitro finished water. Jug No. 1 contained 1 lb. 1 oz. of granular Nuchar carbon: No. 2 contained 2 lb. 14 oz. of Darco granular carbon. The results in the tabulation below were secured before the jugs became clogged beyond repair and it became impossible to operate the filters any longer. The flow was controlled so that it would about equal a flow of 0.6 gpm. if this same amount of carbon were placed in an ordinary filter to a depth of 18 in.

Data	Service Pump Threshold	Effluent Jug No. 1 Threshold Odor No.	Jug No. 2 Threshold
Date			
Oct. 10, 1944		0	0
Oct. 17, 1944		0	0
Oct. 25, 1944	21	0	0
Oct. 31, 1944	13	0	0
Nov. 10, 1944	70	0	4
Nov. 15, 1944	80	0	5
Nov. 21, 1944	60	4	6
Nov. 28, 1944	19	0	2
Jan. 10, 1945		0	0
Jan. 17, 1945		2	0
lan. 25, 1945		0	0
Feb. 7, 1945	50	11	a-10000 V
Feb. 15, 1945		8	-
Feb. 20, 1945		5	
Mar. 6, 1945		2	-
Mar. 14, 1945		2	
Mar. 21, 1945		10	
Mar. 27, 1945		10	_
Apr. 5, 1945	8	4	

The conclusion is that granular activated carbon is valuable in reducing the last fraction of odor after the bulk has been reduced by aeration.

Aeration

Aeration by high pressure has been found to be by far the best means of reducing the chemical odors encountered in Kanawha River water. As much as 98 per cent of the odor has been removed by a single aeration at 110 psi. at the nozzle of the aerator.

The aerator at Nitro was designed by and constructed under the supervision of J. R. Peck, the engineer in charge of the Nitro plant. It consists of 30 No. 11-BA 2-in. Spraco nozzles arranged along a pipe which decreases in diameter in calculated steps from 18 to 8 in., so that practically the same pressure is found at all nozzles. The pumping expense for a single aeration at 55 psi., according to Mr. Peck, is less than the cost of applying 17 ppm. of activated carbon.

When odor is present in the supply at St. Albans, the water is aerated twice. The first aeration is of the raw water through five 2-in. Spraco nozzles with about 30 psi. pressure from the intake pump. Because of lack of space this aerator has four sides boarded up. There is no evidence that this has led to any serious decline in its efficiency.

A second aerator, constructed at St. Albans late in the summer of 1943, picks up the treated water at the end of the first basin and aerates it at about 30 psi. This water then flows into the second basin. Three sides of this aerator are boarded up.

Efficiency of High-Pressure Aeration

Experiments to determine the most efficient method of operation for high-




Fig. 2. Threshold Odor Reduction by Aeration Using 2-in. Spraco Nozzle on Kanawha River Water. Raw Water Thresholds: 1941—1,660; 1944—500

pressure aeration have been conducted in the past four years. In the fall of 1941 an experimental aerator, using a single 2-in. Spraco nozzle, was built at Nitro. Odor tests were run on the raw water and on samples from the aerator using pressures of from 10 to 55 psi. in 5-lb. steps. The threshold odor number of the raw water was 1,660, 95 per cent of which was removed at the highest pressure. This sample had a threshold odor number of 75 (Fig. 2). Treatment of this sample with activated carbon resulted as follows:

The threshold odor was reduced from 75 to 10 by 34 ppm., to a threshof 5 by 68 ppm., to 4 by 103 ppm., and to 2.5 by 137 ppm.

The present aerator at Nitro was built as the result of this experimental work and its use, together with carbon, served to eliminate most of the odor until the summer of 1943.

Under present odor conditions of the river, substantial amounts of odor are removed by raising the pressure on the aerating nozzle from 55 to 110 psi., which is the highest pressure so far tested. This was demonstrated in May 1944 when, on a special one-nozzle aerator, odors were determined on samples of from 55 to 110 psi. The raw river water had a threshold of 356 which in the 55-psi. sample was reduced to 31. The odor dropped consistently with an increase in pressure until the 110-psi. sample had a threshold of 7, or 98 per cent removal.

About the same results were secured when this test was repeated in June. The river odor of 500 dropped to 14 in the 110-psi. sample (Fig. 2).




Fig. 3. Threshold Odor Reduction by Aeration on Kanawha River Water. Threshold Odor 833—17 ppm. Alum Added to Raw Water Before Aeration at 49-psi. Pressure

Percentage of Odor Re

pi

Second the Three

30

f the of the or are on the

ol. 37

psi.,
o far
May
nozzle
d. on
The
of 356

is rel conessure aresh-

June. to 14

Threshto Raw Pressure

60°

Trial runs were made at the Nitro aerator in September 1943 to determine if any position of the nozzles, other than vertical, would give better odor reduction. Kanawha River raw water, to which 17 ppm. of alum had been added, was used. Nozzles were slanted off the vertical at 15, 30, 45 and 60 deg. Samples were taken at 49, 40, 30, and 20 psi, pressure. Best reduction in the odor was secured at 15 deg. and at 49 psi. This reduction was 83 per cent, but at the same pressure and at 60 deg. it had dropped to 77 per cent. In general the more nearly vertical the nozzle, the better was the efficiency. Figure 3 shows these results.

A second aeration of once-aerated and settled water from the 10-mil.gal. primary basin at Nitro was also the




Fig. 4. Threshold Odor Reduction by Second Aeration of Once-Aerated and Settled Water From Primary Basin Effluent— Threshold Odor 313




Fig. 5. Threshold Odor and Residual Chlorine Reduction by Aeration of Plant Effluent From Second Clear Well Using 2in. Spraco Nozzle

basis of a series of odor determinations (Fig. 4). The threshold odor of the once-treated water was 313. What the odor of the raw water was before treatment was impossible to determine because the water in the basin was a mixture of several days' pumping, and what percentage of one or the other day's flow was present could not be calculated. Odor tests on the raw water at that time, however, indicated an odor number between 800 and 1,000.

Aeration of this once-aerated water reduced the odor less, on a percentage basis, than it did in the case of raw water. The fraction of odor remaining appeared to be of a type more difficult to remove. Best results were obtained at 49 psi. and at an inclination of 15 deg. This sample showed a reduction of 73 per cent. Estimating the original odor of the raw water at 833, the total

the

for

the

dit

pos

Pro

tor

tion

(3) duti for com (5) like be e

reduction by double aeration plus 34 ppm, of activated carbon being fed to the basin at that time (see Fig. 1) was 90 per cent. Compare this reduction with that secured in 1941 when a single aeration at 50 psi, removed 94 per cent.

As the odor is reduced step by step, it becomes increasingly difficult to effect a reduction in the next step. Aeration of the plant effluent, using the water from the large second clear well, was tried in April 1944. With a threshold of 11 and the characteristic sweet chemical odor, this was reduced to a threshold odor of 9 at 10 psi., 7 at 20 psi., and 5 at 25 psi. (Fig. 5).

Aeration of water from the second clear well was tried again when the odor was only 2 (Fig. 5). In this case there was almost no odor reduction even at 60 psi., which sample had an odor number of 1.8. Incidental to this investigation was the finding that aeration does not greatly reduce the residual chlorine in water. Before aeration this water showed 0.8 ppm. residual chlorine when tested by orthotolidine with a five-minute contact period. After aeration in steps of 10 psi, to 60 psi, all samples, except one, had a residual chlorine of 0.5 ppm.

A problem encountered in high-pressure aeration is the abrasion of the diffusion vanes, or turbine center, of the nozzle. Abrasion is worse when the river has considerable turbidity. few tests were run to see if these centers could be inverted or eliminated. With the turbine center inverted to give a high spray, a sample at 53 psi. had a threshold odor of 70. When the turbine center was in the normal position and at 55 psi., and other conditions were the same as above, the odor number was 68. Other results showed that little or no change occurs when the turbine center is reversed. At about 90 psi, the same reduction was observed with the turbine center removed as with it in. It is impossible to draw any general conclusions from these few tests, which were not repeated.

Because of the efficiency of highpressure aeration in removing high percentages of these chemical odors, it must not be assumed that the same results can be obtained with odors of other types. In the second week of September 1944 a musty odor was observed in the raw water at Nitro. In spite of aeration at 55 psi. and the addition of 34 ppm. of carbon, it was not entirely eliminated and could be detected in the finished water.

On very cold days the Nitro aerator cannot be used because of the ice which builds up around it. nately there are few days cold enough to cause trouble at Nitro and the river water is usually not so odorous during freezing weather.

Threshold Odors

All threshold odor numbers reported here were determined at room temperature. Checks on the same samples at room temperature and at 60°C. have who shown that the latter odor numbers are usually considerably higher.

Vol. 37

en the l posiditions num-

ed that en the about as ob-

moved draw these ted. high-

g high dors, it e same dors of veek of was obro. In

it was build be aerator the ice

Fortuenough he river us dur-

reported emperanples at C. have numbers

r.

Re-employment of Servicemen

An article based on a pamphlet distributed to its member companies by the American Water Works & Electric Co., New York, N.Y.

In order to provide a workable procedure regarding the re-employment of veterans of the armed forces, the suggestions which follow have been prepared by the American Water Works & Electric Company, New York, for the guidance of its personnel section. Although this article substantially follows the American Water Works & Electric Company's text, it has been adapted to apply to any public or private water utility facing similar problems.

Company Policy

It should be the intent of any company to live up to the spirit as well as the letter of the re-employment provisions of the Selective Service Act. A company should want its servicemen and women to resume their jobs if they wish to do so, and it should want to do everything in its power to help returnees to make a satisfactory transition from military to civilian life (which some will find difficult), and, if they have acquired new skills during their years of service that qualify them for more responsible jobs, to place them in such jobs, if and when conditions within the company make it possible.

Provisions of Selective Service Act

The individuals involved are those who (1) hold certificates of satisfactory service, (2) held permanent positions with the company before service, (3) are still qualified to perform the duties of such positions, and (4) apply for re-employment within 90 days of completion of service. Such persons (5) must be reinstated to a position of like seniority, status and pay, (6) shall be entitled to participate in insurance

and other benefits in accordance with established rules, and (7) shall not be discharged for other than cause for a period of one year.

Suggested Steps

Once the veteran has indicated within the prescribed 90 days—although a company should not necessarily hold rigidly to this 90-day rule his intention to return to his former employment, it is desirable to effect his reinstatement as promptly as possible. The first aim should be to make the returning veteran feel that he is welcome, without singling him out as an object of curiosity. The whole attitude should be such that he will feel he belongs to the group of employees and is one of them, rather than a conspicuous stranger.

The responsibility for welcoming the former employee and for his reemployment should rest, of course, with the company or department manager. The company should rely on the tact and judgment of its officers in conducting such interviews, rather than suggesting any prescribed formula.

However, prior to the time of such interview, a manager or superintendent

ro

in

cer

rei

sho

rea

The

ove

rega

to p

V

should make a thorough analysis of the personnel situation in his company so that the effect of reinstating the veteran in the appropriate job will be clear in his mind, and he will know precisely what may be offered. As a guide to fixing this picture in the manager's mind, the following comments are offered:

1. How to Determine Job To Be Offered Returning Veteran

Study the Problem Now: Generally speaking, if a company's job structure is stable, there will be no problem in determining what job should be offered. If, for example, the employee was an operator at the time of his induction, he should be reinstated as an operator. If the veteran, during his service with the armed forces, has acquired additional skills which might qualify him for some higher rated position in the company, his advancement thereto should be discussed by the staff members concerned, but in the meantime he should be promptly reinstated in employment as previously indicated.

2. How to Determine the Rate of Pay

Pay the Full Rate for the Job: Upon being reinstated in his former position or one of like seniority and status, the veteran should be paid the rate currently attached to such job, not the rate he was being paid at the time of induction. In the event the job classification in which the employee falls has a rate range, it will be necessary to determine at what level in such range this particular employee should be paid. This may be done by adding to his rate at the time of induction any general increases which have been granted. For example, let us assume that John Jones was inducted into the armed forces in November 1942, at which time he was

receiving 60¢ per hour as an operator and at which time the rate range for an operator was 55¢ to 75¢ per hour. On June 1, 1945, John Jones, having received an honorable discharge, applied for reinstatement in his former Subsequent to his induction a new rate range of 65¢ to 85¢ per hour for the position was approved by the War Labor Board, and during the period of his military service the two operators currently on the payroll were granted merit increases of 3¢ each on two occasions. In the first place the general level of pay for the position of operator has been increased 10¢ an E hour; in the second place other operators have received increases aggregating 6¢ an hour. Therefore, the minimum rate for John would be 65¢ per hour. Yet this rate does not seem al- he together fair, as his two fellow opera- w tors are earning 71¢ per hour. It cu would seem, then, that John should be se started at 71¢ per hour, his honorable fu discharge constituting the basis for an tal additional 6¢ per hour.

In the case of a job with a single sit rate, no problem exists, of course.

3. Displacement of Present Employees be

Follow the Line of Seniority: If wh there is a vacancy in the job classification formerly occupied by the returning veteran, his reinstatement entails no complication. The man simply reenters his job at the appropriate rate of pay without any disturbance of other employees or jobs. If there is no vacancy, however, in the job classification to which the employee prop short erly must be assigned, it may be neces pend sary to demote or lay off some other Serv employee. Workers hired to fill vacan abid cies created by the induction of me that into the armed forces are generally or reins a temporary basis. Unfortunately like perator age for r hour. having ge, apformer ction a er hour by the ng the he two oll were each on

Vol. 37

ace the ition of 10¢ an operagregate mini-65¢ per eem aloperaur.

norable s for an a single rse.

nployees

ould be

rity: I assificareturn entails nply re ate rate ance of there is

b classiee prope neces ne other 11 vacanof men



HONORABLE DISCHARGE EMBLEM

Any Returning Employee Who Holds Honorable Discharge Papers Will Be Entitled to Wear This Button-His Fellow Employees Should Be Able to Recognize It Immediately As a Symbol of Honorable Service to the Country

however, the identity of the job in which the replacement has actually occurred may have been obscured by subsequent turnover and where there is a full complement of employees necessitating the release of one person to make room for the returning veteran, the situation should be thoroughly analyzed in writing and discussed by those concerned with personnel. This should be done well in advance of the time when the veteran presents himself for reinstatement. An immediate study should be made of how work is to be reassigned when the occasion demands. The best rule to follow, it is felt, is over-all company seniority, giving due regard to the ability of the serviceman to perform the work.

Veteran Has Super-seniority: It should be emphasized once more that pending clarification of the Selective Service regulations, a company should abide by the present interpretation that the returning veteran is entitled to erally or reinstatement in his old job or one of tunately like seniority and status, even though

an employee of greater service must be displaced (1).

4. Job Requirements

Veteran Must Receive Fair Break: Such matters as night shift assignments, less popular vacation periods and disagreeable duties should not be pushed off on the returning serviceman because he has been away a couple of years. His supervisor and his fellow employees should accord him complete equality in the matter of job requirements. He should have at all times equal treatment with his fellow employees. In thinking about this it would be well to adopt the attitude of mind that the returned serviceman has never been away.

5. Veteran's Legal Rights and Privileges

Be Generally Familiar With Federal Veterans' Benefits: It would be helpful to anyone coming in contact with veterans to familiarize himself with the information contained in the booklet, "The Problem of Re-employing Servicemen: How to Handle It" (2). An interviewer should be especially familiar with the rights and privileges provided for the serviceman, and be in a position to refer him to the local authorities whose duty it is to advise and help veterans. It is not recommended that an individual attempt to advise the veteran himself, but a genuine interest in his problems should be shown and he should be made to feel the individual's desire to help him.

6. Physical Examinations

Follow the Rule of Reason: A returning veteran should take a physical examination if such is required for employment in the company although, generally speaking, physical handicaps

Oct

emj

suc

ing.

it is

fact

The

T

cal

neur

1. F

U

amir

the

cates

abled

sive

train

wher

for a

analy

give

that o

capac

2. Ps

Th

study

low-u

taken

they :

The 1

cases

undul

Anxie

It

which will not preclude the veteran from performing any job for which he is otherwise qualified should not result in a refusal to reinstate him. It should be a company's aim to utilize the services of every veteran who was formerly employed, unless he has suffered disabilities which beyond any doubt in a medical examiner's opinion would prevent him from carrying out the functions of any position which the company has to offer. In such circumstances one should be very sure that by rearranging jobs it would, in fact, be impossible to re-employ the disabled veteran.

Where an obvious physical handicap exists or where a manager feels after his interview with the veteran that there is mental or nervous instability, the reinstatement of the former employee and his assignment to an appropriate job should be immediately discussed with those concerned with personnel problems and a solution sought.*

7. Forms

These Are Necessary: The returning veteran should not be expected or required to complete an application for employment. However, all other forms which must be prepared at the time a new employee is put on the payroll should usually be filled out. There will probably be company forms needed for the record, and of course the withholding exemption certificates for federal income tax purposes should be executed by the employee.

8. Reinstatement of Employee Benefits

The Veteran Will Need This Protection: Any group life insurance coverage, health, accident, unemployment or other benefits should be re-established as of the first day at work. Such coverage should be based on the current rate of pay and on the employee's length of service up to the date of reinstatement, counting all time elapsed while he was in military or naval service.

9. Follow-up

Give the Veteran Interest and Encouragement: This is an important part of the program and should be done methodically, although informally, probably can be done largely through the supervisor. There is no way of anticipating how difficult or easy will be the transition period for the serviceman. It is very likely, however, that in some cases difficulty will be encountered. No civilian can really appreciate the differences between civilian and military life, or the impact that actual combat experience will make on the individual. Therefore, considerable patience and tact may be required in handling some cases.

In any event, the purpose of any program should be to help the veteran make the least painful and speediest possible adjustment to civilian life and family to encourage the feeling of self-respect that comes from making a useful con-perfor tribution to society. Allowances must stant be made for a certain confusion and in and pa decision he may feel at first and every dling t effort made to help him where help intenti seems indicated. It is generally agreed off.

^{*} In the original document, questions of this nature were directed to be referred to the home office of the American Water Works & Electric Company. In the case of a water utility, the management of which is coextensive with the area served, the manager or superintendent would doubtless consult a local physician or psychiatrist. If there is no psychiatrist in the locality, it may be found that there is a psychologist associated with the public school system who might be glad to make his services available.

01.37

old-

leral

ex-

refits

Pro-

COV-

ment

stab-

vork.

1 the

em-

date

time

y or

En-

. It

v of

vice-

that

coun-

eciate

and

ctual

that much responsibility rests upon the employer for the discharged veteran's successful readjustment to civilian living. A follow-up record should be kept on each reinstated employee until it is evident that he has made a satisfactory adjustment.

The Handicapped Veteran

The handicapped veterans fall into two main categories: those with physical disabilities and those with psychoneurotic disturbances.

1. Physical Disabilities

Under the heading, "Physical Examination," are suggestions regarding the reinstatement of veterans in this category. It should be added that disabled veterans are eligible for extenpart sive government rehabilitation and redone training which should be considered when attempting to find a suitable job ough for a handicapped veteran.

It would be well, while making an will analysis of a personnel situation, to give consideration to the kinds of jobs that could be performed by partially incapacitated veterans.

2. Psychoneurotic Disturbances

This type of disability needs careful study and constant but unobtrusive fol-1 the low-up. Also, special care should be le pataken to give these men employment d in they are able to perform successfully. The most familiar symptoms of these procases are (1) the tendency to worry teran unduly and (2) an anti-social attitude. ediest Anxiety may be caused by finances, e and spect family affairs and worry about job con- performance. Kindly counsel and conmust stant interest, plus considerable tact nd in and patience, may be required in hanevery dling these cases; and interest and good help intention must not be allowed to taper greed off.

The man with anti-social tendencies may present the hardest problem of all because of the eventual effect his attitude may have on other employees. It will probably be necessary to make a special effort to enlist the co-operation of his fellow workers in dealing with cases of this kind. Any problems of this nature that seem particularly difficult to cope with should be given special study, perhaps in consultation with a psychologist or physician.

Temporary Employees

Strictly interpreted, the law deals only with permanent employees on military leave, and neither the temporary employee, nor one who replaced a permanent employee and later was himself drafted, has reinstatement rights under the law. Generally speaking, however, a company should take care of the temporary employee who joined the armed forces in the same manner as the permanent employee, insofar as it is able.

Veterans Not Previously Employed by the Company

In every community there will be numbers of returned veterans who, for various reasons, such as age at time of induction, will not have jobs to which to return. In many cases these younger men will want to take advantage of the opportunities they are offered to continue their education, and they should be encouraged to do so. But there will be some who will prefer to work. It is felt that each community should make every effort to help these young men. Therefore, if conditions permit, employment needs above and beyond those to be filled by a company's permanent and temporary returned veterans should be filled from this group. Local vetterans' service organizations will prob-

wor

wen

Si

head

Th

divid

ploye

comp

"obey

the la

vetera

As

lishin

ploye

pany

through

letters

with t

icemen

1

ably be able to provide applicants for such positions. It is good for water works executives to be familiar with these activities in the community and to some extent to identify themselves therewith.

Summary of Veterans' Reinstatement Program

1. Be familiar with provisions of the Selective Service Act re re-employment of returned veterans.

2. Prepare a complete company and military service record for each permanent and temporary employee on military leave.

3. Make an analysis of probable postwar personnel needs.

4. Discuss plans and procedure with supervisory staff.

5. Work out a definite procedure for reinstatement in advance. Have necessary personnel forms ready.

6. Plan a definite follow-up procedure in which supervisors are to participate.

7. Be familiar with local veterans' assistance agencies.

8. If any problem is presented by the physical or mental condition of the veteran, the advice and help of a physician or psychologist should be sought -though this depends on the individual problem. Medical or psychiatric advice should probably not be sought in the presence of the veteran.

Suggestions From a Veteran

Considerable help may be found in the following ideas, taken from a statement made by a returned veteran of maturity and judgment:

1. Tell the veteran that you are glad that he is back.

2. Help him to feel that his services are really needed.

3. Make it a point to show him some rep attention such as to ask his opinion on tua something (always a compliment) if there is any justification for doing so. dig.

4. Tell him that you appreciate the in s difficulty of the return to civilian life risk and invite him to discuss his problems, fam Remember that he will miss the ac- the tivity and excitement, the unique comradeship of others in uniform, the outof-door life (in many instances). Also the he will have more responsibilities and low obligations in civilian life. There will not be so many to take care of the details of living, or at least to do the thinking and planning for him. In its adju way, life in the armed services is relatively carefree or at least restricted to a few specific and well-defined duties It is little wonder that sometimes the veteran is restless and nostalgic.

5. Don't ask him too many questions and respect his wishes if he dosen't want to talk. There are a num ber of reasons why servicemen don' like to describe their personal expen ences:

(a) Modesty and, equally important the fear of being thought a braggar and a bore;

(b) Disappointment in the part h has had to play; that is, embarrass ment over the fact that his record not more distinguished or glamorous

6. If he has been wounded it is ever hind more important not to ask person

7. Don't sympathize with a wounds leave man or make him feel that you con wrote sider him an object of pity. signati

8. Don't offer to help a wounderplans, man unless he invites it in some was acquire I heard one man, who had lost his leg re-emp upon being asked if he'd like to had The his wheel chair pushed up an inclin to fund many (s related to

duties

ies the

ques

if h

a num

don't

experi

ortant

some reply: "Hell, no, I'm no cripple." Acton on thally his feelings were hurt.

nt) if 9. Don't complain that all of the riggrettes, meat and butter go to those in service. After all some of them are risking their lives and supporting families on pay that often is lower than the pay in industries engaged in war com-work.

e out. Above all treat the veteran as the person he actually is; the same fellow human being that he was before he will went away on a leave of absence.

he delo the Soldier to Civilian: Problems in Re-In its adjustment, written by a psychiatrist who has had military experience, offers helpful advice to personnel managers and others dealing with returning servicemen (3).

References

- Selective Service Bulletin 190A. Government Printing Office, Washington, D.C. (10¢ per copy.)
- The Problem of Re-employing Servicemen: How To Handle It—An Explanation of the Selective Service Act and the G.I. Bill of Rights. Prentice-Hall, Inc., New York (1945). (Pamphlet, 32 pp. \$1.00 per single copy, 30¢ per copy in lots of 100.)
- PRATT, GEORGE K. Soldier to Civilian: Problems in Readjustment. Whittlesey House, New York (1944).

ADDENDUM

Since the above story was set in type, information has reached Association headquarters concerning the policies followed by the Johns-Manville Corp.

The first principle of the plan is individual treatment for each former employee returning from service. The company stresses that it attempts to "obey the spirit as well as the letter of the laws" devised for the protection of veterans.

raggar As an introductory step to re-establishing relationships with former emoart h ployees who were in service, the comparrass pany maintained contact with them cord through a bi-monthly house organ, norous letters from the co-workers left beis ever hind and gift packages at Christmas, erson with the intention of making the servicemen feel that they were merely "on ounde leave of absence." The company also ou con wrote to each man, over its president's signature, asking about his postwar ounderplans, what new skills he might have ne was acquired and his intentions regarding his leg re-employment at the company.

to have The company has trained 40 men incline to function as "veterans' advisers" and many of its larger offices have advisory

committees to work with the advisers. In addition, its key executives are kept abreast of all intramural veterans' affairs. The company has prepared a loose-leaf manual for the guidance of all those concerned in the program, setting forth the company policy and including copies of government and company forms of concern to veterans, instructions on interviewing veterans and outlines of the laws protecting veterans and of the government and company benefits to which returning veterans are entitled.

The company has been making job inventories so as to know how the veterans could be fitted in when they returned, and what positions are or could be opened to disabled men.

Through the medium of the house organ, the veteran has been kept informed regarding the procedure to be followed for reinstatement. He has been kept up-to-date on personnel and he knows to whom to go for an interview, whether to his former boss or the "veteran adviser," and after a hearty welcome from one of them he moves on to the personnel manager for the routine filling of record forms, a medical examination and reassignment to his former job or to another one of equal or greater responsibility.

The company tries to do what it can for the returning serviceman who had been only a temporary employee, often a replacement of a draftee. If no job can be found for him, an effort is made, through local community services, to arrange for his employment elsewhere.

The company attempts to arrange for or extend the leave-of-absence for a serviceman who wishes to avail himself of the educational opportunities provided by the "G.I. Bill of Rights."

A follow-up system is designed to ascertain that the veteran is resituated suitably and that no newly-acquired skill is overlooked.



plan pum turb gine rocal trifu

cient

are that

Setti

it ma

fective know little and in below ficulty reason domain tion is sensite.

The effect that r high the puin dis (1945)

ter o

Centrifugal Pump Peculiarities

By Robert W. Angus

Cons. Engr. and Prof. Emeritus of Mech. Eng., Univ. of Toronto, Toronto, Ont. Presented on Mar. 20, 1945, at the Canadian Section Meeting, Toronto, Ont.

PRACTICALLY all pumping units now being installed in water works plants are composed of centrifugal pumps driven by electric motors, steam turbines or internal combustion engines, and few plants today use reciprocating pumps. Experience with centrifugal pumps has now been sufficiently extensive for operators to know many of their peculiarities; yet there are features connected with their use that are worthy of review.

Setting of Pump

Vol. 37

made, es, to where, range

ce for l him-

inities

ghts.'

tuated

The setting of the pump is perhaps one of the most important matters, as it may easily account for any later defective operation. It is, of course, well known that the pump should be set as little above the well level as possible, and it is usually preferable to have it below this level, except for the difficulty of unwatering it, if for no better reason than ease of priming and freedom from the foot valves on the suc-That the pump is unduly sensitive to suction conditions is a matter of general experience, and long and crooked suction piping is to be avoided.

The author has made tests on the effect of foot valves, which showed that resistance in these might cause a high vacuum at the suction flange of the pump and a corresponding decrease in discharge [Jour. A.W.W.A., 37:70 (1945)]. High-suction vacuum nat-

urally induces air leakage into the pump through the glands, and also releases whatever air there is in the water being pumped. In order to investigate the effect of air leakage, a number of experiments were run on a 4-in. pump, in which various volumes of air were admitted into the suction pipe after carefully sealing the glands so that leakage was practically stopped there.

In this pump the percentage decrease in discharge at a given head was roughly proportional to the percentage, by volume, of air admitted, so long as the latter remained below about 1.5 per cent (see Fig. 1), but thereafter the water discharge fell off very rapidly until there was a decreased discharge of over 40 per cent when 4 per cent of air, by volume, was admitted. This merely confirms the well-known fact that at low suction lifts, and consequently low air inlet leakage, the exact elevation of the pump is not so important. There is a critical elevation for each pump and condition, however, and if this is exceeded the loss of water increases at a rapid rate. Clearly the height of the pump above the well level should be kept substantially below this critical elevation.

Specific Speed

Fortunately the importance of this matter is now recognized by the pump builders, and they have found that for each head, discharge and speed there

00

Po

trif

lem

on

this

thre

is a maximum height above the well at which each pump should be set. These three quantities are combined in a formula for "specific speed" which is defined by:

Specific speed = $N \times \sqrt{G/H^{0.75}}$

where N is the revolutions per minute, G is the discharge in U.S. gallons per minute and H is the head in feet.

Pump builders have co-operated in connecting the specific speed and head with the maximum allowable suction lift, basing their conclusions on laboratory tests and on experience with pumps which they have installed. Through the Hydraulic Institute they have given these maximum elevations in the form of diagrams, separate ones being used for single-entry pumps, for double-suction single-stage pumps, etc.

As an illustration, there are four double-suction single-stage raw water pumps at the Victoria Park pumping station, Toronto, Ont., rated at 24, 30, 48 and 60 mgd., respectively, all of them for 9-ft. suction lift and for a total head of 82 ft. The two larger pumps operate at 750 rpm., and if this speed had been adopted for all four pumps, their specific speeds and maximum suction lifts, including velocity head and friction in the suction pipe, would have been, according to the chart of the Hydraulic Institute:

 Size of pump, mgd. (U.S.)
 24
 30
 48
 60

 Specific speed at 750 rpm...
 3545
 3970
 5010
 5610

 Maximum allowable suction lift, ft.
 18
 15
 5
 —

 Necessary suction pressure, ft.
 2
 340
 3749

 Maximum allowable suction lift, ft.
 20
 17

Since the velocity heads in the two larger pumps are 2.3 and 2.1 ft., respectively, and since friction must be allowed for, it is clear that, while there is a margin on the two smaller pumps when run at 750 rpm., the two largest




Fig. 1. Decrease in Discharge of Centrifugal Pump Due to Admission of Air Into Suction Pipe

pumps could not be run at this speed and had to be changed to 500 rpm, which is the next available speed.

Setting pumps too high not only causes them to lose capacity, but also means noisy operation and cavitation, which is frequently destructive As the capacity of a pump at fixed speed is gradually increased by lowering the discharge pressure, a point is finally reached where the characteristic curve is nearly vertical, which point naturally corresponds to the limiting output of the pump. Cavitation and noise are present at such discharge and in its vicinity, and the higher the suction lift the lower this limiting output It is to avoid too close an approach to this point that the charts referred to above have been made. Noise in a pump operating near this limiting point may often be stopped by the admission of a very small volume of air to the suction pipe.

direction rapidan case to ti

mon

head tests a 55 line cord dicat switch the i

than wave 115-ishort under case and the proper both enough was f

by the at there system mum after took

Sho gerou 01.37

Cen-

r Into

speed

rpm.,

only

but

avita-

ctive.

fixed

ower-

int is

eristic

point

niting

1 and

e and

e suc-

utput

roach

erred

e in a

point

ission

to the

Power Failures

Power failures on motor-driven centrifugual pumps present some problems. A check valve is usually placed on the line close to the pump, and if this acts slowly there is backward flow through the pump which reverses its direction of rotation unless specially prevented. If the check valve does act rapidly, however, water-hammer pressures are often excessive, resulting in damage to the plant. A number of cases of the latter have recently come to the author's attention.

Water hammer, contrary to a common belief, is often dangerous in lowhead pumping. The author made some tests on a 12-in. pump working against a 55-ft. static head, with a discharge line only about 350 ft. long, and recorded the pressures with a Crosby indicator with a 30-lb. spring. When the switch was opened the pressure drove the indicator pencil off the top of the drum, indicating a pressure of more than 60 psi., and the first pressure wave measurable showed 50 psi. or a 115-ft. rise. As stated, this was a short line and the pipe velocity was under 4 fps. However, in another case where the static head was 40 ft. and the line was over 2,000 ft. long, the pressure rose to 83 ft. with normal pipe velocity of slightly over 7 fps. In both cases the pressure rise was high enough to cause some anxiety, which was further aggravated in the first case by the noise and shock plainly observed at the pump, while in the second case there was no apparent shock on the system. In the first case, the maximum pressure rise occurred 2.6 seconds after cutting off the power, whereas it took 13.0 seconds in the latter case.

Short lines are sometimes more dangerous than long ones, because in the

latter the water takes an appreciable time to slow down before coming backward, thereby giving the check valve time to close gradually and prevent any real reverse flow of the column. In the pipes the water column reverses in much less time, as the above measurements show, and actually before the check valve has had time to close. The water then gains a high backward velocity, suddenly closing the check valve and producing high pressures. The maximum pressure rise, in feet, reaches about one hundred times the velocity of the water in the pipe at the time the valve suddenly closes.

Sometimes an effort is made to decrease the danger by using an air chamber, but this is far from the best method and does little good unless the chamber is placed on the line near the pump and has a large short connection with the pipe. Air chambers connected to the line with a fairly long branch pipe are of little value and, of course, any virtue the device has will be lost unless there is a good volume of air in the chamber under normal conditions. A well-designed check valve, with a proper controlling mechanism which permits the greater part of the closure to be rapid and the latter part gradual, offers a good solution, and a number of such valves are now on the market. It is a fact that, unless the pump is equipped with a heavy fly-wheel, as is sometimes the case, the pump will often run backward before the check valve closes, but, in general, the reverse speed is not over 20 per cent higher than normal running speed and is not dangerous from that standpoint.

In many installations reverse rotation of the unit causes little difficulty, but where sleeves are screwed on the shaft and pass through the packing gland, the builder usually makes the thread so that during pumping the tendency is to tighten the sleeve against the impeller. If the glands are tight, then when the pump runs backward the sleeves may unscrew, and cases are not unknown where the pump has been damaged by breaking off the bearing bracket. With the sleeve unscrewed the impeller is not properly restrained from moving along the shaft and this further increases the danger of damage.

Pumping Plants

There are some unusual installations. one of which may be mentioned as an illustration. A very large-size pump with a vertical shaft was set up with 40 ft. of vertical discharge pipe, followed by a long horizontal line. The pump was nearly 20 ft. below the water in the well so that no priming was required, but there were nearly 800 ft. of suction pipe in which the velocity was 5.9 fps. at steady operation. It was inconvenient to place the discharge valve close to the pump, and it was actually installed just beyond where the horizontal and vertical pipes joined. There was no valve of any kind on the suction side. The installation is shown diagrammatically in Fig. 2, A being nearly 20 ft.

Following common practice, the motor switch was thrown in with the discharge valve closed, and just as the valve started to open when the pump was up to speed, a pressure shock cracked the pump casing. This might have been foreseen, because, when the pump was shut down with discharge valve closed, water in the vertical discharge pipe quickly fell to the well level, leaving a space filled with air in the discharge line between the well level and the valve. On starting the pump the air was compressed to about discharge pressure, and as the valve

began to open the air rushed out of line, allowing the water to reach full velocity in the vertical pipe. As the front of this column reached the partly open valve the velocity was largely ex-




Fig. 2. Unusual Pump Arrangement That Resulted in Heavy Water Hammer Pressure Until Vacuum Pump Was Installed to Exhaust Air From Discharge Pipe and Fill It With Water Before Starting Up

tinguished and a heavy water hammer pressure resulted. Since it would have been very expensive to lower the valve, the only remedy was to put in a vacuum pump and exhaust the air, in order to fill the line with water before starting up.

The long suction pipe greatly complicated the problem, for the water

of ,

ca cle de

ci

m

is Pu

act

pa

Fun Pun Stat

side put their are two stati ating

J. the chara curve of A each

and thead tical respo

ing t

respo

ut of would be drawn from the pump end of it before the column could be suffifull ciently accelerated to supply the des the mand, and water hammer pressures artly y exwould be set up in the pump from this cause. A well should always be made close to the pump to supply the water demanded while that in the intake line

Pumps Working Together

Where several pumps are to work in narallel on the same line, their characteristics should be given careful con-

is being brought up to running velocity.




Fig. 3. Characteristic Curves of Two Pumps Operating in Parallel in the Same Station

sideration, otherwise their actual output may fall far short of the sum of their individual deliveries. In Fig. 3 are shown the characteristic curves of two actual pumps, A and B, in the same station, their individual normal operating points being indicated by G and J. If these two pumps are thrown on the line at one time their combined characteristic is shown by the plain curve found by adding the discharges of A and B at the same pressure in each case. The static head, corresponding to the tank level, is shown at D and the curve C indicates the dynamic head to be pumped against, the vertical distance between D and C corresponding to the resistance loss for the corresponding discharge.

It is to be noted that, while the sum of the separate discharges at rated heads is 180 per cent of the discharge of the larger pump, yet when both are put on the line at the same time the combined discharge at F is only 133 per cent of that of the larger pump, because of the increased pressure. Where the individual characteristic curves are flat, this decrease is greater than with steep curves, because a slight increase in pressure corresponds to a large decrease in discharge, but, on the other hand, a pump with steep characteristic at the normal output point has a rapid decrease in pressure for discharge above normal, so that other circumstances must be taken into account.

Propeller Pumps

Propeller-type pumps are being introduced to a fairly large extent to cover the field where the head is low and the discharge is large. Centrifugal pumps are used in this service, but must be run at slow speed and involve the use of a speed reducer or an expensive and bulky motor, whereas the propeller-type pump is relatively small and may be run at the speed of the ordinary motor. Its field of service is for drainage and sewage work and for pumping water up to water works filters, but the same type of pump is also used for deep wells because its small diameter enables it to be fitted inside ordinary pipe casing.

As so far developed, these pumps have the undesirable characteristic forms of curves, where the head and power at zero discharge and at full speed are higher than, and sometimes twice as high as, the corresponding quantities at rated discharge, and the curves generally have the reversed form. Usually the pressure is not high

01.37

t That ressure to Ex-Fill It

mmer have valve. acuum der to arting

comwater

fe

th

tin

mı

caj

mi

of

um

per

the

eac

out

cou

trib

put

the

cor

suci

air

stat

thos

each

well

W

are

puni

lasti

puni

ures

tions

by s

1

enough to cause any trouble, but the high power means a correspondingly large torque on the motor, which the latter may not be able to produce. Therefore either special starting devices are necessary or the pump must not be brought up to speed with a closed discharge valve. With a check valve on the discharge and an open gate valve there, the head developed cannot exceed the back pressure from the line. and this is one method of starting used. Also a bypass is sometimes arranged around the pump, having a valve which may be opened so as to allow some water to flow through the pump, thus avoiding the zero discharge condition.

Deep Well Pumps

Deep well pumps must be as small in diameter as possible so that they will fit into the well casing, and for that reason they approach the axial-flow type with relatively small head per stage, although the high motor speeds somewhat compensate for this. However, for the higher heads many stages are used, and guide vanes are placed between each pair of impellers. Both open and closed impellers are used, but the latter are the more common. driving motor is often placed at ground level, and the pump is usually submerged in the well water to avoid priming, but since these wells are sometimes 200 ft. deep, the driving shaft is long and has to be guided at various points at which rubber-lined guide bearings are often used with water lubrication. Some builders, such as Byron Jackson, couple the motor to the shaft as in ordinary installations, and the motor is therefore submerged in the well water and often below the pump.

Power failures on these pumps, where the vertical pipe is long, result

in reverse flow through the pump and cause the pump to run in the reverse direction, but most pumps of this type are designed to withstand this without damage. However, the surges in the pipe during reverse flow of the water affect the pressures in the pump to such a degree that open impellers may be forced to pound down against the casing and wear somewhat rapidly. Some builders arrange a ratchet or a brake on the pump shaft to prevent the latter from turning backwards.

Where both motor and pump are submerged and completely enclosed, it is difficult to tell whether the electrical connections are such that the pump is running backwards, and in three-phase circuits it is well known that the connection for forward rotation can only be found by trial. If it is impossible to tell by visual inspection whether the pump runs backwards or not, about all that can be done is to read the discharge gage pressure; if this pressure at no discharge is very much below the normal working head on the pump. the motor is, in all probability, running backwards.

Summary

Noise accompanied by cavitation damage in pumps is frequent if the pumps are set high above the well level. The same results are noticed when the discharge is low due to either reduced speed or increased head. Foot valves and strainers on the suction inlets may also induce these troubles and should be avoided where possible.

Occasionally cavitation has seriously damaged impellers in less than two years but it is often quite possible to build up the damaged places and completely restore delivery and efficiency. Frequent inspection is necessary. In one case, an impeller was covered with

ol. 37

and

rerse

type

hout

the

p to

may

the

idly.

or a

are

d, it

rical

np is

hase

cononly

le to

the

it all

dis-

ssure

elow

ump,

run-

ation

f the

well

ticed

either

Foot

n in-

s and

ously

two

le to

com-

ency. In with a thick coating of slimy material which much decreased the capacity. This pump was used partly for refilling the coagulating basins and was designed for about a 26-ft. head. When the water was low in the well its capacity fell off.

A number of operators have found that high suction lift decreases output.

Occasionally, noise in the motor gives the impression that the pump is at fault. Noise in the pump may frequently be greatly reduced by admitting air to the suction side, but this must be carefully controlled, as the capacity falls off rapidly as the admitted air increases. In some tests of one pump 4 per cent of air by volume reduced the capacity nearly 40 per cent.

Putting several pumps in parallel on the same line decreases the capacity of each in a way that varies with the pump characteristics. There is, of course, increased friction in the distribution system when more water is put through it, and, as this increases the head on the pump, there will be a corresponding decrease in discharge.

There is an objection to a common suction header for several pumps, as air may leak through the glands on the stationary pumps and interfere with those running. The suction pipe of each pump should run direct to the well.

Water hammer and pressure surges are common on lines having centrifugal pumps. Frequently, a pressure surge, lasting a short time, occurs when a pump is put into service. Power failures cause extensive pressure oscillations which have been greatly reduced by special types of check valves with

a controlled time of closure. Air chambers are not as satisfactory.

The shape of the profile of the discharge main greatly affects water hammer in the line after power failure. In the 48-in. line in Toronto, there is a point where the pressure drops much below atmospheric when power fails, and observations agree with the theory that the water column separates at this point. The use of a specially controlled check valve with 4-in. bypass has prevented a dangerous pressure rise when the columns re-unite; the purpose of the bypass is to fill enough of the space with water before the velocity of the returning column from the reservoir becomes high enough to cause damage when it re-unites with the part of the column coming from the pump. The actual maximum pressure rise is only about 35 per cent and is reached in about 50 seconds where the pipe velocity is low. The pump is about 4,300 ft. from the breaking point of the column and nearly 8 mi. from the reservoir.

Reversal of the pump after power failure has often been observed, but with no harmful results to the motors. A case has been reported, however, of an engine driving a centrifugal pump being damaged by running backward.

Aside from ordinary wear, the mechanical difficulties with pumps are not serious. Some pumps have excessive end thrust, and where this is taken up by ball bearings, the latter run hot. In one case, over-lubrication increased the heating. The bearings were easily cooled with a small stream of water. Hydraulic balancing of end thrust is satisfactory where the pump is running under normal conditions.

Control of Surge in Pipelines

By Charles F. Lapworth

Partner, Herbert Lapworth Partners, Cons. Engrs., London, England
A contribution to the Journal

THE use of electrically-driven pumping equipment for water works purposes has shown that pressures generated in stopping and starting can far exceed the normal working pressures. Similar conditions occur when there is a failure of electric current leading to an involuntary shut-down of the pumping plant. The high pressures which are generated increase the likelihood of broken mains and affect the working of subsidiary apparatus such as chlorination equipment.

The conditions which give rise to these high pressures are sudden changes in the velocity of water flowing in the pipeline, which may occur on the following occasions:

- (1) The stopping of the pump.
- (2) The failure of electric power.
- (3) The starting of the pump.
- (4) The sudden opening or closing of a sluice valve in the pipeline.
- (5) The slamming of a check valve fitted to the pump delivery immediately after the pump is stopped.
- (6) The formation of a partial vacuum at some high point on the pipeline following a shut-down of the plant. High pressures result when the ruptured water column re-unites.

Tests have been carried out by the author at Stevenage and Macclesfield, England, to determine the pressures which may be generated in the delivery main leading from the pumping plants where no special surge control is provided. When pumping conditions had become stable, the current was cut off and the pressure fluctuations were measured by means of a pressure recorder. The pressure recorder consists of a synchronous electric motor driving a circular chart which makes one revolution every four minutes. The high speed of rotation enables quick variations of pressure to be followed accurately. Figure 1 shows the nature of the pressure fluctuations.

It is interesting to note that these fluctuations are in accordance with the elastic water column theory first put forward by Joukovsky. The pressure variations consist of alternate waves of high and low pressure which travel from one end of the pipeline to the other and then back again. The time taken to make the trip, which can be measured from the chart, gives the velocity of the pressure wave. In a large lake or reservoir, this is the velocity of sound in water, about 4,700 Where, however, the water is contained in a pipe, the speed of the pressure wave is reduced by the elasticity of the pipe walls. In the present instance the velocity of the wave is 4,000 fps.

wa

the

gra

allo

fluc

abo

the

is 1

wat

the

sipa

ing

afte

to 2

close

I

I

The magnitude of the pressure rise (h) is closely in accordance with the Joukovsky law:

$$h = \frac{av}{g}$$

had t off were e re-

conotor akes

utes.
ables
fol-

hese

put ssure es of

ravel

time

n be

the

In a

the

4,700

er is

f the

elas-

pres-

wave

rise

h the




Fig. 1. Pressure Fluctuations With Uncontrolled Surge

where a = velocity of the pressure wave, v = original velocity of water in the pipe and g = acceleration due to gravity as modified by Schnyder to allow for pipe friction.

It will be noted that the pressure fluctuations gradually die away, and about three minutes after shut-down the pressure has become stable. This is the result of friction between the water and the pipe walls and within the body of the water itself which dissipates the original energy of the moving water column.

It will also be seen that immediately after the pump stops the pressure falls to zero. Inspection of an air valve close to the pump showed that the air

was sucked into the main at this time, indicating that there was a vacuum pressure and that the water column had ruptured at this point.

The plant was fitted with a motordriven sluice valve to control the surge, which, for the test mentioned above, had been put out of action.

The motor-driven sluice valve consists of a small electric motor operating a small pump which is used to generate oil pressure. This oil pressure is used to open or close the valve. The valve was made to give a closing time, of three minutes. When stopping the plant, the closure of an electric switch brings into operation the motor-driven valve, thus causing the valve to close.

tl

SI

of

115

m

un be

me

tha

to

pui

ap

hig

pri

wh

dri

the

cau

dov

(

suit

slui

surg




Fig. 2. Pressure Fluctuations With Surge Control

When the valve reaches, or almost reaches, its seating, an electrical contact cuts out the main motor driving the pump. By this means the water column is retarded slowly.

Tests were carried out with this valve in operation.

When the diagram, Fig. 2, which shows the nature of the pressure fluctuations, is compared with Fig. 1, it will be seen that the fluctuations are less violent, that a vacuum pressure is prevented and that the maximum rise in pressure is reduced from 200 to 40 ft.

The normal type of check valve as fitted to the delivery side of a centrifugal pump works satisfactorily with the

sluggish type of water column consisting of a long main under relatively low head, common in water works practice. Where, however, the column is more mobile, shock pressures may occur following the rapid reversal of the water column after the pump stops. The ideal check valve would reach its seating at the exact moment that the water column is at rest, that is, before reversal occurs. With the more mobile columns, however, the water column reverses before the valve is closed, thus causing the valve to shut. Tests were made on this plant, using a check valve with the normal type of flap. The tests showed that this could cause very high shock pressures with audible water

01.37

nsisty low

prac-

nn 15

V 00-

of the

stops.

ch its

at the

efore

nobile

olumn

. thus

were

valve

e tests

/ high

water

hammer. The oscillations were so violent that the pen was thrown off the chart of the pressure recorder, but it is certain that the pressures exceeded three times the static head, or over 500 ft. The reflection period of the pipeline is six seconds. The flap of the check valve closed about ¹⁰/₁₁ seconds after the pump was shut down, that is, during the period of the first pressure rise.

When the valve in the bypass around the check valve was opened, the pressure rise was reduced to that shown in Fig. 1, which is closely in accordance with the Joukovsky theory, indicating that the slamming of the flap was responsible for the excessive pressure.

Where these conditions occur, the remedy lies in the use of a check valve of a more scientific design, or in the use of one of the surge control devices to be mentioned later.

The problem of surge control is to vary the velocity of the water column more slowly or, alternatively, to dissipate the energy of the moving column of water harmlessly. Control may be achieved by any of the following methods:

(1) Fly-Wheel. It is noticeable that surge pressures are not developed to anything like the same degree with pumping plant using an oil engine as a prime mover. This is because of the high inertia of the moving parts of the prime mover. In some instances a flywheel has been added to electrically-driven equipment in order to add to the inertia of the moving parts and thus cause the pump, on stopping, to slow down more gradually.

(2) Motor-Driven Sluice Valve. In suitable circumstances the motor-driven sluice valve can be effective in reducing surge pressures to reasonable limits.




Fig. 3. Use of Surge Tower, Surge Tank and Surge Buffer

(3) Delayed Action Stop/Start. This device consists of a series of electrical resistances placed in the starter circuit of the motor driving the pump. A small electrically-driven motor is used to drive a shaft carrying a number of cam type contacts. These contacts are connected to the electrical resistances, the effect being that the speed of the pump motor is increased or decreased more slowly.

In the case of water works equipment at Eddisbury, England, which consists of a vertical spindle centrifugal borehole pump, excessive surge pressures were generated on starting the pump. A delayed action device was fitted to give a 30-second interval between full speed and complete stopping. No further trouble was experienced with surge.

(4) Pressure Relief Valve. The relief valve is normally fitted to a tee branch on the pipeline. The device consists of a valve held against its seat by a spring or weighted arm. A rise

iI

n

la

h

in

in

ta

ri: th

fle

va

su

su

is

lin

Wa




Fig. 4. Test on Surge Buffer

of pressure in excess of the pre-determined amount causes the valve to open and the water to be passed to waste. Where the buildup of pressure is very quick, however, it may sometimes happen that the valve does not operate sufficiently quickly to permit the relief of pressure. The useful application of the pressure relief valve is, therefore, limited to cases where the pressure rise is moderately slow.

(5) Surge Suppressor. The surge suppressor is a relief valve in which the port of the valve is arranged to open before the rise of pressure occurs. This is achieved by making use of a period of subnormal pressure to open the valve by hydraulic means. The surge suppressor, therefore, is suitable only where subnormal pressures occur before the pressure rise, such as for the protection of the delivery main against sudden shut-down. Surge suppressors are in common use in the U.S.; some of these have been used for very high heads up to 3,000 ft. At the Hoover Dam for the Boulder City water supply the fitting of surge suppressors reduced the pressure rise from 400 to 120 ft.

(6) Air Vessel. An air vessel consists of a steel cylinder connected to a branch on the pipeline. The vessel is partially filled with air, the small loss of air by solution being made good by a small electrically-driven air compressor. The effect of the air vessel is to damp the surge action by the elasticity of the air in the vessel.

At high points in the pipeline it sometimes happens that the effect of starting or stopping the pump is to cause cavitation or the formation of a partial vacuum in the pipe. Where this is likely to occur, the following control devices may be of use.

(7) Surge Tower (Fig. 3). It is common in hydro-electric installations to provide an open surge tower on the inlet pipe to the turbines. The tower acts as a reservoir to provide the extra water required when the turbine gates are opened. It also provides an outlet for the water no longer required by the turbines when the gates are closed. As far as is known, the surge tower

ol. 37

200

160

DISPLACED-0

40 WATER (has not been applied to water works installations.* There would seem to be no reason, however, why this should not be done in suitable cases, particularly where the pipeline lies near the hydraulic gradient.

(8) Surge Tank (Fig. 3). This device consists of an open tank connected to the pipeline by a branch pipe carrying a check valve. When the pressure in the main falls below the level of the water in the tank, water flows from the tank into the main. On the subsequent rise of pressure, the check valve closes, thus preventing the tank from being flooded.

A pipe of small diameter connected to the pipeline and controlled by a ball valve is used for re-filling the tank.

(9) Surge Buffer (Fig. 3). The surge buffer is a development of the surge tower, but, being a closed vessel, is not confined to places where the pipeline lies near the hydraulic gradient.

A surge buffer has been fitted to a water works pumping plant at Crewe, England, for the protection of a delivery main 15 mi. in length operating under a low static head of 25 ft. The buffer consists of a vertical steel cylinder inserted in the pipeline close to the pump. At the top of the cylinder is a special air valve. When the pumps are running, the surge buffer is filled with water, any air being expelled automatically through the air valve.

When the plant is shut down, water in the buffer flows into the main to take the place of the water which has gone forward away from the pump. When this happens, the air valve at the top of the buffer opens, thus admitting air into the cylinder. On the return surge of the water column the large aperture of the air valve closes, thus trapping the air in the cylinder to form a cushion or buffer. Air is gradually blown off through a small aperture in the air valve until all the air has been replaced by water. operation is thus entirely automatic. As shown by tests carried out by the author (Fig. 4) the buffer has been completely successful in preventing cavitation in the pipeline and excessive surge pressures.

from

to a sel is l loss od by com-

elasne it ect of is to

of a re this ontrol

ations on the tower extra gates

ed by losed. tower

^{*}This "surge tower" principle was put into practical use at the Springwells filter plant in Detroit in 1931.

Customers' Complaints As a Guide to Better Service

By M. Warren Cowles

Health Officer, Hackensack Water Co., New Milford, N.J.

Presented on Nov. 3, 1944, at the New Jersey Section Meeting, Atlantic City, N.J.

It is assumed that the water leaving a plant is of safe quality, reasonably free from taste, odor and sediment; that there are adequate records of the distribution system, showing size of mains, location of valves and services and materials used; and that records of customer complaints are kept. It is further assumed that such complaints are not taken for granted but are approached with an open mind. It is both the avoidance of and the solution to the problems which cause such complaints that this paper will undertake to discuss.

Corrosion and Red Water Complaints

Corrosion is always active to a greater or lesser degree in a distribution system; yet, under normal conditions, there may be little visible evidence of it except with the appearance of red water troubles and, perhaps, excessive sediment in certain areas. Information concerning such appearances is likely to be derived only from customer complaints. Corrosion may occur in the distribution system or in the service lines, if the pipe is poorly protected or if two or more metallic substances have been employed, causing galvanic action. Or the water may be, from the time it leaves the plant, of such a corrosive nature that rectification lies in treatment of the water itself.

Combating Corrosion by Protecting the Pipe Surface

tl

d

ti

cl

SU

in

pl

to

Ci

SV

sta

pe

lit

lai

Wa

rat

15

life

ble

ope

pea

wa

ing

cor

the

sol

enc

ties

affe

a t der

whi

Son

Much research has been carried on to find adequate coatings for cast-iron pipe. Old pipe may be relined in place. New cast-iron pipe often needs better protection than afforded by the present tar coating put on at the foundry. The rough surface of pit-cast cast-iron pipe makes protection with a thin coating material difficult. Cement lining protected by a tar coating seems to be the best method available at present for cast-iron pipe of 12 in. or less.

Regardless of the practicability of any particular coating, the problem arises of the best point of application. Coatings may be applied at the foundry, at the water works storage yard or on the site of installation. Cost and the possibility of damage in transit or in storage are the factors to be considered. Cement lining and tar coating of pipe 12 in. or less seem to be most practicably performed at the foundry. The over-all cost of such pipe is somewhat greater but the advantages more than justify the added expense.

Combating Corrosion by Treating Water at the Source

Treatment of supplies at the source to decrease the rate of corrosion in the distribution system is feasible. Frequently, however, particularly in New Jersey waters, protection by this N.J.

tecting

ied on

st-iron

place.

better

resent

. The n pipe

oating

g probe the

nt for

ity of

oblem

cation.

undry.

or on

nd the

or in

dered.

of pipe

prac-

. The

newhat

e than

eating

source

in the

1 New

this

Fre-

method can be obtained only by raising the pH of the water to so high a value that too much mineral matter is introduced. In some well supplies, this treatment might involve extensive rearrangement of pumping station facilities.

Progress has been made in the development of more effective treatment materials than are now available. The chemical industry is working on such substances as the phosphates, silicates in combination and sodium tetra-phospho-glucosate. These and other materials should be inexpensive and simple to apply.

Combating Corrosion by Correcting Electrolytic Conditions

Electrolytic corrosion may arise from the use of a variety of metals in one system. Many water works have installed ferrous metals, copper and copper alloys (brasses and bronzes) with little attention to the fact that dissimilar metals connected and immersed in water will cause corrosion at a rapid rate by galvanic action.

Such use of heterogenous materials is uneconomical because it shortens the life span of pipe, but the principal trouble encountered in the water works operator's immediate sphere is the appearance of sediment and discolored water on customers' premises, producing the usual complaints in the water company office.

Water is a universal solvent. Even the so-called "pure" metals are dissolved in varying degrees. The presence of very small amounts of impurities in nearly pure metals may greatly affect the durability of the metals. For a time, a good deal of trouble was derived from washing-machine parts which were die-cast from zinc alloys. Some copper pipe will develop a tenacious corrosion-resistant scale and other pipe in the same line may have a soft, easily-displaced scale which will expose the metal to corrosion and cause a greenish or bluish sediment in the water.

Inside piping presents much the same picture as the distribution system, and usually service pipes, in older buildings and even in new construction, offer an even greater assortment of materials. The water drawn from a customer's tap is affected by piping on his premises as well as in the street. The fact that the physical quality of water may vary from house to house along one street suggests that greater uniformity in metals used in water pipe systems is desirable and necessary, although all the factors in this problem are not yet known, and it is not a simple matter to achieve such uniformity.

Parts of interior piping are subjected to wider ranges of temperature than are underground pipes. Insertion of brass or copper pipe in a galvanizediron piping system of older buildings will usually greatly increase the rate of corrosion of the iron pipe, making complete replacement necessary sooner than if a piece of iron pipe had been in-Similar acceleration of corrosion may occur, though not invariably, when a galvanized-iron hot water tank is connected to lengths of brass or copper pipe. Poor workmanship in making threaded joints on brass pipes also may contribute to corrosive action.

The use of insulating couplings between dissimilar metals may help to prevent damage by galvanic action. There is also a need for increased cooperation between plumbers and plumbing inspectors and the water works industry on the matter of inside piping.

Stray electrical currents of normal magnitude may also be a factor in elec-

B

di

ha

wa

ve

tio

siti

pip

rod

the

sec

bui

In

a n

and

pres

fron

vice

nati

H

does

ther

ach

to it

to t

woul

there

tome

requi

pecui

Lack

ence

probl

trolytic corrosion, but the widespread practice of using dissimilar metals has made it difficult for researchers to determine to what degree such currents enter into the problem.

There is a large area of undiscovered information on this subject and customers' complaints might be explored for guideposts. Manufacturers are keenly interested in these problems, but have been unable to obtain authoritative data. The water works operator can be of assistance to them by carefully investigating customer complaints.

Combating Corrosion With New Materials

It is possible that manufacturers may develop for postwar promotion a cast iron more resistant to corrosion than is the present formula. This may be achieved by the introduction of other metals in small amounts, or by special heat treatment. It is hoped that it will be possible to machine this new material for working parts of valves and other items.

Service pipe corrosion problems may be overcome by the use of the special cast-iron alloy pipe with valves of the same material, by the use of insulating couplings at several points in the service line or by the use of non-metallic piping materials, such as asbestoscement and the various types of plastics developed during the war years.

Well-known and relatively inexpensive materials (steel, for example) can be made more acceptable if provided with new lining materials utterly different from lead or from the present process of galvanizing. Plastics may possibly be among the materials used.

Corrosion of the materials now used in water meters has precipitated many customer complaints. The changes resulting from wartime controls over critical metals have not been too serious and it may be found that they were definitely efficacious. There have resulted stimulation and renewed interest on the part of the manufacturers, which may produce some healthy results and which need encouragement. Certain fundamental conceptions should probably be changed. The buyers of meters may pose the questions: Is the frostproof bottom adequate? Are there other improvements needed which I, as a user, might suggest to the manufacturers?

Ordinary galvanized-iron hot-water tanks produced during the war years may present problems. They are less durable because the galvanizing is altered in content; the coating looks much brighter and shinier. To maintain a hot water temperature much over 140° is to court trouble, for the corrosion rate is greatly accelerated after that point is reached. New and better devices for temperature and pressure relief can be designed and should be located over a plumbing fixture, so as to prevent water from spilling onto the floor. No outlet piping is needed if such provision is made.

Bronze and copper alloys that are ordinarily very resistant to chemical corrosion have been used in hot water tanks, but here again the alloys have reacted peculiarly and with an apparent lack of uniformity.

Water in hot water tanks may be treated with sodium silicate and other substances to cut down corrosion of tanks and piping. Such procedure is particularly adapted to large buildings.

Better methods of protecting hot water tanks are needed. The use of insulating couplings has already been mentioned. However, such practice is simple for use with a small tank but

Vol. 37

over

seri-

were

ve re-

inter-

urers.

iv re-

ement.

should

ers of

Is the

e there

ich I.

manu-

-water

years

re less

is al-

looks

main-

much

or the

lerated

w and

d pres-

should

ure, so

g onto

needed

at are

nemical

water

s have

parent

nay be

1 other

sion of

dure is

ildings.

ng hot

use of

y been

ctice is

nk but

difficult in the case of a large steel tank with copper steam-heating coils. Tank linings of glass and other substances are being investigated and hold some promise.

Backflow or Back-Siphonage

Some water purveyors have become dangerously complacent regarding conditions on their customers' premises, perhaps because no serious outbreak of water-borne disease has occurred in their respective territories. Others have magnified the hazard. Unless customers request the water purveyor to investigate possible deterioration of water on their premises, the water purveyor is usually unaware of the conditions which may exist. Thus this situation may get scant attention.

Many things may happen. Interior piping in a house can be so badly corroded that a heavy flow of water in the cellar will produce a vacuum on the second floor of a house. In larger buildings, this is extremely serious. In addition, vacuums may result from a number of other possible conditions and, where a vacuum or a reduction of pressure is produced, back-siphonage from fixtures or water-connected devices may occur, resulting in contamination.

However, although back-siphonage does occur oftener than is realized, there are few cases of illness or stomach upset on record directly traceable to it. They certainly are not reported to the health departments, or more would be heard about them. It is, therefore, important to have good customer relations, so that consumers will request investigations if they note any peculiarity in the delivered water. Lack of exact data may cause indifference or may be used to magnify the problem far beyond its true size.

Therefore the customer with his complaints can help the water works operator to find the true solution.

Backflow connections (not inluding cross-connections) will permit backsiphonage from plumbing fixtures and other water outlets to tanks, vats, sewers and drains.

Not much progress can be made in the matter of backflow connections until the major number of outlets on a water piping system in a building (e.g., plumbing fixtures) can be protected. As a result of some four years work by a committee on plumbing standardization (A-40) of the American Standards Association, standards for air gaps were developed and issued by the ASA in 1942. A large majority of new faucets now manufactured are not siphonable except where used with some obsolete types of fixtures. Here is one definite national advance in the complex problem. The backflow preventer design and performance standards were set up by the same committee and published by the ASA in 1943. These two standards have been very helpful. The manufacturers of plumbing goods generally have been exceedingly co-operative in making the new designs available, even though it has meant changes in the manufacture.

The above standards refer, of necessity, to protection against backflow at water outlets either by air gaps or by a mechanical or a non-mechanical backflow preventer. Most water works operators insist that the air gap is the only safe method but in some cases preventers may be installed on a conditional basis, for even though they have been used for many years, they are still mechanical devices and liable to failure. They can be tampered with. In each municipality a ruling on this question should be made co-operatively.

00

wi

the

che

the

wil

ter

pla

tion

cula

nin

help

stre

ther

the

cust

fire

mai

mai

som

side

in th

ods

evol

men

tiny

hous

Radi

Ra

wart

In New Jersey, backflow connections are not covered by a state law. Control of them is left in the hands of individual municipalities.

The National Plumbing Laboratory, established several years ago, has accomplished much in examining control valves and water-connected devices with the hope that their findings would secure nation-wide acceptance, and eliminate, in part at least, conflicting reports of other testing agencies. To secure protection against back-siphonage, radical changes in some designs submitted were made. Some 40 valves and devices were approved.

The National Association of Master Plumbers has been active in educating its members and the general public regarding the hazards of other backflow connections.

The war limited the availability of brass and bronze for use in flush valves and plastics were substituted in some of the working parts with not too good results. Customer relationships may help to locate these difficulties.

Cross-Connections

Water purveyors in general are going to have more difficulty in securing elimination of cross-connections by separation as a result of temporary wartime changes. Fundamental conceptions may be seriously shaken when confronted with some of the devices other than double check valves which have been installed throughout the country to protect cross-connections as a result of wartime requirements.

Customers usually do not volunteer the information that cross-connections exist on their property, and many water plant executives might be surprised to learn how many are extant in the areas they serve. Such a condition has appeared on the Pacific coast and in other areas where there has been extensive war plant construction and expansion.

When the consumer gets in trouble with actual or suspected contamination. he notifies the water department, and it is then that the operator has an opportunity to act. He should investigate the number of auxiliary supplies in the territory served and determine the number of cross-connections. He should decide how to discourage the re-installation of the cross-connections after they have been removed. policy should be formulated for all classifications of cross-connections. keeping in mind that for cross-connections 4 in. or less in diameter, double check valves are not a reliable means of protection against backflow.

Cross-connections in the fire protection systems of large industrial plants may come about by reason of the present requirements of fire insurance companies for a dual source of supply on sprinkler systems. Co-operation with the customer in such cases is of the greatest value. Newer methods of putting out fires by fog nozzles, carbon dioxide gas and several other possible systems are proving valuable. Their advantages may possibly effect a change in the present insurance company requirements for dual supplies.

Water purveyors in other states may find guidance in the cross-connection law of New Jersey, the author's state (Chap. 308, P.L. 1942).

Avoiding Sluggish Circulation and Dead Ends

A common source of customer complaints is the existence of sluggish circulation and dead ends in outlying districts. Sluggish circulation results in the appearance of bacterial aftergrowths and related effects, of which the customers' complaints should promptly ap-

Vol. 37

ensive

msion.

rouble

nation.

t, and

an op-

ivesti-

pplies

rmine

I. A

or all

ctions.

onnec-

double

means

rotec-

plants

pres-

com-

oly on

with

of the

of put-

arbon

ossible

Their

ect a

com-

lies.

s may ection state

and

comsh cirig disilts in owths e custly apprise the operator. Chloramination, and in some cases super-chlorination, will contribute to the surmounting of these difficulties. Other sterilizing chemicals will doubtless be available in the post-war period and perhaps they will also be toxic to lower forms of bacteria and protozoal life.

As a distribution system is extended, plans should be made to avoid the crea-. He tion of permanent areas of sluggish cirge the culation and dead ends. Local planections ning boards and municipal officers will help in securing proper layouts of the streets in new developments. Perhaps there should be a re-examination of the use of small mains for residential customers and provision for adequate fire flows for hydrants located on larger Installation costs for water mains. mains may remain at present levels for some years to come and therefore double building lines should be considered. This is particularly important in the light of the new low-cost methods of housing production now being evolved. Land costs and all development costs will come under close scrutiny by the builders of such low-cost housing.

Radio for Improved Service

Radio in various forms, perfected for wartime purposes, will enable a super-

intendent to maintain contact with his men wherever they are, whether in car or on foot. This will improve water works operations and functioning and thus improve service to consumers.

Conclusions

Only when the water works operator realizes that customers are sometimes dissatisfied with the water they get and the operator in turn becomes dissatisfied with existing conditions will he begin to explore new fields and avoid old pitfalls. The operator must be ready to accept the advantages of new ideas, new methods and new materials and weigh the advantages impartially against the disadvantages which may appear. As a group and as individuals, the members of the water works brotherhood must better understand the problems involved on customers' premises, the sizing of water piping and tanks, the effects of the installation of water-connected devices, backflow conditions of all types and the conditions under which backflow occurs. There is no clear and definite road to follow. The path is full of "booby-traps." By sincere exploration of customer complaints and co-operation with other agencies in finding solutions, much can be accomplished.

Politics and Public Service

By Willard Chevalier

Vice-Pres., McGraw-Hill Publishing Co., Inc., New York, N.Y.

At the meeting of the Executive Committee of the A.W.W.A. held in New York on June 29, 1945, Honorary Membership certificates were presented to Messrs. George W. Booth and Willard Chevalier. Mr. Chevalier's impromptu but brilliant response was recorded by the stenotypist and is herewith published in the Journal for the benefit of all its readers. The concept expressed by Mr. Chevalier, that politics (in the proper meaning of the word) and public service are essential each to the other, will elicit affirmation from experienced and successful administrators of public water supply properties.

Samuel F. Newkirk Jr., President of the Association, introduced Mr. Chevalier with these words: "Mr. Chevalier, I once heard you remark that there were two things that could not be taken out of water. One was salt and the other was politics. A global war has produced, as we all know, desalting kits. I wonder what sort of an upheaval would be necessary to remove politics."

What your Chairman said about the place of politics in water makes it incumbent upon me, I think, to extend that comment.

We in this country have come to invest the word "politics" with a highly unpleasant connotation—one that is both inaccurate and unfair. Without politics, there can be no democracy. Without politics, there can be no great business corporations, no great associations of individuals engaged in any sort of co-operative endeavor. "Politics" in its true sense derives from the word "polity," and that, in turn, goes back to the principles and the measures that make it possible for men to work together in their common interest. Whenever you bring together more than one person with purpose to work to a common end, you must have of necessity a compromise of interestsyou establish a polity and you must practice politics.

As more and more people thus work together and as their interests become more vital and far-reaching, the compromises become more numerous and more searching with respect to the life and the interests of each individual. I do not believe we shall ever get politics out of water or out of anything else that is sufficiently important to justify community of effort on the part of large numbers of people. So we have governmental politics, association politics, industrial politics, lodge politics even church politics.

th

ar

Sig

pu

to

get

kne

tici

mu

the

par

poli

the

long

But

life

ties,

of c

peop

livel

I

to s

polit

peop

enou

as v

judg

high

with

comr

than

nical has

Th

The only reason for this extension of my thought on the subject is that in my judgment, we are going to have more politics in the future than in the past. Our concern, therefore, is to see that we raise our politics to a higher plane than they have attained in the past and that we keep them on the highest possible plane most of the time

I am one of those who are convinced

New

ted to

mptu

lished

y Mr.

ervice

d suc-

Mr.

there

id the

g kits.

work

ecome

com-

is and

he life

ual. I

politics

ng else

justify

art of

e have

n poli-

olitics.

tension

is that.

to have

in the

to see

higher

in the

on the

ne time

nvinced

that the relations between the people and their governments are going to be more comprehensive and more intimate than they ever have been. I think that government is going to have more to do with individuals, with business and with industry than ever before.

Certainly, the kinds of community services of which water supply is typical are going to become more and more significant. They are going to demand the attention and touch the interests of more and more of the people. That means that the politics of water and of public service in every department are to be of increasing importance.

It seems to me, therefore, that the chief tenet of our politics should be to get more and more of the people to know and to understand and to participate in the conduct of those community activities. So long as we have public servants living in a world of their own, wrapped up in their own particular bureau politics and in the politics of the party that happens for the moment to be in power, just so long will our politics be on a low level. But the more we can get the whole life of the community into those activities, the more shall we raise the level of our politics; because more of the people will be interested and take a lively interest in what goes on.

I hope that I shall live long enough to see the taint that now attaches to politics removed from the minds of our people. I have lived and worked close enough to politics to see its seamy side as well as its brighter side. In my judgment, community service is on a higher plane today than at any time within my knowledge.

The type of man who is serving our community facilities today is higher than it ever was. Certainly his technical competence is higher than it ever has been. I believe his aspirations

are higher than they ever have been.

Considering the life of this Association, we all know how steadily it has climbed in its own conception of the job it has to do. The men who come after us who are here today will have still higher concepts. They will look back to what we now think is pretty good and they will say, "Well, those fellows were certainly on the way up, but from our vantage point they don't appear to have gotten very far at the time they were working."

This is as it should be. If there is any hope at all for democracy, we shall find it only in a growing sense of civic honesty and civic responsibility, and that is bound to appear, first of all, among the men who are elected or selected to serve the people.

I remember a time when a "government job" was not looked upon as being very much other than a job. The idea of a career in public service was tied up with the idea of getting a political pull and of keeping it effective.

That still is true in some quarters. But more and more we recognize and honor men who, going into public service during that period, were primarily concerned with rendering faithful service and were not a bit concerned about "getting in right." More and more we have seen those men reach the top in public service because the civic conscience has been rising as they came along. And because of the high standards they set, high-grade men today are finding it less and less necessary to cultivate that "get-in-right" quality and more and more necessary to do the kind of job that the public has a right to expect.

Our only hope lies in our ability to maintain that trend. And associations such as this one can have no more vital objective than to nourish and strengthen it.

Promotion of Fraudulent Water Purifiers

A device, which comprises two electrodes and which is represented to treat water electrically upon immersion of the electrodes into the water to be treated, has been offered for sale intermittently in one place or another over the country for at least 25 years. One of the latest episodes of this sort was recently investigated by the Indiana State Board of Health and the results of its report published in the July 1945 Bulletin of the Indianapolis Better Business Bureau. The Bulletin's story, reprinted by permission of the Indianapolis Better Business Bureau, follows:

The "Aquatron" is a widely sold device on the representation that it is a water purifier. It might be briefly described as a gallon glass jar or jug with a screw top in which are fastened two electrodes. Both electrodes are of aluminum. When the jar is filled with water, the electrodes are connected to a house current thus "purifying" approximately one gallon of water. When called to the Bureau's attention it was being sold by "Brown's G & W Health Food Store." . . .

The printed literature issued in connection with it states that it is manufactured by the Kruse System, Inc., of Indianapolis.

A Health Aid

A shopper went to the store to see what representations were made concerning it. The shopper was informed that the city water we are drinking is at no time completely pure, and that sometimes it is practically untreated; that each week human bodies, such as suicides, and animals fall into the canal, which decompose and add to the impurities of the water we are drinking; that by buying the little gadget known as the "Aquatron" at \$37.50 each, pure water thus obtained would be worth many times the price by protecting one's health.

Demonstration

The salesman then conducted a demonstration. He placed the "Aquatron" in a gallon jug of city water and connected the plug to a wall outlet. Immediately small white particles began to form and drop to the bottom of the jug. The salesman claimed that such particles were the filth in the water, and when the electrodes were removed, such bacteria would die and eventually sink to the bottom, leaving the clear purified water on the top.

lei

Be

su

of

In

suc

san

call

afte

ord

bee

tru

is '

scie

here

rou

ing

F

char

cally

India

fore

noth

"Aqt

Se

gross

logic

tate

ing.

mean

certa

In the literature given all buyers or potential buyers of the "Aquatron," the claim is made that such device is constructed to remove "all harmful bacterias, chlorine, filth and all suspended matter, leaving the pure organic mineral matter which is essential to cell life." In the same pamphlet it is also claimed that the "Allied Governments of World War II are using the Aquatron method of water purification in all theatres of war to give our boys PURE DRINKING WATER."

Further the literature claims, "Eminent physicians throughout the world agree that thousands of people could be spared the suffering of such diseases or ailments as rheumatism, arthritis, diabetes, headaches and all kidney disorders, together with a host of many

treat

eated.

untry

tly in-

report

ureau.

Busi-

ted a

Aqua-

er and

outlet.

les be-

tom of

d that

in the

s were

ie and

eaving

vers or

atron,"

vice is

armful

ll sus-

ire or-

ssential

phlet it

d Gov-

e using

urifica-

ive our

TER."

"Emi-

world

e could

ch dis-

arthri-

kidney

f many

top.

other ailments which are too numerous to mention," the inference and the context meaning to the reader that the Aquatron would be a relief to such ailments.

Laboratory Tests

After learning from various sources such statements were being made concerning the device and the impression left that the city water was impure, the Better Business Bureau was interested to discover exactly what the merit of such water purification device was.

A series of experiments were conducted for us by the laboratory of the Division of Environmental Sanitation of the Indiana State Board of Health. In carrying out such investigations, the device was operated strictly in accordance with the directions accompanying such instrument. A number of water samples were examined both chemically and bacteriologically before and after the "Aquatron" treatment in order to determine what changes had been produced and to ascertain how true the claims were. Since the report is very extensive and of a complex scientific nature, no attempt is made here to present all the factual data surrounding such experiments. Following are the conclusions reached:

First: A city water sample was scarcely changed either bacteriologically or chemically. The sample met standards of the Indiana State Board of Health both before and after treatment. Absolutely nothing was gained by the use of the "Aquatron."

Second: A water sample containing gross pollution was improved bacteriologically due to the effect of the precipitate formed while the device was operating. The water, however, was by no means sterile after the treatment, and certainly would not be called safe for

drinking purposes. No particular change took place chemically.

Third: A water sample containing a moderate amount of pollution is improved somewhat bacteriologically, but again the chemical results show little difference before and after the use of the "Aquatron."

Fourth: The white precipitate which is observed on all experiments after the machine has been operated for the specified length of time does not come from the water (claimed to be filth by the agent selling such device), but is from the action of the current on the electrodes. The precipitate is a hydroxide of aluminum formed by the action of the electric current on the electrodes, which apparently are aluminum or an alloy of aluminum. Experiments revealed that the water contained no aluminum before the tests, but contained some at the end.

Fifth: A claim is made that the chlorine is removed from the water during the "Aquatron" treatment. One of the experiments showed that the free chlorine was not removed, but reduced slightly, which could have been due to the effect of the aluminum hydroxide absorbing the chlorine while settling. Again, removal of the chlorine is not a point of merit because it is a very common recommended practice to maintain some residual chlorine in a public water supply at all times.

Sixth: One test showed that the same results could be accomplished by using a slight amount of filter aluminum sulphate.

Seventh: It was noted that the same visible action observed in the use of the "Aquatron" could be produced by merely placing two aluminum strips into a sample of water and attaching these to an AC current outlet.

The results of all these experiments showed that the claims concerning the action of the "Aquatron" are not substantiated. Very little change takes place in the chemical content of the water, and the "Aquatron" is vicious in that it does not purify impure water

C

10

pe

iat org of wa

Mo fig

(ca Ale

and

sufficiently to make it safe for drinking purposes. Also, the operation is dangerous because of the explosion hazard, particularly if only a small amount is being treated, leaving space above it in the jar for the oxygen and hydrogen to collect. It is amusing to note that while the salesman himself was operating such device in the G & W Health Food Stores when he removed the cover from the jar before pulling the plug from the outlet, there was a loud explosive noise.

No justification for its use on the ordinary public water supply is noted. From several expert sources it was also determined that a unit comparable

to the "Aquatron" could be produced at a cost of somewhat under \$5.00, which price would include material, labor and transportation.

We have been assured by an executive of the Kruse System that they did not authorize the oral representations made by the salesman in this instance; also that they will withdraw all literature now using such representations; and that they will destroy and not distribute some fifty thousand pieces of present literature on hand; and that they will either withdraw the "Aquatron" from the market, or sell it for some other purpose or in some other manner.

Elimination of Midge Fly Larvae With DDT

By Martin Flentje

San. Eng. Dept., American Water Works & Electric Co., New York, N.Y.

A contribution to the Journal

DT, applied for the first time (so far as is known) to a potable public water supply, was recently found effective in eliminating an infestation of midge fly larvae at Alexandria, Va., which is served by a subsidiary of American Water Works and Electric Company. A dose of 1 part DDT in 100,000,000 parts of water (0.01 ppm.) was applied on Aug. 31, 1945, and was found effective in eliminating these pests. The offending organisms, idenfified as belonging to the Chironomidae family (also called Tendipedidae). were demonstrated in laboratory tests to be typically resistant to copper suliate and high chlorine dosages. The organism present was fortunately not of the common "blood-worm" type, but was instead colorless to faint green and it was short—4 to 5 mm. in length. Movement was with the characteristic figure-eight motion typical of these larvae.

V ol. 37

\$5.00, terial

execu-

ev did

tations

tance;

ations:

ot dis-

ces of

d that

Aqua-

it for

other

The source of the infestation was the two clear water storage reservoirs (capacity, 16.5 mil.gal.) located at the Alexandria Water Company's filtration plant.

The use of DDT was first suggested to the author by Sanitarians English and Slaymaker and Dr. Shrop, Head,

all of the Alexandria City Health Department. Before proceeding with the application, numerous authorities on entomology and public health were consulted, either directly or through one of those named. Among them were Doctors Dove, Bishopp and Lindquist. Entomologists of the U.S. Department of Agriculture; Dr. Calvery of the Pure Food and Drug Administration; J. K. Hoskins of the U.S. Public Health Service; and Richard Messer, State Sanitary Engineer of Virginia.

A dosage of 0.01 ppm. DDT killed these larvae in approximately eight hours under laboratory conditions; kill was also obtained in somewhat less than sixteen hours with a dose of 1 part in 200,000,000.

On August 31, 0.01 ppm. DDT made up in Triton X and Xylene (25 per cent DDT) was diluted with water to an emulsion strength of approximately 1 per cent and this was sprayed on the surface of the reservoirs with a civilian defense stirrup pump. A boat with an outboard motor was employed and the wake of the boat was used for mixing and diffusion. Three to three and one-half days after this treatment the larvae disappeared from the distribution system.

Alexandria, Virginia—Survival and Retirement Experience With Water Works Facilities

As of December 31, 1940

THE privately-owned Alexandria Water Company serves the city of Alexandria, Va., and adjacent territory. The 1940 population of the city was 33.523.

Alexandria is located on the Potomac River in the northern part of the state, about 7 mi. south of Washington, D.C. It was first incorporated in 1749. In 1850 it had a population of 8,754 and grew very slowly until the late twenties, when, because of improved transportation facilities, it benefited greatly from the population overflow from Washington. As a result the population has more than doubled in the last fifteen years and it is continuing to grow rapidly.

The territory served is predominantly residential but there are a few scattered industries. The Potomac Yards, one of the largest freight classification yards in the country, is located at the city's northern limits.

As of Dec. 31, 1940, the date of this study, there were 8,181 consumers, about 55 per cent of whom were served through meter measurement. There were 87 mi. of mains. The average pumpage in 1940 was 3.23 mgd., equivalent to 81 gpd. per capita. About 5 per cent of the water served was for industrial use. Not included in the above is the sale of untreated water to the Southern Railway which amounted to 118 mil.gal.

Development of Existing System

0

Si

4 6 8

12

16

20

2

6

8

12

1

1

1

2

2

3

1

1

T

Perc

Aver

S

2

6

8

10

0

6

To

The Alexandria Water Company was incorporated in 1851 and the plant was built in 1851–1852 and put in service in June 1852. The construction was done under the direction of an engineer who had previously built the water works at Harrisburg, Pa., and Fredericktown, Md.

The company was financed by local capital and continued to operate under local ownership and management until 1929 when the capital stock was acquired by the American Water Works and Electric Company, Inc., under whose ownership and management it continues in operation.

The original works consisted of a pumping station at which water was pumped to a 2.5-mil.gal. storage basin from which it was delivered by gravity to consumers through 7 mi. of castiron pipe.

The source of supply was Cameron Run. Water from this source was diverted from the stream by a diversion dam below the junction of its tributaries, Holmes Run and Back Lick Run. There were no impounding facilities on the watershed, the natural flow of the streams being sufficient for the requirements at that time. From the diversion dam a race some 9,000 ft. long conveyed the water to the pumping station. The race delivered water

t

plant ervetion enthe and

local inder until acorks inder int it

of a was asin wity cast-

eron
s dision
ribuLick
ding
rural
for
rom
0 ft.
mprater

TABLE 1
SUMMARY OF WATER MAINS
ALEXANDRIA, VIRGINIA

Size,	Kind	No. of Feet Identified*	Percent- age of Total	No. of Feet Retired	Percent- age of Total	No. of Feet in Service	Percent- age of Total	Year of First Instal- lation	Averag Age,
4)		97,978	21.6	1,425	6.9	96,553	22.3	1852	48.2
6		125,650	27.7	1,658	8.1	123,992	28.5	1852	28.8
8	C	30,169	6.6	528	2.6	29,641	6.8	1852	32.8
10	Cast-iron	23,404	5.1	42	0.2	23,362	5.4	1852	32.5
12	unlined	22,017	4.8	42	0.2	21,975	5.1	1885	25.8
16		3,329	0.7	0	0.0	3,329	0.7	1885	46.7
20		4,246	0.9	0	0.0	4,246	1.0	1885	51.1
2		27,392	6.0	3,032	14.7	24,360	5.6	1930	6.3
6	Cast-iron	63,096	13.9	0	0.0	63,096	14.5	1930	3.7
8	cement-lined	18,693	4.1	0	0.0	18,693	4.3	1930	3.1
12		2,061	0.5	0	0.0	2,061	0.5	1931	2.8
2		349	0.1	0	0.0	349	0.1	1923	16.8
1		266	0.1	0	0.0	266	0.1	1924	16.5
11	C 1 :1	1,280	0.3	473	2.3	807	0.2	1923	16.7
2	Galvanized	12,248	2.7	1,363	6.6	10,885	2.5	1918	15.8
21	steel	1,373	0.3	258	1.3	1,115	0.3	1921	14.5
3		1,649	0.4	0	0.0	1,649	0.4	1924	14.2
4		4,249	0.9	2,676	13.0	1,573	0.4	1913	16.5
11		3,131	0.7	1,850	9.0	1,281	0.3	1852	15.9
2	Galvanized	9,366	2.1	6,613	32.2	2,753	0.6	1852	15.5
21	wrought-iron	600	0.1	600	2.9	0	0.0	1866	
3		1,643	0.4	0	0.0	1,643	0.4	1925	15.5
1	Lead	16	0.0	0	0.0	16	0.0	1923	17.5
11	Lead	18	0.0	0	0.0	18	0.0	1926	14.5
Тот	AL	454,223	100.0	20,560	100.0	433,663	100.0		27.0
ercen	tage of Total	100,00		4.53		95.47			
vera	ge size, in.	5.97		2.87		6.12			

Mortality Survival Ratios

Size, in.	Kind	No. of Feet	Period Covered, yr,	Percentage
1-11	All	5,060	40.5	0
2-4	Galvanized wrought-iron and galvan- ized steel	31,128	31.5	0
4		97,978	88.5	97.991
6		125,650	88.5	88.818
8	Cast-iron unlined	30,169	88.5	95.324
10-12		45,421	88.5	99.068
Over 12		7,575	55.5	100.000
2	Cast-iron cement-lined	27,392	10.5	82.734
6-12	Cast-iron cement-lined	83,850	10.5	100.000
TOTAL		454,223		

^{*}Unindentified Pipe: 74 ft. of 4-in. cast-iron unlined; 201 ft. of 6-in. cast-iron unlined.

00

0 60

in sufficient quantity and head to furnish not only the water supply but to provide power to drive an overshot water wheel. A 1-mgd. reciprocating pump, actuated by the water wheel, elevated the water to the storage basin from which it flowed by gravity to the distribution system.

The original pumping station building, which was constructed of limestone, and the raceway were originally part of a mill property constructed many years before. The race still continues in service and the major part of the original building is incorporated in the existing pumping station.

In 1855 a steam engine and boiler were installed in the pumping station, affording an alternate source of power for pumping. The orig-

inal pump has also continued in service until the present time.

In 1874 and 1875 a second storage basin, with a capacity of about 13.5 mil.gal., was built adjacent to the original basin. These basins are located on a hill about 1 mi. west of the center of Old Alexandria at an elevation of about 100 ft.

The supply as it existed in 1875 sufficed until 1913 when increased demands for water necessitated the construction of an impounding dam on the upper waters of Holmes Run. This dam, known as the Barcroft Dam, is




Fig. 1. Mortality Survival Curve—4-20-in, Cast-Iron Unlined Mains—Alexandria, Virginia

BASE: Feet	Survival: 1852-1940				
SIZE in.	EXPOSURES ft.	RETIREMENTS ft.			
4	97,978	1,425			
6	125,650	1,658			
8	30,169	528			
10 and 12	45,421	84			
Over 12	7,575	0			

a stone and concrete masonry dam, 500 ft. long, with a spillway section 160 ft. long. It is of gravity type construction with a spillway elevation of 205 ft. and a capacity of 600 mil.gal.

The total area of the watershed above the dam is about 14 sq.mi. and the combined area of the sheds on Holmes Run and Back Lick Run above the point of diversion is 33 sq.mi. As presently developed they have an estimated total safe yield of about 7 mgd. The impounded storage is released through control gates into Holmes Run as required. The manner in which the

Fig.

Size in.

2-4

water

1-14

race
In
was b
It is
basin

consis

tanks

The was p of Ale of abo

tem e

1. 37

Un-

NTS

500

0 ft.

ction

and

shed

and

5 01

bove

As

esti-

mgd.

eased

Run

h the




Fig. 2. Mortality Survival Curve—‡-4-in. Mains—Alexandria, Virginia

BAS	E: Feet Surv	IVAL: 185	2-1940
		Ехро-	RETIRE-
SIZE in.	KIND	sures ft.	MENTS ft.
1-11	Wrought-Iron and Steel	5,060	2,323
2-4	Wrought-Iron and Steel	31,128	11,510
2	Cast-Iron Cement Lined	27,392	3,032

water is brought to the pump station from the diversion dam through the race is the same now as it was in 1852.

In 1918 a 2.5-mgd. filtration plant was built. It went into service in 1919. It is located adjacent to the storage basins and the original construction consisted of two cypress sedimentation tanks and five New York Continental rapid sand filters.

The elevation of the storage basins was planned to supply the original town of Alexandria, which has an elevation of about 50 ft., by gravity. As the system extended to take in contiguous

territory, three separate high-service areas supplied by booster pumps were developed so that the elevations now served range from sea level to 275 ft. above.

In 1933 it became necessary to increase pressures throughout the original system. This was accomplished by discontinuing gravity feed and returning the water from the basins to the pump station where high-service pumps were installed which delivered the water at greater pressure to the distribution system.

The original filter plant consisted of five 0.5-mgd. units. An additional unit was added in 1929 and two more units in 1937. Also at this time the original filter house, which was of wood construction, was replaced with a brick structure.

Basis of Study

The data on pipe and valves were compiled from a study made for the purpose of listing all pipe and valves that had been retired over the life of the property. The study was made coincidently with an inventory of existing mains. Company records pertaining to size, kind and date of installation were fairly complete over the entire plant life. Existing retirement records were checked and supplemented by a comparison of pipe and valves installed with the present existence by specific locations.

The record on valves has not been carried forward beyond the date of the original study. This record is through Dec. 31, 1930.

Mortality Survival Study

Mortality studies were made of mains and valves. Table 1 is a summary of the pipe installed, the amount retired and that still in service, as well as other pertinent data. Figures 1 and

00

2 show the mortality survival curves covering the amount and classification of pipe grouped as shown.

Table 2 and Figure 3 represent a similar study of valves.

A brief summary of Class B facilities covering the major items is given below.

Causes of Retirement

There exists no complete record from which could be determined the causes of retirement of mains and valves.

Acknowledgments

The collection and compilation of data pertaining to the Alexandria Water Company were carried out by the personnel of the American Water Works and Electric Company, Inc.




Fig. 3. Mortality Survival Curve—4-20-in. Gate Valves—Alexandria, Virginia

D II :-	C	1052 1010
BASE: Unit	SURVIVAL:	1852-1940
SIZE in.	Exposures Units	RETIREMENTS Units
4	156	2
6	182	1
8	49	0
10 and 12	54	0
Owen 12	0	0

SUMMARY OF CLASS B FACILITIES ALEXANDRIA, VIRGINIA

Impounding Reservoirs

Barcroft Reservoir—On Holmes Run, concrete masonry dam, 500 ft. long, maximum height 68 ft., capacity 617 mil.gal. Constructed in 1915 and still in service.

Aqueducts

Cameron Raceway—From diversion dam to pumping station, 9,000 ft. long, 12 to 15 ft. wide, 3 ft. deep. Originally constructed in 1800, straightened in 1866, 1,250 ft. relocated in 1875 and still in service.

Taylors Run Aqueduct—Section of above raceway over Taylors Run, concrete filled brick arches on steel I beams: 40 ft. long, 20 ft.

wide and 8 ft. high. Built in 1893 and still in service.

Purification Plant

Two wood sedimentation tanks, 44 ft. in diameter by 16 ft. high. Three wood coagulating tanks, 5 ft. in diameter by 5 ft. high. Six wood filter units, 15 ft. in diameter by 8 ft. high. Chemical feed equipment. Constructed in 1918 and still in service.

Pumping Equipment

No. 1—Reciprocating pump, driven by water wheel, capacity 1 mgd. at 81-ft. head. Installed in 1851, original water wheel replaced in 1902, pump and water wheel still in service.

Te

То

No.
ity 1..
and st
No.

No.
pump

No. capaci

No.

ol. 37

ves-

INTS

d still

ft. in

oagu-

high.

er by

Con-

n by

head.

placed

ervice

TABLE 2 SUMMARY OF VALVES ALEXANDRIA, VIRGINIA

Size.	Number Installed	Number Identified	Number Retired	Number in Service	Year of First Installation	Average Age
1	4	4	0	4	1926	4,5
2	50	25	0	25	1912	5.5
21/2	1	1	0	1	1926	4.5
3	5	5	0	5	1925	27.5
4	224	156	2	154	1852	35.4
6	314	182	1	181	1852	22.4
8	58	49	0	49	1852	24.8
10	41	36	0	36	1852	18.0
12	26	18	0	18	1885	20.8
16	6	5	0	5	1885	40.7
20	3	3	0	3	1885	38.5
TOTAL	732	484	3	481		25.5
rcentage o	f Total	100.00	0.62	99.38		

Mortality Survival Ratios

Size, in.	Number	Period Covered, yr.	Percentage
1-3	35	28.5	100.000
4	156	88.5	93.333
6	182	88.5	94.118
8	49	88.5	100.000
10 and 12	54	88.5	100.000
Over 12	8	55.5	100.000
OTAL	484		

SUMMARY OF CLASS B FACILITIES (contd.)

Pumping Equipment (contd.)

No. 2—Steam engine-driven pump, capacity 1.5 mgd. at 81-ft. head. Installed in 1898 and still in service.

No. 3—Steam turbine-driven centrifugal pump, capacity 3 mgd. at 110-ft. head. Installed in 1928 and still in service.

No. 4—Water turbine-driven centrifugal pump, capacity 1.3 mgd. at 105-ft. head. Installed in 1928, replaced in 1937 by diesel unit. Pump in stock, turbine \$100 salvage.

No. 5—Motor-driven centrifugal pump, capacity 0.3 mgd. at 192-ft. head, 20-hp. motor. Installed in 1928 and still in service.

No. 6—Motor-driven centrifugal pump, capacity 0.3 mgd. at 253-ft. head, 30-hp.

motor. Installed in 1929 and still in service.

No. 7—Motor-driven centrifugal pump, capacity 0.14 mgd. at 268-ft. head, 15-hp. motor. Installed in 1927 and still in service.

No. 8—Motor-driven centrifugal pump, capacity 0.14 mgd. at 130-ft. head, 7.5-hp. motor. Installed in 1927 and still in service.

Wash Water Pump—Motor-driven centrifugal pump, capacity 0.5 mgd. at 55-ft. head, 10-hp. motor. Installed in 1918 and still in service.

Seminary Station—Motor-driven triplex pump, 7.5-hp. motor. Installed in 1928 and still in service.

Belle Haven Station—Small vertical deep well pump, 3-hp. motor. Installed in 1927 and still in service.

SUMMARY OF CLASS B FACILITIES (contd.)

Distribution Reservoirs

No. 1 Reservoir—Open, excavated, brick lined, 182-ft. square reservoir; capacity 2.5 mil. gal., 17 ft. deep. Constructed in 1852 and still in service.

No. 2 Reservoir—Open, excavated, stonepaved reservoir; capacity 14 mil.gal., 337 ft. wide by 500 ft. long, 17 ft. deep. Constructed in 1875 and still in service.

St. Elmo Reservoir—Covered reinforced concrete reservoir; capacity 0.7 mil.gal., 70.67 ft, wide by 94.67 ft. long, 16.5 ft. deep. Constructed in 1927 and still in service.

Tanks and Standpipes

Jefferson Park Standpipe—Covered steel standpipe, capacity 705,000 gal., 40 ft. in diameter by 75 ft. high. Erected in 1928 and still in service.

Seminary Elevated Tank—Covered steel elevated tank, capacity 50,000 gal., 18 ft. in diameter by 20 ft. deep, 50 ft. to flow line. Erected in 1913 and still in service.

Belle Haven Elevated Tank—Covered wood tank, capacity 20,000 gal.; 16 ft. in diameter by 13.33 ft. deep, 50 ft. to flow line. Erected in 1927 and still in service.

1888

24

SUMMARY OF INSTALLATIONS AND RETIREMENTS ALEXANDRIA, VIRGINIA

MAINS

4-IN. CAST-IRON UNLINED MAINS

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1852	14,032	13,996	36	1902	147	147	0
1853	933	933	0	1903	542	542	0
1856	307	307	0	1904	1,856	1,856	0
1858	627	627	0	1905	1,374	1,374	0
1869	323	323	0	1907	2,027	2,027	0
1870	602	591	11	1908	11,555	11,555	0
1871	1,260	1,260	0	1909	2,516	2,516	0
1875	387	387	0	1910	10,880	10,880	0
1878	409	409	0	1911	2,410	2,410	0
1879	865	865	0	1912	2,451	2,451	0
1880	1,508	1,508	0	1913	2,892	2,892	0
1881	316	316	0	1914	309	309	0
1882	420	420	0	1916	378	378	0
1884	2,814	2,814	0	1918	202	202	0
1885	2,570	2,570	0	1919	29	29	0
1886	309	309	0	1920	20	20	0
1887	330	330	0	1921	283	283	0
1888	2,564	2,540	24	1923	192	192	0
1889	1,149	1,149	0	1925	11	11	0
1891	2,842	2,842	0	1926	468	468	0
1892	932	932	0	1927	6	6	0
1893	1,863	1,863	0	1928	209	209	0
1894	6,120	6,120	0	1929	203	203	0
1895	1,390	766	624	1940	0	0	0
1896	1,420	1,206	214				-
1897	1,941	1,941	0	SUBTOTAL	97,978	96,553	1,425
1898	2,226	2,226	0	Unknown	74	0	74
1899	3,550	3,034	516				
1900	420	420	0	TOTAL	98,052	96,553	1,499
1901	2,589	2,589	0				
			Retirement	s by Years			
Year				Year			
Installed	Feet	Year		Installed	Feet	Year	
1852	36	1909		1895	624	1907	
1870	11	1897		1896	214	1907	
1000	2.4	1011		1070	217	1301	

6-IN. CAST-IRON UNLINED MAINS

1899

516

1939

1911

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1852	10,702	9,454	1,248	1888	1,701	1,701	0
1853	313	313	0	1890	410	0	410
1877	420	420	0	1892	2,851	2.851	0
1878	409	409	0	1893	774	774	0
1885	244	244	0	1896	875	875	0
1886	423	423	0	1897	3,695	3,695	0

steel in di-8 and

ol. 37

steel ft. in v line.

wood meter rected

To

Ins 1

18 19 19

Тота

2-Yes Insta 193 193 193 193

6-IN. CAST-IRON UNLINED MAINS (contd.)

Year		Feet		Year		F	eet	
Installed	Installed	In Service	Retired	Installed	Installed	In S	ervice	Retire
1898	1,811	1,811	0	1922	4,191	4	,191	0
1899	711	711	0	1923	6,249	6	,249	0
1902	377	377	0	1924	6,189	6	,189	0
1903	2,314	2,314	0	1925	3,587	3	,587	0
1904	753	753	0	1926	9,694	9	,694	0
1905	434	434	0	1927	11,930	11	,930	0
1906	1,530	1,530	0	1928	10,740	10	,740	0
1907	2,062	2,062	0	1929	4,434	4	434	0
1908	5,309	5,309	0	1940	0		0	0
1909	2,008	2,008	0			-		
1910	5,067	5,067	0	SUBTOTAL	125,650	123	,992	1,658
1911	726	726	0	Unknown	201		0	201
1913	2,217	2,217	0					
1914	2,778	2,778	0	TOTAL	125,851	123.	992	1.859
1915	2,949	2,949	0					,,,,,,
1916	3,090	3,090	0		Retireme	ents by 1	lears	
1918	5,516	5,516	0	Year				
1919	2,858	2,858	0	Installed	Feet	Year	Feet	Year
1920	1,870	1,870	0	1852	24	1909	1,224	1913
1921	1,439	1,439	0	1890	410	1914	,	*/*0

8-IN CAST-IRON UNLINED MAINS

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1852	4,776	4,776	0	1926	4,750	4,750	0
1870	1,317	867	450	1927	9,580	9,580	0
1872	54	0	54	1928	262	262	0
1897	1,244	1,244	0	1940	0	0	0
1898	1,961	1,937	24				-
1902	450	450	0	TOTAL	30,169	29,641	528
1905	417	417	0				
1907	24	24	0		Retiremen	its by Years	
1916	1,876	1,876	0	Year			
1918	978	978	0	Installed	Feet	Year	
1919	394	394	0	1870	450	1902	
1920	882	882	0	1872	54	1885	
1921	38	38	0	1898	24	1907	
1922	1,166	1,166	0				

10-IN. CAST-IRON UNLINED MAINS

Year		Feet			Retirements by	Years
Installed	Installed	In Service	Retired	Year Installed	E4	17
1852	3,908	3,884	24		Feet	Year
1885	3,450	3,432	18	1852	24	1910
1905	938	938	0	1885	18	1914
1927	3,969	3,969	0			
1928	11,139	11,139	0			
1940	0	0	0			
TOTAL	23,404	23,362	42			

0 1,658 201 1,859

1	TAY.	(ACT.	DOM	UNLINED	MATRIC
- 4	2 - 114	C'421.	I BOOK	UNLINED	TATIVITA

	Year		Feet	
Retired	Installed	Installed	In Service	Retired
0	1885	1,719	1,677	42
0	1897	1,900	1,900	0
0	1906	1,425	1,425	0
0	1908	916	916	0
0	1911	4,523	4,523	0
0	1920	414	414	0
0	1922	1,749	1,749	0
0	1923	3,614	3,614	0
0	1926	568	568	0
	1927	2,424	2,424	0
1,658	1928	2,765	2,765	0
201	1940	0	0	0
1,859	TOTAL	22,017	21,975	42
		Retiremen	ts by Years	
Year	Year			
	Installed	Feet	Year	
1913	1885	42	1914	

16-IN. CAST-IRON UNLINED MAINS

	10-11	" CAUL INC.	CHUINDD III	CALLYS
	Year		Feet	
Retired	Installed	Installed	In Service	Retired
0	1885	1,443	1,443	0
0	1897	1,675	1,675	0
0	1928	211	211	0
0	1940	0	0	0
528	TOTAL	3,329	3,329	0

20-IN. CAST-IRON UNLINED MAINS

Year		Feet	,
Installed	Installed	In Service	Retired
1885	3,308	3,308	0
1905	938	938	0
1940	0	0	0
TOTAL	4,246	4,246	0

2-IN. CAST-IRON CEMENT-LINED MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1930	8,327	7,412	915		
1931	2,272	2,151	121		
1932	833	559	274		
1933	3,299	1,607	1,692		
1934	1,409	1,409	0		

2-IN. CAST-IRON CEMENT-LINED MAINS (contd.)

	MIMINS	(conta.	,	
Year		Fee	t	
Installed	Installed	In Ser	vice	Retired
1935	1,645	1,6	15	30
1936	791	7	91	0
1937	703	7	03	0
1938	3,392	3,3	92	0
1939	3,200	3,2	00	0
1940	1,521	1,5	21	0
TOTAL	27,392	24,3	60	3,032
	Retiremen	nts by Ye	ars	
Year				
Installed	Feet	Year	Feet	Year
1930	781	1936	134	1938
1931	121	1938		
1932	274	1936		
1933	1,692	1936		
1935	30	1936		

6-IN. CAST-IRON CEMENT-LINED MAINS

Year		Feet	
Installed	Installed	In Service	Retired
1930	3,305	3,305	0
1931	3,041	3,041	0
1933	292	292	0
1934	84	84	0
1935	8,120	8,120	0
1936	12,249	12,249	0
1937	7,897	7,897	0
1938	8,978	8,978	0
1939	8,224	8,224	0
1940	10,906	10,906	0
TOTAL	63,096	63,096	0

8-IN. CAST-IRON CEMENT-LINED MAINS

Year		Feet	
Installed	Installed	In Service	Retired
1930	789	789	0
1931	348	348	0
1933	36	36	0
1935	132	132	0
1936	6,085	6,085	0
1937	2,113	2,113	0
1938	1,373	1,373	0
1939	3,160	3,160	0
1940	4,657	4,657	0
TOTAL	18,693	18,693	0

I

T

In

To

2-

Ye

Inst 18 18.

> 18 180 180

Year		Feet	
Installed	Installed	In Service	Retired
1931	50	50	0
1937	1,405	1,405	0
1939	41	41	0
1940	559	559	0
TOTAL	2,061	2,061	0

4-IN, GALVANIZED STEEL MAINS

Year		Feet	
Installed	Installed	In Service	Retire
1923	88	88	0
1924	261	261	0
1940	0	0	0
TOTAL	349	349	0

1-IN. GALVANIZED STEEL MAINS

Year		Feet	
Installed	Installed	In Service	Retired
1924	266	266	0
1940	0	0	0
TOTAL	266	266	0

14-IN. GALVANIZED STEEL MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1923	153	153	0		
1924	1,127	654	473		
TOTAL	1,280	807	473		
Year	Retiremen	ats by Years			
W D.CO.					

2-IN. GALVANIZED STEEL MAINS

Year

1936

Feet

473

Installed

1924

Feet		
Installed	In Service	Retired
276	276	0
173	173	0
821	821	0
4,717	4,717	0
385	385	0
2,938	2,938	0
810	810	0
	276 173 821 4,717 385 2,938	Installed In Service 276 276 173 173 821 821 4,717 4,717 385 385 2,938 2,938

12-in. Cast-Iron Cement-Lined Mains | 2-in. Galvanized Steel Mains (contd.)

Year		Feet	
Installed	Installed	In Service	Retired
1928	765	765	0
1929	1,363	0	1,363
1940	0	0	0
TOTAL	12,248	10,885	1,363
Year	Retiremen	nts by Years	
Installed	Feet	Year	
1929	1,363	1936	

21-IN. GALVANIZED STEEL MAINS

Year	Feet		
Installed	Installed	In Service	Retired
1921	258	0	258
1926	1,115	1,115	0
1940	0	0	0
TOTAL	1,373	1,115	258
	Retiremen	ats by Years	
Year			
Installed	Feet	Year	
1921	258	1935	

3-IN. GALVANIZED STEEL MAINS

Year	Feet		
Installed	Installed	In Service	Ketired
1924	508	508	0
1927	952	952	0
1929	189	189	0
1940	0	0	0
TOTAL	1,649	1,649	0

4-IN. GALVANIZED STEEL MAINS

Year	Feet			
Installed	Installed	In Se	ervice	Retire
1913	1,222		0	1,222
1924	3,027	1,	573	1,454
1940	0		0	0
TOTAL	4,249	1,	573	2,676
Year	Retireme	ents by Y	ears	
Installed	Feet	Year	Feet	Year
1913	1,222	1928		
1924	145	1936	1,309	1939

V ol. 37	
ntd.)	

1	Retire
	0
1	,363
	0
	-

1,363

S
Ketire
258
0

0
258

5	
Ret	ire
	0
	0
	-

0
0
0
-
0

Retire
1,222
1,454
0

Ye	ear

2,676

	1	0	12	Ġ
	3	3	IJ	7

1-IN.	LEAD	MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1923	16	16	0		
1940	0	0	0		
	-	-	-		
TOTAL	16	16	0		

12-IN. LEAD MAINS

Year	Feet			
Installed	Installed	In Service	Retired	
1926	18	18	0	
1940	0	0	0	
		-	-	
TOTAL	18	18	0	

14-IN. GALVANIZED WROUGHT-IRON MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1852	100	0	100		
1853	400	0	400		
1859	1,200	0	1,200		
1924	890	740	150		
1925	445	445	0		
1927	96	96	0		
1940	0	0	0		
TOTAL	3,131	1,281	1,850		

Retirements by Venes

Year	Ke	ettreme	nts by	rears		
Installed	Feet	Year	Feet	Year	Feet	Year
1852	100	1880				
1853	400	1893				
1859	425	1871	375	1877	400	1885
1924	150	1937				

2-IN. GALVANIZED WROUGHT-IRON MAINS

Year		Feet	
Installed	Installed	In Service	Retired
1852	650	0	650
1853	725	0	725
1860	2,150	0	2,150
1866	444	0	444
1867	1,522	0	1,522

2-IN. GALVANIZED WROUGHT-IRON MAINS (contd.)

Year	Feet			
Installed	Installed	In Service	Retired	
1868	768	0	768	
1869	243	0	243	
1871	111	0	111	
1925	2,753	2,753	0	
1940	0	0	0	
TOTAL	9,366	2,753	6,613	

	Ret	iremen	ts by	Years		
Year Installed	Feet	Year	Feet	Year	Feet	Year
1852	650	1875				
1853	725	1884				
1860	1,200	1885	950	1890		
1866	198	1880	246	1893		
1867	450	1880	186	1893	436	1894
	450	1895				
1868	207	1882	205	1888	158	1892
	198	1896				
1869	243	1896				
1871	111	1896				

21-IN. GALVANIZED WROUGHT-IRON MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1866	600	0	600		
1940	0	0	0		
TOTAL	600	0	600		
Year	Retiremen	sts by Years			
Installed	Feet	Year			

3-IN. GALVANIZED WROUGHT-IRON MAINS

1886

600

1866

Year	Feet				
Installed	Installed	In Service	Retired		
1925	1,643	1,643	0		
1940	0	0	0		
TOTAL	1,643	1,643	0		

VALVES

			VA	LVES			
1-IN. VALVES				4-IN. VALVES (contd.)			
Year		Number		Year		Number	
Installed	Installed	In Service	Ketired	Installed	Installed	In Service	Ketire
1926	4	4	0	1875	1	1	0
1930	0	0	0	1878	2	2	0
	_	-	-	1880	3	3	0
TOTAL	4	4	0	1881	1	1	0
				1884	2	2	0
	2	**		1885	2	2	0
2-IN. VALVES				1886	1	1	0
Year		Number		1887	2	2	0
Installed	Installed	In Service	Retired	1888	3	3	0
1912	1	1	0	1889	3	3	0
1918	î	i	0	1891	3	3	0
1925	13	13	0	1892	1	1	0
1926	3	3	0	1893	4	4	0
1926	5	5	0	1894	6	6	0
1927	2	2	0	1895	3	3	0
1928	0	0	0	1896	2	2	0
1930	_		-	1897	9	9	0
SUBTOTAL	25	25	0	1898	7	7	0
Unknown	25	25	- 0	1899	12	12	0
Unknown	20	20		1900	1	1	0
TOTAL	50	50	0	1901	1	1	0
TOTAL	30	30		1902	1	1	0
				1903	1	1	0
	2½-IN.	VALVES	1	1904	1	1	0
Year		Number		1905	3	3	0
			22.45.4	1906	2	2	0
Installed	Installed	In Service	Retired	1907	14	14	0
1926	1	1	0	1908	12	12	0
1930	0	0	0	1909	2	2	0
	abbrest	-	-	1910	2	2	0
TOTAL	1	1	0	1911	6	6 -	0
				1912	3	3	0
	9 700 1			1913	6	6	0
3-IN. VALVES				1914	2	2	0
Year		Number		1917	1	1	0
Installed	Installed	In Service	Retired	1918	2	2	0
		In Service	0	1920	1	1	0
1925	5	-		1926	2	2	0
1930	0	0	0	1927	1	1	0
	5	5	0	1930	2	2	0
FOTAL	3	3	U		-		
				SUBTOTAL	156	154	2
4-IN. VALVES				Unknown	68	68	0
Year		Number		TOTAL	224	222	2
nstalled	Installed	In Service	Ketired				
1852	20	18	2		Retirements	by Years	
	1	18	0	Year	******	0,7	
	1	A.	U		37. 1	17	
1869 1870	1	1	0	Installed	Number	Year	

6-IN. VALVES

	O-IN. V	ALVES	
Year		Number	
Installed	Installed	In Service	Kettred
1852	14	13	1
1876	1	1	0
1878	1	1	0
1879	1	1	0
1882	1	1	0
1885	1	1	0
1886	2	. 2	0
1888	3	3	0
1892	4	4	0
1893	1	1	0
1896	2	2	0
1897	21	21	0
1898	4	4	0
1899	2	2	0
1902	1	1	0
1903	6	6	0
1904	3	3	0
1905	1	1	0
1906	3	3	0
1907	4	4	0
1908	5	5	0
1910	2	2	0
1911	1	1	0
1912	1	1	0
1913	6	6	0
1914	9	9	0
1915	8	8	0
1916	5	5	0
1917	1	1	0
1918	5	5	0
1920	1	1	0
1921	3	3	0
1923	1	1	0
1926	6	6	0
1927	23	23	0
1928	21	21	0
1929	6	6	0
1930	2	2	0
SUBTOTAL	182	181	1
Unknown	132	132	0
	132	102	
TOTAL	314	313	1
Venn	Retirements b	y Years	
Year Installed	Number	Year	
4000			

8-IN. VALVES

Year		Number				
Installed	Installed	In Service	Retired			
1852	8	8	0			
1870	2	2	0			
1897	2	2	0 :			
1898	5	5	0			
1905	1	1	0			
1906	1	1	0			
1912	1	1	0			
1916	4	4	0			
1919	2	2	0			
1926	5	5	0			
1927	18	18	0			
1930	0	0	0			
	-					
SUBTOTAL	49	49	0			
Unknown	9	9	0			
TOTAL	58	58	0			

10-IN. VALVES

	10 1111	4 1 EM 4 EM			
Year	Number				
Installed	Installed	In Service	Retired		
1852	3	3	0		
1885	7	7	0		
1906	1	1	0		
1927	8	8	0		
1928	17	17	0		
1930	0	0	0		
		-	-		
SUBTOTAL	36	36	0		
Unknown	5	5	0		
	_	MANAGER	_		
TOTAL	41	41	0		

12-IN. VALVES

Year	Number				
Installed	Installed	In Service	Ketired		
1885	3	3	0		
1897	3	3	0		
1906	2	2	0		
1908	1	1	0		
1911	2	2	0		
1923	1	1	0		
1926	1	1	0		
1927	2	2	0		
1928	3	3	0		

12-in. Valves (contd.)

Year	Number				
Installed	Installed	In Service	Retired		
1930	0	0	0		
		-			
SUBTOTAL	18	18	0		
Unknown	8	8	0		
	-	-			
TOTAL	26	26	0		

16-IN. VALVES

		* **** * ****			
Year	Number				
Installed	Installed	In Service	Retired		
1885	3	3	0		
1897	2	2	0		
1930	0	0	. 0		
			-		

16-IN. VALVES (contd.)

Year	Number				
Installed	Installed	In Service	Retired		
SUBTOTAL	5	5	0		
Unknown	1	1	0		

TOTAL	6	6	0		

20-IN. VALVES

	40 4111				
Year	Number				
Installed	Installed	In Service	Retired		
1885	2	2	0		
1906	1	1	0		
1930	0	0	0		
			-		
TOTAL	3	3	0		

1 ni ni of for leg

mi adi res cor the fac Tu and

of t T dist ated bein peg, is th and

Tra

cente ing e work ment locat ence At

cent

40,47 withi the c within mgd.

ol. 37

Retired 0 0

Retired 0 0 0

Winnipeg, Manitoba—Survival and Retirement Experience With Water Works Facilities

As of December 31, 1942

THE Greater Winnipeg Water Dis-1 trict represents the group of municipalities centered in the city of Winnipeg, located in the south central part of the Province of Manitoba. It was formed through incorporation by the legislature and is managed by a commission under the jurisdiction of an administration board composed of representatives from the municipalities concerned. These communities include the cities of Winnipeg and St. Boniface; the municipalities of St. James, Tuxedo, Fort Garry, St. Vital, East and West Kildonan; and the town of Transcona. The aggregate population of this area is approximately 260,000.

This report is confined to studies of distribution facilities owned and operated by the city of Winnipeg. Besides being the capital of Manitoba, Winnipeg, the fourth largest Canadian city, is the urban center of central Canada and is the retail, wholesale and trading center of the area. It is also a railroad center and has important manufacturing establishments represented in woodworking, clothing, iron, farm implements and packing plants. The city is located on level terrain at the confluence of the Red and Assiniboine rivers.

At the date of the study there were 40,471 consumers receiving service within the city. Water purchased by the city from the district and used within its service area averaged 16.4 mgd. (Imperial gallons are used

throughout), serving 227,000 people, or about 72.3 gpd. per capita.

Development of the Existing System

The original water facilities serving Winnipeg secured their supply from the Assiniboine River. These works were constructed by a private company and so operated from about 1882 to 1899 when they were purchased by the city. The city in 1912 joined with the surrounding municipalities in promoting the formation of the Greater Winnipeg Water District, which developed the existing supply and furnishes water in bulk to the several communities by meter measurement.

About the time of the purchase of the privately-operated works the development of a well supply was started and from 1901 to the commencement of operation of the district supply system in 1919 the entire supply for the city was obtained from wells.

The present supply is secured from Shoal Lake located about 95 mi. east of the city and flows by gravity through a concrete aqueduct to the city. The district supplies water in bulk, under low pressure, from the aqueduct to the city of Winnipeg, which, upon receipt of the water at the reservoirs, assumes control of its storage, treatment, pumping and distribution, the latter functions being carried out under the direction of the city engineer. The city in turn provides treated water under serv-

TABLE 1 SUMMARY OF MAINS WINNIPEG, MANITOBA

Size,	Kind	No. of Feet Installed	Percent- age of Total	No. of Feet Retired	Percent- age of Total	No. of Feet in Service	Percent- age of Total	Year of First Instal- lation	Averag Age, 3r.
3)		199	0.01	0	0	199	0.01	1942	0.5
4		195,136	10.93	58,955	48.89	136,181	8.18	1882	40.9
5		14,775	0.83	9,005	7.47	5,770	0.35	1883	54.4
6		951,972	53.30	26,475	21.96	925,497	55.58	1882	32.7
8		244,035	13.66	20,856	17.29	223,179	13.40	1882	27.7
10	Cast-iron	164,306	9.19	532	0.44	163,774	9.84	1882	31.4
12	unlined	94,684	5.30	3,458	2.87	91,226	5.48	1882	28.5
14		40,268	2.25	45	0.04	40,223	2.42	1889	33.6
16		18,868	1.06	0	0	18,868	1.13	1899	36.9
18		39,750	2.26	1,113	0.92	38,637	2.32	1899	26.5
20		4,200	0.23	148	0.12	4,052	0.24	1899	41.6
24		11	0.00	0	0	11	0.00	1919	23.5
1	Cast-iron								
10	flexible	839	0.05	0	0	839	0.05	1904	36.0
12	joint unlined	782	0.04	0	0	782	0.05	1925	17.5
18	Cast-iron victaulic unlined	113	0.01	0	0	113	0.01	1939	3.5
6		571	0.02	0	0	571	0.03	1940	2.5
10	Asbestos-	8,854	0.50	0	0	8,854	0.53	1937	4.0
14	cement	431	0.02	0	0	431	0.03	1932	10.5
18		859	0.05	0	0	859	0.05	1932	9.6
24	Concrete	3,899	0.22	0	0	3,899	0.23	1938	4.5
36	Steel, concrete covered	1,200	0.07	0	0	1,200	0.07	1919	23.5
Тот	AL	1,785,752	100.00	120,587	100.00	1,665,165	100.00		32.3
Percen	atage of	100.00		6.75		93.25			
lverag	ge Size, in.	7.44		5.61		7.54			

Fi

10 a

ice Eas

Gartow Brosuppendo to the of Topum citiz St. under palit

Mortality Survival Ratios

Size, in.	Kind	No. of Feet	Period Covered, yr.	Percentage
3-5		210,110	60.5	36.572
16		951,972	60.5	68.606
F8 }	Cast-iron unlined	244,035	60.5	17.914
10-12		258,990	60.5	97.800
Over 12		103,097	53.5	97.997
6-18	Asbestos-cement	10,715	10.5	100.000
10-18	Cast-iron flexible and victaulic	1,734	38.5	100.000
24	Concrete	3,899	4.5	100.000
36	Steel, concrete covered	1,200	23.5	100.000
TOTAL		1,785,752		

verage

Age. yr. 0.5 40.9 54.4

32.7

27.7

28.5

33.6 36.9 26.5 41.6 23.5 36.0 17.5

3.5

2.5

4.0

10.5

9.6 4.5 23.5

32.3

centage

6.572

8.606

7.914

7.997

000.00

000.00

000.00

00.000





Fig. 1. Mortality Survival Curve—3-24-in. Cast-Iron Unlined Mains— Winnipeg, Manitoba

Base: Feet	Survival.: 1882-1942			
SIZE in.	Exposures ft.	RETIREMENTS ft.		
3-5	210,110	67,960		
6 8	951,972 244,035	26,475 20,856		
10 and 12	258,990	3,990		
Over 12	103,097	1,306		

ice pressures to the municipalities of East Kildonan, West Kildonan, Fort Garry, St. James, Charleswood, the town of Tuxedo, and the village of Brooklands. Water in bulk is also supplied by the district, through independent connections to the aqueduct, to the city of St. Boniface and the town of Transcona, which also store, treat, pump and distribute the water to the citizens resident in these municipalities. St. Boniface in turn provides water under service pressure to the municipality of St. Vital.



BASE: Unit		Survival: 1899-1942		
Size in.	KIND	Exposures Units	RETIREMENTS Units	
A.	Disc	2,056	1,132	
4	Piston	37,646	1,401	
1-3	Disc	262	92	
3-4	Piston	2,955	58	
2-6	Other	112	7	

The Shoal Lake supply was first considered in 1912 but preliminary work over the several following years, including the building of a standard gage railroad along the line of the aqueduct, was required before actual construction could be started in 1915. Water was turned into the system in April 1919.

Shoal Lake is an arm of the Lake of the Woods, the geography of which is international and is situated about 95 mi. east of and 300 ft. in elevation above the city. Shoal Lake has a drainage area of about 360 sq.mi., with

pi ta

Pero

TABLE 2 SUMMARY OF METERS WINNIPEG, MANITOBA

Size,	Kind	Number Installed	Number Identified	Number Retired	Number in Service	Average Age, 37
£)		2,099	2,056	1,132	924	17.4
8 3 4		54	51	9	42	1.5
1		136	117	35	82	15.5
11	Disc	54	30	8	22	8.7
2		59	56	35	21	13.6
2 3		9	8	5	3	22.2
		37,937	37,646	1,401	36,245	29.0
5 8 3 4		1,695	1,662	27	1,635	33.8
1		756	743	13	730	30.9
11	Piston	322	322	6	316	24.7
2	1 15101.	215	214	11	203	25.5
2 3		13	12	1	11	32.9
4	1	2	2	0	2	30.5
2		4	4	4	0	******
3		19	18	2	16 .	32.1
3 4	Current	8	7	1	6	26.8
6		1	1	0	1	16.5
6 3		55	55	0	55	17.0
4	Compound	23	23	0	23	16.2
6	Compound	4	4	0	4	15.8
Total		43,465	43,031	2,690	40,341	28.8
rcentag	ge of Total		100.0	6.25	93.75	

Mortality Survival Ratios

Size, in.	Kind	Number	Period Covered, yr.	Percentag
1	Disc	2,056	36.5	26.810
i	Piston	37,646	43.5	94.954
3-3	Disc	262	31.5	36.221
1-4	Piston	2,955	43.5	97.369
2-6	Other	112	39.5	84.976
TOTAL		43,031		

a water area of 107 sq.mi., and, with the Lake of the Woods, constitutes a supply which may be said to be virtually inexhaustible.

The intake at Shoal Lake is a concrete chamber with trash racks, screens and stop logs for control. The aqueduct, 96.5 mi. in total length from the

lake to a point about 16 mi. east of the city's reservoir, consists of arch gravity sections varying from 6 ft. $4\frac{3}{4}$ in. by 5 ft. $4\frac{3}{4}$ in. to 10 ft. 9 in. by 9 ft., depending on the slope. Its designed capacity was 85 mgd. but tests subsequently made indicate that its actual capacity is about 100 mgd.

1073

From the end of the gravity section, 16 mi. east of the city, the conduit continues as an 8-ft. reinforced concrete pipe of equivalent capacity for a distance of 4 mi. to a proposed reservoir site at Deacon. Continuing 9.3 mi. to the Red River the reinforced concrete pipe is 66 in. in diameter, with a capacity of 52 mgd., and thence continues

2.4 mi. as a 48-in. pipe, having a capacity of 30 mgd. to the reservoirs. When consumption requirements dictate, booster pumping is proposed at the Red River crossing.

The Greater Winnipeg Water District's 48-in. main terminates in reservoirs located within the city from which the supply is pumped by the city with-

TABLE 3
SUMMARY OF SERVICES
WINNIPEG, MANITOBA

Size.	Kind	No. of Feet Installed	No. of Feet Identified	No. of Feet Retired	No. of Feet in Service	Average Age, yr.
1		259	156	156	0	
i		33	33	33	0	
1	Galvanized-	2,123	1,490	1,490	0	
1	iron	655	399	399	0	
11		28	0	0	0	
11		132	98	98	0	
1		6,017	5,190	5,190	0	
5		112	112	112	0	
3 4		19,186	17,139	17,139	0	
1		4,109	2,944	2,944	0	
11	Wrought-iron	163	163	163	0	
14		286	266	266	0	
2		651	605	605	0	
21		123	66	66	0	
3		153	153	153	0	
1		657,933	655,752	101,050	554,702	29.8
1		260,603	259,905	39,445	220,460	32.8
1	Lead	109,297	107,737	21,166	86,571	28.7
1	Leau	51,411	51,054	5,754	45,300	28.5
14		122	122	18	104	32.5
2		421	421	77	344	24.6
1		77,625	77,556	652	76,904	12.3
1		17,765	17,659	132	17,527	12.0
3		93,975	93,901	407	93,494	4.8
)	Copper	14,832	14,832	304	14,528	8.0
I A		344	344	0	344	2.5
1		593	593	0	593	5.0
!		2,313	2,313	0	2,313	10.2
3		460	460	185	275	42.4
1	Cast-iron	11,684	11,674	413	11,261	28.9
5	Cast-IIOII	7,243	7,243	55	7,188	19.7
3		739	739	0	739	16.9
TAL		1,341,390	1,331,119	198,472	1,132,647	26.3
entag	e of Total		100.00	14.67	85.33	

7.4 1.5 5.5 8.7

3.6 2.2 9.0 3.8 0.9

4.7 15.5 12.9 10.5

6.8 6.5 7.0 6.2 5.8

8.8

tage

of the gravity in. by ft., de-

esigned s subactual

wh

and

fire

SVS

to 1

boo

sur

Th

as :

the

331

ame

high

Clas

with

7 ft.

and

pipe

sma

iron

which

cast-

1927

T

7

TABLE 3 (contd.) Mortality Survival Ratios

Size, in.	Kind	No. of Feet	Period Covered, yr.	Percentage
$\left.\begin{array}{c} \frac{1}{2} - \frac{3}{4} \\ 1 - 3 \end{array}\right\}$	Galvanized-iron and Wrought-iron	24,120	38.5	0.000
1-3		4,694 655,752	34.5 48.5	0.000 63.600
5 Lea		259,905	47.5	72.638
	Lead	107,737	48.5	60.416
1-2		51,597	47.5	82.697
3 1	Connor	93,901	15.5	98.322
$-2 \left(\text{excl.} \frac{3}{4} \right) $	Copper	113,297	17.5	98.870
3-8	Cast-iron	20,116	55.5	91.934
TOTAL		1,331,119		




Fig. 3. Mortality Survival Curve—1-2-in. Lead Services-Winnipeg, Manitoba

BASE: Feet	SURVIV	AL: 1894-1942
Size	EXPOSURES	RETIREMENTS
in.	ft.	ft.
1	655,752	101,050
5 8	259,905	39,441
3	107,737	21,166
1-2	51 507	5 849

out treatment other than algal control and ammonia and chlorination to the distribution system. The original covered concrete reservoir of 6-mil.gal. capacity was built in 1906 and abandoned in 1929. There are two reservoirs now in service; one, a concrete covered reservoir of 18-mil.gal. capacity, was constructed in 1913, and the other, an open concrete 40-mil.gal reservoir was constructed in 1930.

The existing high-lift pumping station, constructed in 1930, replaced a steam turbo-generated electric station constructed in 1901. Pumping equipment consists of six motor-driven centrifugal pumps having a total rated apacity of 45 mgd. Power is secured chiefly from the city's hydro-electric system but standby connections are maintained with several private sources

In addition the city operates a auxiliary electric power and central steam heating plant adjacent to the pumping station which can furnish power in emergencies.

The normal pressure maintained the pumping station is about 75 ps. In addition to the normal water distribution system the city has a separate The entage

000 .000 .600 .638 .416 697 3.322 3.870 .934

control to the al covnil.gal.

aban-

reser-

ncrete

capac-

nd the

mil.gal

ng sta-

aced a

station

equip-

en cen-

ted ca-

secured

electric

ns are

ources.

tes an

centra

to the

furnish

75 psi

er dis

eparate

30.

TABLE 4

CAUSES OF RETIREMENTS OF CAST-IRON UNLINED MAINS WINNIPEG, MANITOBA

Size, in.		Cause of Retirement—Percente						
	Feet Retired	Wear and Tear	Inadequacy	Obsolescence	Action of Public Authority			
4	58,955	83.2	0.7	13.7	12.4			
5	9,005	100.0						
6	26,475	61.8	3.7	14.2	20.3			
8	20,856	74.0	1.4	18.0	6.6			
10	532	9.2		66.4	24.4			
12	3,458			21.0	79.0			
14	45				100.0			
18	1,113				100.0			
20	148				100.0			
TOTAL	120,587	74.6	1.4	13.8	10.2			

fire service system started in 1908 which serves the principal mercantile and industrial areas and is used for fire protection purposes only. system has an independent connection to the Shoal Lake conduit and, through booster pumping, maintains a pressure of about 75 psi. in the fire mains. This in turn can be raised to as high as 300 lb. when required.

The main distribution system within the city consists of approximately 331.13 mi, of mains 3 to 36 in, in diameter (inclusive of 12.8 mi. in the high-pressure system), predominantly Class C, pit-cast, tar-coated pipe laid with lead joints with a cover of about 7 ft. Equivalent class asbestos-cement and bolted-joint "Universal" cast-iron pipe has lately been used. Only a small amount of centrifugally-cast castiron pipe has been used.

There are 40,794 service connections ined at which, with the exception of the larger cast-iron services and recent (since 1927) copper installations, are of lead. The city's system has 5,375 valves.

2,737 hydrants and 40,471 meters as of the date of the study. Active services are about 100 per cent metered, and these meters account for approximately 80 per cent of the total amount of water purchased.

Basis of Study

The records of installation and retirement of pipe, in the form of field books, are substantially complete from the original date of construction in 1882 to date.

The records of meters are substantially complete from 1899 to date and of services from 1882 to date. Class B facilities are not included in this study.

Mortality Survival Study

Mortality studies of mains, meters and services were made. Table 1 is a summary of the pipe installed, the amount retired and that still in service, as well as other pertinent data relative thereto. Figure 1 shows the mortality survival curves covering the rec-

Tor

tirem

made Walte

missi

Distri

tee or




FIG. 4.—Mortality Survival Curve—½-8-in.
Services Other Than Lead—
Winnipeg, Manitoba

BASE: Feet Survival: 1884-1942

Size in.	KIND	EXPO- SURES ft.	RETIRE- ments ft.
1-1	Galvanized-Iron and Wrought-Iron	24,120	24,120
1-3	Galvanized-Iron and Wrought-Iron	4,694	4,694
3	Copper	93,901	407
1-2	Copper*	113,297	1,096
3-8	Cast-Iron	20,116	653

* Excluding 1-in.

ord of the amount and sizes of pipe grouped as shown.

Tables 2 and 3 are similar summaries of meters and services and Figs. 2, 3 and 4 present the applicable mortality survival curves.

Causes of Retirement

The causes of retirement of mains have been determined and classified

under four general divisions as shown in Table 4. Of the total retirements of water mains 74.6 per cent were caused by wear and tear, 1.4 per cent by inadequacy, 13.8 per cent by obsolescence and 10.2 per cent by the action of pub-Two major factors lic authorities. have been influential in causing retire. ment of pipe because of wear and tear The character of the soil in the Red River Valley has had much to do with the disintegration of pipe material The soil contains certain soluble salts. including sulfates of sodium, magnesium and calcium. As a result, disintegration of the pipe has been relatively

The other major factor causing disintegration of pipe material has been electrolysis. Experts investigated this influence in 1906, 1909 and 1915, and concluded that electrolysis was particularly active in Winnipeg and a considerable number of retirements of pipe have been caused by its action.

While an analysis of the causes of retirement of meters has not been made, the retirement of large numbers of disc meters has been the result of standardization on the piston type meter. Further, in repairing meters, whenever a new upper or lower casing is renewed the original meter is considered retired, although a major part of such meter may remain in service.

Spot checks were made to determine the cause of retirement of $\frac{1}{2}$ -1-in. lead services by analyzing the retirements made at six-year intervals. Table 5 shows the results of the analysis with the retirements separated into five classifications.

Acknowledgments

The collection and compilation of data relative to the installation and re-

Vol. 37

shown

ents of

by inescence of pubfactors retired tear. e Red o with aterial. e salts, magnedisinatively

ng diss been ed this 5, and s parand a ents of tion. ises of made. of disc ndardmeter. whensing is considpart of ce. ermine n. lead ements able 5 is with o five

tion 0

and re

TABLE 5
CAUSES OF RETIREMENT OF LEAD SERVICES
WINNIPEG, MANITOBA

	I	1		1120, 1417				1	1
				No. of Feet	Retired			Total	Percen
Size,	Cause of Retirement		Installed in Year					No. of Feet Retired	age of Total
		1894	1900	1906	1912	1918	1924		
1	Not used Inadequate Street paving	835 160	828 290 92	3,060 1,439 28	414 154 186	16 28	34	5,187 2,071 306	21.6 8.7 1.2
	Corrosion Other	1,277 163	5,050 178	6,720 55	2,491 138	192 46	182	15,912 580	66.1
	TOTAL	2,435	6,438	11,302	3,382	282	216	24,056	100.0
5)8	Not used Inadequate Street paving Corrosion		425 106 941	1,620 166 168 2,829	192 14 1,460		14	2,251 272 182 5,230	27.5 3.3 2.2 63.8
	Other		131	104	24			259	3.2
	TOTAL		1,603	4,887	1,690		14	8,194	100.0
34	Not used Inadequate Street paving Corrosion Other	173 15 466 126	330 398 151	824 168 17 435	192 14 1,187	102	84 46 52 42	1,705 229 83 2,486 319	35.4 4.7 1.8 51.5 6.6
	TOTAL	780	879	1,444	1,393	102	224	4,822	100.0
1	Not used Inadequate Street paving Corrosion			109 28 251	90 84 146 190	163	264	686 112 146 633	43.5 7.1 9.3 40.1
	Total			448	510	206	413	1,577	100.0
OTAL	—Not used Inadequate	1,008	1,583 396	5,673 1,801	888 238	281	396 46	9,829 2,684	25.4 7.0
	Street paving Corrosion Other	1,743 289	92 6,389 460	213 10,235 159	360 5,328 162	235	52 331 42	717 24,261 1,158	1.9 62.7 3.0
	TOTAL	3,215	8,920	18,081	6,976	590	867	38,649	100.0

tirement of facilities in Winnipeg were made under the general direction of Walter M. Scott, Chairman of Commissioners, Greater Winnipeg Water District, and a member of the Committee on Survival and Retirement Ex-

perience With Water Works Facilities. H. Shand, Engineer of the Winnipeg Water District, and W. D. Hurst, City Engineer (at the time of the study. Engineer of Water Works), were in charge of abstracting the records.

SUMMARY OF INSTALLATIONS AND RETIREMENTS WINNIPEG, MANITOBA

MAINS

Year

41 1929

3-IN	. CAST-IRO	N UNLINED MA	AINS
Year		Feet	
Installed	Installed	In Service	Retired
1942	199	199	0
TOTAL	199	199	0

Year		Feet	
Installed	Installed	In Service	Retired
1882	2,021	634	1,387
1883	3,606	935	2,671
1884	8,105	3,587	4,518
1885	2,782	852	1,930
1886	312	312	0
1887	4,375	634	3,741
1888	13,276	3,642	9,634
1889	6,835	3,872	2,963
1890	1,790	609	1,181
1891	2,495	745	1,750
1892	-2,427	352	2,075
1893	1,788	495	1,293
1894	2,287	0	2,287
1895	261	261	0
1899	18,065	11,421	6,644
1900	36,228	31,496	4,732
1901	7,643	5,777	1.866
1902	5,990	5,207	783
1903	7,187	6,152	1,035
1904	16,134	13,984	2,150
1905	32,546	28,501	4,045
1906	4,009	3,136	873
1907	6,375	5,097	1,278
1908	1,479	1,401	78
1909	1.046	1,046	0
1910	832	832	0
1912	219	219	0
1913	1,081	1,040	41
1914	212	212	0
1919	12	12	0
1923	610	610	0
1924	1,037	1,037	0
1925	1,047	1,047	0
1927	51	51	0
1929	11	11	0
1936	62	62	0
1939	25	25	0

red	Retir	K		Service	In	stalled	d In	Installe
	0			666		666		1941
	0			209		209		1942
5	,955	8,	58	6,181	13	5,136	19	TOTAL
				Years	ents by	etirem	R	
	77		P	Vann	Fact	Voar	I Fact	Year Installe
38	193	4	64	1924	1,204		39	1882
				1000	4 204	1939		4002
		_	(m. m	1939	1,201	1924	1,470	1883
11	191	2	772	1909	507	1906	04	1884
	193		252	1924	2,294	1923		100#
30	193	0	1,240	1911	20	1907		1885
				1021	2.060		570	100*
17	192	3		1924	, , , , ,	1912		1887
				1911		1907	222	1888
			1,880			1924		
9	1939	3	1,088	1934	400	1930		
						1940		
3	1923	2	502	1922	1,662			1889
						1924		
						1938		1890
9	1929)	170	1923	633			1891
1						1936	7	
	1930			1923			1,329	1892
1	1939)	950	1923		1922		1893
ı				1939				1894
4	1924		247	1922	1,757	1915	253	1899
1	1937	,	58	1933	1,170			
ı							2,647	
ı	1924		1,177		1,795			1900
ı	1936	1	46		618			
ı					173	1939		
ı					945	1935		1901
	1939			1935		1929		1902
ı	1935	1	65	1928	342	1923		1903
ı						1939		
ı	1930	1	332	1926		1910		1904
I					1,058			
ı	1930	1	441	1922		1913		1905
ı					2,982			
ı			190		619	1923		1906
ı	1937	1	15	1936	330	1909		1907
ı							923	
				1937	58	1913	20	1908

4-IN. CAST-IRON UNLINED MAINS (contd.)

Feet

2 1930

5-IN. CAST-IRON UNLINED MAINS

Year	Feet				Retires	nents by 1	Years	
Isstalled 1883 1886 1887 1888 1889 1891 1893 1942 Total	Installed 1,790 1,677 4,143 1,959 2,819 1,737 650 0	In Service 0 1,677 953 1,959 0 531 650 0 5,770	Retired 1,790 0 3,190 0 2,819 1,206 0 9,005	Year Installed 1883 1887 1889 1891	Feet 1,790 1,637 1,729 1,206	Year 1924 1927 1922 1939	Feet 1,553 1,090	Year 1939 1939

6-IN. CAST-IRON UNLINED MAINS

	1			0-1N.	CASI-IRON	UNLINED I	CALAIN		
	Year	Year		Feet		Year		Feet	
14	1938	Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
		1882	10,814	9,075	1,739	1916	2,957	2,957	0
20	1011	1883	2,610	2,045	565	1917	2,495	2,495	0
2	1911	1884	436	0	436	1918	320	309	11
0	1936	1887	1,152	663	489	1919	6,932	6,766	166
0	1930	1888	8,808	7,486	1,322	1920	5,409	5,409	0
	1022	1889	978	329	649	1921	7,900	7,900	0
	1927	1890	1,827	48	1,779	1922	13,553	13,553	0
	1923 1929 3 1939	1891	1,869	1,542	327	1923	16,597	16,028	569
		1892	1,368	330	1,038	1924	16,526	16,526	0
00		1895	114	114	0	1925	4,418	4,418	0
10	1001	1896	360	360	0	1926	4,465	4,335	130
12	1923	1899	44,696	39,114	5,582	1927	4,146	4,146	0
		1900	24,142	22,731	1,411	1928	3,840	3,840	0
	1929	1901	25,687	24,064	1,623	1929	13,677	13,677	0
0	1929	1902	38,074	37,237	837	1930	6,532	6,484	48
	1020	1903	23,549	21,079	2,470	1931	4,154	4,154	0
	1930	1904	38,737	37,625	1,112	1932	4,446	4,446	0
00	1939	1905	113,233	112,025	1,208	1933	400	400	0
	1001	1906	59,083	59,083	0	1934	610	610	0
	1924	1907	90,434	88,905	1,529	1935	2,795	2,795	0
18	1937	1908	30,242	30,242	0	1937	237	237	0
-	.00	1909	32,462	31,693	769	1938	513	513	0
	1924	1910	51,334	50,896	438	1939	20,477	20,477	0
0	1936	1911	56,268	56,257	11	1940	1,008	1,008	0
		1912	40,641	40,484	157	1941	7,135	7,135	0
0	1939	1913	55,078	55,078	0	1942	213	213	0
		1914	41,765	41,705	60				
5	1935	1915	4,456	4,456	0	TOTAL	951,972	925,497	26,475

Retirements by Years

	Year			
Year Feel Year Feel	l Year Installed	Feet Year	Feet Year	Feet Year
1939	1888	52 1919	590 1934	148 1938
1924		532 1939		
1939	1889	649 1922		
939	1890	608 1907	150 1929	1,021 1939
	1939	Year Feel Year Feet Year Installed 1939 1888 1924 1889	Year Feet Year Feet Year Installed Feet Year 1939 1888 52 1919 1924 532 1939 1939 1889 649 1922	Year Feet Year Feet Year Installed Feet Year Feet Year 1939 1888 52 1919 590 1934 1939 532 1939 1889 649 1922

I

Ve Inst

6-IN. CAST-IRON UNLINED MAINS (contd.)

Retirements by Years (contd.)

Year							Year						
Installed	l Feet	Year	Feet	Year	Feet	Year	Installed	Feet	Year	Feet	Year	Feet	Year
1891	66	1911	261	1939			1907	1,338	1922	20	1931		1932
1892	888	1935	150	1940				5	1934	86	1936		1939
1899	46	1921	514	1922	23	1927	1909	567	1924	202	1940		-207
	1,305	1929	251	1935	24	1936	1910	80	1931	358	1932		
	3,419	1939					1911	11	1924				
1900	709	1934	702	1939			1912	52	1914	105	1932		
1901	482	1905	619	1910	150	1919	1914	60	1924				
	372	1921					1918	11	1941				
1902	56	1910	304	1932	477	1941	1919	166	1924				
1903	21	1909	1,622	1935	364	1939	1923	569	1940				
	463	1942					1926	130	1939				
1904	650	1911	462	1939			1930	48	1940				
1905	142	1910	70	1913	174	1932							
	12	1933	810	1939									

8-IN. CAST-IRON UNLINED MAINS

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retire
1882	13,119	2,451	10,668	1920	3,033	3,033	0
1883	2,028	0	2,028	1921	4,360	4,360	0
1887	1,492	569	923	1922	809	809	0
1889	3,988	1,266	2,722	1923	1,385	1,385	0
1899	15,342	14,820	522	1924	15,320	15,320	0
1900	11,543	11,310	233	1925	159	159	. 0
1901	2,940	195	2,745	1926	5,868	5,868	0
1902	7,787	7,787	0	1927	5,208	5,208	0
1903	2,282	2,282	0	1928	4,493	4,493	0
1904	6,129	5,792	337	1929	2,281	2,281	0
1905	6,591	6,591	0	1930	8,107	8,107	0
1906	5,936	5,279	657	1931	50	50	0
1907	1,753	1,753	0	1932	5,778	5,778	0
1908	15,152	15,152	0	1935	639	639	0
1909	7,951	7,951	0	1936	13	13	0
1910	10,559	10,548	11	1937	19	19	0
1911	11,216	11,216	0	1939	7,748	7,748	0
1912	14,904	14,894	10	1940	778	778	0
1913	20,390	20,390	0	1941	112	112	0
1914	9.049	9.049	0	1942	0	0	0
1915	1,473	1,473	0				
1916	1,968	1,968	0	TOTAL	244,035	223,179	20,856
1919	4,283	4,283	0				

Retirements by Years

Year Installed	Feet	Year	Feet	Year	Feet	Year	Year Installed	Feet	Year	Feet	Year	Feet	Yes
1882	300	1904	3,634	1923	2,296	1937	1900	225	1921	8	1939		
2002	4,438	1939	,				1901	2,745	1935				
1883	2,028	1924					1904	107	1912	220	1935	10	1936
1887	725	1922	198	1938			1906	285	1911	372	1937		
1889	2,722	1938					1910	11	1937				
1899	425	1904	97	1913			1912	10	1936				

01.37

Year 1932 1939

Retired

0,856

t Yeu

0 1936

10-IN. CAST-IRON UNLINED MAINS

Year		Feet		Year		Fee	et	
Installed	Installed	In Service	Retired	Installed	Installed	In Ser	vice	Retired
1882	905	905	0	1924	1,699	1,6	99	0
1891	2,840	2,507	333	1925	1,099	1,0	99	0
1899	9,477	9,408	69	1926	3,124	3,1	24	0
1900	5,309	5,309	0	1927	1,032	1,0	32	0
1901	2,202	2,202	0	1928	719	7	19	0
1902	7,606	7,606	0	1929	1,586	1,5	86	0
1903	4,286	4,286	0	1930	2,306	2,3	106	0
1904	5,705	5,705	0	1931	3,399	3,3	99	0
1905	10,072	10,072	0	1932	739	7	39	0
1906	5,411	5,411	0	1933	175	1	75	0
1907	8,281	8,281	0	1935	540	5	40	0
1908	10,246	10,246	0	1936	143	1	43	0
1909	1,768	1,768	0	1937	2,298	2,2	98	0
1910	6,055	6,055	0	1938	201	2	01	0
1911	7,899	7.769	130	1939	616	6	16	0
1912	11,899	11,899	0	1942	21		21	0
1913	20,440	20,440	0			-	-	-
1914	7,934	7,934	0	TOTAL	164,306	163,7	74	532
1915	3,829	3,829	0					
1916	1,384	1,384	0		Retireme	nts by Ye	ears	
1917	1,138	1,138	0	Year				
1919	1,106	1,106	0	Installed	Feet	Year	Feet	Year
1920	2,000	2,000	0	1891	333	1926		
1921	283	283	0	1899	20	1919	49	1939
1922	1,180	1,180	0	1911	130	1936	• -	
1923	5,354	5,354	0			3,00		

12-IN. CAST-IRON UNLINED MAINS

Year		Feet		Year		F	eet	
Installed	Installed	In Service	Retired	Installed	Installed	In S	Service	Retired
1882	2,675	0	2,675	1928	280		280	0
1899	5,768	5,684	84	1929	3,393	3	,393	0
1901	2,248	2,248	0	1930	3,146		.146	0
1902	1,577	1,577	0	1931	8		8	0
1903	1,137	1,137	0	1932	2,062	2	,062	0
1904	557	557	0	1935	3,441	3	,441	0
1905	2,110	2,058	52	1938	20		20	0
1906	2,501	2,493	. 8	1939	2,540	2	,540	0
1907	8,176	8,093	83	1940	41		41	0
1908	11,184	11,134	50	1941	157		157	0
1909	7,976	7,887	89	1942	7		7	0
1910	3,282	3,167	115			-		-
1911	2,393	2,165	228	TOTAL	94,684	91	,226	3,458
1912	1,129	1,055	74					
1913	7,266	7,266	0		Retireme	ents by	Years	
1914	5,291	5,291	0	Year				
1915	2,380	2,380	0	Installed	Feet	Year	Feet	Year
1916	736	736	0	1882	170	1901	2,505	1905
1917	1,245	1,245	0	1899	84	1904	2,000	1700
1919	2,083	2,083	0	1905	52	1932		
1920	345	345	0	1906	8	1941		
1921	811	811	0	1907	83	1922		
1922	1,679	1,679	0	1910	115	1918		
1925	3,620	3,620	0	1911	228	1919		
1926	865	865	0	1912	74	1922		
1927	555	555	0	1712		1744		

Year Installed	Installed	In Service	Retired
1889	2,406	2,406	0
1899	6,548	6,548	0
1900	294	294	0
1902	1.718	1,718	0
1903	2,032	2,032	0
1905	6,361	6,316	45
1907	5,795	5,795	0
1908	1,706	1,706	0
1911	2,251	2,251	0
1913	1,259	1,259	0
1914	1,383	1,383	0
1919	44	44	0
1923	2,998	2,998	0
1924	1.241	1.241	0
1929	154	154	0
1930	3,081	3.081	0
1932	9	9	0
1939	934	934	0
1941	54	54	0
1942	0	0	0
TOTAL	40,268	40,223	_
			45
	Retiremen	s by Years	
Year			
Installed	Feet	Year	
1905	45	1919	

16-IN. CAST-IRON UNLINED MAINS

Year		Feet	
Installed	Installed	In Service	Retired
1899	5,126	5,126	0
1902	213	213	0
1905	1,935	1,935	0
1906	2,914	2,914	0
1907	5,872	5,872	0
1908	1,446	1,446	0
1909	772	772	0
1939	590	590	0
1942	0	0	0
TOTAL	18,868	18,868	0

18-IN. CAST-IRON UNLINED MAINS

	Feet						
ed	Installed	In Service	Retired				
	1,863	1,863	0				
	5,236	4,219	1,017				
	6,442	6,346	96				
	579	579	0				
	257	257	0				
		1,863 5,236 6,442 579	ed Installed In Service 1,863 1,863 5,236 4,219 6,442 6,346 579 579				

14-IN. CAST-IRON UNLINED MAINS (contd.)

Year		Fe	eet	
Installed	Installed	In S	Service	Retired
1909	3,380	3,	,380	0
1911	2,081	2,	,081	0
1912	1,000	1,000 1,000		0
1919	7,172	7,	,172	0
1930	11,356	11,	356	0
1932	295		295	0
1938	35		35	0
1939	54		54	0
1942	0		0	0
TOTAL	39,750	38,	637	1,113
	Retirem	ents by Y	lears .	
Year				
Installed	Feet	Year	Feet	Year
1905	847	1910	170	1930
1906	96	1941		

20-in. Cast-Iron Unlined Mains

Year	Feet							
Installed	Installed	In Service	Retired					
1899	4,001	3,853	148					
1919	17	17	0					
1940	182	182	0					
1942	. 0	0	0					
TOTAL	4,200	4,052	148					
	Retiremen	its by Years						
Year Installed	Feet	Year						

24-IN. CAST-IRON UNLINED MAINS

1940

148

1899

21-1	i. Casi-ino	N CHEINED WE	24143			
Year	Feet					
Installed	Installed	In Service	Retire			
1919	11	11	0			
1942	0	0	0			
		_	_			
TOTAL	11	11	0			

6-IN. ASBESTOS-CEMENT MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1940	571	571	0		
1942	0	0	0		
TOTAL	571	571	0		

1 Ins

00

Tot

Inste 19. 19

TOTA

Yea

TOTAL

Year Install 1904 1908

10-11

1942 TOTAL

Year Installe 1900

37

red

0 3

ear 930

18

ired

0

0 0

Year		Feet	
Installed	Installed	In Service	Retired
1937	935	935	0
1938	2,703	2,703	0
1939	5,216	5,216	0
1942	0	0	0
TOTAL	8,854	8,854	0

14-IN. ASBESTOS-CEMENT MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1932	431	431	0		
1942	0	0	0		
TOTAL	431	431	0		

18-IN. ASBESTOS-CEMENT MAINS

Year	Feet					
Installed	Installed	In Service	Retired			
1932	752	752	0			
1959	107	107	0			
1942	0	0	0			
TOTAL	859	859	0			

10-in. Cast-Iron Flexible Joint Mains

Year	Feet				
Installed	Installed	In Service	Retired		
1904	314	314	0		
1908	525	525	0		
1942	0	0	0		
TOTAL	839	839	0		

10-in. Asbestos-Cement Mains 12-in. Cast-Iron Flexible Joint Mains

Year	Feet				
Installed	Installed	In Service	Retired		
1925	782	782	0		
1942	0	0	0		
TOTAL	782	782	0		

18-IN. VICTAULIC UNLINED MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1939	113	113	0		
1942	0	0	0		
TOTAL	113	113	0		

24-IN. CONCRETE MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1938	3,899	3,899	0		
1942	0	0	0		
TOTAL	3,899	3,899	0		

36-IN. STEEL CONCRETE COVERED MAINS

Year	Feet				
Installed	Installed	In Service	Retired		
1919	1,200	1,200	0		
1942	0	0	0		
	Academic Designation	-	-		
TOTAL	1.200	1.200	0		

METERS

5-IN. DISC METERS

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1900	1	0	1	1912	7	1	6
1901	1	0	1	1913	54	3	51
1902	81	0	81	1914	3	0	3
1904	115	0	115	1915	21	. 5	16
1906	203	104	99	1916	14	6	8
1907	6	0	6	1917	4	1	3
1908	4	2	2	1918	7	4	3
1909	999	320	679	1919	7	3	4
1910	3	1	2	1920	10	3	7
1911	2	1	1	1921	6	2	4

I

Su

To

Ins

Sub1 Unki

Тота

Yea Instal

SUBTO Unkno TOTAL

5-IN. DISC METERS (contd.)

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1922	6	1	5	1936	6	6	0
1923	7	3	4	1937	1	1	0
1924	5	2	3	1938	1	1	0
1925	5	2	3	1939	4	4	0
1926	6	3	3	1940	4	4	0
1927	2	1	1	1941	68	68	0
1928	2	0	2	1942	356	356	0
1929	4	0	4			-	-
1930	10	3	7	SUBTOTAL	2,056	924	1,132
1931	1	1	0	Unknown	43	3	40
1933	5	2	3			-	
1934	12	7	5	TOTAL	2,099	927	1,172
1935	3	3	0				-1

					Re	tiremen	ts by Years						
Year	Num-		Num		Num-		Year	Num-		Num-		Num	-
Installed	ber	Year	ber	Year	ber	Year	Installed	ber	Year	ber	Year	ber	Yea
1900	1	1900					1909	37	1940	12	1941	15	194
1901	1	1908					1910	1	1925	1	1936		.,,
1902	1	1904	7	1906	37	1907	1911	1	1922				
	7	1908	12	1909	2	1910	1912	1	1915	1	1918	1	191
	1	1911	1	1912	4	1913		1	1922	1	1923	1	194
	3	1914	2	1915	2	1918	1913	1	1914	14	1915	12	191
	1	1929	1	1930				4	1917	2	1918	2	191
1904	1	1904	2	1905	8	1906		2	1920	2	1922	1	192
	22	1907	7	1908	5	1909		1	1926	1	1928	1	192
	5	1910	4	1911	6	1912		2	1932	1	1933	1	193
	12	1913	13	1914	9	1915		3	1939	1	1941		
	3	1916	5	1917	1	1919	1914	2	1934	1	1935		
	1	1922	1	1926	1	1930	1915	2	1923	1	1926	1	1929
	3	1931	4	1932	1	1933		2	1934	1	1938	9	1940
	1	1935					1916	1	1919	1	1920	1	1924
1906	2	1907	1	1908	2	1909		1	1934	1	1938	3	1939
	3	1910	3	1911	2	1912	1917	1	1931	1	1936	1	1937
	1	1914	2	1915	1	1916	1918	1	1920	1	1934	1	1937
	2	1917	2	1918	4	1919	1919	1	1919	1	1920	1	1928
	3	1920	3	1921	1	1922		1	1940				
	1	1923	1	1924	1	1925	1920	2	1921	1	1924	3	1933
	3	1926	4	1930	5	1931		1	1934				
	6	1932	15	1933	2	1934	1921	1	1925	1	1934	1	1936
	5	1935	7	1936	2	1937		1	1939				
	4	1938	4	1939	5	1940	1922	3	1933	2	1935		
	2	1942					1923	2	1933	1	1937	1	1939
1907	4	1907	1	1908	1	1909	1924	2	1935	1	1940		
1908	1	1913	1	1914			1925	1	1930	1	1932	1	1939
1909	3	1910	1	1911		1912	1926	1	1929	2	1933		
	4	1913	4	1914	8	1915	1927	1	1929				
	15	1916	6	1917	6	1918	1928	1	1933	1	1940		
	5	1919	1	1920	2	1921	1929	2	1932	1	1933	1	1941
		1922	7	1923	1	1924	1930		1931	2	1933	1	1934
	2	1925	2	1926	1	1927		1	1936	1	1937	1	1940
		1928	23	1929	30	1930	1933		1939	2	1940		
		1931	55	1932	62	1933	1934	1	1935	2	1936	1	1937
		1934	54	1935	58	1936		1	1939				
		1937		1938		1939							

1.37

tired

Year

‡-IN. DISC METERS

Year		Number			Re	tireme	ents by	Years		
Installed	Installed	In Service	Retired	Year	Num-		Num-		Num-	
1901	1	0	1	Installed	ber	Year	ber	Year	ber	Year
1902	8	0	8	1901	1	1906				
1934	1	1	0	1902	2	1906	2	1907	1	1909
1939	3	3	0		1	1910	1	1911	1	1912
1940	10	10	0							
1941	7	7	0							
1942	21	21	0							
SUBTOTAL	51	42	9							
Unknown	3	2	1							
	-		-							
TOTAL	54	44	10							

1-IN. DISC METERS

Year		Number			Re	tireme	ents by	Years		
Installed	Installed	In Service	Retired	Year	Num-		Num-		Num-	
1902	1	0	1	Installed	. ber	Year	ber	Year	ber	Year
1911	22	15	7	1902	1	1914				
1912	47	21	26	1911	2	1911	2	1925	1	1927
1925	1	1	0		2	1938				
1934	4	3	1	1912	1	1923	3	1925	3	1926
1938	2	2	0		2	1927	5	1928	3	1929
1939	16	16	0		1	1930	2	1933	1	1935
1940	17	17	0		4	1938	1	1940		
1941	7	7	0	1934	1	1940				
1942	0	0	0							
	-	-	-							
SUBTOTAL	117	82	35							
Unknown	19	0	19	14						
		-								
TOTAL	136	82	54			*				

14-in. Disc Meters

Year		Number			Re	etireme	ents by	Years		
Installed	Installed	In Service	Retired	Year	Num-		Num-		Num-	
1911	5	3	2	Installed	ber	Year	ber	Year	ber	Year
1912	4	1	. 3	1911	1	1925	1	1933		
1914	1	0	1	1912	1	1923	1	1933	1	1938
1916	3	1	2	1914	1	1924				
1934	1	1	0	1916	1	1928	1	1940		
1939	3	3	0							
1940	5	5	0							
1941	4	4	0							
1942	4	4	0							
	-		-							
SUBTOTAL	30	22	8							
Unknown	24	0	24							
	-	-	-							
TOTAL	54	22	32							

Ins

19

15

19

190

190

1907

2-IN. DISC METERS

Year		Number		1	R	etireme	ents by	Years		
Installed	Installed	In Service	Retired	Year	Num-		Num-		Num-	
1900	1	0	1	Installed	ber	Year	ber	Year	ber	Year
1911	9	3	6	1900	1	1907				
1912	14	1	13	1911	1	1912	1	1921	3	1934
1913	8	1	7		1	1941				4701
1914	8	2	6	1912	1	1917	1	1922	2	1924
1915	2	0	2		6	1934	1	1937	2	1938
1917	1	1	0	1913	1	1922	1	1923	1	1924
1921	1	1	0		2	1925	2	1931		
1934	1	1	0	1914	1	1923	3	1924	1	1925
1938	1	1	0		1	1927				
1940	1	1	0	1915	1	1923	1	1924		
1941	7	7	0							
1942	2	2	0							
		-								
SUBTOTAL	56	21	35							
Unknown	3	0	3							
		-	- 1							
TOTAL	59	21	38							

3-IN. DISC METERS

Year		Number			Re	etireme	nts by	Years		
Installed	Installed	In Service	Retired	Year	Num-		Num-		Num-	
1901	3	0	3	Installed	ber	Year	ber	Year	ber	Year
1913	4	2	2	1901	1	1911	1	1912	1	1916
1935	1	1	0	1913	2	1941				
1942	0	0	0							
		-	-							
SUBTOTAL	8	3	5							
Unknown	1	0	1							
	-									
TOTAL	9	3	6							

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1899	909	893	16	1915	632	611	21
1900	490	482	8	1916	29	24	5
1901	115	115	0	1917	246	239	7
1902	35	35	0	1918	208	192	16
1903	842	824	18	1919	99	96	3
1904	1,447	1,399	48	1920	160	152	8
1905	1,336	1,305	31	1921	449	441	8
1906	3,113	2,859	254	1922	605	586	19
1907	1,502	1,248	254	1923	1,108	1,083	25
1908	815	808	7	1924	663	649	14
1909	3,760	3,541	219	1925	331	329	2
1910	2,569	2,443	126	1926	673	667	6
1911	2,553	2,467	86	1927	681	677	4
1912	2,438	2,354	84	1928	1,005	1,002	3
1913	3,271	3,216	55	1929	809	804	5
1914	2,471	2,431	40	1930	777	774	3

Year

Year

etired

§-IN. PISTON METERS (contd.)

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1931	463	462	1	1940	23	23	0
1932	356	355	1	1941	222	222	0
1933	80	79	1	1942	77	77	0
1934	84	82	2		-		
1935	62	61	1	SUBTOTAL	37,646	36,245	1,401
1936	90	90	0	Unknown	291	5	286
1937	26	26	0			-	
1938	11	11	0	TOTAL	37,937	36,250	1,687
1939	11	11	0				

Retirements by Years

					Re	lirement	s by Years						
Year	Num		Num-		Num-		Year	Num-		Num-		Num-	
Installed	ber	Year	ber	Year	ber	Year	Installed	ber	Year	ber	Year	ber	Year
1899	1	1907	1	1912	1	1924	1907	4	1917	2	1918	5	1919
	2	1925	4	1928	3	1929		6	1920	1	1921	5	1922
	1	1930	1	1932	1	1938		6	1923	5	1924	4	1925
	1	1940						1	1926	5	1927	3	1928
1900	1	1906	1	1912	2	1922		3	1929	5	1930	7	1931
	1	1926	1	1928	1	1929		3	1932	9	1933	11	1934
	1	1933						17	1935	16	1936	6	1937
1903	1	1913	1	1923	1	1924		1	1938	3	1939	3	1940
	2	1929	2	1930	1	1932		4	1941	6	1942		
	1	1933	2	1934	2	1935	1908	1	1920	1	1935	3	1936
	1	1936	1	1938	1	1939		1	1938	1	1939		
	1	1940	1	1941			1909	1	1909	1	1910	5	1911
1904	1	1904	3	1910	1	1911		4	1912	3	1913	2	1914
	9	1912	1	1916	1	1917		2	1915	7 :	1916	2	1917
	1	1918	2	1921	2	1922		5	1918	2	1919	14	1920
	1	1924	2	1925	1	1927		7	1921	8	1922	9	1923
	3	1928	3	1929	1	1932		12	1924	5	1925	5	1926
	4	1934	1	1935	2	1937		7	1927	8	1928	7	1929
	1	1938	1	1939	2	1940		3	1930	4	1931	6	1932
	3	1941	2	1942				8	1933	14	1934	19	1935
1905	1	1910	4	1912	2	1914		15	1936	8	1937	2	1938
	1	1917	1	1925	1	1927		1	1939	5	1940	7	1941
	3	1928	1	1929	1	1930		11	1942				
	2	1933	4	1934	4	1935	1910	10	1911	6	1912	1	1913
	2	1936	3	1940	1	1941		3	1914	6	1915	3	1916
1906	1	1908	8	1909	7	1910		2	1917	4	1918	1	1919
	11	1911	23	1912	4	1913		1	1920	4	1921	7	1922
	3	1914	5	1915	9	1916		10	1923	6	1924	3	1925
	5	1917	5	1918	5	1919		2	1926	6	1928	3	1929
	1	1920	2	1921	2	1922		5	1930	5	1931	1	1932
	7	1923	10	1924	10	1925		3	1933	11	1934	5	1935
	6	1926	3	1927	8	1928		8	1936	1	1937	2	1941
	7	1929	6	1930	1	1931		7	1942				
	6	1932	5	1933	22	1934	1911	6	1911	11	1912	1	1913
	13	1935	32	1936	8	1937		2	1914		1915		1916
	4	1938	7	1940	7	1941		2	1918	2	1919	1	1920
	1	1942							1921		1922	-	1923
1907	1	1908	15	1909	17	1910		3	1924	1	1925	2	1926
	25	1911	12	1912		1913		2	1927	1	1928	4	1929
	15	1914		1915		1916		1	1930	4	1932	2	1933

0

I

Ins

19

Inst 18

§-IN. PISTON METERS (contd.)

Retirements by Years (contd.)

Year	Num-		Num-		Num-		Year	Num-		Num-		Num-	
Installed	ber	Year	ber	Year	ber	Year	Installed	ber	Year	ber	Year	ber	Year
1911	3	1934	1	1935	4	1936	1918	1	1924	1	1925	1	1926
	3	1939	4	1940	1	1941		2	1927	1	1929	1	1930
	9	1942						1	1931	1	1934	2	1936
1912	2	1912	2	1913	1	1914		1	1942				
	11	1915	12	1916	7	1917	1919	1	1921	1	1934	1	1942
	3	1918	3	1919	3	1921	1920	1	1922	1	1923	1	1928
	2	1923	2	1924	2	1925		1	1931	1	1934	1	1936
	2	1926	2	1927	2	1928		2	1942				
	2	1929	1	1931	1	1932	1921	1	1922	1	1924	1	1925
	3	1933	4	1934	3	1935		1	1926	1	1929	1	1936
	3	1936	1	1937	3	1938		1	1941	1	1942		
	3	1939	2	1941	2	1942	1922	1	1924	3	1927	2	1928
1913	2	1913	1	1915	3	1917		1	1930	2	1931	1	1934
	4	1918	4	1919	4	1920		2	1935	1	1941	6	1942
	3	1921	2	1922	3	1923	1923	1	1924	2	1925	1	1926
	2	1924	1	1925	1	1926		3	1927	1	1928	1	1929
	1	1927	4	1928	3	1929		1	1930	1	1933	1	1935
	2	1930	2	1932	4	1934		2	1936	1	1938	3	1941
	2	1935	1	1936	1	1938		7	1942				
	1	1940	4	1942			1924	3	1925	1	1926	2	1927
1914	1	1914	1	1917	1	1918		1	1928	1	1929	1	1931
	3	1919	2	1920	1	1921		1	1932	2	1935	1	1941
	2	1922	1	1923	1	1924		1	1942				
	. 1	1925	1	1926	5	1928	1925	1	1932	1	1937		
	1	1929	3	1932	2	1933	1926	1	1929	2	1930	1 .	1936
	6	1934	3	1936	1	1937		2	1942				
	1	1940	2	1941	1	1942	1927	2	1933	1	1940	1	1941
1915	1	1917	1	1920	7	1923	1928	1	1936	1	1938	1	1940
	1	1924	1	1925	1	1926	1929	1	1929	1	1933	1	1936
	1	1927	1	1928	2	1930		1	1938	1	1940		
	1	1933	2	1934	1	1935	1930	1	1934	1	1935	1	1942
	1	1938					1931	1	1936				
1916	1	1920	1	1922	1	1935	1932	1	1934				
	2	1942					1933	1	1934				
1917	1	1919	1	1925	2	1930	1934	2	1937				
	1	1931	1	1941	1	1942	1935	1	1936				
1918	1	1918		1921	2	1923							

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1899	218	216	2	1909	70	70	0
1900	216	214	2	1910	59	58	1
1901	60	60	0	1911	46	42	4
1902	33	33	0	1912	50	49	1
1903	227	224	3	1913	82	77	5
1904	44	43	1	1914	39	39	0
1905	54	54	0	1915	22	21	1
1906	71	71	0	1916	4	3	1
1907	31	30	1	1917	1	1	0
1908	58	57	1	1918	5	4	1

etired

3-IN. PISTON METERS (contd.)

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1920	3	3	0	1932	24	24	0
1921	5	5	0	1933	1	1	0
1922	3	3	0	1934	3	3	0
1923	6	6	0	1935	1	1	0
1924	3	2	1	1938	1	1	0
1925	7	7	0	1941	2	2	0
1926	5	5	0	1942	3	3	0
1927	24	24	0			-	-
1928	29	29	0	SUBTOTAL	1,662	1,635	27
1929	62	62	0	Unknown	33	2	31
1930	59	58	1		-		-
1931	31	30	1	TOTAL	1,695	1,637	58

Retirements by Years

Year Installed	Num- ber	Year	Num- ber	Year	Num- ber	Year	Year Installed		Year	Num- ber	Year	Num- ber	Year
1899	1	1932	1	1938			1912	1	1920				
1900	1	1906	1	1930			1913	1	1918	1	1924	1	1926
1903	1	1919	1	1924	1	1939		1	1930	1	1942		
1904	1	1927					1915	1	1915				
1907	1	1925					1916	1	1920				
1908	1	1926					1918	1	1927				
1910	1	1925					1924	1	1927				
1911	1	1918	1	1925	1	1934	1930	1	1935				
	1	1942					1931	1	1934				

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1899	15	15	0	1921	4	4	0
1900	18	18	0	1922	9	8	1
1901	152	148	4	1923	11	11	0
1902	6	6	0	1924	6	6	0
1903	17	.16	1	1925	13	1.3	0
1904	11	11	0	1926	15	15	0
1905	26	25	1	1927	17	17	0
1906	48	48	0	1928	17	17	0
1907	32	31	1	1929	30	30	0
1908	4	4	0	1930	6	6	0
1909	13	13	0	1931	15	15	0
1910	40	36	4	1932	8	8	0
1911	6	5	1	1933	2	2	0
- 1912	25	25	0	1934	3	3	0
1913	77	77	0	1940	1	1	0
1914	47	47	0	1942	0	0	0
1915	22	22	. 0		-		-
1916	4	4	0	SUBTOTAL	743	730	13
1917	6	6	0	Unknown	13	1	12
1918	4	4	0		-	-	
1919	8	8	0	TOTAL	756	731	25
1920	5	5	0				

In

Ins

Sub Unk

Tor.

Yes Insta

Yea Instal 191 194

TOTAL

1-IN. PISTON METERS (contd.)

Retirements by Years

Year Installed	Num- ber	Year	Num- ber	Year	Num- ber		Year Installed	Num- ber		Num- ber	Year	Num- ber	Year
1901	1	1906	1	1921	1	1932	1910	1	1911	- 1	1913	1	1922
	1	1938						1	1940				
1903	1	1932					1911	1	1934				
1905	1	1934					1922	1	1930				
1907	1	1934											

14-IN. PISTON METERS

1			13-IN. 1 151	ON METER	(5			
Year		Number		Year		N	umber	
Installed	Installed	In Service	Retired	Installed	Installe	d In	Service	Retire
1899	2	2	0	1924	7		7	0
1900	4	4	0	1925	7	•	7	0
1901	9	9	0	1926	1.3	;	12	1
1902	12	11	1	1927	1.5	;	15	Ô
1903	2	2	0	1928	24		24	0
1904	7	7	0	1929	23	3	23	0
1905	11	11	0	1930	12		12	0
1906	11	11	0	1931	9		9	0
1907	10	10	0	1932	4		4	0
1908	7	7	0	1933	3		3	0
1909	5	5	0	1935	1		1	0
1910	13	11	2	1936	2		2	0
1912	5	5	0	1937	1		1	0
1913	3	3	0	1942	0		0	. 0
1914	47	45	2					
1915	11	11	0	TOTAL	322		316	6
1916	2	2	0					
1917	4	4	0		Retiren	ients by	Years	
1918	8	8	0	Year				
1919	5	5	0	Installed	Number	Year	Number	Year
1920	6	6	0	1902	1	1937		
1921	3	3	0	1910	1	1935	1	1937
1922	4	4	0	1914	2	1936		
1923	10	10	0	1926	1	1929		

Year		Number		Year		Number			
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired		
1899	1	1	0	1912	2	2	0		
1900	19	18	1	1913	5	5	0		
1901	4	4	0	1914	3	3	0		
1902	7	7	- 0	1915	6	5	1		
1904	9	9	0	1916	8	8	0		
1905	10	10	0	1917	5	5	0		
1906	4	3	1	1918	7	7	0		
1907	7	7	0	1919	1	1	0		
1908	2	2	0	1920	3	2	1		
1909	3	2	1	1921	5	5	0		
1910	12	11	1	1922	10	10	0		

lear.

ired

Year

etired

2-IN. PISTON METERS (contd.)

Year		Number		Year		Number	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1923	9	9	0	1937	1	1	0
1924	5	5	0	1938	1	1	0
1925	7	6	1	1939	3	3	0
1926	8	7	1	1940	5	5	0
1927	5	4	1	1942	0	0	0
1928	8	8	0			-	-
1929	8	7	1	SUBTOTAL	214	203	11
1930	9	8	1	Unknown	1	0	1
1931	9	9	0		-	-	
1932	2	2	0	TOTAL	215	203	12
1933	1	1	0				
			Retirement	s by Years			
Year				Year			

		Re	tirements by Years		
Year Installed	Number	Year	Year Installed	Number	Year
1900	1	1923	1925	1	1926
1906	1	1938	1926	1	1926
1909	1	1920	1927	1	1927
1910	1	1932	1929	1	1930
1915	1	1937	1930	1	1930
1920	1	1929			

	3-IN. PIST	ON METERS		1	2-in. Cui	RRENT A	METERS
Year		Number		Year		Nu	mber
Installed	Installed	In Service	Retired	Installed	Installed	In.	Service
1901	3	3	0	1905	3		0
1906	1	1	0	1919	1		0
1911	2	1	1	1942	0		0
1912	5	5	0		_		***
1926	1	1	0	TOTAL	4		0
1942	0	0	0				
	-				Retirem	ents by	Years.
SUBTOTAL	12	11	1	Year			
Unknown	1	0	1	Installed	Number	Year	Numb
	-	40 Olderado		1905	1	1919	2
TOTAL	13	11	2	1919	i	1920	-
Year	Retirement	s by Years					
Installed	Number	Year			3-IN. CUI	RENT A	AETERS

Installed	Number	Year	
1911	• 1	1926	
	4-in. Pisto	ON METERS	
Year		Number	
Installed	Installed	In Service	Retired
1912	2	2	0
1942	0	0	0
	Primary .	-	
TOTAL	2	2	0

	3-IN. CURR	ENT METERS	
Year		Number	
Installed	Installed	In Service	Retired
1903	1	1 '	0
1904	1	1	0
1908	3	3	0
1909	2	2	0
1910	1	1 .	0
1911	1	1	-0
1912	3	2	1
1914	3	2	1

Retired

Number Year

In

To

In: 1

Y Ins

18

Sub Unk

Тот

Ye Inste 188

188

Year		Number	
Installed	Installed	In Service	Retired
1915	3	3	0
1942	0	0	0
	-	-	-
SUBTOTAL	18	16	2
Unknown	1	0	1
	arraga		
Total.	19	16	3
	Retirement	s by Years	
Year			
Installed	Number	Year	
1912	1	1919	
1914	1	1934	

4-IN. CURRENT METERS

Number							
Installed	In Service	Retired					
2	1	1					
1	1	0					
1	1	0					
2	2	0					
1	1	0					
0	0	0					
-	-	-					
7	6	1					
1	0	1					
-	_						
8	6	2					
	2 1 1 2 1 0	2 1 1 1 1 2 2 1 1 0 0 7 6 1 0					

Retirements by Years

Year		
Installed	Number	Year
1906	1	1935

6-IN. CURRENT METERS

Year		Number	per			
Installed	Installed	In Service	Retired			
1926	1	1	0			
1942	0	0	0			
TOTAL	1	1	0			

3-IN. COMPOUND METERS

Year		Number	
Installed	Installed	In Service	Retired
1913	1	1	0
1915	5	5	0
1916	2	2	0
1917	1	1	0
1918	2	2	0
1919	1	1	0

3-IN. CURRENT METERS (contd.) 3-IN. COMPOUND METERS (contd.)

Year		Number	
Installed	Installed	In Service	Retire
1920	5	5	0
1921	1	1	0
1922	5	5	0
1923	1	. 1	0
1924	3	3	0
1925	3	3	0
1926	6	6	0
1929	2	2	0
1930	3	3	0
1931	1	1	0
1932	1	1	0
1933	1	1	0
1934	1	1	0
1935	3	3	0
1936	1	1	0
1938	1	1	0
1939	1	1	0
1940	4	4	0
1942	0-	0	0
TOTAL	55	55	0

4-IN. COMPOUND METERS

	T-IN. COMP	DUND MIETERS	2	
Year		Number		
Installed	Installed	In Service	-	Retired
1913	1	1		0
1916	2	2		0
1918	1	1		0
1919	1	1		0
1920	1	1		0
1924	3	3		0
1926	2	2		0
1928	2	2		0
1929	1	1		0
1930	2	2		0
1931	4	4		0
1932	1	1		0
1938	1	1		0
1941	1	1		0
1942	0	0		0
TOTAL	23	23		0

6-IN. COMPOUND METERS

Year		Number				
Installed	Installed	In Service	Retire			
1920	1	1	0			
1925	1	1	0			
1928	1	1	0			
1934	1	1	0			
1942	0	0	0			
TOTAL	4	4	0			

01.37

tired

0 0 0

0

0 0 0

0

SERVICES

1	LINI	CALVA	NIZED-	PON	SERVI	CES
- 1	- I.N.	UALVA	INIZED-1	RON	SERV.	ICES

Year		Feet	reet			
Installed	Installed	In Service	Retired			
1882	124	0	124			
1883	32	0	32			
1942	0	0	0			
Commonal	156	0	156			
SUBTOTAL	103	0	103			
Unknown	103		103			
TOTAL	259	0	259			

Retirements by Years

Year Installed	Feet	Year	Feet	Year	Feet	Year
1882	29	1895	47	1901	47	1916
1883	32	1901				

5-IN. GALVANIZED-IRON SERVICES

Year		Feet				
Installed	Installed	In Service	Retired			
1882	33	0	33			
1942	0	0	0			
	*	reliano	- Contraction			
TOTAL	33	0	33			
Year	Retiremen	its by Years				
Installed	Feet	Year				
1882	33	1901				

3-in. Galvanized-Iron Services

Year		Feet				
Installed	Installed	In Service	Retired			
1882	509	0	509			
1883	292	0	292			
1884	689	0	689			
1942	0	0	0			
SUBTOTAL	1,490	0	1,490			
Unknown	633	0	633			
TOTAL	2,123	0	2,123			

Retirements by Years

Year	Λ	eureme	nis oy	rears		
Installed	Feet	Year	Feet	Year	Feet	Year
1882	30	1891	105	1895	66	1898
	76	1900	48	1901	20	1904
	103	1905	20	1908	41	1909
1883	40	1894	103	1900	18	1903
	102	1905	29	1906		

s | 3-in. Galvanized-Iron Services (contd.)

	Retire	ments h	v Yea	rs (con	td.)	
Year Installed						Year
1884	40	1893	114	1894	161	1895
	49	1896	46	1897	45	1898
	86	1900	102	1906	46	1912

1-IN. GALVANIZED-IRON SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1882	34	0	34
1883	122	0	122
1884	243	0	243
1942	0	0	0
	-	-	-
SUBTOTAL	399	0	399
Unknown	256	0	256
TOTAL	655	0	655

Retirements by Years

	11	eareme	nis oy	1 eurs		
Year Installed	Feet	Year	Feet	Year	Feet	Year
1882	34	1896				
1883	42	1886	33	1900	47	1904
1884	105	1891	138	1894		

14-IN. GALVANIZED-IRON SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
Unknown	28	0	28
	-	100000	-
TOTAL	28	0	28

14-IN. GALVANIZED-IRON SERVICES

Year	Feet					
Installed	Installed	In Service	Retired			
1882	98	. 0	98			
1942	0	0	0			
SUBTOTAL	98	0	98			
Unknown	34	0	34			
TOTAL	132	0	132			
**	Retiremen	its by Years				
Year Installed	Feet	Vear				

1903

4-IN. WROUGHT-IRON SERVICES				
	1 737	Whomen	Inov	CEDITORS

Year	Feet					
Installed	Installed	In Service	Retired			
1884	46	0	46			
1886	205	0	205			
1887	1,065	0	1,065			
1888	1,464	0	1,464			
1889	933	0	933			
1890	268	0	268			
1891	451	0	451			
1892	322	0	322			
1893	436	0	436			
1942	0	0	0			
SUBTOTAL	5,190	0	5,190			
Unknown	827	0	827			
TOTAL	6,017	0	6,017			

	h	Retireme	ents by	Years		
Year	-					
Installed	Feet	Year	Feet	Year	Feet	Vear
1884	46	1895				
1886	73	1894	61	1895	71	1900
1887	37	1891	39	1893	180	1894
	136	1895	131	1896	43	1898
	138	1899	111	1900	110	1901
	46	1902	20	1903	28	1907
	46	1915				
1888	20	1889	46	1890	12	1892
	45	1893	145	1894	78	1895
	65	1897	37	1898	109	1899
	135	1900	318	1901	20	1902
	46	1903	92	1904	33	1905
	40	1906	46	1907	46	1908
	84	1909	18	1920		
1889	33	1893	103	1894	20	1895
	79	1896	46	1897	52	1898
	88	1899	114	1900	119	1901
	54	1902	129	1906	96	1909
1890	30	1897	16	1898	40	1899
	102	1901	20	1903	20	1905
	20	1909	20	1911		
1891	27	1896	20	1897	92	1898
	20	1899	20	1900	92	1901
	80	1903	16	1904	20	1906
	12	1907	20	1910	32	1911
1892	20	1898	40	1900	35	1901
	76	1903	43	1905	88	1906
	20	1907				
1893	175	1900	20	1901	15	1902
	59	1903	20	1904	15	1905
	20	1906	112	1907		

5-IN. WROUGHT-IRON SERVICES

Year		Feet					
Installed	Insta	lled	In Service	Retired			
1888		112	0	112			
1942		0	0	0			
TOTAL		112	0	112			
Year	Reti	rements	by Years				
Installed	Feet	Year	Feet	Year			
1888	20	1901	92	1912			

3-IN. WROUGHT-IRON SERVICES

Year	Feet						
Installed	Installed	In Service	Retired				
1885	97	0	97				
1886	310	0	310				
1887	888	0	888				
1888	1,907	0	1,907				
1889	2,682	0	2,682				
1890	2,381	0	2,381				
1891	2,802	0	2,802				
1892	2,289	0	2,289				
1893	3,567	0	3,567				
1894	46	0	46				
1896	40	0	40				
1898	130	0	130				
1942	0	0	0				
SUBTOTAL	17,139	0	17.139				
Unknown	2,047	0	2,047				
TOTAL	19,186	0	19,186				

	F	Retirem	ents by	Years		
Year Installed	Feet	Year	Feet	Year	Feet	Year
1885	45	1890	20	1896	32	1900
1886	46	1886	49	1893	104	1894
	18	1895	24	1899	27	1900
	42	1903				
1887	7	1891	110	1894	20	1895
	56	1896	. 60	1897	72	1898
	111	1899	109	1900	150	1901
	82	1904	46	1905	45	1908
	20	1909				
1888	20	1890	44	1892	83	1893
	66	1894	130	1895	114	1896
	198	1898	237	1899	391	1900
	168	1901	46	1903	132	1904

Ins

1.37

tired

Vear

3-IN. WROUGHT-IRON SERVICES (contd.) Delivements by Veges (could)

	Retire	ements	by Yea	urs (con	(d.)	
Year			N	umher		
Installed	In	stalled	In	Service	1	Retirea
1888	40	1905	46	1906	192	1907
1889	136	1894	124	1895	66	1896
	196	1897	112	1898	320	1899
	343	1800	209	1901	237	1902
	116	1903	129	1904	99	1905
	223	1906	184	1907	64	1908
	20	1909	38	1911	20	1922
	46	1927				
1890	92	1894	47	1896	92	1897
	154	1898	20	1899	388	1900
	514	1901	137	1902	244	1903
	94	1905	88	1906	258	1907
		1908	46	1914		
1891	35	1895	265	1896	193	1897
	46	1898	279	1899	619	1900
		1901	142	1902	168	1903
	20	1904	82	1905	284	1906
	92	1907	40	1908	112	1909
	18	1910	46	1912	58	1914
	46	1915				
1892	21	1895	39	1897	46	1898
		1899	452	1900		
	351	1901	219	1902	188	1903
		1904	66	1905	201	1906
		1907	106	1908	112	1909
	52	1910	18	1924		
1893	46	1896	67	1897	96	1898
	108	1899	419	1900	555	1901
		1902		1903	248	1904
		1905	426	1906	663	1907
		1908	142	1909	46	1910
		1914	10	1915	46	1926
1894		1903				
1896		1905				
1898	130	1904				

1-IN WPOUGHT-IPON SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1884	430	0	430
1885	306	0	306
1886	263	0	263
1887	116	0	116
1888	229	0	229
1889	417	0	417
1890	307	0	307
1891	183	0	183

Year			N	umber		
Installed	In	stalled	In	Service	1	Retired
1892	343			0		343
1893	277			0		277
1896		20		0		20
1898		53		0		53
1942		0		0		0
SUBTOTAL		2,944		0	2	.944
Unknown		1,165		0	1	,165
TOTAL		4,109		0	4	,109
	I	Retireme	nts by	Years.		
Year	W7 .	37	F1 .	**	**	
Installed .		Year	Feet	Year	Feet	
1884	97		24		47	1899
	107		155			
1885	47		20		29	1899
1004	180		30			
1886	27	1888	15		136	1899
100*	46		39			
1887	36		80			4004
1888	46		56	1901	18	1904
1889	109	1908 1896	66	1000	126	1000
1009	41	1901	66	1898 1903	126	1900 1904
	46	1901	46	1903	46	1904
1890	50	1897	14	1900	46	1904
1090	46	1906	101	1908	50	1904
1891	98		29	1901	29	1905
1021	27	1906	27	1901	49	1903
1892	20	1898	98	1900	46	1901
2074	46	1902	113	1906	20	1908
1893	103	1899	128	1901	46	1907
1896	20	1903	140		10	
1898	53	1899				

14-IN. WROUGHT-IRON SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1895	163	0	163
1942	0	0	0
TOTAL	163	0	163
Year	Retiremen	at by Years	
Installed	Feet	Year	
1895	163	1900	

I

St

To

In.

19

Y Inst 19 19 19 19. 19. 19. 193 193 193

13-IN	WROUGHT-	DON	SERVICES	
15-174	WKUUGHI".	LKUN	SERVICES	۶.

Year		Feet	
Installed	Installed	In Service	Retired
1886	45	0	45
1893	18	0	18
1895	183	0	183
1896	20	0	20
1942	0	0	. 0
	-		
SUBTOTAL	266	0	266
Unknown	20	0	20
	-	-	100
TOTAL	286	0	286
	Retiremen	ts by Years	

Year			1000	2 0000		
Installed	Feet	Year	Feet	Year	Feet	Year
1886	45	1896				
1893	18	1899				
1895	136	1899	27	1912	20	1917
1896	20	1913				

2-IN. WROUGHT-IRON SERVICES

Year		Feet				
Installed	Installed	In Service	Retired			
1884	211	0	211			
1885	20	0	20			
1886	24	0	24			
1889	31	0	31			
1890	49	0	49			
1892	46	0	46			
1893	46	0	46			
1895	163	0	163			
1900	15	0	15			
1942	0	0	0			

SUBTOTAL	605	0	605			
Unknown	46	0	46			
	-					
TOTAL	651	0	651			

	R	etireme	ents by	Years		
Year Installed	Feet	Year	Feet	Year	Feet	Year
1884	86	1898	102	1901	23	1908
1885	20	1897				
1886	24	1901				
1889	31	1896				
1890	49	1910				
1892	46	1906				
1893	46	1903				
1895	163	1909				
1900	15	1904				

2½-IN. WROUGHT-IRON SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1885	46	0	46
1895	20	0	20
1942	0	0	0
			-
SUBTOTAL	66	0	66
Unknown	57	0	57
	-		Name and
TOTAL	123	0	123
Year	Retiremen	ts by Years	
Installed	Feet	Year	
1885	46	1898	
1895	20	1908	

3-IN. WROUGHT-IRON SERVICES

Year		F	eet	
Installed	Installed	In S	service	Retired
1885	133		0	133
1897	20		0	20
1942	0		0	0
			-	-
TOTAL	153		0	153
Year	Retirem	ents by	Years	
Installed	Feet	Year	Feet	Year
1885	105	1902	28	1906
1897	20	1931		

1-IN. COPPER SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1925	1,122	1,112	0
1926	14	14	0
1927	5,054	5,054	0
1928	8,095	8,095	0
1929	19,479	19,413	66
1930	14,455	14,337	118
1931	11,146	11,036	110
1932	6,591	6,405	186
1933	5,470	5,418	52
1934	3,597	3,477	120
1935	1,242	1,242	0
1936	727	727	0
1937	143	143	0
1938	48	48	0
1939	285	285	0

. 37

tired

Year

etired

1-IN.	COPPER	Services	(contd.)
-------	--------	----------	----------

Year				Feet		
Installed	In	stalled	In	Service	I	Retired
1940		58		58		0
1941		30		30		0
1942		0		0		0
SUBTOTAL	7	7,556	7	6,904		652
Unknown		69		69		0
TOTAL	7	7,625	7	6,973		652
	R	etireme	nts by	Years		
Year Installed F	eet	Year	Feet	Year	Feet	Year
1929	52	1931	14	1941		
1930	14	1932	52	1933	52	1942
1931	40	1933	18	1939	52	1940
1932	18	1932	52	1933	96	1938
	20	1939				
1933	52	1933				
1934	104	1941	16	1942		

SIN COPPER SERVICES

	3-IN. COPP	PER SERVICES	
Year		Feet	
Installed	Installed	In Service	Retired
1927	1,002	1,002	0
1928	3,880	3,834	46
1929	3,626	3,564	62
1930	2,120	2,120	0
1931	1,643	1,633	10
1932	996	996	0
1933	1,449	1,449	0
1934	1,690	1,676	14
1935	802	802	0
1936	122	122	0
1937	10	10	0
1938	158	158	0
1939	95	95	0
1940	66	66	0
1942	0	0	0
SUBTOTAL	17,659	17,527	132
Unknown	106	106	0
TOTAL	17,765	17,633	132
Vear	Retiremen	ts by Years	

TOTAL	17,765	17,6	533	132
Year	Retirem	ents by Y	ears	
Installed	Feet	Year	Feet	Year
1928	46	1941		
1929	46	1930	16	1939
1931	10	1936		
1934	14	1940		

3-IN. COPPER SERVICES

Year		Feet	
Installed	Installed	In Service	Retired
1927	492	492	0
1928	1,017	933	84
1929	2,177	2,125	52
1930	1,643	1,643	0
1931	2,500	2,500	0
1932	1,242	1,192	50
1933	1,566	1,539	27
1934	1,359	1,343	16
1935	4,446	4,330	116
1936	7,627	7,565	62
1937	11,688	11,688	0
1938	11,440	11,440	0
1939	13,124	13,124	0
1940	18,171	18,171	0
1941	15,409	15,409	0
1942	0	0	0
SUBTOTAL	93,901	93,494	407
Unknown	74	74	0
TOTAL	93,975	93,568	407
	D. C.		

Retirements by Years

Year				2 00.0		
Installed	Feet	Year	Feet	Year	Feet	Year
1928	14	1928	14	1929	56	1931
1929	52	1941				
1932	50	1938				
1933	27	1934				
1934	16	1942				
1935	116	1936				
1936	52	1936	10	1940		

1-IN. COPPER SERVICES

		wante decrease	TOTAL COMPANY	
	Year		Feet	
	Installed	Installed	In Service	Retired
	1927	379	359	20
	1928	1,182	1,130	52
	1929	2,142	2,142	0
	1930	911	873	38
	1931	1,130	1,114	16
	1932	400	400	0
i	1933	594	582	12
Ì	1934	324	324	0
-	1935	429	429	0
	1936	676	676	0
ı	1937	591	425	166
ı	1938	1,153	1,153	0
	1939	2,556	2,556	0
	1940	867	867	0
	1941	1,498	1,498	0
- Married	1942	0	0	0
	TOTAL	14,832	14,528	304

19. 19.

1-IN. COPPER SERVICES (contd.)

	Retirement	s by Years	
Year Installed	Feet	Year	
1927	20	1939	
1928	52	1929	
1930	38	1936	
1931	16	1939	
1933	12	1940	
1937	166	1939	

14-IN. COPPER SERVICES

Year	Feet				
Installed	Installed	In Service	Retired		
1938	24	24	0		
1940	256	256	0		
1941	64	64	0		
1942	0	0	0		
TOTAL	344	344	0		

11-IN COPPER SERVICES

Year		Feet				
Installed	Installed	In Service	Retired			
1935	131	131	0			
1936	109	109	0			
1937	58	58	0			
1938	61	61	0			
1939	134	134	0			
1940	38	38	0			
1941	62	62	0			
1942	0	0	0			
TOTAL	593	593	0			

2-IN. COPPER SERVICES

Year	Feet					
Installed	Installed	In Service	Retire			
1927	95	95	0			
1928	249	249	0			
1929	409	409	0			
1930	297	297	0			
1931	194	194	0			
1932	147	147	0			
1933	126	126	0			
1934	166	166	0			
1935	131	131	0			
1936	72	72	0			
1937	98	98	0			
1938	76	76	0			
1939	13	13	0			
1940	108	108	0			
1941	132	132	0			
1942	0	0	0			
TOTAL	2,313	2,313	0			

3-IN. CAST-IRON SERVICES

Year		Feet					
Installed	In	stalled	In	Service		Retired	
1884		62		0		62	
1895		16		0		16	
1899		149		149		0	
1900		205		98		107	
1906	1906 28			28		0	
1942		0		0		0	
TOTAL		460		275		185	
V	R	etireme	ents by	Years			
Year Installed	Feet	Year	Feet	Year	Feet	Year	
1884	16	1895	46	1902			
1895	16	1907					
1900	2.3	1912	52	1924	32	1030	

4-IN. CAST-IRON SERVICES

Year		Feet				Feet		
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retire	
1887	78	78	0	1903	111	111	0	
1888	66	66	0	1904	544	485	59	
1890	15	15	0	1905	228	172	56	
1893	50	50	0	1906	553	431	122	
1895	30	0	30	1907	468	468	0	
1899	46	46	0	1908	436	436	0	
1900	275	275	0	1909	705	705	0	
1901	319	319	0	1910	897	878	19	
1902	288	274	14	1911	74	74	0	

1.37

0 0 0

4-IN. CAST-IRON SERVICES (contd.)

Year		Feet		Year				Feet		
Installed	Installed	In Service	Retired	Installed	Inst	alled	ln	Service	A	Retired
1912	1,461	1,376	85	1937		46		46		0
1913	558	558	0	1938		19		19		0
1914	501	501	0	1939		116		116		0
1915	380	380	0	1940		106		106		0
1916	235	235	0	1941		14		14		0
1917	165	165	0	1942		0		0		0.
1918	117	117	0			-	-	-		-
1919	283	283	0	SUBTOTAL	. 11	,674	1	1,261		413
1920	261	247	14	Unknown		10		10		
1921	209	209	0							
1922	346	346	0	TOTAL	11	,684	1	1,271		413
1923	14	14	0							
1924	252	252	0		Rei	lireme	nts by	Years		
1925	42	28	14	Year						
1926	212	212	0	Installed I	Feet	Year	Feet	Year	Feet	Year
1927	219	219	0	1895	30 1	1903				
1928	91	91	0	1902	14 1	1941				
1929	210	210	0	1904	59 1	937				
1930	256	256	0	1905	56 1	932				
1931	150	150	0	1906	122 1	933				
1932	126	126	0	1910	19 1	939				
1933	23	23	0	1912	18 1	934	53	1935	14	1941
1934	15	15	0	1920	14 1	935				
1935	64	64	0	1925	14 1	927				

6-IN. CAST-IRON SERVICES

07			0-1	A. CASI-II	ON SERVICE	6.5					
0	Year		Feet		Year	Feel					
0 In	stalled	Installed	In Service	Retired	Installed	Installed	In Service	Retired			
85 1	1898	46	46	0	1926	470	470	0			
	1899	20	20	0	1927	167	167	0			
1	1904	267	267	0	1928	446	446	0			
	1905	19	19	0	1929	180	180	0			
107	1906	347	347	0	1930	351	351	0			
1	907	226	226	0	1931	288	288	0			
1 1	1908	83	83	0	1932	114	114	0			
39 1	909	227	227	0	1933	152	152	0			
- 1	910	22	22	0	1934	145	145	0			
1	911	188	188	0	1935	304	304	0			
	1912	458	458	0	1936	60	60	0			
1	913	159	159	0	1937	83	83	0			
	914	166	166	0	1938	57	57	0			
-	915	170	170	0	1939	393	393	0			
	1916	71	71	0	1940	228	228	0			
) 1	917	14	14	0	1941	55	55	0			
,	918	14	14	0	1942	0	0	0			
6 1	919	68	68	0		-		-			
2 1	920	109	109	0	TOTAL	7,243	7,188	55			
0 1	921	22	22	0		-					
0	922	105	105	0		Retiremen	its by Years				
0	923	373	373	0	Year	**					
	924	281	226	55	Installed	Feet	Year				
0 1	925	295	295	0	1924	55	1941				

18

8-IN. CAST-IRON SERVICES

Year		Feet		Year	Feet					
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired			
1913	25	25	0	1929	208	208	0			
1914	9	9	0	1931	12	12	0			
1915	100	100	0	1939	55	55	0			
1916	48	48	0	1940	20	20	0			
1925	24	24	0	1942	0	0	0			
1926	224	224	0				-			
1928	14	14	0	TOTAL	739	739	0			

1-IN. LEAD SERVICES

			T-IN. LEA	DERVICES			
Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retires
1894	3,750	1,426	2,324	1918	2,884	2,542	342
1895	3,793	1,322	2,471	1919	3,809	3,529	280
1896	2,490	1,184	1,306	1920	10,580	8,376	2,204
1897	2,145	823	1,322	1921	16,536	15,121	1,415
1898	1,683	668	1,015	1922	24,311	23,170	1,141
1899	5,994	1,629	4,365	1923	18,197	17,810	387
1900	9,536	3,142	6,394	1924	13,380	13,164	216
1901	7,671	2,419	5,252	1925	16,500	16,187	313
1902	1,494	1,203	291	1926	17,316	16,835	481
1903	29,393	23,713	5,680	1927	15,937	15,651	286
1904	29,297	23,975	5,322	1928	13,760	13,538	222
1905	52,802	40,861	11,941	1929	1,809	1,757	52
1906	55,825	43,984	11,841	1930	2,374	2,360	- 14
1907	40,588	35,303	5,285	1931	648	648	0
1908	19,823	17,337	2,486	1932	258	258	0
1909	29,899	27,016	2,883	1933	10	10	0
1910	36,883	31,741	5,142	1941	378	378	0
1911	42,394	37,329	5,065	1942	1,261	1,261	0
1912	47,150	43,576	3,574				
1913	38,440	34,064	4,376	SUBTOTAL	655,752	554,702	101,050
1914	23,929	20,038	3,891	Unknown	2,181	520	1,661
1915	5,296	4,912	384				
1916	2,568	1,988	580	TOTAL	657,933	555,222	102,711
1917	2.961	2.406	555				-

Retirements by Years

Year							Year						
Installed	Feet	Year	Feet	Year	Feet	Year	Installed	Feet	Year	Feet	Year	Feet	Yeu
1894	58	1896	61	1898	101	1899	1895	66	1900	76	1901	150	1902
	6	1900	17	1901	20	1903		53	1905	20	1907	31	1908
	36	1904	77	1905	80	1906		80	1910	20	1911	224	1912
	46	1907	149	1908	112	1909		46	1913	273	1914	46	1915
	59	1910	46	1911	47	1913		46	1916	20	1917	21	1918
	20	1915	16	1916	32	1917		92	1919	132	1920	96	1921
	95	1918	20	1920	132	1922		20	1922	170	1923	20	1924
	46	1923	86	1924	46	1925		46	1925	17	1926	80	1927
	40	1926	46	1927	149	1928		92	1929	67	1933	46	1934
	20	1929	46	1930	63	1932		46	1935	20	1936	46	1937
	227	1933	46	1936	65	1937		46	1938	186	1939	46	1940
	46	1938	105	1939				31	1941				

}-IN. LEAD SERVICES (contd.) Retirements by Years (contd.)

					A	Retiren	nents by	Years (con	ntd.)						
	Year		**			_		Year							
,	Installed	Feet	Year	Feet	Year	Feet	Year	Installed	Feet	Year	Feet	Year	Feet	Year	
	1896	47	1904	80	1905	195	1906	1901	176	1914	110	1915	320	1916	
		71	1907	7	1908	46	1910		370	1917	136	1918	156	1919	
		46	1918	20	1920	102	1921		193	1920	191	1921	98	1922	
		46	1923	66	1924	32	1925		159	1923	152	1924	202	1925	
		40	1927	98	1929	134	1930		80	1926	46	1927	10	1928	
		58	1931	20	1932	27	1933		124	1929	14	1930	66	1931	
		20	1934 1940	77	1936	20	1939		56	1932	74	1933	56	1935	
	1007	34 69	1940	20 58	1941 1903	48	1905		52	1936	98	1937	67	1938	
	1897	70	1906	47	1911	46	1912	1902	164 25	1939 1907	44	1940	10	1020	
		127	1913	46	1914	20	1916	1902	20		66	1918	10	1920	
		85	1919	20	1925	66	1926		18	1921 1935	104	1926 1939	20	1933 1940	
		395	1927	20	1929	20	1937	1903	56	1903	92	1906	14	1909	
		66	1938	119	1939	20	1931	1903	166	1910	196	1911	139	1912	
	1898	136	1899	15	1901	60	1904		444	1913	98	1914	138	1917	
	1070	111	1906	26	1912	37	1913		14	1918	144	1919	276	1920	
		66	1914	70	1919	66	1920		286	1921	162	1922	94	1923	
		46	1922	46	1924	86	1926		92	1924	146	1925	126	1926	
		20	1928	70	1930	37	1934		186	1927	110	1928	82	1929	
		20	1935	43	1936	20	1937		171	1930	90	1931	88	1932	
		20	1939	20	1942	20	1701		136	1933	196	1934	258	1935	
	1899	36	1900	36	1901	36	1902		341	1936	210	1937	258	1938	
	10//	126	1903	52	1904	184	1905		266	1939	232	1940	160	1941	
		83	1906	164	1907	294	1908		213	1942	202	1210	100	1711	
		224	1909	215	1910	140	1911	1904	16	1905	32	1906	46	1907	
		246	1912	72	1913	113	1914		46	1908	61	1910	80	1911	
		217	1915	46	1916	67	1918		174	1912	488	1913	124	1914	
		166	1919	274	1920	50	1921		28	1915	48	1916	14	1917	
		66	1922	138	1923	98	1924		20	1918	63	1919	152	1920	
		46	1925	154	1926	106	1927		114	1921	80	1922	134	1924	
		36	1928	20	1929	212	1930		136	1925	98	1926	222	1927	
		52	1931	14	1933	14	1935		66	1928	146	1929	92	1930	
		26	1937	124	1938	188	1940		256	1931	131	1932	342	1933	
		63	1941	32	1942				136	1934	220	1935	106	1936	
	1900	66	1900	76	1901	150	1902		414	1937	92	1938	454	1939	
		133	1905	220	1906	268	1907		201	1940	246	1941	244	1942	
		214	1908	298	1909	245	1910	1905	24	1905	60	1906	153	1907	
		24	1911	217	1912	338	1913		74	1908	73	1909	62	1910	
		151	1914	94	1915	64	1916		248	1911	205	1912	497	1913	
		306	1917	266	1918	216	1919		272	1914	313	1915	74	1916	
		214	1920	147	1921	209	1922		14	1917	48	1918	26	1919	
		232	1923	304	1924	86	1925		439	1920	345	1921	184	1922	
		230	1926	285	1927	159	1928		387	1923	86	1924	385	1925	
		24	1929	182	1930	52	1931		310	1926	258	1927	430	1928	
		54	1932	74	1933	69	1934		476	1929	390	1930	624	1931	
		160	1936	249	1937	80	1938		263	1932	340	1933	504	1934	
		98	1939	66	1940	60	1941		208	1935	438	1936	563	1937	
	1001	14	1942						563	1937	564	1938	656	1939	
	1901	20	1901	29	1903	10	1904		532	1940	979	1941	437	1942	
		65	1905	315	1906	172	1907	1906	52	1906	106	1907	114	1908	
		358	1908	320	1909	140	1910		106	1909	399	1910	269	1911	
		164	1911	274	1912	171	1913		163	1912	264	1913	169	1914	

Ye Inste

1-IN. LEAD SERVICES (contd.) Retirements by Years (contd.)

Year Installed Feet Year Feet Year Feet Year Installed Feet Year	35 282 1936 38 413 1936 41 156 1946 12 35 1916 15 40 1916 18 34 1916 16 1926 24 10 1926 24 10 1926 28 52 1929 31 164 1936 34 82 1938 37 338 1938
1906 221 1915 150 1916 41 1917 1910 152 1934 50 19. 6 00 1918 114 1919 419 1920 662 1937 466 19. 315 1921 206 1922 258 1923 354 1940 458 19. 428 1924 407 1925 302 1926 1911 74 1911 341 19. 279 1927 387 1928 313 1929 80 1914 12 19. 352 1930 609 1931 354 1932 40 1917 46 19. 283 1933 196 1934 309 1935 165 1920 157 19. 623 1936 541 1937 677 1938 161 1923 128 19. 762 1939 373 1940 880 1941 40 1927 52 19.	35 282 193 38 413 193 41 156 194 12 35 191 15 40 191 18 34 191 21 168 192 24 10 192 28 52 192 31 164 193 34 82 193 34 82 193 37 338 1938
60 1918 114 1919 419 1920 662 1937 466 19.3 315 1921 206 1922 258 1923 354 1940 458 194 428 1924 407 1925 302 1926 1911 74 1911 341 191 279 1927 387 1928 313 1929 80 1914 12 191 352 1930 609 1931 354 1932 40 1917 46 191 283 1933 196 1934 309 1935 165 1920 157 192 623 1936 541 1937 677 1938 161 1923 128 192 762 1939 373 1940 880 1941 40 1927 52 192	388 413 193 411 156 194 12 35 191 15 40 1916 18 34 1919 21 168 192 224 10 1926 228 52 1929 31 164 193 34 82 1933 37 338 1938
315 1921 206 1922 258 1923 428 1924 407 1925 302 1926 279 1927 387 1928 313 1929 352 1930 609 1931 354 1932 283 1933 196 1934 309 1935 623 1936 541 1937 677 1938 762 1939 373 1940 880 1941 315 1940 458 194 1911 74 1911 341 194 80 1914 12 194 40 1917 46 194 165 1920 157 194 161 1923 128 194 40 1927 52 194	41 156 194, 12 35 191, 15 40 1916 18 34 1919 21 168 192; 224 10 1926 228 52 1926 31 164 193; 34 82 1933 37 338 1938
428 1924 407 1925 302 1926 1911 74 1911 341 19 279 1927 387 1928 313 1929 80 1914 12 19 352 1930 609 1931 354 1932 40 1917 46 19 283 1933 196 1934 309 1935 165 1920 157 193 623 1936 541 1937 677 1938 161 1923 128 192 762 1939 373 1940 880 1941 40 1927 52 193	12 35 191; 15 40 1916 18 34 1919 21 168 192; 24 10 1926 28 52 1929 31 164 193; 34 82 1933 37 338 1938
279 1927 387 1928 313 1929 80 1914 12 19 352 1930 609 1931 354 1932 40 1917 46 19 283 1933 196 1934 309 1935 165 1920 157 193 623 1936 541 1937 677 1938 161 1923 128 192 762 1939 373 1940 880 1941 40 1927 52 193	15 40 1916 18 34 1919 21 168 1922 24 10 1926 28 52 1926 31 164 1933 34 82 1938 37 338 1938
352 1930 609 1931 354 1932 283 1933 196 1934 309 1935 623 1936 541 1937 677 1938 762 1939 373 1940 880 1941 40 1927 52 193	18 34 1919 21 168 1927 24 10 1920 28 52 1920 31 164 1931 34 82 1931 37 338 1938
283 1933 196 1934 309 1935 165 1920 157 193 623 1936 541 1937 677 1938 161 1923 128 193 762 1939 373 1940 880 1941 40 1927 52 193	21 168 1922 24 10 1926 28 52 1926 31 164 1933 34 82 1938 37 338 1938
623 1936 541 1937 677 1938 161 1923 128 193 762 1939 373 1940 880 1941 40 1927 52 193	24 10 1926 28 52 1929 31 164 1933 34 82 1933 37 338 1938
762 1939 373 1940 880 1941 40 1927 52 192	28 52 1929 31 164 1933 34 82 1933 37 338 1938
102 1707 010 1710 000 100	31 164 1932 34 82 1933 37 338 1938
	34 82 1935 37 338 1938
261 4022 202 403	37 338 1938
1907 16 1907 46 1910 55 1911 264 1933 292 193 97 1912 196 1913 66 1914 264 1936 452 193	
14 1915 24 1916 155 1917 290 1939 354 194	
46 1918 96 1919 217 1920 150 1942	1741
206 1921 139 1922 94 1923 1912 102 1913 40 191	14 68 1915
88 1924 74 1925 40 1926 50 1916 40 191	
163 1927 45 1928 246 1929 163 1920 34 192	
60 1930 121 1931 154 1932 168 1923 24 192	
123 1933 274 1934 369 1935 160 1928 90 192	
350 1936 323 1937 160 1938 10 1931 99 193	
295 1939 312 1940 369 1941 66 1934 367 193	
252 1942 126 1937 311 193	
1908 12 1908 14 1909 40 1910 386 1940 312 194	
16 1911 147 1912 52 1913 1913 126 1913 14 191	
60 1914 92 1918 46 1919 66 1920 127 192	
20 1920 25 1921 52 1922 140 1924 358 192	
37 1923 55 1924 14 1925 126 1927 128 192	
14 1927 100 1928 60 1929 134 1930 196 193	
76 1930 76 1931 97 1932 268 1933 144 193	
127 1933 14 1934 52 1935 270 1936 241 193	
144 1936 86 1937 140 1938 204 1939 462 194	
266 1939 245 1940 203 1941 182 1942	0.00 1741
104 1942 1914 40 1914 52 191	5 50 1916
1909 80 1911 34 1912 60 1913 43 1917 50 191	
52 1914 153 1915 72 1916 136 1920 190 192	
104 1917 79 1918 65 1919 75 1923 36 192	
52 1920 66 1921 34 1922 132 1927 40 192	8 114 1929
14 1923 14 1925 88 1926 149 1930 42 193	
50 1927 66 1928 132 1929 116 1933 330 193	
184 1930 80 1931 54 1932 254 1936 426 193	
64 1933 106 1934 52 1935 112 1939 158 194	
64 1936 76 1937 118 1938 132 1942	
330 1939 100 1940 166 1941 1915 29 1915 14 192	6 20 1927
274 1942 78 1928 24 192	9 79 1930
1910 52 1911 260 1912 52 1913 14 1938 14 193	
130 1914 47 1915 54 1917 52 1941	
12 1919 92 1920 50 1921 1916 52 1918 46 1920	0 46 1921
132 1922 14 1923 83 1924 14 1924 46 192	
161 1925 191 1926 94 1927 16 1932 77 193	
156 1928 63 1929 114 1930 14 1937 18 193	
238 1931 66 1932 88 1933 14 1941 72 1945	

½-IN. LEAD SERVICES (contd.)
Retirements by Years (contd.)

Year Installed	Foot	Year	Foot	Year	Feet	Year	Year Installed	Foot	Veam	East	V	Feet	17
									Year		Year		Year
1917	104	1920	60	1922	46	1923	1922	62	1923	26	1928	64	1929
	46	1926	52	1928	66	1929		107	1930	93	1931	104	1932
	7	1934	14	1936	56	1939		74	1934	175	1937	96	1938
	52	1940	52	1941				165	1939	116	1940	59	1941
1918	52	1921	52	1923	46	1924	1923	46	1926	46	1929	14	1930
	46	1926	14	1933	28	1936		12	1933	52	1934	34	1937
	28	1939	16	1940	60	1942		66	1939	52	1940	23	1941
1919	14	1920	10	1922	14	1929		42	1942				
	34	1930	50	1935	14	1936	1924	52	1934	52	1935	32	1937
	14	1938	66	1939	66	1941		14	1938	52	1939	14	1940
1920	21	1921	52	1922	37	1923	1925	20	1927	25	1929	48	1930
	52	1924	89	1925	104	1926		20	1931	52	1937	52	1938
	104	1928	72	1929	215	1930		82	1939	14	1940		
	36	1931	52	1932	170	1933	1926	72	1928	52	1929	14	1931
	46	1934	62	1935	126	1936		14	1936	60	1937	41	1939
	180	1937	429	1938	72	1939		80	1940	128	1941	20	1942
	104	1940	64	1941	117	1942	1927	28	1933	52	1935	156	1937
1921	66	1923	14	1924	46	1926		14	1939	36	1940		
	97	1928	126	1929	28	1930	1928	128	1932	52	1935	14	1937
	52	1931	52	1932	28	1933		14	1939	14	1941		
	52	1935	156	1936	156	1937	1929	52	1929				
	52	1938	222	1939	112	1940	1930	14	1942				
	156	1941											

§-IN. LEAD SERVICES

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1895	160	160	0	1919	830	750	80
1898	77	31	46	1920	2,832	2.663	169
1899	1,253	678	575	1921	2,688	2,477	211
1900	4,191	2,574	1,617	1922	3,271	2,802	469
1901	6,207	4,129	2,078	1923	2,341	2,275	66
1902	17,730	11,683	6,047	1924	2,252	2,238	14
1903	7,723	5,470	2,253	1925	2,058	2,037	21
1904	14,203	12,362	1,841	1926	2,344	2,258	86
1905	29,551	25,685	3,866	1927	3,004	3,004	0
1906	26,121	21,117	5,004	1928	1,003	933	70
1907	15,676	12,642	3,034	1929	942	942	0
1908	15,847	14,461	1,386	1930	204	204	0
1909	12,745	10,531	2,214	1931	255	255	0
1910	14,966	12,855	2,111	1939	112	112	0
1911	18,301	17,301	1,000	1941	438	438	0
1912	20,035	18,327	1,708	1942	656	604	52
1913	17,351	14,980	2,371		-		
1914	10,003	9,065	938	SUBTOTAL	259,905	220,460	39,445
1915	1,056	1.004	52	Unknown	698	96	602
1916	464	412	52				
1917	513	499	14	TOTAL	260,603	220,556	40,047
1918	502	502	0		*		

5-IN. LEAD SERVICES (contd.)

Retirements by Years

							R	etireme	ents by Yo	ears								
Yea									Yea									
Insta			Yea		eet Y	ear	Feet	Year	Insta		Feet	Yea	r F	eet	Year	Z	eet	V.
189	40	46	194						190		184				1937			Year
189	9	60	190			13	68	1914			170				1940		88	1938
		14	191			20	20	1921			14			00	1740	1	50	1941
		14	192		20 19		52	1929	190.	5	14			14	1907		12	
		46	193		20 19		68	1935			50		-		1913			1909
100		18	193		32 19		14	1942			52				1918			1914
1900)	75	190		10 19		29	1906			118	192			1921	(1919
		20	190		8 19		52	1913			86	192			1925		-	1922
		46	191		4 19	18	46	1919			84	192			930			1928
		54	1920		6 192		14	1924			94	193		-	933	20		931
		12	1926		2 192		95	1928			217	193			936	27		934
		50	1929				119	1931			214	1938			939			
		46	1935				102	1937			375	1941		_	942	7	0 1	940
		66	1938		1 193	9	46	1940	1906		74	1909			910	7	7 1	911
1901		86	1941			2	0.0			1	182	1912		-	913	2	-	914
1901		52	1901	-			20	1905	1		68	1916			917	5		914
		66 34	1906				39	1908	1		80	1919			920	11		221
			1910				08	1913			25	1922			923	5		024
			1914 1917				30	1916			04	1925			926	129		27
	14		1917				64	1921			73	1928	117		29	301		
			1922	59 65			52	1926			46	1931	156		32	313		
	6		1931	46			25	1930			22	1934	156	19	35	244	~ .	
	7		1936	52			10	1933			38	1937	176		38	501		
	40		940	52			36	1939	4000		58	1940	366	-	41	52		
1902	56		903	82	1941		52	1942	1907		14	1910	109	-	11	66		
	128		908	14	1910			1907 1911			28	1913	14	19		14		
	20		912	351	1913			1911			06	1918	20	-		121		0
	42		915	106	1916			1914			52	1921	114	19.		66		
	108		918	120	1919	16		1920		23		1924	142	19		92	192	
	155		921	127	1922	20		1923			4	1928	167	19:		52	193	
	14		924	206	1925	11		1926		22		1931	92	19.		108	193	18
	188		927	286	1928	25		1929		10		1935	105	193		88	1937	18
	48		930	148	1931	31		1932		13 19		1938	160	193		352	1940	
	83		933	268	1934	10	-	1935	1908	2		1941	41	194				18
	294		936	124	1937	46.	-	938	1908	5.		1912	52	191		12	1918	189
	350	19	039	261	1940	10-		941		1.30		1919	38	192		14	1921	190
	210	19	142					**		89	-	922	46	192		52	1924	190
1903	60	19	006	84	1908	62	1	910		40		932	10	193		14	1931	190
	14	19	13	14	1917	56	-	919		150		932	97	193		52	1934	190
	156	19	20	52	1921	14		923		68		940	96	193		52	1938	190
	123	19		52	1925	152		926	1909	52		912	178	194	-	08	1942	190.
	108	19		170	1928	216		929	1707	14		915	24 81	191.		52	1914	1900
	122	19		52	1932	196		933		72		920	118	1918		14	1919	1907
	60	19.		60	1935	20		937		62			106	1922		50	1923	1908
	30	19,		180	1939	80		040		66		931		1926			1929	1909
	120	19								52		934	14	1932			1933	1910
1904	46	190		79	1909	52	19	11		232			152	1935			1936	1911
	14	191		66	1913	72		15		158		940	80	1938			1939	1912
	52	191		24	1920	80		21	1910	130		112		1941			1942	1913
	156	192		36	1925	95	19			95		119		1913			1917	1914
	58	192		14	1929	66	19	- 1		66		24		1920			1922	1915
	52	193	2 1	03	1934	52	19			118		30		1926	_		1927	1916
										110	19	30	98	1931	4	0 1	9,33	

1-IN. LEAD SERVICES (contd.)

Retirements by Years (contd.)

				•	Comen	iems oy	10013 (00)	icu.,					
Year Installed	Feet	Year	Feet	Year	Feet	Year	Year Installed	Feet	Year	Feel	Year	Feet	Year
1910	86	1934	96	1935	60	1936	1913	343	1941	52	1942		
	178	1937	66	1938	112	1939	1914	24	1917	52	1921	53	1922
	208	1940	500	1941	104	1942		52	1929	52	1930	91	1931
1911	10	1912	52	1915	66	1920		46	1933	52	1934	60	1935
	42	1922	92	1923	38	1925		152	1936	152	1937	14	1938
	24	1929	14	1930	14	1932		52	1940	12	1941	74	1942
	40	1936	52	1937	14	1939	1915	52	1942				
	168	1940	374	1941			1916	52	1919				
1912	14	1914	52	1916	60	1917	1917	14	1921				
	12	1919	229	1920	52	1922	1919	52	1921	10	1935	18	1940
	44	1923	40	1924	30	1925	1920	14	1922	14	1929	35	1931
	52	1926	11	1927	24	1928		54	1934	52	1937		
	102	1929	14	1930	118	1932	1921	14	1926	47	1933	52	1936
	126	1933	106	1934	60	1935		46	1940	52	1941		
	102	1936	102	1937	170	1938	1922	20	1923	136	1929	15	1930
	66	1939	42	1940	14	1941		32	1934	18	1935	52	1936
	66	1942						138	1938	58	1939		
1913	52	1920	156	1923	70	1924	1923	14	1930	52	1931		
	104	1925	52	1926	46	1928	1924	14	1934				
	52	1929	118	1930	90	1931	1925	21	1937				
	46	1932	96	1933	66	1934	1926	52	1930	20	1938	14	1942
	106	1935	104	1936	196	1937	1928	56	1931	14	1941		
	196	1938	172	1939	254	1940	1942	52	1942				

3-IN. LEAD SERVICES

Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retired
1894	1,560	806	754	1917	484	377	107
1895	2,741	1,103	1,638	1918	1,044	942	102
1896	1,818	1,177	641	1919	760	657	103
1897	1,663	865	798	1920	1,654	1,408	246
1898	1,453	753	700	1921	1,512	1,345	167
1899	2,628	2,035	593	1922	2,203	2,151	52
1900	1,675	850	825	1923	1,506	1,322	184
1901	2,065	1,102	963	1924	1,427	1,151	276
1902	4,049	2,992	1,057	1925	1,654	1,541	113
1903	5,357	4,065	1,292	1926	1,541	1,423	118
1904	5,462	4,589	873	1927	1,304	1,264	40
1905	5,137	3,689	1,448	1928	1,293	1,279	14
1906	10,827	9,170	1,657	1929	1,952	1,938	14
1907	3,670	2,691	979	1930	672	672	0
1908	3,162	2,564	598	1931	342	316	26
1909	4,136	3,042	1,094	1932	76	76	0
1910	3,745	3,010	735	1939	66	66	0
1911	3,690	3,166	524	1942	9,452	9,452	0
1912	5,210	3,779	1,431				
1913	4,041	3,433	608	SUBTOTAL	107,737	86,571	21,166
1914	3,164	2,824	340	Unknown	1,560	332	1,228
1915	1,039	1,001	38				
1916	503	485	18	TOTAL	109,297	86,903	22,394

3-IN. LEAD SERVICES (contd.)

Retirements by Years

					1	cerer emer	us by rear.	3						
Year			-	24	_		Year	-						
Install	ed Fee	et Yea	r Fee	et Year	Fee	t Year	Installed	Feel	t Year	Feel	Year	Fee	t Ye	ar In
1894	20			1906	46	1907	1903	29	1921	74	1922	56	19	24
	1.				130			42					19	27
	6				20			14						30
	40			5 1929	46	1936		14						36
	104							120		46	1939	126	19	10
1895	6.				114			46						
	39				20		1904	46		26				
	66				19			46						14
	52				228			20				52		
	46				46			46		14	1929	76		
	20				282	1937		14	1932	40	1934	104		5
	64							46	1937	36	1938	48		
1896	46				46			52	1940	14	1941	20		2 19
	32				46		1905	40	1908	44	1910	66		1
	14				1.7	1940		27	1912	52	1913	24		
	46		21					98	1917	12	1918	66	192	0 19
1897	46				105	1913		20	1921	104	1922	52	192	6
	135				20	1922		36	1928	100	1929	88	193	
	46		34		97	1930		14	1931	42	1932	54	193	3
	20		20	1933	100	1936		38	1934	14	1935	151	193	5
	86		46	1940	20	1941		70	1938	110	1939	106	194	
1898	50	1902	67	1905	14	1906		20	1941					Inste
	197	1908	40	1910	20	1911	1906	46	1906	27	1910	27	1911	
	42	1913	18	1914	138	1920		49	1912	56	1914	41	1917	189
	20	1921	22	1930	46	1931		82	1919	46	1920	45	1921	189
	26	1936						23	1925	80	1926	30	1927	190
1899	14	1904	26	1914	12	1915		83	1928	46	1929	67	1930	190
	46	1922	52	1923	52	1925		54	1931	27	1932	173	1933	190
	52	1926	56	1929	52	1930		66	1934	25	1935	56	1936	190
	69	1931	52	1936	20	1937		166	1939	96	1940	32	1941	190
	60	1941	30	1942				214	1942					190
1900	46	1901	24	1903	20	1904	1907	140	1913	46	1916	52	1918	190
	154	1908	20	1910	73	1915		12	1920	31	1921	56	1922	190
	20	1919	14	1921	10	1924		45	1925	52	1932	52	1933	1908
	42	1926	20	1927	66	1930		52	1934	46	1935	52	1936	1909
	12	1933	46	1935	7	1936		56	1937	175	1939	52	1940	1910
1.00	99	1939	152	1940				60	1941					1911
1901	32	1903	97	1908	70	1910	1908	20	1909	108	1911	14	1912	1912
	33	1912	120	1913	29	1915		62	1913	58	1915	37	1916	1913
	30	1916	20	1917	15	1918		25	1929	104	1935	14	1938	1914
	114	1919	55	1920	15	1921		104	1939	52	1940		30.	1915
	62	1924	56	1926	97	1939	1909	42	1911	52	1912.	124	1913	1916
	14	1940	104	1941				54	1914	82	1919	52	1921	1917
1902	112	1903	48	1905	14	1908		62	1929	14	1930	52	1931	1918
	46	1911	116	1913	14	1914		52	1936	66	1937	168	1938	
	24	1915	50	1922	46	1923		50	1939	196	1940		1941	
	24	1927	84	1928	59	1929	1910	37	1912	64	1913		1926	17
	14	1930	24	1932	66	1933			1928	28	1929	~ ~	1932	Year
	20	1934	78	1935		1936			1934	96	1936		1938	Installe
	30	1937	47	1938	31	1939			1939	14	1940		1941	1897
	14	1941	44	1942			1911	52	1916	16	1917		1921	1898
1903	28	1905	53	1908	52	1911		52	1924	36	1930		1935	1899
	72	1912	128	1913	66	1914		52	1936	52	1937	126	1938	1901

1-IN. LEAD SERVICES (contd.)

Retirements by Years (contd.)

Year Installed	Feet	Vear	Feet	Year	Feet	Vear	Year Installed	Feet	Year	Feet	Year	Feet	Year
	52	1939	14	1940	2 000		1917	20	1918	46	1935	41	1937
1911	46	1914	27	1916	52	1918	1918	50	1929	52	1941	**	1701
1912	52	1919	90	1922	14	1924	1919	20	1921	83	1941		
	46	1925	14	1927	46	1928	1920	52	1922	14	1926	62	1929
	137	1929	46	1931	66	1932		66	1940	52	1941		
	14	1934	52	1936	104	1937	1921	129	1936	38	1939		
	193	1938	54	1939	222	1940	1922	52	1942				
	104	1941	52	1942			1923	14	1926	52	1935	118	1941
1913	42	1924	14	1928	52	1931	1924	82	1930	90	1939	104	1941
	88	1933	52	1934	156	1936	1925	52	1937	9	1939	52	1941
	86	1937	52	1939	52	1940	1926	52	1936	14	1940	52	1941
	14	1942					1927	26	1931	14	1939		
1914	26	1915	46	1927	14	1928	1928	14	1940				
	104	1936	52	1938	98	1940	1929	14	1941				
1915	14	1926	24	1931			1931	26	1937				
1916	18	1938											

1-IN. LEAD SERVICES

			I-IN. LEAI	DERVICES			
Year		Feet		Year		Feet	
Installed	Installed	In Service	Retired	Installed	Installed	In Service	Retire
1897	90	20	70	1919	1,292	1,137	155
1898	20	0	20	1920	1,199	990	209
1899	130	78	52	1921	885	743	142
1900	455	455	0	1922	928	669	259
1901	387	236	151	1923	630	520	110
1902	462	388	74	1924	1,075	818	257
1903	212	152	60	1925	848.	727	121
1904	791	573	218	1926	1,655	1,655	0
1905	2,218	2,037	181	1927	1,136	1,070	66
1906	2,648	2,200	448	1928	1,192	1,192	0
1907	1,534	1,292	242	1929	1,111	1,111	0
1908	1,378	952	426	1930	334	334	0
1909	2,491	2,402	89	1932	14	14	0
1910	3,191	2,872	319	1933	26	26	0
1911	4,117	3,728	389	1939	1.5	15	0
1912	5,659	5,144	515	1942	0	0	0
1913	4,169	3,824	345				
1914	5,134	4,832	302	SUBTOTAL	51,054	45,300	5,754
1915	860	860	0	Unknown	357	46	311
1916	801	693	108		-	-	
1917	975	755	220	TOTAL.	51,411	45,346	6,065
1918	992	786	206				

Retirements by Years

Year Installed	Feet	Year	Feet	Year	Feet	Year	Year Installed	Feet	Year	Feet	Year	Feet	Year
		1915					1902	20	1906		1933		
1898	20	1935					1903	46	1909	. 14	1926		
1899 1901	52	1928					1904	98	1909	14	1927	46	1932
1901	46	1903	105	1908				14	1935	46	1940		

1-IN. LEAD SERVICES (contd.)

Retirements by Years (contd.)

Year	Fast	Veen	Each	Wagn	Fred	17	Year	F 4	17	P. 4	27		
Installed	Feet		Feet		Feet		Installed		Year	reet	Year	Feet	Year
1905	40	1907	15	1922	14	1928	1913	20	1914	21	1922	14	1924
	20	1929	46	1936	12	1937		40	1931	44	1936	46	1939
	34	1939						28	1940	132	1941		*
1906	15	1912	28	1913	15	1925	1914	12	1917	14	1927	52	1931
	16	1927	66	1929	78	1932		14	1934	14	1937	14	1938
	40	1933	104	1934	20	1935		40	1939	10	1940	132	1941
	20	1936	46	1938			1916	108	1940				
1907	58	1913	14	1927	31	1928	1917	36	1920	132	1926	52	1940
	20	1930	39	1937	80	1940	1918	59	1929	104	1935	43	1939
1908	30	1913	54	1920	46	1923	1919	28	1922	63	1936	46	1940
	24	1925	81	1928	44	1929		18	1941				
	114	1930	33	1939			1920	144	1930	14	1934	28	1936
1909	24	1926	13	1927	52	1934		23	1939				
1910	52	1910	48	1913	14	1919	1921	14	1928	52	1931	76	1936
	10	1921	15	1924	58	1929	1922	186	1933	38	1935	21	1936
	60	1937	58	1940	14	1941		14	1942				
1911	14	1917	10	1928	75	1934	1923	24	1928	86	1941		
	16	1939	118	1940	156	1941	1924	108	1937	129	1939	20	1941
1912	33	1914	43	1920	40	1924	1925	54	1927	15	1935	52	1941
	21	1926	46	1933	16	1935	1927	14	1927	52	1941		*- **
	52	1938	62	1940	202	1941							

LIN LEAD SERVICES

			and the state of	DERVICES		
Year		Feet			Retirements	by Years
Installed	Installed	In Service	Retired	Year	_	
1899	18	0	18	Installed	Feet	Year
1910	104	104	0	1899	18	1939
1942	0	. 0	0			
TOTAL	122	104	18			

2-IN. LEAD SERVICES

Year		Feet			Retirements	by Years
Installed	Installed	In Service	Retired	Year	P 1	17
1895	21	0	21	Installed	Feet	Year
1906	116	70	46	1895	21	1919
1917	48	48	0	1906	46	1928
1918	24	14	10	1918	10	1935
1919	160	160	0			
1931	52	52	0			
1942	0	0	0			
	-					
TOTAL	421	344	77			

(M

(M by 194 follo Hea Met

T Unit G. Tek! (Ger boile preving water

adde

4-11' vent bicar' Meth Na h Amer tions vente satn.

with I rides; exchar water bicarb bonate of H₂S since c 4.6% c of cooli

scale for off port water : gypsum tion wo improb:

Amt. of residual and con proved

Abstracts of Water Works Literature

Key: In the reference to the publication in which the abstracted article appears, 34: 412 (Mar. '42) indicates volume 34, page 412, issue dated March 1942. If the publication is paged by the issue, 34: 3: 56 (Mar. '42) indicates volume 34, number 3, page 56, issue dated March 1942. Initials following an abstract indicate reproduction, by permission, from periodicals, as follows: B.H.—Bulletin of Hygiene (British); C.A.—Chemical Abstracts; P.H.E.A.—Public Health Engineering Abstracts; W.P.R.—Water Pollution Research (British); I.M.—Institute of Metals (British).

BOILERS, FUEL AND FEEDWATER

The Combating of Boiler Scale in Cooling Units Having Recirculated Water Supplies. G. E. KRUSHEL. Vodosnabzhenie i Sanit. Tekh. (U.S.S.R.) 16: 5: 29 ('41); Chem. Zentr. (Ger.) II: 1832 ('42). Formation of inorg. boiler scale in closed cooling systems can be prevented by drawing off portion of circulating water or by chem. treatment of added water. Former method effective only when added water carries temporary hardness of 4-11°. Added water can be treated to prevent decompn. of bicarbonates or to reduce bicarbonate hardness of evapg. water to <12°. Methods used for this purpose: (1) addn. of Na hexametaphosphate (this method used in America but according to Russian investigations deposition of CaCO3 not entirely prevented by use of small amts. of reagent); (2) satn. of circulating water with CO2 to maint. state of equil.; (3) treatment of added water with HCl to convert bicarbonates into chlorides; (4) softening added water in cationexchange filters; (5) addn. of lime to added water with subsequent filtration to remove bicarbonates; and (6) conversion of bicarbonates in added water into sulfates by addn. of H2SO4. Last method especially expedient, since consumption of addnl. water only 2.6 or 4.6% of circulating water, depending on type of cooling unit. This an advantage even when scale formation can be prevented by drawing off portion of water as, e.g., in regions where water supply not abundant. Deposition of gypsum need not be feared, since such deposition would be possible only for water having improbably high gypsum hardness of 35-40°. Amt. of H2SO4 used must be such that certain residual alky, remains so that attack of metal and concrete avoided. Methods 3 and 4 also proved satisfactory.—C.A.

Year

1924 1939

1931

1938

1941

1940

1939

1940

1936

1936

1936

1941

1941

Determining Amounts of Contaminated Material Entering Boilers. B. C. SPRAGUE. Combustion 16: 1: 45 ('44). Measure of contaminating impurities entering boiler can be had from relation of concns. of components of treating chems, and of impurities remaining in soln. in boiler water. Simple expression is offered to illustrate this method. Measure based on principle that, to extent that various chem. components added to boiler water remain in soln., their concns. in feedwater will have same relation to each other as amts. added. Where phosphate treatment employed, measure of contamn. can probably most conveniently be based on concns. of PO4 and SO4 in boiler water. Since phosphate treatment prevents pptn. of sulfates, all of sulfate in impurities remains in soln. in boiler Some of phosphate added enters into combination with Ca and Mg salts getting into feedwater with impurities and is pptd. from soln., leaving in soln. uncombined phosphate. Knowledge of hardness and SO₄ concn. of raw water makes it possible to adjust for quant. of phosphate which will be elimd. in pptg. Ca and Mg salts. In order to minimize effect of treatment added to boilers on filling, SO4 and PO4 concns. in boiler water should be based on avgs, from boilers that have been in service some time since refilling.—C.A.

The Removal of Silica From Boiler Water. W. F. GERRARD. Power & Works Engr. (Br.) 38: 281 ('43). Effects of silica in boiler water and methods for its removal from water described. Methods for removing silica may be divided into 3 classes: those in which chems., added to softened water, combine with residual calcium and so prevent formation of calcium silicate which produces scale; those in

of

ppr

bin

SiO

SiO

wat

pou

UFE

Ren

hard

with

hard

expt

filter

then

phen

quan

time

fies a

min.

addir

of 48

soln.

salts

cation

ples p

treatr

FeCl₃

agent

mg./1.

adsorp

silicat

water

Freun

CaO, amt.,

dissolv

from 1

pptn.

pptd.

Wat

Vapor-

Units

C. E. I

lems o

side or

brittler

oil fron glucosa

condens

which silica adsorbed by coagulants added with chems, used for softening; and those in which silica pptd. In third class of methods insoluble silica compd. removed by filters in softening plant. In B.P. 527,153 use of magnesium oxide and barium hydroxide for softening water and for removing silica described. Further work has shown that removal of silica by magnesium oxide affected by commercial grade of magnesium oxide used, by temp., and by intimacy and period of contact of reagent with water. Method of application of magnesium oxide to boiler water described in B.P. 542,751 now in use on large scale and known as "M.W." process. Magnesium oxide added to softened water to remove silica also removes permanent hardness remaining in water; also reacts with carbon dioxide and maints. pH value of boiler water above 9.4. Old deposits in boilers often disintegrate after water treated for few months by this process.—W.P.R.

Use of Electrophotometric Methods for Analysis of Raw, Treated and Boiler Waters, Boiler Scale and Boiler Sludge. H. M. LAUDEMANN ET AL. Am. Ry. Engr. Assn. 45: 441: 52 (Nov. '43). Investigation indicates that development of these methods not yet reached stage where suitable standardized procedures can be recommended. Types of equip. in use described briefly.—R. C. Bardwell.

Modern Water Purification for High-Pressure Boilers in Industrial Plants. E. PFLEIDERER. Chem.-Ztg. (Ger.) 68: 56 ('44). For boiler water, prelim. treatment with CaO followed by phosphate treatment. After settling and filtering, water treated with SO₂ to remove traces of O. With turbines, difficulties encountered owing to pptn. of SiO₂. Removed by addns. of MgO and CaO. Use of Mg(OH)₂ leads to better floc. Residual hardness removed with nonsiliceous exchange substance (Wofatit). Flow sheets included and use of complete demineralization with exchange substances noted.—C.A.

Inhibitors for Acid Washes to Remove Boiler Scale. A. P. Mamet. Tekstil. Prom. (U.S.S.R.) 4: 7: 25 ('44). More than 40 substances tested for eff. in protecting metal parts when boilers and similar installations acid-treated to remove scale. Inhibiting effect (τ) measured by percentage by which inhibitor decreases loss in wt. of metal treated in given acid in g. per sq.m. per hr. High τ due to

presence of certain polar groups. Of these most effective are N- and S-contg. heterocycles, and CHO group; NH2 and azo groups less effective; OH, CO2H and SO3H, still less so, \u03c4 increases with increase in molecular wt. of compd. and number of polar groups. For most effective inhibitors tested, added in quants. of 2-10 g./l. to 10% HCl (cold), 7 85-99%. In decreasing order of their effectiveness they were urotropine (I), formalin (II), Unicol (vegetable extract) (III), quinoline (IV), furfural and joiners glue (V). Inhibit. ing action specific and depends on acid and temp. I and II most effective in cold 10% HCl ($\tau = 94\%$). In cold 5% H₂SO₄ IV (τ = 96%) and NH₄CNS most effective. In cold 10% $H_3PO_4NH_4CNS$ ($\tau = 98\%$) and V $(\tau = 96\%)$ most effective. For HCl + HF I and II gave best results. In HCl (concn. 2-10%) τ diminishes with increase in concn. of acid; in H3PO4 it increases; while in H2SO4 (concn. 0.5-5%) not affected significantly. Increase in temp. generally lowers 7. When added in sufficient quants. 7 of V remained const. for rising temps. up to 100° in all acids except H₃PO₄. For III τ declines sharply at temps. above 60-70°. In HCl and HCl + HF I and II remain almost unaffected by temp. Furfural strongly affected by temp. Generally at elevated temps. H₂PO₄ hardest to inhibit, while HF and HCl + HF easiest. Effect of most inhibitors on soly. of CaCO in acids not significant; soly. of CaCO2 in cold HCl decreased noticeably by V and that in warm H₃PO₄ by I. Thus boiler scale can be safely dissolved at any temp, up to boiling provided proper inhibitor added to acid soln. At boiling temps. H₃PO₄ better avoided.-C.A.

Common Causes of Boiler Tube Failures. H. GLYDE GREGORY. Intern. Sugar J. (Br.) 47: 45 ('45). Most frequent causes of boiler tube failures are bagging, blistering, or rupturing due to internal deposits which insulate tube metal from cooling medium, and corrosion due to oxygen or other components of feed and boiler water. In sugar mills greatest loss caused by outside corrosion during dead season. All soot should be removed from tubes and coat of preservative added after crop.—C.A.

Silica Deposition in Steam Turbines. F.G. STRAUB & H. A. GRABOWSKI. Combustion 16: 7: 41 ('45). Lab. and power-plant tests conducted to det. cause of deposition of SiO:

01.37

these

etero-

roups

l less

wt. of

For

ed in

ld), +

effec-

malin

noline

hibit-

and

10%

IV (T

. . In

and V

+ HF

concn.

H2SO,

antly. When

acids

ply at + HF

temp.

Gener-

est to

asiest.

CaCO₁

n cold

hat in

can be

ooiling I soln.

ded.-

ilures.

(Br.)

boiler

r rup-

sulate

corro-

nts of

reatest g dead

from

after

F.G.

ustion

t tests of SiO₁ in steam turbines indicate that SiO_2 leaves boiler as vaporized silicic acid, which later crystallizes on blades in lower-pressure stages of turbine. When SiO_2 in steam below 0.1 ppm., no appreciable deposits found in turbines. Deposits can be prevented by maintg. SiO_2 in boiler water below 5 ppm. or removing SiO_2 from steam by scrubbing with pure mater.—C.A.

Silica Removal From Water With Compounds of the Alkaline Earth Metals. WILLI UFER. Angew. Chem. (Ger.) 54: 496 ('41). Removal of silica from tap water with total hardness of 12-13.6° (Ger.) investigated with CaO. Before addn. of lime, carbonate hardness removed by boiling for 1 hr. All expts. performed in iron vessels. Samples filtered prior to pptn. of dissolved lime and then CO2 passed into water to permanent phenolphthalein pink. Desilicification with quants, of CaO less than soly, dependent upon time at 100°. At 100°, 150 mg./l. CaO desilicifies after 10 min. to 1.6 mg./l. S'O2, after 40 min. to 0.6. Desilicification is improved on adding amts. of CaO exceeding soly. Addn. of 4800 mg./l. at 30° leaves 0.2 mg. SiO₂ in soln. In presence of excess solid, CaO neutral salts and temp. have no influence on desilicification. Effectiveness of different lime samples proportional to their surface area. After treatment of limed water with 20 mg./l. FeCl₃ and 20 mg./l. AlCl₃ as flocculating agents clarifies soln. and desilicifies to 0.1 mg./l. SiO₂. That desilicification depends on adsorption as well as on pptn. of insol. Ca silicate shown by adsorption expt. with lime water (1.45 mg./l. CaO) which followed Freundlich adsorption law. With excess solid CaO, equil. concn., independent of initial amt., adjusts itself to 0.2 mg./l. Pptn. of dissolved lime also causes desilicification, e.g., from 1.0 mg./l. SiO2 before pptn. to 0.5 after pptn. Same effect also occurs when lime is pptd. with $(NH_4)_2C_2O_4$.—C.A.

Water Treating. Corrosion Prevention by Vapor-Phase Treatment in Steam-Making Units Is One of the New Developments. C. E. Erb. Oil Gas J. 41: 198 ('43). Problems of treatment of water in oil refineries discussed. Treatment of water with β-glucoside or its derivatives prevented caustic embittlement. Glucosate effective in removing oil from tubes of water tube boiler. Chrome glucosates prevented corrosion on oil side of condensers and in units using steam for proc-

essing. Inhibitors in aqueous soln. injected into steam have reduced corrosion in pipes carrying condensed steam. Methods for control of algae and bacteria and for prevention of scale formation discussed. Cupric chromoglucosate has proved useful for control of micro-organisms and for prevention of corrosion.—W.P.R.

Tube Pitting Traced to Unequal Water Flow. RALPH BRISCOE. Elec. World 119: 443 (Feb. 6, '43). Importance of proper feedwater distr. within boiler drum to provide uniform water quants. for circulation to all parts of boiler demonstrated. In boilers installed only 2 yr. previously, pitting occurred in front row tubes. No such evidence for 5- to 6-yr.-old boilers. Actual pressure under which water injected into drum and distributed is difference between boiler-line feed pressure and drum steam pressure. In this case, differential never exceeded 50 psi. With boiler out of service, therefore, simple to reproduce operating conditions. Boiler-feed line disconnected and reconnected to house service supply, about 80 psi. at this el. With orifice in line and boiler drum manhole doors removed, possible to observe and measure water flow and distr. along feed trough inside drum. As water led into 2 top outside drums, quant. equal to 1 steam output introduced at all outputs. By varying water quant., observed distr. corresponding to various outputs in boiler. Revealed water quant. flowing from feed trough at one end greatly exceeded that from other over wide range. Corrosion or pitting confined to tubes in section where flow from feed trough least, i.e., end nearest inlet end of feed pipe and in tubes nearest fire. Little or no pitting occurred in portion securing large quants. of water. After capping end of 25' feed pipe, 2\frac{1}" diam., plugging some of \frac{1}" holes near outlet, alternate holes for first 4', and every third hole for next 4', pitting did not recur, even though water distr. along trough for all boiler outputs not perfect.-Ralph E. Noble.

Fixing and Determining Oil in Feedwater and Boiler Water. C. A. Noll & W. J. Tomlinson. Ind. Eng. Chem.—Anal. Ed. 15: 629 (Oct. '43). Available methods for oil detn.: (a) std. method, involving extraction of residue on evapn. by petroleum ether; (b) tech. method, liquid-liquid extraction with chloroform; (c) ether extraction method, liquid-liquid extraction; (d) Am. Boiler Mfrs.

aı

gr

fa

be

pe

Ty

no

tio

of

res

res

chl

tre

cm

ter

exp

kg.

We

exc

sati

and

adv

valı Wo

able

for

shou

ble

salt

wate

tem

rege

used

coole

mov

softe

Wofa

conta

plete

rials

which ter a

and i

other

throu

excep

must

for c

Assn. Method involving acidification and extraction with chloroform or ether, or low temp. concn. before extraction; and (e) Scott's method, in which oil adsorbed on ferric hydroxide floc and then extracted. Direct extraction methods err by including some inorg, salts in wt. of oil residue. Scott method fails to recover oil which has separated on walls of container during standing. Method described, modification of Scott method, fixes oil on floc at source of collection.—A. A. Hirsch.

Steam Contamination by Aquaglobejection. R. W. SENIFF. Bul. Am. Ry. Eng. Assn. 446: 57 (July '44). Research program started in '27 on Alton RR, to det, cause and remedy for boiler water carry-over. Equip. developed which can be used to differentiate between carry-over resulting from foam and moisture ejected into steam space from bursting of steam bubbles, which investigation has indicated to be of considerable importance in boiler operation. Author has termed this ejected moisture which carries boiler water salts as "aquaglobejection" to differentiate this from carry-over from foam. Larger particles, of sizes up to 4-in. diam., called "micraglobes" and smaller, of fog or mist proportions "migroglobes." Photographs taken with this equip, show ejection definitely above water surface from bursting bubbles, of various particles of moisture from microscopic size to larger dimensions, based on qual, of water and size of bubbles. Layer of foam on surface, such as occurs when water of high concn. boiled, appears to retard moisture ejection, which explains why trouble has not been serious in locomotive boiler operation but may be contributing cause for turbine blade deposits with steam from h-p. boilers. Details of test equip. and photos of results given.-R. C. Bardwell.

Internal Feedwater Treatment of Locomotive Boilers. JEAN DE FRANK. Proc. Master Boilermakers Assn. 69 ('44). After description of possible reactions taking place in treatment of water with org. colloids, claim made that all-colloidal water treatment does not soften water or cause changes in chem. composition of impurities but, instead, helps to ppt. and renders them harmless by purely phys. process. Development work claimed to have been done at Riga, Latvia, but no specific data given for such treatment on railroads in U.S.—R. C. Bardwell.

Methods for Taking Water Spimples. R. M. Stimmel et al. Am. Ry. Eng. Assn. 46: 448: 66 (Nov. '44). Progress report calls attention to precautions to be taken in obtaining representative water sample from locomotive boilers and avoid loss from "Flashing."—R. C. Bardwell.

Mechanics of Foaming and Carry-Over in Locomotive Boilers. WALTER LEAF ET AL Am. Ry. Eng. Assn. 46: 448: 59 (Nov. '44). Foam height found to be critical formation of vol. rate of steam evolution and for any vol. rate there is limiting foam height which does not depend on composition of dissolved solids Calcite pptd. inside boiler or later added increases foam height beyond that from dissolved solids only if appreciable amt, of foam caused by dissolved solids, but max. foam that can be formed by any combination corresponds to limiting foam height caused by rate of evapn. Mg(OH)2 first depresses foam height, later increases it and then gradually loses its stabilization power.-R. C. Bardwell.

Study of Treating Boiler Feedwater. C. A. HARPER ET AL. Proc. Master Boilermakers Assn. 63 ('44). Replies from 36 railroads to questionnaire developed that scale formation no longer problem with proper water treatment. Foaming and carry-over still matter of major concern and recommendation made to increase steam space in boilers to permit raising point of critical concn. and to control concn. by well-supervised blow-down schedule. —R. C. Bardwell.

Modern Treatment of Feedwater Using Wofatits (artificial-resin exchange materials). W. WESLY. Chem.-Ztg. (Ger.) 67: 338 ('43). Methods of treating water for boiler feed may be divided into 2 classes: those depending on pptn. of substances to be removed from water and those depending on ion exchange. Disadvantages of former class of method discussed. Ion-exchange methods remove only electrolytes from water. Characteristics required in water to be used for boiler feed and methods for removal of suspended matter, oil, iron, manganese, bicarbonate, carbon dioxide silica and sodium hydroxide described. Properties of synthetic resins (Wofatits) discussed. Synthetic resins capable of removing ions from soln. by reversible exchange process. Both cation- and anion-exchange materials condensation products of aromatic compds. of acid character, particularly phenols, with aro01.37

R

. 46-

s at-

ining

otive

er in

'44).

on of

vol

does

olids.

d in-

dis-

foam

that

orre-

rate

foam

ually

lwell.

C. A.

akers

ds to

ation

reat-

atter

made ermit

ntrol

edule.

Using

ials).

('43).

may

ng on

water

Dis-

dis-

only

cs re-

d and

r, oil,

oxide.

Prop-

issed.

from

Both

COn-

is. of

h are-

matic or aliphatic sulfo- or carboxylic acids. and with aldehydes, particularly formaldehyde. Anion-exchange materials condensation products of aromatic or aliphatic amines with aldehydes and related compds. Possible to produce cation-exchange materials which will remove carbonate but not non-carbonate hardness. Synthetic resins have large surface. area and therefore high rate of exchange, and great mech. stability. Filter medium can be fairly coarse. Resins do not yield to water being filtered any silica or org. matter. Susnended matter must be removed from water which is to be filtered through synthetic resins. Type of resin suitable for treating hot water not necessarily suitable for cold water. Cation-exchange materials generally used in form of sodium salts; cations in water taken up by resin which liberates sodium ions. When resin exhausted, regenerated with sodium chloride. Specific load, that is, vol. of water reated (in cm./hr.) divided by vol. of resin (in cm.) varies with different cation-exchange materials between 10 and 25. Exchange capac. expressed as wt. of ions absorbed (expressed as kg, of calcium oxide) by 100 l. of resin. Wofatit P in large-scale operation has shown exchange capac. of 1.0 to 1.1; it has been used satisfactorily to treat water at temp. of 95°C. and with pH value of 8.5, and has not been adversely affected by boiler water with pH value of 10.6 and temp. of 95°C. Stability of Wofatit P to heat makes it particularly suitable for softening condensate. Salt soln, used for regeneration of cation-exchange resins should be clear and should be as free as possible from hardness-forming salts. Temp. of salt soln. should be about same as that of water to be treated to prevent fluctuations of temp. in filter. To displace salt soln. after regeneration, softened or raw water may be used; recently boiler water, which has been cooled and from which sludge has been removed, has been used. Hardness in water softened by Wofatit resins 0.05° (Ger.) or less. Wofatits P and KS will soften water which contains much sodium chloride. For complete removal of salts cation-exchange materials used in form of acids. If Wofatit used in which acid stronger than mineral acids in water all cations in water replaced by hydrogen and filter effluent contains carbonic acid and other mineral acids. If this effluent now flows through anion-exchange material, all acids except carbonic acid removed. Carbonic acid must be subsequently removed. Specific load for complete removal of salts about 10.

Cation-exchange material regenerated with soln. contg. 50 to 70 g. of hydrochloric acid per l.; amt. of hydrochloric acid required varies between 180 and 230% of calcd. amt., that is, between about 24 and 30 g. per deg. (Ger.) of hardness removed per cm. of filter medium. Anion-exchange material regenerated with soln, contg. not more than 20 g. of sodium hydroxide or 100 g. of sodium carbonate per l. Amt. of alkali required up to 200% of calcd. amt. Freshly regenerated anion-exchange material releases some alkali into treated water; when resin becoming exhausted small amts. of hydrochloric acid appear in water. Fluctuations in pH value due to these compds. can be avoided by subsequent filtration of water through buffer filter. which is usually cation-exchange material. At first this filter takes up sodium ions and releases hydrogen ions; later opposite reaction occurs. Filter therefore automatically regenerated and pH value of water remains practically const. Removal of salts from water contg. much sodium chloride usually achieved by filtration through 2 filters in series. Divalent ions more readily removed than monovalent ions. Wofatit P and Wofatit M used for treating hot water. Compn. of water to be treated affects type of prelim. treatment given, choice of Wofatit, and size, number and arrangement of Wofatit filters. If desired to remove carbon dioxide and hardness-forming compds, but not all cations, water divided into 2 parts. One part filtered through hydrogen-exchange material, and other through sodium-exchange material. Proportions of 2 parts so adjusted that acids in one part just sufficient to neutralize sodium bicarbonate in other part. After neutralization free carbon dioxide removed. In another method for partial removal of salts, water first filtered through hydrogen-exchange material in which acid not sufficiently strong to decompose non-carbonate hardness but which decomposes carbonates. If filter effluent contains small amts. of mineral acids passed through buffer filter contg. cation-exchange material such as Wofatit C; this removes mineral acids and non-carbonate hardness but not carbonic acid. Effluent contains sodium salts instead of non-carbonate hardness and free carbon dioxide instead of carbonate hardness. Complete removal of carbon dioxide and oxygen from water can be achieved only by chem. methods. Carbon dioxide formed in boilers by decompn. of sodium carbonate neutralized by addn. of ammonium salts,

which give condensate pH value above 9 and make it non-corrosive. 3 examples given of treatment of feedwater for boilers operating at pressure of 120 atm. In first example, raw water is well water contg., in mg./l., total solids 220 to 290; sulfate 40 to 60; chloride 25 to 45; silica 8 to 12; and having carbonate hardness of 6° to 8° (Ger.); non-carbonate hardness of 2.2° to 4.5° (Ger.); and potassium permanganate demand of 6 to 9 mg./l. Water heated to 97°C, and treated with 200 g, of calcined dolomite per cm. in mixing tanks with period of retention of 4 min. before flowing to sedimentation tank with period of retention of 2 hr. Water next pumped through Magno filter, and, after addn, of sulfur dioxide to remove oxygen, passed through Wofatit filter. Mixt. of ammonium sulfate and diammonium phosphate added to feedwater, which contains, in mg./l., total solids 160 to 200, silica 0.25, and combined carbon dioxide 8 to 11 (expressed as sodium bicarbonate). Contains no oxygen and has hardness of 0.015° (Ger.). Wofatit regenerated with dil. soln. of sodium chloride at temp. of 75°C. Hardness removed by 100 I. of Wofatit equivalent to 1.13 kg. of calcium oxide. No deposits have formed on turbines. In second example boiler operates on condensate to which added up to 30% of chemically treated water. Raw water contains, in

mg./l., chloride 30 to 40, sulfate 60, and silica 11 to 12; has carbonate hardness of 1.0° to 1.5° (Ger.), total hardness of 5° to 7° (Ger.) magnesium hardness of 2° (Ger.), and potassium permanganate demand of 40 to 100 mg.A Treatment carried out in cold. Sodium aluminate and magnesium chloride added in raw water. Mixing tank and sedimentation tank together have period of retention of 2 hr. Water next passed through Magno filters Wofatit KS filters and Wofatit P filter. Fi nally oxygen removed first by heating and then by treatment with sodium sulfite. Feel. water contains 0.3 mg. of silica per l. and has hardness of 0.02° (Ger.). In third example raw water same as in second. To raw water is added 40 g. of ferric chloride per l.; water next filtered through gravel filters without being allowed to settle. Then filtered through cation- and anion-exchange materials and through buffer filter. Oxygen removed by heating water to 103°C. and by addn. of sodium sulfite. Treated water contains no sulfate, 3 to 7 mg. of chloride per l., and 9 mg. of silica per 1., and has hardness of 0.02 (Ger.) and potassium permanganate demand of 10 to 20 mg./l. Make-up water amts, to 10% of boiler water, so that concn. of silica in boiler only 0.9 mg./l. Operation has been satisfactory over period of 18 mo. - W.P.R.

CHEMICAL FEEDING, CONDITIONING AND SEDIMENTATION

The Development of Emergency Equipment at Montebello. A. A. BAILEY. Proc. Md.-Del. W. & Sew. Assn. p. 51 ('44). Alum soln. control: Original alum soln. controllers consisted of const. level tank with adjustable orifice at bottom. Const. level controlled by balanced piston valve operated by float. These valves so large in comparison with quant. of soln. passing through them that small objects, such as match sticks, would wedge themselves between seat and disc and prevent them from shutting off properly. Valves recently replaced by pinch valve arrangement, consisting of piece of 2½" pure gum hose, 8" long, clamped to inlet pipe and pinch arm operated by float. Outlet in bottom of controller consisted of bronze ring bolted to c-i. base and cylinder having irregular-shaped slot cut in one side forming orifice. Cylinder could be raised and lowered through ring to give necessary rate of flow (Fig. 1). Combined chem. action of alum

and abrasive material carried in soln., cut into surface both of cylinder and ring, so that in very short time after new outfit installed would be necessary to set back on opening to secure proper quant. Also, impinging of soln. on side opposite orifice slot would som cut through cylinder. Thickening of wall at this point helped to increase life of cylinder. Because of these difficulties decided to try new arrangement. Original controller lead lined and used simply as const. level tank and soln. piped to new controller orifice. Controller consists of short lead cylinder 4" in diam. with hard rubber nozzle and plug with bronze stem. Held in place by framework in which it is free to slide in order to secure proper elevation. Orifice adjustment made by means of knarled nut on stem held in place by framework supporting indicator and dia Dial marked in percentage of capac. If in dication had been made to show percentage of capac. by direct reading of movement of stem

perceduced them ing of easily Pin is slot point and significant si

by cl chang opening opening above of 40 g tom of above Valve

contro

ol. 37

cut into

that in

istalled.

opening

nging of

ald soon

wall at

ylinder.

try new

ad lined

nd soln.

ontrolle

diam.

h bronze

in which

e proper

place by

nd dial

. If in-

entage of

of stem



Fig. 1. Alum Controller

percentages between 20 and 50 would be so dose together would be impossible to read them accurately. In order to get even spacing on dial and large enough spacing to read easily, arrangement made as shown in Fig. 2. Pin in end of arm attached to stem slides in slot in pointer. This makes movement of pointer greatest when stem movement is least and smallest when stem movement is greatest, giving nearly even spacing on dial. Original idea was to have 2 methods of regulation, one by changing elevation of nozzle, thereby changing head, and other by changing orifice opening. Satisfactory results obtained by keeping head const. and varying nozzle opening only. Now operating with 3'9" head above nozzle opening which gives max, output of 40 gpm. Soln. not taken from extreme bottom of controller but from point about 20" above bottom, elimg. much of heavy sludge. Valve provided at bottom of cone-shaped controller to flush out sludge. After 16 yr.




Fig. 2. Alum Controller-Indicator

of service of one of these nozzles no appreciable wear on any rubber or lead parts. Only parts that have had to be replaced are bronze stem and bronze tip on rubber plug. Lime soln. controller: Lime soln. hard to control accurately due to clogging of orifice openings, especially during low flows. Best arrangement for handling this material is with simple pinch valve made of piece of rubber hose, preferably sandblast hose, which, while soft, has enough rigidity to hold its shape even under suction (Fig. 3). Two of these outfits in use at present time. In one, control accomplished by cam pressing against swinging plate which in turn flattens hose to secure



Fig. 3. Lime Controller

desired opening. Arm, which operates cam, clamps to quadrant to maint. desired setting. Quadrant also graduated to show degs. of opening. In second case, control accomplished by use of old 21" valve bonnet and stem, welded to framework which supports hose. Bar that presses against hose fastened to inner end of stem so that stem free to turn. Gives better control because finer adjustment can be made with screw than with cam and lever. Any clogging that might occur in restricted section of hose easily and quickly elimd, by opening valve wide for second and then returning it to its original setting. Lime does not have same tendency to build up on hose as on metal parts. With even less attention control as accurate as with metal valves and only critical material necessary is about 10" of rubber hose. Sand washing: Experienced much trouble with mud balls in filters and washing with Nichols equip. did not remove them. After sand completely washed and returned to filter and filter backwashed, top several in. of sand contained innumerable mud balls, approx. size of peas. These very soft and by running sand through two ejectors instead of one, mud balls could be completely removed. To accomplish double ejection before sand entered separator, welded extra high section on top of std. ejector hopper. One side of extension 2"

lower than other three and bent over to form overflow from hopper. Necessary because impossible for second, ejector (see Fig. 4), same size as first, to carry combined output of first ejector plus its own water. Trough with 3" outlet at one end attached under this overflow and piece of 3" downspouting carries overflow waste to wash trough. Trouble experienced at first with air drawn into first hopper causing great amt. of boiling up and spattering in second hopper. Overcome by hanging series of baffles in second hopper. With this arrangement sand discharged from separator completely cleaned and free from mud balls. Handling wet copperas: Until few vears ago dry ferrous sulfate purchased in carload lots and stored in bins. In last few years wet copperas purchased locally at much lower cost. Originally this material dissolved by placing it in tank which had spray pipes in bottom. Water from spray pipes aided by occasional stirring with shovels, dissolved copperas and soln, run into soln, tank. Wet copperas delivered in drums contg. about 200 lb. Drums raised by elec. hoist and dumped into dissolving tank. Next built concrete hopper with ejector in bottom. Drums handled in same way as before and dumped into hopper. Spray pipes around top washed copperas down and ejector forced mixt, out and through 25' length of 3" hose



Fig. 4. Second Sand Ejector




Fig. 5. Portable Emergency Chlorinator

FIG.

ol. 37

form

cause

utput

rough

er this

carries

rouble

o first

p and

ne by

opper.

from

from

til few

sed in

st few

much

1 dis-

spray

pipes

ls, dis-

tank.

about

t and

built

ottom.

re and

round

forced
' hose

to soln. tank. When copperas reached soln. rank completely dissolved. This work done an second floor of chem. bldg., necessitating considerable handling of drums. To lessen work and elim. much of mess due to leaky drums and careless handling, decided to put dissolving equip. in basement. Shute built through large window, down which copperas dumped directly from truck. Wooden platform built under shute and from this copperas shoveled into hopper ejector similar to Nichols sand ejector. Hopper and ejector made of bronze which holds up very well under action of copperas. Mixt. of water and copperas nasses through hose to small tank and from this tank pumped by Duriron pump to soln. tanks. With this method of handling any mess that might occur can be easily flushed down basement drain and mixing room can be kept dry and clean. If dry material used shoveling would be elimd, as it could be run directly from storage bin into hopper, but in case of wet material, this cannot be done.




Fig. 6. Chlorinator—2000-lb./Day Capacity

Possible to dissolve and deliver to soln tanks from 61 to 81 tons of copperas per hr., depending on its condition. Chlorinators: 2 types of chlorinators for emergency use, one a portable outfit for use in chlorination of mains, other used in Montebello plant to supplement regular equip. in handling large quants. of chlorine until central chlorinator station built with up-to-date equip. 16 portable outfits, built at beginning of war with idea of chlorinating mains after bombing raid. Very simple in design, consisting only of hard rubber ejector, necessary hose for handling pressure water and chlorine soln., soln, tube and copper tube to connect ejector to chlorine cylinder. Soln. tube made from piece of 3" od. copper tubing, lined with piece of 37" wall rubber tubing \formall' id. Rubber tubing pulled through copper tube and about 2" on end folded back on outside of copper tube, over which soln. hose clamped (Fig. 5). So far, this soln. tube has proved very satisfactory for emergency use and could be used to replace std. silver tube on permanent installations in case of necessity until new one could be secured. Entire outfit can be made for about \$50, including labor and material. After war plan to build central chlorinator station which will supply post-chlorination to water before it is divided between two filtration plants. With increased demand for water during last few years, and fact that rate of chlorination greatly increased, became necessary to add to chlorinating equip. Rather than purchase extra equip., which probably would not be satisfactory for future development, decided to build 2 emergency outfits to carry over until new program could materialize. These outfits use ordinary line regulator, mfd. by Alexander Milburn, from which seat and disc have been removed and silver parts substituted. Rate of flow of gas can be controlled by varying pressure through this regulator. Quant. measured by Schutte-Koerting rotometer. Second Milburn regulator connected to outlet of rotometer to act as back-pressure valve. From this gas piped to hard rubber ejector and from thence to water. One of these outfits has capac. of 1200 lb. per day and other has capac, of 2000 lb. per day (Fig. 6). Have proved very satisfactory for manually-operated machine where control does not have to be perfect. Cost of building one of these units approx. \$150, including labor and material.—Ed.

inator

"Flexiflow" Automatic Chemical The Doser. Anon. Wtr. & Wtr. Eng. (Br.) 48: 145 (Mar. '45). Unifilters "Flexiflo" chemical doser effects rate of admin. of chems. so that it keeps in step with flow being treated. Operated by water pressure. Diaphragm controlling element connected across Venturi tube fitted in main at point where treatment is desired. Differential pressure causes diaphragm to pulsate with frequency in direct ratio to rate of flow through Venturi tube. Valve gear supplies operating water to one or more diaphragm-type chem. pumps so that their movement is synchronized with that of motive unit. Normal range of these machines has been designed to give 8:1 ratio. Larger or smaller ratios can be dealt with. Three sizes of units have been designed: 5, 15 and 45 gal. (Imp.) per hr. These chem. dosing sets have been supplied to Army for mobile sterilization units.-H. E. Babbitt.

Chemical-Mechanical Treatment of Water With FeCl₃. A. K. MEHNER. Chem. Tech. (Ger.) 15: 129 ('42). Use of FeCl₃ in purif. of water, sewage and trade-waste waters discussed. Solns. of FeCla varying in strength from 50 to 400 g./l. used. Dose required varies with each water; as small a dose as possible should be added to avoid unnecessary costs and formation of bulky sludge, but below certain concn. pptn. slow and incomplete. This coagulant will remain in treated water if too little has been added or if too little alkali present; when FeCl₃ used, this is readily detected by yellow color of water. Adequate mixing of FeCl, with water essential, either by baffles, aeration or stirring. Floc removed by settling, with or without final nitration, or by direct filtration through coarse and fine filters in series. FeCla added to water coagulates fine suspended and colloidal matter and removes color, org. Fe and Mn compds., H2S, sulfides, NH3, silica, oil, algae and bacteria. In aq. soln. FeCla dissociates into ferric, hydroxyl, H and chloride ions. HCl produced neutralized by Ca-(HCO₃)₂ in water or by added alkali, and flocs of gelatinous Fe(OH)3 formed. Content of chloride in treated water increased, but this does little harm. Fe(OH)3 floc has very large surface and adsorbs fine suspended matter. Pos, ferric ions neutralize negative charge on colloidal matter which is then adsorbed on floc. Up to limit, increasing quants. of

suspended matter make water easier to treat. Sulfides form Fe₂S₃, and if they are present in any quant. precautions must be taken to prevent their remaining in colloidal state. Eff. of coagulation by FeCl, only slightly decreased at low temps., and improved at high temps. Coagulation effective over relatively wide range of pH values. In acid waters, addn. of alkali necessary to insure pptn., and in very alk. waters coagulant can be saved by adding acid to neutralize some of alkali. Special uses of FeCla discussed. Ow. ing to increasing demand for drinking water. surface waters and ground waters of inferior qual, have had to be used. These waters must be treated for removal of color, turbidity, Fe, Mn, org. matter, H2S, tastes and odors and bacteria. All removed by treatment with FeCl3. Process also suitable for treating indus. water supplies, including boiler feedwater. Up to present, chem. mech. treatment of sewage with FeCla has been little investigated. Amt. of solid matter removed by settling can be greatly increased by coagulation with FeCl₄. Coagulation can be used intermittently, at times when sewage particularly strong. If sewage has become septic, FeCla will remove H2S which has been produced. On avg., chem. treatment, compared with settling only, improves removal of B.O.D. by 100%, of settleable solids by 57%, and of bacteria by 33%, and process also highly accelerated. Biol. treatment will produce more highly purified effluent than mech. treatment, but trickling filters produce odors and encourage flies, and activated sludge process very sensitive to changes in compn. of sewage, so therefore cannot be used when any large quant, of trade-waste waters reaches sewage works. Many cases where chem.-mech. treatment purifies sewage sufficiently for discharge to stream. Costs of various processes compared. Prelim. treatment with FeCl₃ can be used to improve performance of overloaded biol. sewage-treatment plants. FeCla can be used for treating many types of trade-waste waters, either alone or in admixt. with sewage. Sludge from pptn. with FeCla digests more rapidly than sludge from simple sedimentation and though vol. of sludge greater, digestion tanks of greater capac. not required; compn. of sludge gas not affected. Sludge contg. FeCl suitable for use as fertilizer and readily de watered on vacuum filters.—C.A.

Vol

I's men

D

it a have lish cour serv Geor

land Nord lina, consi

New ing t At Ham

chuse

out s Th Missi